

SS. REC. BY:

REF: CS/MSG/1906188/R1qf3

Special Instruction: 12

SURVAYOR: Raisal

ASSIGNMENT (Office)

From (Person): Christine Wong of MSG Date/Time: 12.9.19 15.44p.m

Estimated Cost: Bill to:

OD (TP) WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SLE 256K Insured: SGX 8417U

at Workshop m/s Teamwork Garage Tel: 66442475

of 53 Ubi Ave 1 #01-24

Policy No: 80457010 Claim No: 605352

Sum Insured: Excess:

Make of Veh: D.O.A. 7.9.2019

(Client's Record)

CA / REV / REP. / REV 24 HRS

Date/Time: 12.9.19 3.52pm Person Contacted: Shu Shan

H.O.D. Endorsement:

Vehicle IN/OUT

Date/Time	Action/Instruction (✓) Estimate
	SLE 256K - NA/LIP19015966/24 D.O.A. - 07/09/2019
	SGX 8417U - NA/LIP19015966/24 D.O.A. - 07/09/2019
16/9/19 @ 9.59am	revised to Christine Wong via Meimuen.
11/10/19 @ 12.16pm	Ram analysed is \$10000 with Darren.
	(Red \$2768.21, 73%.)

ASS. REC. BY:

REF: MS19

7222

ASSIGNMENT

From:

Date: 13.9.2019

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SLE 256 K

at Workshop m/s Teamwork Garage
of 53 vbi Ave 1 #01-24

Insured:

Policy No.


Claims No.

Sum Insured: Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

46K

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

16 days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

my

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

SLE 256K

Yr Regn: 2016 / July

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

MITSUBISHI ATTAGE 1200 c.c 1A3

Colour:

Grey

A/C: Insured / Std / NI / NA

Sp. Reading:

253616

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

MMBSTA13AHH001581

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

185/55R15

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

NEUMON

Front

Rear

R/Bal.

5

mm

R/Bal.

5

mm

L/Bal.

5

mm

L/Bal.

5

mm

D.O.A.

07/09/19

D.O.I.

13/09/19

Survey held at

Teamwork

Des. of Damages: Fr / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

refer to email for repair limit

Repair limit is 10K

RECEIVED 15 OCT 2019

Date/Time, File Pass to?



Preli. Report

1) 15/10 11:58



Final Report

Date/Time, File Return to?

2)

Rep. Form:

MER-TP

Lump Sum / F.P. / C.

10000

Days Of Repair:

16

Resurvey No. of Trip:

2

Add Fee:



Site Insp (\$)



Interview (\$)



Tech. Invs (\$)



Week end (\$)

Survey Fee:

Transportation:

S + RS, SI

Photos

Others

TOTAL

250

11

261

Note: This document has not been finalised.**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Christina Wong

Date: 16 Sep 2019

Preliminary Advice

Insured Vehicle No	: SGX8417U	Accident Date	: 07/09/2019
TP Vehicle No	: SLE256K	Assignment Date	: 12/09/2019
Make	: MITSUBISHI ATTRAGE	Est. Duration of Repair	: 16.00
Date of Inspection	: 13/09/2019		
Inspection At	: TEAMWORK GARAGE PTE LTD (HQ) 53 UBI AVE 1 #01-24, PAYA UBI INDUSTRIAL PARK SINGAPORE 408934		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front and rear portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	37,168.21
Revised Amount	:S\$	18,498.48
Check Items (Estimated)	:S\$	4,051.64
Total	:S\$	22,550.12

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	
COE / PARF Rebate	:S\$	
Salvage Value	:S\$	
Margin for Repair	:S\$	

Remarks

- () The vehicle is economical/not economical for repair.
- (X) The above survey was conducted on a 'without prejudice' basis.

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	09 Sep 2019		12 Sep 2019 15:44 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS		[Created by insurer]							
Insured:	ASCENXUS PTE LTD, Co. Reg. No.: 201536828D, Tel: +6581112875								
Main Claimant:	ROSET LIMOUSINE SERVICES PTE LTD, Co. Reg. No.: 200406722Z								
Vehicle Reg. No.:	SLE256K	Date of Loss:	07/09/2019 12:00 - :59 [38 Months and 3 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 605352	Policy/Cover Note No.:	80467010 (Comprehensive) Coverage: 10/03/2019 - 09/03/2020						
Vehicle Reg. No. (Insured):	SGX8417U	Policy No. (Claimant):							
		Excess:	S\$500.00						
Repairer:	Teamwork Garage Pte Ltd (HQ) 53 Ubi Ave 1 #01-24, Paya Ubi Industrial Park, 408934 Ubi - Tel: 6844 2475								
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Christina Wong - 6643 1311]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 13/09/2019]								
Driver/Custodian (Insured):	TAN CHEAH HOONG (CHEN ZHENGHONG) (30 / Male) , NRIC: S8847357D, Tel: +6581575097 Email: JOE.TAN@ASCENXUS.COM								
Adj Asg. Remarks:	on WP, please arrange ASAP. Workshop selected LKK to suvey. Liab: 100%. Agree on SJE. Contact: Su San / Darren @ 6844 2475.								
ASSOCIATED MAIL RECEIVED		View All Compose Case Mail							
There are no mail for this case.									
ALL ASSOCIATED TASKS									
View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Rasul (LKKAUTO)

From: Rasul (LKKAUTO)
Sent: Friday, 11 October, 2019 12:16 PM
To: Darren
Subject: RE: SLE 256K DOA : 07/09/19

Hi Darren,

Finalised amount at \$10K is confirmed

Best Regards,

Rasul | Assessor

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Rasul@lkkauto.com | fax: 6841-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



Auto
Consultants
Pte Ltd

Save the Earth. Print only when necessary.

From: Darren [<mailto:claims@teamworkgarage.com>]
Sent: Wednesday, 9 October, 2019 6:18 PM
To: Rasul (LKKAUTO)
Subject: RE: SLE 256K DOA : 07/09/19

Hi Rasul,

Can we close?

Darren
Teamwork Garage Pte Ltd
53 Ubi Avenue 1
#01-24 Paya Ubi Industrial Park
Singapore 408934
Tel: 68442475
Fax: 68442474

From: [Rasul \(LKKAUTO\)](#)
Sent: Friday, 13 September 2019 5:34 PM
To: [Darren](#)
Subject: SLE 256K DOA : 07/09/19

Hi Darren,

As spoken,

Repair limit for this case is 10K

Best Regards,

Rasul | Assessor

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Rasul@lkkauto.com | fax: 6841-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



Auto
Consultants
Pte Ltd

Save the Earth. Print only when necessary.

Shiau Chan (LKKAuto)

From: Darren <claims@teamworkgarage.com>
Sent: Monday, 30 September 2019 10:26 AM
To: Rasul (LKKAuto)
Subject: RE: SLE 256K DOA : 07/09/19
Attachments: 2b5cd349-71aa-4cbe-ab73-cb8b2caff8f4.jpg;
4f788b31-4742-447e-9f8a-5d6f764ddd33.jpg; 21ebc6a0-f46e-4bc0-a16c-87d65c3d14ff.jpg; 79090fa2-ba99-4499-96e2-b452ff767ba6.jpg;
79325b85-174b-4e72-9ab8-884146c77eeb.jpg; 4810763e-0230-4c76-a4b1-e6cefc61e5cc.jpg; image001.jpg

Hi Rasul,

FYNA

We refer to your email dated 13 Sept 2019.

Repair limit @ \$10k.

Please confirm so that we can close case

Darren
Teamwork Garage Pte Ltd
53 Ubi Avenue 1
#01-24 Paya Ubi Industrial Park
Singapore 408934
Tel: 68442475
Fax: 68442474

From: Rasul (LKKAuto)
Sent: Friday, 13 September 2019 5:34 PM
To: Darren
Subject: SLE 256K DOA : 07/09/19

Hi Darren,

As spoken,

Repair limit for this case is 10K

Best Regards,

Rasul | Assessor

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Rasul@lkkauto.com | fax: 6841-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



Auto
Consultants
Pte Ltd

Save the Earth. Print only when necessary.

Rasul (LKKAUTO)

From: Rasul (LKKAUTO)
Sent: Friday, 13 September, 2019 5:34 PM
To: 'Darren'
Subject: SLE 256K DOA : 07/09/19

Hi Darren,

As spoken,

Repair limit for this case is 10K


Best Regards,

Rasul | Assessor

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Rasul@lkkauto.com | fax: 6841-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



Auto
Consultants
Pte Ltd

Save the Earth. Print only when necessary.

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Details	
Owner ID Type:	Company
Owner ID:	722Z

Vehicle Details	
Vehicle No.:	SLE256K
Vehicle to be Exported:	No
Intended Deregistration Date:	13 Sep 2019
Vehicle Make:	MITSUBISHI
Vehicle Model:	ATTRAGE 1.2 CVT
Primary Colour:	Grey
Manufacturing Year:	2016
Engine No.:	3A92UDH3361
Chassis No.:	MMBSTA13AHH001581
Maximum Power Output:	57.0 kW (76 bhp)
Open Market Value:	\$14,083.00
Original Registration Date:	04 Jul 2016
First Registration Date:	04 Jul 2016
Transfer Count:	1
Actual ARF Paid:	\$5,000.00

Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	03 Jul 2026
PARF Rebate Amount:	\$3,750.00

Intended COE Rebate Details	
COE Expiry Date:	03 Jul 2026
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$47,020.00
COE Rebate Amount:	\$31,998.00
Total Rebate Amount:	\$35,748.00

The information contained herein is correct as at 13 Sep 2019

OK

45,000
35,748

10,252

(10K)

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	09/09/2019 18:47
Date Of Accident	07/09/2019 12:50
Exact Location Of Accident	PIE (CHANGI) BEFORE KIM KEAT LINK EXIT
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLE256K
Insured/Policyholder	
Name Of Registered Owner	ROSET LIMOUSINE SERVICES PTE LTD
Co Reg No	200406722Z
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-89999999

Vehicle Particulars

Manufacturer	MITSUBISHI
Model	ATTRAGE 1.2 CVT
Exact Purpose for which vehicle was being used at time of accident	COMMERCIAL USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE HIRE

Insurance Company

Name of Insurance Company	LIBERTY INSURANCE PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	SD18V12322/VPZ/R00
Cover Note Number	

Driver

Name of Driver	MOHAMED IZZUL BIN MOHAMED TAHIR
NRIC No	S8737913B
Date Of Birth	24/11/1987
Occupation	OUTDOOR
Date Of Driving Pass	04/02/2016
Driving Experience	3 YEARS AND 7 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-94522415
Fax Number	
Contact Number	OFFICE-94522415
Email Address	NOEMAIL

Address	BLK 293D BUKIT BATOK STREET 21 #05-536
Postcode	654293
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - HIRER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	CHAIN COLLISION
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	4
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	3
Passenger 1	NAME: : DIAN IZZATI BINTE MOHAMED IZZUL GENDER: : FEMALE
Passenger 2	NAME: : DAANIA IZZAH BINTE MOHAMED IZZUL GENDER: : FEMALE

Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	TRAFFIC POLICE DIVISION HQ - SINGAPORE CITY
Police Station Address	ROAD: 10 UBI AVENUE 3 , POSTCODE: 408865 , COUNTRY: SINGAPORE
Police Station Contact	TEL NO: 65470000 - FAX NO:
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO POLICE REPORT - T/20190907/7019.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	VIDEO FOOTAGE WITH DRIVER
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SGX8417U
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR

Name of Driver
NRIC/Passport Number
Contact Number 81575097
Address
Postcode
Insurance Company Name
Nature Of Damage
No. Of Passenger (Including Driver)

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number SLJ5595Y
Vehicle Make/Model/Colour
Details Of Properties
Vehicle Category PRIVATE CAR
Name of Driver
NRIC/Passport Number
Contact Number 97933275
Address
Postcode
Insurance Company Name
Nature Of Damage
No. Of Passenger (Including Driver)

DETAILS OF OTHER VEHICLE PROPERTY 3

Vehicle Registration Number SLG8758R
Vehicle Make/Model/Colour
Details Of Properties
Vehicle Category PRIVATE CAR
Name of Driver
NRIC/Passport Number
Contact Number 83381371
Address
Postcode
Insurance Company Name
Nature Of Damage
No. Of Passenger (Including Driver)

DETAILS OF INJURED PERSON 1

Name MOHAMED IZZUL BIN MOHAMED TAHIR
Approximate Age
Injuries Sustain NECK & BACK
Injured person in which vehicle? SLE256K
Were seat belts worn? YES
Was this injured conveyed to hospital by ambulance? NO
Address
Postcode

DETAILS OF INJURED PERSON 2

Name DIAN IZZATI BINTE MOHAMED IZZUL
Approximate Age
Injuries Sustain NECK & BACK
Injured person in which vehicle? SLE256K
Were seat belts worn? YES

Was this injured conveyed to hospital by ambulance?

NO

Address

Postcode

DETAILS OF INJURED PERSON 3

Name

DAANIA IZZAH BINTE MOHAMED IZZUL

Approximate Age

Injuries Sustain

NECK & BACK

Injured person in which vehicle?

SLE256K

Were seat belts worn?

YES

Was this injured conveyed to hospital by ambulance?

NO

Address

Postcode

Accident Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time




Driver's Signature
(If driver is not the policyholder)
Date & Time

Reporting Centre Personnel's Signature
Name
NRIC/FIN No.:

Accident Sketch Plan

SKETCH PLAN



A SLR256K
B SGX 84174
C SLJ5595Y
D SLG8758R

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Refer to Police Report

DECLARATION

I/We declare the foregoing particulars are true in every respect.



Policyholder's Signature
Date & Time

Driver's Signature
(if driver is not the policyholder)
Date & Time

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No:

Police Report



**SINGAPORE
POLICE FORCE**



T/20190907/7019

1 of 4

Police Station Of Origin:
Traffic Police
10 Ubi Avenue 3 SINGAPORE 408665
Tel No: 65470000

Report No. T/20190907/7019

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 07/09/2019 17:16		Vide Report No.:		Station Diary No.:	
Informant's Particulars					
Name of Informant: MOHAMED IZZUL BIN MOHAMED TAHIR			Address: APT BLK 293D BUKIT BATOK STREET 21 #05-536 SINGAPORE 654293		
ID Type / ID No.: NRIC NO / S8737913B			Contact No.: Home/Office: Mobile: 94522415		
Nationality: SINGAPORE CITIZEN			Email: eezul87@gmail.com		
Sex: Male	Age: 31	Date of Birth: 24/11/1987	Type of Informant: Driver		
Race: Malay			Language: English		Institution / School Name:
Occupation: Customs/Immigration officer			Driving Licence Information: Class:		Date of Expiry:

General Information of the Accident

Type of Accident:	Injury Others	Drink Drive: No	Date/Time of Accident: 07/09/2019 12:50	Type of Location: Straight Road
Location: PAN ISLAND EXPRESSWAY				
Weather: Clear		Road Surface: Dry		Road Speed Limit:
Traffic Flow: One Way		Traffic Control: Not Controlled		Traffic Volume: Moderate
Type of Collision: Between Moving Vehicles - Head To Rear				Anyone conveyed by ambulance: No

Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
SGX8417U	Car	HONDA	CIVIC		Seriously Damaged	1
SLE256K	Car	MITSUBISHI	ATTRAGE		Seriously Damaged	2
SLG8758R	Car	TOYOTA			Slightly Damaged	0
SLJ5595Y	Car	HYUNDAI			Slightly Damaged	0

Police Report



**SINGAPORE
POLICE FORCE**



T/20190907/7019

2 of 4

Police Station Of Origin:
Traffic Police
10 Ubi Avenue 3 SINGAPORE 408865
Tel No: 65470000

Report No. T/20190907/7019

CONTINUATION OF REPORT

Details of Person Involved			
Any Pedestrian Involved: No			
No. of Pedestrians Injured: NIL		Use of Pedestrian Crossing: NA	
Driver			
Name	MOHAMED IZZUL BIN MOHAMED TAHIR	ID No.	S8737913B
Related Vehicle	SLE256K (Car)	Contact No.	94522415
Hospital/Clinic	NATIONAL UNIVERSITY HOSPITAL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	07/09/2019	Date Discharge	07/09/2019
No. of Days granted Medical Leave	02	Degree of Injury	Slight
Passenger			
Name	DAANIA IZZAH BINTE MOHAMED IZZUL	ID No.	T1804553I
Related Vehicle	SLE256K (Car)	Contact No.	94522415
Hospital/Clinic	NATIONAL UNIVERSITY HOSPITAL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	07/09/2019	Date Discharge	07/09/2019
No. of Days granted Medical Leave	NIL	Degree of Injury	Slight
Passenger			
Name	DIAN IZZATI BINTE MOHAMED IZZUL	ID No.	T1601910G
Related Vehicle	SLE256K (Car)	Contact No.	94522415
Hospital/Clinic	NATIONAL UNIVERSITY HOSPITAL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	07/09/2019	Date Discharge	07/09/2019
No. of Days granted Medical Leave	NIL	Degree of Injury	Slight

Brief Details.

ON 07/09/2019 AT ABOUT 12:52HR, I WAS DRIVING VEHICLE NUMBER - SLE256K, ALONG WITH MY 2 DAUGHTERS ON PIE IN THE DIRECTION OF CHANGI. BEFORE THE EXIT TO KIM KEAT, FRONT VEHICLE SUDDENLY STOPPED, AND I IMMEDIATELY STOP AS WELL, WITHOUT CONTACTING THE FRONT VEHICLE. ABOUT 3-4 SECONDS LATER, I FELT AN IMPACT ON MY STATIONARY VEHICLE'S REAR PORTION. THE GREAT IMPACT CAUSED MY VEHICLE TO PROPEL FORWARD AND HIT ONTO THE FRONT VEHICLE.

1ST VEHICLE - SLG8758R
2ND VEHICLE - SLE256K

Police Report



**SINGAPORE
POLICE FORCE**



T/20190907/7019

Police Station Of Origin:
Traffic Police
10 Ubi Avenue 3 SINGAPORE 408865
Tel No: 65470000

3 of 4

Report No. T/20190907/7019

CONTINUATION OF REPORT

3RD VEHICLE - SGX8417U
4TH VEHICLE - SLJ5595Y

MY DAUGHTERS & I THEN SEEK MEDICAL ATTENTION AT NUH AND I WAS GIVEN 2 DAYS MC.

Police Report



**SINGAPORE
POLICE FORCE**



T/20190907/7019

4 of 4

Police Station Of Origin:
Traffic Police
10 Ubi Avenue 3 SINGAPORE 408865
Tel No: 65470000

Report No: T/20190907/7019

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

Signature Of Officer Recording The Report:
Not applicable

Signature Of Interpreter:
Not applicable

Officer In Charge Of Case:
TP / TPHQ /
YEO GEAK ENG CECILIA
Contact No.: 65476404

Authentication Stamp

NP158

Signature Of Informant:
The identity of the person making this report has
been authenticated by SingPass. No signature is
required.

Date/Time:
07/09/2019 17:16

Classification Of Case:



Pte Ltd

TeamWork Garage Pte Ltd

53 Ubi Avenue 1 #01-23/24 Spore 408934

Paya Ubi Industrial Park

Tel : 6844 2475

E-mail : claims@teamworkgarage.com

Register number : 201015366H

REPAIR PERFORMA INVOICE

MSIG

Vehicle number	SLE256K
Make / Model	MITSUBISHI ATTRAGE 12016
Chassis number	MMBSTA13AHH001581
Accident date	7/9/2019
Reference	1909-14

Qty Particulars Unit Price - SGD \$

PARTS REPLACEMENT - LIST ITEMS	
1	REAR BUMPER <i>de</i>
2	REAR BUMPER RETAINER <i>neu</i>
1pc 2	REAR BUMPER REFLECTOR <i>RH neu / LH-X^{suc} @ 34</i>
2	REAR NUMBER PLATE LAMP <i>X^{suc}</i>
1	REAR NUMBER PLATE WIRE <i>X^{suc}</i>
1	END PANEL <i>bt</i>
1	END PANEL TOP GARNISH <i>de</i>
1	END PANEL OUTER GARNISH <i>X^{suc}</i>
1	END PANEL KEYLESS SENSOR <i>? X^{suc}</i>
1	END PANEL KEYLESS SENSOR SPEAKER <i>X^{suc}</i>
2	TAILLAMP <i>neu @ 295</i>
1pc 2	TAILLAMP PANEL <i>RH-bt / LH-repair @ 155.05</i>
1pc 2	TAILLAMP SEALER <i>RH neu</i>
1	BOOTLID <i>bt</i>
1	BOOTLID LOCK <i>bt</i>
1	BOOTLID LOCK STRIKER <i>bt</i>
1	BOOTLID CHROME OUTER GARNISH <i>neu</i>
1	BOOTLID WEATHERSTRIP <i>cut</i>
1	BOOTLID EMBLEM - ATTRAGE <i>neu</i>
1	BOOTLID EMBLEM - C & C <i>neu</i>
1	BOOTLID EMBLEM - MIVEC <i>neu</i>
1	BOOTLID - LOGO <i>neu</i>
2	BOOTLID HINGE <i>? X^{suc}</i>
2	BOOTLID ABSORBER <i>X^{suc}</i>
1	BOOTLID INNER TRIM <i>X^{suc}</i>
1	SPARE TYRE TOP BOARD <i>neu</i>
1	FLOOR PANEL <i>neu</i>
1	REAR RH CHASSIS MEMBER <i>bt</i>
1	REAR RH WHEEL HOUSE <i>repair</i>
2	REAR FENDER <i>neu @ 723</i>
2	REAR FENDER INNER TRIM <i>de neu @ 154</i>
1pc 2	REAR FENDER AIR VENT <i>RH-X^{suc} / LH-X^{suc}</i>
1	REAR WINDSCREEN MOULDING <i>neu</i>
1	REAR AIR DUCT <i>X^{suc}</i>
1	REAR AIR DUCT COVER <i>X^{suc}</i>
1	REAR EXHAUST SILENCER <i>bt</i>
1	REAR EXHAUST HEATSHIELD <i>X^{suc}</i>
2	REAR EXHASUT MOUNTING <i>neu @ 28</i>
1	THIRD BRAKE LIGHT <i>X^{suc}</i>
2	MUD FLAP <i>X^{suc}</i>

7986

7286

13164.47

6576

1	FRONT BUMPER <i>de</i>	818.80 <i>666</i>
1	FRONT BUMPER TOP BEAM <i>Xsuc</i>	170.00 X
2	FRONT BUMPER RETAINER <i>neu</i>	43.20 ✓
1	FRONT TOP GRILLE <i>neu</i>	410.55 <i>371</i>
1	FRONT LOWER GRILLE <i>de</i>	151.30 ✓
1	FRONT GRILLE EMBLEM <i>neu</i>	48.00 ✓
1	FRONT BUMPER REINFORCEMENT <i>1 Xsuc</i>	350.50 X
2	FRONT BUMPER REINFORCEMENT BRACKET <i>1 Xsuc</i>	312.00 X
1	FRONT TOW COVER <i>de</i>	18.00 ✓
2	HEADLAMP RH-CRA / LH-?CRA @654	1978.00 <i>1308</i>
2	FRONT FOG LAMP X	609.50 X
2	FRONT FOG LAMP COVER X } <i>Xsuc</i>	288.00 X
2	FRONT FOG LAMP CHROME MOULDING X }	210.00 X
1	FRONT SUPPORT PANEL <i>repair</i>	1147.70 X
1	FRONT SUPPORT PANEL TOP GARNISH <i>? de</i>	130.00 <i>59</i>
1	AIRCON CONDENSER <i>? bt</i>	899.30 <i>750</i>
1	AIRCON FAN COWLING <i>? X } Xsuc</i>	237.60 X
1	AIRCON FAN MOTOR X	198.00 X
1	RADIATOR <i>? bt</i>	967.15 <i>912</i>
1	RADIATOR FAN COWLING <i>? X } suc</i>	237.60 X
1	RADIATOR FAN MOTOR X	319.70 X
1	BONNET <i>bt</i>	1200.30 <i>552</i>
1	BONNET INSULATOR X	101.50 X
1	BONNET HINGE X } <i>suc</i>	98.00 X
1	BONNET CABLE X }	59.00 X
1	BONNET LOCK X	247.20 X
1	FRONT FENDER RH-bt / LH-Xsuc @	1988.00 <i>380</i>
1	FRONT RH SEAT ASSY <i>X T w i</i>	1092.50 ✓
1	FRONT RH SEATBELT ASSY X	991.90 X
1	REAR AXLE X	2198.21 X
1	REAR RH WHEEL HUB BEARING X } <i>Xsuc</i>	310.48 X
1	REAR RH WHEEL HUB X }	510.90 X
1	REAR RH SHOCK ABSORBER <i>X ? bt</i>	590.40 <i>225</i>
		32097.76
Less 20%		6419.55
Subtotal		25678.21
Balance C/F		25678.21
<u>PARTS REPLACEMENT - SPECIAL NETT ITEMS</u>		<i>25678.21</i>
Balance B/F		25678.21
1	FRONT NUMBER PLATE <i>bt</i>	80.00 <i>35</i>
1 SET	FRONT BUMPER CLIP <i>neu</i>	50.00 <i>30</i>
2 SET	FRONT GRILLE CLIP <i>neu</i>	100.00 <i>30</i>
1 SET	BONNET INSULATOR CLIP <i>neu</i>	30.00 ✓
1 SET	REAR BUMPER CLIP <i>neu</i>	50.00 <i>30</i>
1 SET	REAR FENDER INNER TRIM CLIP <i>neu</i>	60.00 <i>40</i>
1 SET	BOOTLID INNER TRIM CLIP <i>neu</i>	60.00 <i>40</i>

CDA

18933.29

14,562

20%

11,649.60

1	REAR NUMBER PLATE <i>bt</i>	80.00 <i>35</i>
1	WINDSCREEN SEALANT <i>ne</i>	50.00
1 BOT	COOLANT <i>ne</i>	60.00
1 BOT	BRAKE FUILD <i>X</i>	60.00 <i>Xm</i>
1 SET	REVERSE SENSOR <i>ne</i>	500.00 <i>200</i>
1	REAR NUMBER PLATE GARNISH <i>X</i>	60.00 <i>Xm</i>
1	SUPPORT PANEL TOP GARNISH CLIP <i>ne</i>	60.00 <i>30</i>
1	END PANEL TOP GARNISH CLIP <i>ne</i>	60.00 <i>30</i>
Subtotal		1360.00
Balance C/F		27128.21
S/No	<u>LABOUR AND MISCELLANEOUS CHARGES</u>	
Balance B/F		27128.21
1	CHECK FRONT & REAR WIRING AND LIGHTNING SYSTEM	120.00 <i>60</i>
2	REMOVE, RENEW CONDENSER AND TOP UP GAS	150.00 <i>100</i>
3	REMOVE, RENEW RADIATOR AND TOP UP COOLANT	150.00 <i>80</i>
4	REMOVE, REFIT REAR LINING, TRIM AND GARNISH	200.00 <i>100</i>
5	REMOVE AND RENEW REAR REVERSE SENSOR	150.00 <i>60</i>
6	REMOVE AND RENEW UNDERCARRIAGE	200.00 <i>80</i>
7	MOUNT VEHICLE ON BENCH FOR CHASSIS REPLACEMENT	500.00 <i>250</i>
8	CHECK WHEEL ALIGNMENT	150.00 <i>60</i>
9	REMOVE AND REFIT FUEL TANK	300.00 <i>100</i>
10	REMOVE AND REFIT REAR WINDSCREEN	150.00 <i>100 80</i>
11	TRANSFER PARTS, ATTACHMENT FROM OLD BOOTLID TO NEW	200.00 <i>60</i>
12	REMOVE AND RENEW FLOOR INSULATOR	120.00 <i>Xm</i>
13	REMOVE AND RENEW REAR EXHAUST SILENCER	200.00 <i>100</i>
14	PANEL BEATING ON AFFECTED AREAS	3500.00 <i>2000 2200</i>
15	SPRAY PAINTING ON AFFECTED AREAS	3500.00 <i>2000</i>
16	APPLY ANTI RUST ON AFFECTED AREAS	150.00 <i>100 120</i>
17	REMOVE AND REPASTE STICKER ON AFFECTED AREAS	300.00 <i>Xm</i>
Subtotal		10040.00
Grand total		37078.21
		37168.21

640

5450

Signature
16/9/19

11,649.60 *Resue*
640.00 *Ap 900/100 68*

5450.00
17,739.60 *16 days*

20% *4/5*
14,191.68 *13/09/19 @ 1530*

45-10,000

Repair limit

Require to check mv & repair limit

LKK Auto Consultants hereby notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurer

Acknowledged by Repairer:
Signature:
Date:

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG19016188/R1QF3N2

Date: 17/10/2019

REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	80467010
Claimant Vehicle No :	SLE256K	Insured Vehicle No :	SGX8417U
Date of Loss:	07/09/2019	Nature of Claim:	TP
		Claim No:	605352

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLE256K	Engine No:	3A92UDH3361
Make & Model:	MITSUBISHI ATTRAGE, 1.2 CVT (A)	Chassis No:	MMBSTA13AHH001581
Reg. Date:	04/07/2016 (Man. Year: 2016)	Odometer:	253616 km
Colour:	Grey		
Engine Capacity:	1193 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	185/55 R15	Rear Tyre Size:	185/55 R15
Front Left Side:	Neuton 5 mm	Rear Left Side:	Neuton 5 mm
Front Right Side:	Neuton 5 mm	Rear Right Side:	Neuton 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	27,038.21	12,289.64	14,748.57	54.55
Miscellaneous Items	0.00	0.00	0.00	
Labour	10,040.00	5,450.00	4,590.00	45.72
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	37,078.21	17,739.64	19,338.57	52.16
Approved Total (Overridden) (\$\$)		10,000.00		
(\$\$)	37,078.21	10,000.00	27,078.21	73.03
+ GST 7.00/7.00% (\$\$)	2,595.47	700.00	1,895.47	73.03
Nett Amount (\$\$)	39,673.68	10,700.00	28,973.68	73.03

INSPECTION

Date of Assignment:	12/09/2019	
Date Inspected:	13/09/2019	Inspected At:
		Teamwork Garage Pte Ltd (HQ)
		53 Ubi Ave 1 #01-24, Paya Ubi
		Industrial Park
		Singapore 408934
Estimated Period of Repair:	16.0 days	

Adjuster: MOHD RASUL

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our

knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 17 Oct 2019)	
Parts:	N/A	MITSUBISHI ATTRAGE 1.2 CVT (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLE256K)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	849.60 FL	*708.00 FL
2	2		*REAR BUMPER RETAINER	Necessary	60.00 FL	*60.00 FL
3	1		*REAR BUMPER REFLECTOR	O/s Cracked/N/s Serviceable	68.00 FL	*34.00 FL
4	2		*REAR NUMBER PLATE LAMP	Serviceable	216.00 FL	*- FL
5	1		*REAR NUMBER PLATE WIRE	Serviceable	85.02 FL	*- FL
6	1		*END PANEL	Bent	582.00 FL	*415.00 FL
7	1		*END PANEL TOP GARNISH	Deformed	178.00 FL	*75.00 FL
8	1		*END PANEL OUTER GARNISH	Serviceable	165.00 FL	*- FL
9	1		*END PANEL KEYLESS SENSOR	Serviceable	114.00 FL	*- FL
10	1		*END PANEL KEYLESS SENSOR SPEAKER	Serviceable	241.50 FL	*- FL
11	2		*TAILLAMP	Cracked	662.50 FL	*590.00 FL
12	1		*TAILLAMP PANEL	O/s Bent/N/s Repair	390.10 FL	*155.05 FL
13	2		*TAILLAMP SEALER	Necessary	50.00 FL	*50.00 FL
14	1		*BOOTLID	Bent	993.60 FL	*798.00 FL
15	1		*BOOTLID LOCK	Bent	247.20 FL	*225.00 FL
16	1		*BOOTLID LOCK STRIKER	Bent	48.00 FL	*48.00 FL
17	1		*BOOTLID CHROME OUTER GARNISH	Cracked	219.40 FL	*219.40 FL
18	1		*BOOTLID WEATHERSTRIP	Cut	177.60 FL	*148.00 FL
19	1		*BOOTLID EMBLEM-ATTRAGE	Necessary	26.40 FL	*26.40 FL
20	1		*BOOTLID EMBLEM-C & C	Necessary	54.00 FL	*54.00 FL
21	1		*BOOTLID EMBLEM-MIVEC	Necessary	65.00 FL	*65.00 FL
22	1		*BOOTLID-LOGO	Necessary	49.20 FL	*49.20 FL
23	2		*BOOTLID HINGE	Serviceable	192.00 FL	*- FL
24	2		*BOOTLID ABSORBER	Serviceable	360.00 FL	*- FL
25	1		*BOOTLID INNER TRIM	Serviceable	230.50 FL	*- FL
26	1		*SPARE TYRE TOP BOARD	Cracked	222.00 FL	*205.00 FL
27	1		*FLOOR PANEL	Buckled	1,087.20 FL	*906.00 FL
28	1		*REAR RH CHASSIS MEMBER	Bent	862.50 FL	*700.00 FL
29	1		*REAR RH WHEEL HOUSE	Repair	862.50 FL	*- FL
30	2		*REAR FENDER	Buckled	1,716.00 FL	*1,446.00 FL
31	2		*REAR FENDER INNER TRIM	Deformed	379.30 FL	*308.00 FL
32	2		*REAR FENDER AIR VENT	Serviceable	90.00 FL	*- FL
33	1		*REAR WINDSCREEN MOULDING	Necessary	48.00 FL	*48.00 FL
34	1		*REAR AIR DUCT	Serviceable	40.50 FL	*- FL
35	1		*REAR AIR DUCT COVER	Serviceable	54.00 FL	*- FL
36	1		*REAR EXHAUST SILENCER	Bent	871.20 FL	*597.00 FL
37	1		*REAR EXHAUST HEATSHIELD	Serviceable	170.45 FL	*- FL
38	2		*REAR EXHAUST MOUNTING	Necessary	67.20 FL	*56.00 FL
39	1		*THIRD BRAKE LIGHT	Serviceable	252.00 FL	*- FL
40	2		*MUD FLAP	Serviceable	117.00 FL	*- FL
41	1		*FRONT BUMPER	Deformed	818.80 FL	*666.00 FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
42	1		*FRONT BUMPER TOP BEAM	Serviceable	170.00 FL	*- FL
43	2		*FRONT BUMPER RETAINER	Necessary	43.20 FL	*43.20 FL
44	1		*FRONT TOP GRILLE	Cracked	410.55 FL	*371.00 FL
45	1		*FRONT LOWER GRILLE	Deformed	151.30 FL	*151.30 FL
46	1		*FRONT GRILLE EMBLEM	Necessary	48.00 FL	*48.00 FL
47	1		*FRONT BUMPER REINFORCEMENT	Serviceable	350.50 FL	*- FL
48	2		*FRONT BUMPER REINFORCEMENT BRACKET	Serviceable	312.00 FL	*- FL
49	1		*FRONT TOW COVER	Deformed	18.00 FL	*18.00 FL
50	2		*HEADLAMP	Cracked	1,978.00 FL	*1,308.00 FL
51	2		*FRONT FOG LAMP	Serviceable	609.50 FL	*- FL
52	2		*FRONT FOG LAMP COVER	Serviceable	288.00 FL	*- FL
53	2		*FRONT FOG LAMP CHROME MOULDING	Serviceable	210.00 FL	*- FL
54	1		*FRONT SUPPORT PANEL	Repair	1,147.70 FL	*- FL
55	1		*FRONT SUPPORT PANEL TOP GARNISH	Deformed	130.00 FL	*59.00 FL
56	1		*AIRCON CONDENSER	Bent	899.30 FL	*750.00 FL
57	1		*AIRCON FAN COWLING	Serviceable	237.60 FL	*- FL
58	1		*AIRCON FAN MOTOR	Serviceable	198.00 FL	*- FL
59	1		*RADIATOR	Bent	967.15 FL	*912.00 FL
60	1		*RADIATOR FAN COWLING	Serviceable	237.60 FL	*- FL
61	1		*RADIATOR FAN MOTOR	Serviceable	319.70 FL	*- FL
62	1		*BONNET	Bent	1,200.30 FL	*552.00 FL
63	1		*BONNET INSULATOR	Serviceable	101.50 FL	*- FL
64	1		*BONNET HINGE	Serviceable	98.00 FL	*- FL
65	1		*BONNET CABLE	Serviceable	59.00 FL	*- FL
66	1		*BONNET LOCK	Serviceable	247.20 FL	*- FL
67	1		*FRONT FENDER	O/s Bent/N/s Serviceable	1,988.00 FL	*380.00 FL
68	1		*FRONT RH SEAT ASSY	Twisted	1,092.50 FL	*1,092.50 FL
69	1		*FRONT RH SEATBELT ASSY	Serviceable	991.90 FL	*- FL
70	1		*REAR AXLE	Serviceable	2,198.21 FL	*- FL
71	1		*REAR RH WHEEL HUB BEARING	Serviceable	310.48 FL	*- FL
72	1		*REAR RH WHEEL HUB	Serviceable	510.90 FL	*- FL
73	1		*REAR RH SHOCK ABSORBER	Bent	590.40 FL	*225.00 FL
74	1		*FRONT NUMBER PLATE	Bent	80.00 FS	*35.00 FS
75	1		*SET FRONT BUMPER CLIP	Necessary	50.00 FS	*30.00 FS
76	2		*SET FRONT GRILLE CLIP	Necessary	100.00 FS	*30.00 FS
77	1		*SET BONNET INSULATOR CLIP	Necessary	30.00 FS	*30.00 FS
78	1		*SET REAR BUMPER CLIP	Necessary	50.00 FS	*30.00 FS
79	1		*SET REAR FENDER INNER TRIM CLIP	Necessary	60.00 FS	*40.00 FS
80	1		*SET BOOTLID INNER TRIM CLIP	Necessary	60.00 FS	*40.00 FS
81	1		*REAR NUMBER PLATE	Bent	80.00 FS	*35.00 FS
82	1		*WINDSCREEN SEALANT	Necessary	50.00 FS	*50.00 FS
83	1		*BOT COOLANT	Necessary	60.00 FS	*60.00 FS
84	1		*BOT BRAKE FUILD	Not Necessary	60.00 FS	*- FS
85	1		*SET REVERSE SENSOR	Not Working	500.00 FS	*200.00 FS
86	1		*REAR NUMBER PLATE GARNISH	Not Necessary	60.00 FS	*- FS
87	1		*SUPPORT PANEL TOP GARNISH CLIP	Necessary	60.00 FS	*30.00 FS
88	1		*END PANEL TOP GARNISH CLIP	Necessary	60.00 FS	*30.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	33,457.76	15,202.05
- List Item Discount on L Items 20.00/20.00% (\$\$)	6,419.55	2,912.41
Total Parts (\$\$)	27,038.21	12,289.64

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	CHECK FRONT & REAR WIRING AND LIGHTINGS SYSTEM	New	120.00	60.00
2	REMOVE,RENEW CONDENSER AND TOP UP GAS	New	150.00	100.00
3	REMOVE,RENEW RADIATOR AND TOP UP COOLANT	New	150.00	80.00
4	REMOVE,REFIT REAR LINING,TRIM AND GARNISH	New	200.00	100.00
5	REMOVE AND RENEW REAR REVERSE SENSOR	New	150.00	60.00
6	REMOVE AND RENEW UNDERCARRIAGE	New	200.00	80.00
7	MOUNT VEHICLE ON BENCH FOR CHASSIS REPLACEMENT	New	500.00	250.00
8	CHECK WHEEL ALIGNMENT	New	150.00	60.00
9	REMOVE AND REFIT FUEL TANK	New	300.00	100.00
10	REMOVE AND REFIT REAR WINDSCREEN	New	150.00	80.00
11	TRANSFER PARTS,ATTACHMENT FROM OLD BOOTLID TO NEW	New	200.00	60.00
12	REMOVE AND RENEW FLOOR INSULATOR	New	120.00	0.00
13	REMOVE AND RENEW REAR EXHAUST SILENCER	New	200.00	100.00
14	PANEL BEATING ON AFFECTED AREAS	New	3,500.00	2,200.00
15	SPRAY PAINTING ON AFFECTED AREAS	New	3,500.00	2,000.00
16	APPLY ANTI RUST ON AFFECTED AREAS	New	150.00	120.00
17	REMOVE AND REPASTE STICKER ON AFFECTED AREAS	New	300.00	0.00
Gross Labour Cost (S\$)			10,040.00	5,450.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >