

ASS. REC. BY:

REF: CS/FCI/9016189/Ad3n2

Special Instruction:

Surveyor: Achan

ASSIGNMENT (Office)

From (Person): Jason Tea

of

FCI

Date/Time: 11:18am @ 12/9/19

Estimated Cost:

Bill to:

OD/TP/WS/TP RES/OD RES/EVA/INV/MV/CS

To Inspect Vehicle No:

SFE 3101A

Insured:

SH 8118A

at Workshop m/s

CAS Garage

Tel:

6484 2220

of

1 Kaki Bukit Ave 6 # 02-22

Policy No:

Claim No:

D19005896MFSH

Sum Insured:

Excess:

Make of Veh:

D.O.A.

11/09/2019

(Client's Record)

CA / REV / REP. / REV 24 HRS

(CPS)

H.O.D. Endorsement:

Date/Time: 11:30am @ 12/9/19

Person Contacted:

Nicole

Vehicle IN/OUT

Date/Time

Action/Instruction

Estimate /

SFE 3101A - NA/III/8022830/74

D.O.A.: 19/12/2018

SH 8118A - CC3/CI/19005802/Nov 3yo

D.O.A.: 29/03/2019

13/9 @ 9:54am - Inform by email pending estimate.

lump sum \$3250/- (Red: 10543.76, 76%)

ASSIGNMENT

From:

Date:

12/09/2019

Veh No:

SFE3101A

Yr Regn:

2007, Feb.

Estimated Cost:

Type: ☒ M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

OD ☒ TP / WS / TP RES / OD RES / EVA / INV / MV

Make:

Honda Civic

c.c 1799.

To Inspect Vehicle No:

SFE 3101A

Colour:

Red.

A/C: Insured / Std / NI / NA

at Workshop m/s

CAS Garage

Sp. Reading

152186

T/Radio: Insured / Std / NI / NA

of 1kakki Bukit Aves # 02-22

Eng/No:

Insured:

C/No:

FD11100244

Policy No.

Gen. Cond: ☒ Good / Fair / Poor / Burnt

Claims No.

Steering: ☒ In order / Jammed / Leaked / Burnt or

Sum Insured:

Excess:

Brake: ☒ In order / Jammed / Leaked / Burnt or

(Client's Record)

Modi: Nil / ☒ STD A/Rim or

Make of Veh:

Tyre Size:

F:

215/60R16.

R:

215/60R16.

(Policy Condition)

N/S	O/S

Remark: The veh had commenced its
repair at the time of inspection.

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or Roadstone

Bal. or Market Value:

Front

Rear

IDAC Accident Rpt:

Consistent?: Yes or No

R/Bal.

06

mm

R/Bal.

06

mm

GIA / PR Seen:

Consistent?: Yes or No

L/Bal.

06

mm

L/Bal.

06

mm

Est. Repairs:

days

Res.: Yes or No

D.O.A.

D.O.I.

12/01/19.

Lum Sum:

%

3 Val.: Yes or No

Survey held at

CAS.

CA / REV / REP. / 24 HRS (DS)

Des. of Damages: Frt / ☒ Rear / O/S / N/S / U/C / Rooftop or

Date:

Person Contacted:

Vehicle: IN / OUT

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

TP 1st Cp

COE Expiry: 11/02/22

MV: 20,000/-

LTA: 12588

NW: 7412

RECEIVED 15 NOV 2019

mv: 20K.

PV: 12.6K.

Nett: 7.4K

Date/Time, File Pass to?



Preli. Report

1) 15/11 Typist



Final Report

Date/Time, File Exam to?

2)

Days Of Repair: 6

Resurvey No. of Trip:

Add Fee:



Site Insp (\$)



Interview (\$)



Tech. Insp (\$)



Workshop (\$)

Survey Fee:

Transportation:

3 + RS. SI

Photos

Others

TOTAL

3x15 = 45

170 + 45

50

50

37

352

Report Format:

TP

Lump Sum / H.B. / C.

3250/-

MOTOR SURVEY ASSIGNMENT

Date	11-09-2019	Our Ref No.	D19005896MFSH
Accident Date	11-09-2019	Claim Type.	Third Party
Insured Vehicle	SH8118A	Third Party Vehicle.	SFE3101A
Survey Location	NO.1 KAKI BUKIT AVE 6 #02-22		
Contact Person.	NICOLE CHONG		
Contact No.	64842220/ 97916119	Fax No.	0
Survey Type	WITHOUT PREJUDICE: WE ADMIT LIABILITY QUANTUM TO BE AGREED:		
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD		
Contact Person	NA	Fax No.	68416315
Contact Number.	NA		

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	CAS GARAGE PTE LTD	Attention.	NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No.	NA
Officer Incharge	JASON TEA CHEE KIAT		

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Denise Tay (LKKAuto)

From: Denise Tay (LKKAuto)
Sent: Friday, 13 September 2019 9:54 AM
To: Admin-D (LKKAuto); 'CWS Motor Claims'; assignments
Cc: 'Jason Tea'; SUR
Subject: RE: SURVEY ASSESSMENT - D19005896MFSH/1

Dear Sir/Madam,

Please be informed that we have inspected the vehicle SFE 3101A on 12/09/2019
We are pending estimate from repairer.

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: denisetay@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto) <admin-d@lkkauto.com>
Sent: Thursday, 12 September 2019 11:33 AM
To: 'CWS Motor Claims' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: 'Jason Tea' <JasonTea@msfirstcapital.com.sg>; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D19005896MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

Best Regards

G.NIVITHA

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: CWS Motor Claims [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]
Sent: Thursday, 12 September 2019 11:18 AM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWS Motor Claims <cwsmotorclaims@msfirstcapital.com.sg>; Jason Tea <JasonTea@msfirstcapital.com.sg>
Subject: PRI: SURVEY ASSESSMENT - D19005896MFSH/1

FOR SALE BY OWNER

Post an Advertisement
Sell it yourself! Advertise it at just
\$58 until it's SOLD!

 Post an Ad
  Advertiser Login
  Ways of Selling

BMW 730i M-Sport Model For Sale! Brand New Condition

 Limited Exclusive 1.99% Interest
Rate! Come With PML
Warranty, 100% Accident Free
Seng Hup Auto StarAd

KA-HUP

**VALUE FOR MONEY
VALUE FOR TIME
A PEACE OF MIND**

HOTLINE: 6741 9997 [View Our Cars](#)

Browse by Category 
 Save Search
  Print
 « Back (1 2 3 4 5 6 7 8) Next »
 Sort by Date Posted  20 results/page 

160 vehicles **Search** [Advanced Search](#) [Search](#) [View All](#)

Make  Model  Price  Depreciation  Reg Date  Eng Cap  Mileage  Veh Type  Status 

Search Selection	civic	Any	Any	> 10 year(s) old	Any	Any	Any	Available
------------------	-------	-----	-----	------------------	-----	-----	-----	-----------



☐ **Honda Civic 1.6A VTI (COE till 02/2022)**
\$20,800
\$8,440 /yr
01-Mar-2007
1,595 cc
95,071 km
Sedan
Available

Very Low Mileage At 95071Km, And Well Maintained, Probably The Best In Town. Check This Up To Be Convinced. Warranty And Maintenance Package Available For Your Total Peace Of Mind. Next Drive Enhance Your Buying Experience. Let The Condition Speak By...

 Posted: 27-Aug-2019 Tags: 2007 Honda Civic, 2007 honda civic, Honda Civic, honda civic, Honda, Civic, civic, Used Honda



☐ **Honda Civic 1.6A VTI (COE till 03/2022)**
\$43,800
\$5,850 /yr
10-Mar-2007
1,595 cc
155,000 km
Sedan
Available

One Of The Best Japanese Made Sedan Model To Own In Town! Low Depreciation! Affordable Monthly Payment! Welcome Trade In Or High Loan! Come View Today! Not To Be Missed!

 Posted: 17-Sep-2019 Tags: 2007 Honda Civic, 2007 honda civic, Honda Civic, honda civic, Honda, Civic, civic, Used Honda



☐ **Honda Civic 1.8A VTI-S (COE till 05/2022)**
\$25,000
\$9,350 /yr
16-May-2007
1,799 cc
137,000 km
Sedan
Available

1 Owner Only For The Past 12 Years. Superb Well Maintained, Brand New Glossy Pearl White Paintwork. Low Mileage Clocked. View To Believe. No Repairs Required, Drive Till The End With No Worries. High Loan And Trade In Available. Hurry Call/Whatsapp Us Today.

Monster Motors Pte Ltd

 Posted: 01-Aug-2019 Tags: 2007 Honda Civic, 2007 honda civic, Honda Civic, honda civic, Honda, Civic, civic, Used Honda



☐ **Honda Civic 2.0A Si (COE till 05/2022)**
\$49,999
\$6,500 /yr
21-May-2007
1,998 cc
169,000 km
Sedan
Available

Genuine Low Mileage, 10 Years COE Renewal Done In 2017, Road Tax Fully Paid Till May 2019, Direct Owner, I Invested A Lot On This Ride. The Following Has Been Done By Me In 2017 - 2018: Anti-theft Alarm System, Regular Servicing With Engine Br Ake. All Liquid Ch...

 Posted: 29-Jul-2019 Tags: 2007 Honda Civic, 2007 honda civic, Honda Civic, honda civic, Honda, Civic, civic, Used Honda

**GET YOUR
COE
RENEWAL
LOAN**

Is your COE expiring? Let us help you renew it!

Getting your COE renewed is easy, fast and affordable. We'll help you renew your COE and get a loan for it. Get the cheapest loan in town and an approval in 2 days without effort! Enquire today.



☐ **Honda Civic 1.8M VTI-S (COE till 06/2022)**
\$24,800
\$8,940 /yr
22-Jun-2007
1,799 cc
-
Sedan
Available

In-House Finance And Low Downpayment Available, Fast Loan Approval, STA Evaluation Welcome, One Of The Few 1.8 Manual Civic Left, CF Body Kits, Road Tax Till 12/2019, Last Servicing On 08/2019, Don't Miss The Chance To Own This Civic With Many Goodies To Go WL...

Speedo Motoring

 Posted: 23-Aug-2019 Tags: 2007 Honda Civic, 2007 honda civic, Honda Civic, honda civic, Honda, Civic, civic, Used Honda



☐ **Honda Civic 1.8A VTI-S (COE till 05/2022)**
\$28,800
\$10,600 /yr
26-Jun-2007
1,799 cc
-
Sedan
Available

Well Maintained, Excellent Condition, Accident-Free, Bank And In House Loan Available, Trade In Are Welcome, Powerful Engine And Smooth Transmission, Buy With Confidence! Call Us Now To Make An Appointment To Viewing.

Car Search

 Posted: 10-Jul-2019 Tags: 2007 Honda Civic, 2007 honda civic, Honda Civic, honda civic, Honda, Civic, civic, Used Honda

SHORTLISTED HISTORY

Compare [4] 

☐ **Honda Civic 1.6A VTI (COE till 06/2022)**
\$20,800
\$7,430 /yr
13-Jul-2007
1,595 cc
158,000 km
Sedan
Available

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	927A
Vehicle Details	
Vehicle No.:	SFE3101A
Vehicle to be Exported:	Yes
Intended Deregistration Date:	12 Sep 2019
Vehicle Make:	HONDA
Vehicle Model:	CIVIC 1.8 A
Primary Colour:	Silver
Manufacturing Year:	2006
Engine No.:	R18A1030245
Chassis No.:	FD11100244
Maximum Power Output:	103.0 kW (138 bhp)
Open Market Value:	\$19,860.00
Original Registration Date:	12 Feb 2007
First Registration Date:	12 Feb 2007
Transfer Count:	3
Actual ARF Paid:	\$19,544.00
Intended PARF Rebate Particulars	
PARF Eligibility:	Forfeited
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Particulars	
COE Expiry Date:	11 Feb 2022
COE Category:	E - Open Category
COE Period(Years):	5
PQP Paid:	\$26,039.00
COE Rebate Amount:	\$12,588.00
Total Rebate Amount:	\$12,588.00

Message

Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 12 Sep 2019

OK

**CAS GARAGE PTE LTD**

(Reg No: 201828067M)

1 KAKI BUKIT AVENUE 6, #02-22 AUTOBAY, SINGAPORE 417883

VEHICLE REPAIR ESTIMATE

Insurance Company: MS FIRST CAPITAL INSURANCE LIMITED

Address: NO 36, ROEBINSON ROAD, #16-01
CITY HOUSE, S(068877)*Derise*

Telephone: 65073848 Fax: 65073849

Email motorclaims@msfirstcapital.com.sg

Make/ Model : HONDA CIVIC FD1

Date: 11.09.2019

Chassis No : FD11100244

Vehicle No: SFE3101A

Date/Time of Accide 11.09.2019/1210

Materials Cost/ Spare Parts Cost**TO BE COMPLETED BY SERVICE ADVISOR**

ITEMS	PARTS DESCRIPTION	QTY	LIST PRICE \$	PARTS DISCOU	FINAL PRICE \$
1	BOOTLID <i>Derised</i>	1	\$ 756.80		\$ 756.80
2	BOOTLID REFLECTORS <i>new</i>	2	\$ 305.60		\$ 611.20
3	BOOTLID INNER TRIM <i>new</i>	1	\$ 185.40		\$ 185.40
4	BOOTLID LOGO <i>new</i>	1	\$ 85.60		\$ 85.60
5	BOOTLID NUMBER PLATE LAMPS <i>new</i>	2	\$ 58.30		\$ 116.60
6	BOOTLID INNER LOCK <i>Derised</i>	1	\$ 185.80		\$ 185.80
7	BOOTLID HINGES <i>new</i>	2	\$ 65.70		\$ 131.40
8	BOOTLID HINGES COVER <i>new</i>	2	\$ 85.60		\$ 171.20
9	BOOTLID LOWER LATCH <i>new</i>	1	\$ 45.60		\$ 45.60
10	BOOTLID WEATHERSTRIP <i>Not in</i>	1	\$ 145.30		\$ 145.30
11	REAR BUMPER RETAINERS <i>new</i>	2	\$ 75.60		\$ 151.20
12	REAR BUMPER BRACKETS <i>new</i>	2	\$ 85.90		\$ 171.80
13	TAILAMPS <i>Not in</i>	2	\$ 398.70		\$ 797.40
14	TAILAMPS INNER SEALER <i>2</i>	2	\$ 49.80		\$ 99.60
15	TAILAMPS BRACKETS	2	\$ 56.80		\$ 113.60
16	TAILAMPS PANELS <i>Not in</i>	2	\$ 298.60		\$ 597.20
17	REAR FENDERS	2	\$ 1,620.80		\$ 3,241.60
18	REAR FENDER INNER COWLING <i>2</i>	2	\$ 325.80		\$ 651.60
19	REAR FENDER INNER TRIMS <i>new</i>	2	\$ 485.60		\$ 971.20
20	REAR FENDER AIR VENTS	2	\$ 126.20		\$ 252.40
21	REAR END PANEL <i>Derised</i>	1	\$ 568.90		\$ 336 568.90
22	REAR END PANEL TOP GARNISH <i>Derised</i>	1	\$ 165.80		\$ 165.80
Total List Price Cost					\$ 10,217.20
PARTS DISCOUNT 20%					\$ 8,173.76

1594

1275.20

SPECIAL NETT	PARTS DESCRIPTION	QTY	PRICE \$		FINAL PRICE \$
1	REAR NUMBER PLATE WITH CASING <i>new</i>	1 SET	\$ 100.00		\$ 100.00 +
2	REAR BUMPER CLIPS <i>new</i>	1 SET	\$ 30.00		\$ 30.00 -
3	REAR FENDER INNER TRIMS CLIPS <i>new</i>	1 SET	\$ 30.00		\$ 30.00 +
4	REAR END PANEL TOP GARNISH CLIPS <i>new</i>	1 SET	\$ 30.00		\$ 30.00 +
5	REVERSE SENSOR <i>changed</i>	1 SET	\$ 250.00		\$ 250.00 2w
6	REAR BUMPER (ACCESSORIES) <i>behind</i>	1	\$ 680.00		\$ 680.00 -
7	REAR FENDER COWLING SET <i>3 new</i>	2 SET	\$ 60.00		\$ 60.00 +
8	REAR TAILAMP CLIPS	2 SET	\$ 60.00		\$ 60.00 +
9	END PANEL INSULATOR SEAL <i>new</i>	2	\$ 80.00		\$ 80.00 760
Total Special Nett Items					\$ 1,320.00

970

Labour Works/ Panel Beating Related Works	
Job Scope	Quotation
TO RENEW DAMAGED PARTS, REPLACE, BEAT, WELD, REALIGN AND ALIGN ALL PARTS	\$ 1,600.00
800	
Spray Painting	
Job Scope	Quotation
TO RESPRAY AFFECTED AREAS	\$ 1,600.00
800	
Others Cost (Accident Repair Related Expenses)	
Job Scope	Quotation
TO TUFFCOAT AFFECTED AREA	\$ 200.00 60
TO REMOVE/ REFIT INTERIOR UPHOLSTERY	\$ 150.00 60
TO APPLY SEALANT TO THE AFFECTED AREAS	\$ 180.00 60
TO REMOVE/ REFIT WIRING CHECKS ON REAR TAILAMPS	\$ 120.00 30
TO CONDUCT WATER LEAKAGE TEST	\$ 150.00 X
TO REMOVE/ REPLACE REVERSE SENSORS AND DISTANCE SETTLING	\$ 150.00 50
TO REMOVE AND REPLACE BOOTLID MECHANISM	\$ 150.00 X
Total Others Cost	\$ 1,100.00
GRAND TOTAL	
	\$ 13,793.76

1860

Adrian Lj
w/s 12/09/19.
06 Days.

CAS GARAGE PTE LTD

Person Incharge: Allan
Direct Contact: +65 8782 7171
Email: allangoh.cas@gmail.com
Fax: +65 6509 9501

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

total: 4105.20
h/s: 3250



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
MS FIRST CAPITAL INSURANCE LTD		Ref : CS/FCI19016189/Atd3n2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 15-11-2019	
		Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SH 8118A	Veh. Inspected	SFE 3101A
Policy No.		Coverage (\$)	0.00
Claim No.	D19005896MFSH	Excess (\$)	0.00
Assign From	JASON TEA	Assign Date	12/09/2019
2. Vehicle Particulars & Condition			
Make & Model	HONDA CIVIC	c.c	1799
Engine No.	HIDDEN	Year of Reg.	2007
Chassis No.	FD11100244	Colour	RED
Odometer	152186	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	215/60 R16	ROADSTONE	6 mm
L/H Front Tyre	215/60 R16	ROADSTONE	6 mm
R/H Rear Tyre	215/60 R16	ROADSTONE	6 mm
L/H Rear Tyre	215/60 R16	ROADSTONE	6 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.			
DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	11/09/2019	Inspection Date	12/09/2019
Survey held at	CAS GARAGE PTE LTD NO. 1 KAKI BUKIT AVE 6, #02-22 AUTOBAY 417883 KAKI BUKIT		
5a. Remarks			
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		6 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SFE 3101A

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	BOOTLID	DENTED	756.80	756.80
2	BOOTLID REFLECTORS @\$305.60	NOT NECESSARY	611.20	-
1	BOOTLID INNER TRIM	NOT NECESSARY	185.40	-
1	BOOTLID LOGO	NECESSARY	85.60	85.60
2	BOOTLID NUMBER PLATE LAMPS @\$58.30	NOT NECESSARY	116.60	-
1	BOOTLID INNER LOCK	DAMAGED	185.80	185.80
2	BOOTLID HINGES @\$65.70	NOT NECESSARY	131.40	-
2	BOOTLID HINGES COVER @\$85.60	NOT NECESSARY	171.20	-
1	BOOTLID LOWER LATCH	NOT NECESSARY	45.60	-
1	BOOTLID WEATHERSTRIP	NOT NECESSARY	145.30	-
2	REAR BUMPER RETAINERS @\$75.60	NECESSARY	151.20	64.00
2	REAR BUMPER BRACKETS @\$85.90	NOT NECESSARY	171.80	-
2	TAILLAMPS @\$398.70	NOT NECESSARY	797.40	-
2	TAILLAMPS INNER SEALER @\$49.80	NOT NECESSARY	99.60	-
2	TAILLAMPS BRACKETS @\$56.80	NOT NECESSARY	113.60	-
2	TAILLAMPS PANELS @\$298.60	NOT NECESSARY	597.20	-
2	REAR FENDERS @\$1620.80	NOT NECESSARY	3,241.60	-
2	REAR FENDER INNER COWLING @\$325.80	NOT NECESSARY	651.60	-
2	REAR FENDER INNER TRIMS @\$485.60	NOT NECESSARY	971.20	-
2	REAR FENDER AIR VENTS @\$126.20	NOT NECESSARY	252.40	-
1	REAR END PANEL	DENTED	568.90	336.00
1	REAR END PANEL TOP GARNISH	DEFORMED	165.80	165.80
	LESS 20% DISCOUNT		-2,043.44	-318.80
			8,173.76	1,275.20
SPECIAL NETT ITEMS				
1	SET REAR NUMBER PLATE WITH CASING (SN)	NOT NECESSARY	100.00	-
1	SET REAR BUMPER CLIPS (SN)	NECESSARY	30.00	30.00
1	SET REAR FENDER INNER TRIM CLIPS (SN)	NOT NECESSARY	30.00	-
1	SET REAR END PANEL TOP GARNISH CLIPS (SN)	NOT NECESSARY	30.00	-
1	SET REVERSE SENSOR (SN)	DAMAGED	250.00	200.00

Report Ref No. CS/FCI19016189/Atd3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	REAR BUMPER (ACCESSORIES)(SN)	DEFORMED	680.00	680.00
2	SET REAR FENDER COWLING (SN)	NOT NECESSARY	60.00	-
2	SET REAR TAILAMP CLIPS (SN)	NOT NECESSARY	60.00	-
2	END PANEL INSULATOR SEAL (SN)	NECESSARY	80.00	60.00
			1,320.00	970.00
	LABOUR			
	TO RENEW DAMAGED PARTS,REPLACE,BEAT,WELD,REALIGN AND ALING ALL PARTS.		1,600.00	800.00
	TO RESPRAY AFFECTED AREAS.		1,600.00	800.00
	TO TUFFCOAT AFFECTED AREA.		200.00	60.00
	TO REMOVE/REFIT INTERIOR UPHOLSTERY.		150.00	60.00
	TO APPLY SEALANT TO THE AFFECTED AREAS.		180.00	60.00
	TO REMOVE/REFIT WIRING CHECKS ON REAR TAILLAMPS.		120.00	30.00
	TO CONDUCT WATER LEAKAGE TEST.	NOT NECESSARY	150.00	-
	TO REMOVE/REPLACE REVERSE SENSORS AND DISTANCE SETTLING.		150.00	50.00
	TO REMOVE AND REPLACE BOOTLID MECHANISM.	NOT NECESSARY	150.00	-
			4,300.00	1,860.00
GRAND TOTAL			13,793.76	4,105.20
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				3,250.00

Report Ref No. CS/FCI19016189/Atd3n2

MARKET VALUE: \$20,000.00 (EST)-LTA REIMBURSEMENT VALUE: \$12,588.00=NETT VALUE: \$7,412.00

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.