

ASS. REC. BY:

REF: 08/GAI/90/6193 /TY d3er Special Instruction:

Surveyor: Tausif

ASSIGNMENT (Office)

From (Person): Sheng Wong of GAI Date/Time: 12/9/19 @ 2:17pm

Estimated Cost: Bill to:

OB TP/WS/TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: FBK 6057R Insured:

at Workshop in/s Leong Seng Motor Tel:

of Blk 1006 Bukit Merah Lane 2 # 01-08

Policy No: Claim No: CLMOM VM000000508

Sum Insured: Excess: TBA

Make of Veh: D.O.A. 06/09/2019
(Client's Record)

CA / (REV) / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time: 9:31pm @ 12/9/19 Person Contacted: Mr. Leo Vehicle IN/OUT

Date/Time	Action/Instruction
12/9/19	Vehicle in Rdy but Repairer doesn't want to send to survey, so he ask put tomorrow (13/9/19) and ask Tausif to Survey. called Mr. Leo
	FBK 6057R - X
18/9/19	Sent Preli by email
19/9/19	Call to Workshop to confirm the Excess \$1500/- Authorise 9:30am

Asst. P.C. BY: Taukiah

REP: GAI

ASSIGNMENT

From: _____ Date: 13/09/19

Estimated Cost: _____

☒ OD / ☐ TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: FBK 6057R

at Workshop m/s Leong Seng Motor

of Blk 1006 Bukit Merah Lane 2 #01-08

Insured: _____

Policy No. _____

Claims No. _____


Sum Insured: _____ Excess: TBA

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: \$13K.

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / ☒ REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: FBK 6057R Yr Regn: 2015, Nov.

Type: ☒ M.Car / ☐ M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Honda CB 400X c.c. 399

Colour: white A/C: ☐ Insured / ☐ Std / ☐ NI / ☐ NA

Sp. Reading: 130176 T/Radio: ☐ Insured / ☐ Std / ☐ NI / ☐ NA

Eng/No: _____

C/No: _____

Gen. Cond: ☒ Good / ☐ Fair / ☐ Poor / ☐ Burnt

Steering: ☒ Inorder / ☐ Jammed / ☐ Leaked / ☐ Burnt or

Brake: ☒ Inorder / ☐ Jammed / ☐ Leaked / ☐ Burnt or

Modi: ☒ Nil / ☐ S/Rim / ☐ STD A/Rim or

Tyre Size: F: 120/70 R17

R: 160/60 R17

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU ☒ PIR / SUMI /

TOYO / YOKO or

Front

R/Bal. 5 mm

L/Bal. _____ mm

D.O.A. _____

Rear

R/Bal. 5 mm

L/Bal. _____ mm

D.O.I. _____

Survey held at Leong Seng Motor 13/9/19 4:50pm

Des. of Damages: ☒ Fr / ☐ Rear / ☐ O/S / ☒ N/S / ☐ U/C / ☐ Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

8/10/19

Confirm L/S \$6400/- attach e-mail (Red \$2751.50, 30%)

RECEIVED 8 OCT 2019

Date/Time, File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

8/10/19 Typist

Days Of Repair: 5

Resurvey No. of Trip: 1

Arbit Fee: ☐ : Site Insp (\$ _____)

☐ : Interview (\$ _____)

☐ : Tech. Invs (\$ _____)

☐ : Wheel and (\$ _____)

Survey Fee: 240

Transportation: _____

☐ S + RS, SI

Photos

Others

TOTAL

240

Report Format :

Lump Sum L/S: \$6400/-

Yvonne Wong (LKK Auto)

From: leongseng <leongsen@singnet.com.sg>
Sent: Friday, September 27, 2019 6:15 PM
To: Taufikh (LKKAuto)
Subject: Re: FBK6057 marked estimate

Dear Sir

Thanks for your confirmation, will submit our final bill based on your recommendation.

Regards

c s teo

From: Taufikh (LKKAuto)
Sent: Friday, September 27, 2019 5:09 PM
To: 'leongseng'
Subject: RE: FBK6057 marked estimate

Hi Teo,

Refer to attached. COR I/s\$6400, 5 days.

Regards
Taufikh
Lkk Auto

From: leongseng [mailto:leongsen@singnet.com.sg]
Sent: Monday, 23 September 2019 3:25 PM
To: taufikh@lkkauto.com
Subject: FBK6057 marked estimate

Dear Sir

Pls find enclosed FBK6057 marked estimate

Pls check and keep us posted of your recommended COR

Pls find below are our working on COR

parts	\$5510.00
less 10%	(\$ 551.00)
	\$4959.00
net items & labour	\$3216.00
sub total	\$8175.00
less 20%	(\$1635.00)
total	\$6540.00

Based on our above working, we will like to request for Lump Sum repair of \$6500.00.

Pls also find enclosed 1 of our inv for the top crash bar (item 25) that we purchase from our supplier, our cost was \$390, but we only quoted \$350.

Pls be informed that you revised our quote of Bottom crash bar (item 26) from \$340 to \$240, and Rear crash bar (item 27) from \$280 to \$180. Pls be informed that we got these 2 items from another supplier and our cost are \$320 and \$260 respectively.

Pls check and update us on your recommendation.

Thanks

c s teo



This email has been checked for viruses by AVG antivirus software.
www.avg.com

Yvonne Wong (LKK Auto)

From: Yvonne Wong (LKK Auto)
Sent: Friday, September 20, 2019 9:21 AM
To: leongseng
Subject: Our Ref:CLMOMVM000000508, Accident involving FBK6057 on 6/9/19 - Authorise

Dear C S Teo

As instructed by our client , please proceed to repair the **insured vehicle FBK6057R (Excess S1500/-)**.

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their right **not to pay** if there is no valid approval obtained before repair

Thank you.

Best Regards,

Yvonne Wong (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: yvonnewong@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: leongseng [mailto:leongseng@singnet.com.sg]
Sent: Thursday, September 19, 2019 7:06 PM
To: Yvonne Wong (LKK Auto) <yvonnewong@lkkauto.com>
Cc: SUR <sur@lkkauto.com>
Subject: Re: Our Ref:CLMOMVM000000508, Accident involving FBK6057 on 6/9/19 - request for survey

Dear Yvonne

Thanks for your update, we will follow up accordingly.

Regards

c s teo

From: Yvonne Wong (LKK Auto)
Sent: Thursday, September 19, 2019 6:11 PM
To: leongseng@singnet.com.sg
Cc: SUR
Subject: Our Ref:CLMOMVM000000508, Accident involving FBK6057 on 6/9/19 - request for survey

Yvonne Wong (LKK Auto)

From: Yvonne Wong (LKK Auto)
Sent: Thursday, September 19, 2019 6:12 PM
To: leongsen@singnet.com.sg
Cc: SUR
Subject: Our Ref:CLMOMVM000000508, Accident involving FBK6057 on 6/9/19 - request for survey

Hi

As per tele-conversation 19/09/2019. Vehicle authorise please proceed the repair and excess is

\$1500.00 before GST. Repair 5 days

Thank you.

Best Regards,

Yvonne Wong (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: yvonnewong@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Ngian, Kelvyna [mailto:Kelvyna.Ngian@sg.gaig.com]
Sent: Thursday, September 19, 2019 9:17 AM
To: Admin-D (LKKAuto) <admin-d@lkkauto.com>
Cc: SUR <sur@lkkauto.com>; assignments <assignments@lkkauto.com>
Subject: RE: Our Ref:CLMOMVM000000508, Accident involving FBK6057 on 6/9/19 - request for survey

Hi Yvonne,

May proceed if consistent, excess \$1500 applicable

Thanks
Kelvyna

From: Yvonne Wong (LKK Auto) <yvonnewong@lkkauto.com>
Sent: 18 September 2019 5:51 PM
To: Motor Claims <MotorClaims@sg.gaig.com>
Cc: Ngian, Kelvyna <Kelvyna.Ngian@sg.gaig.com>; SUR <sur@lkkauto.com>
Subject: [External] Our Ref:CLMOMVM000000508, Accident involving FBK6057 on 6/9/19 - request for survey

Dear Sir/ Madam

Enclosed preliminary revised of vehicle FBK6057R
Date of survey : 13/09/2019

Number of days : 5 days

We did not authorise repair
Repair on lump sum

Thank you.

Best Regards,

YC Wong (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: yvonnewong@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto)

Sent: Thursday, September 12, 2019 3:13 PM

To: 'Motor Claims' <MotorClaims@sg.gaig.com>; assignments <assignments@lkkauto.com>

Cc: 'Ngian, Kelvyna' <Kelvyna.Ngian@sg.gaig.com>; SUR <sur@lkkauto.com>

Subject: RE: Our Ref:CLMOMVM000000508, Accident involving FBK6057 on 6/9/19 - request for survey

Dear Sir/Mdm,

Thank you for the assignment.

Best Regards

G.NIVITHA

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Wong, Shery [<mailto:Shery.Wong@sg.gaig.com>] **On Behalf Of** Motor Claims

Sent: Thursday, 12 September 2019 2:17 PM

To: assignments@lkkauto.com; Admin-D (LKKAuto) <admin-d@lkkauto.com>

Cc: Ngian, Kelvyna <Kelvyna.Ngian@sg.gaig.com>; SUR <sur@lkkauto.com>

Subject: Our Ref:CLMOMVM000000508, Accident involving FBK6057 on 6/9/19 - request for survey

Hi Cs,

Noted on your request.

Aside to LKK,

Kindly assist to conduct OD survey.

Regards

Shery Wong, Executive, Claims | P. +65 68046077 | F. +65 62353354 | shery.wong@sg.gaig.com



Claims | 3 Temasek Avenue #16-01 Centennial Tower Singapore 039190



A+ (Superior)
Affirmed August 17, 2018

Moody's
A1 (Good)
Published December 2018

Standard & Poor's
A+ (Strong)
Affirmed February 23, 2018

For more information on our financial ratings, visit GAIG.com/FinancialStrength.

From: leongseng <leongsen@singnet.com.sg>

Sent: 12 September 2019 12:54 PM

To: Ngian, Kelyna <Kelyna.Ngian@sg.gaig.com>; Motor Claims <MotorClaims@sg.gaig.com>

Subject: [External] Accident involving FBK6057 on 6/9/19 - request for survey

Dear Sir/Mdm

Pls be informed that FBK6057 owner had appointed us to submit an O/D claim for them

Pls find enclosed accident report and our repair estimate.

Kindly arrange your appointed surveyor to conduct damage survey at our workshop at your early convenience.

Thanks

c s teo

The content of this e-mail message and any attachments are confidential and may be legally privileged, intended solely for the addressee. If you are not the intended recipient, be advised that any use, dissemination, distribution, or copying of this e-mail is strictly prohibited. If you receive this message in error, please notify the sender immediately by reply email and destroy the message and its attachments.



This email has been checked for viruses by AVG antivirus software.
www.avg.com

The content of this e-mail message and any attachments are confidential and may be legally privileged, intended solely for the addressee. If you are not the intended recipient, be advised that any use, dissemination, distribution, or copying of this e-mail is strictly prohibited. If you receive this message in error, please notify the sender immediately by reply email and destroy the message and its attachments.



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: CLMOMVM000000508

Date: 18/09/2019

Our Ref: CS/GAI19016193/T1yd3

The Motor Claims Department
GREAT AMERICAN INSURANCE COMPANY

Dear Sirs/Mdm,


PRELIMINARY ADVICE OF VEHICLE NO. FBK6057R .

Please be informed that we had conducted the inspection of the above-mentioned vehicle on 13/09/2019 at the premises of M/s Leong Seng Motor and have the following to report: -

Workshop Estimate Amount	: S\$ 9,151.50
Revised Estimate Amount	: S\$ 6,954.50
Check" Items Amount	: S\$ 1,264.50
Total	: S\$ 8,219.00
Market Value	: S\$ 13,000.00
LTA Reimbursement Value	: S\$ 3,809.00
Nett Value	: S\$ 9,191.00

Description of Damage:

The vehicle sustained at the front portion
And n/s body.



Comments/ Present Status:

Damage consistent
Repair cost economical

Yours faithfully
Taufikh
Automotive Assessor

Yvonne Wong (LKK Auto)

From: Yvonne Wong (LKK Auto)
Sent: Wednesday, September 18, 2019 5:51 PM
To: 'Motor Claims'
Cc: 'Ngian, Kelvyna'; SUR
Subject: Our Ref:CLMOMVM000000508, Accident involving FBK6057 on 6/9/19 - request for survey
Attachments: FBK6057R DOA 06092018 REVERT.pdf; FBK6057R.pdf

Dear Sir/ Madam

Enclosed preliminary revised of vehicle FBK6057R
Date of survey : 13/09/2019
Number of days : 5 days

We did not authorise repair
Repair on lump sum

Thank you.

Best Regards,

YC Wong (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: yvonne Wong@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto)
Sent: Thursday, September 12, 2019 3:13 PM
To: 'Motor Claims' <MotorClaims@sg.gaig.com>; assignments <assignments@lkkauto.com>
Cc: 'Ngian, Kelvyna' <Kelvyna.Ngian@sg.gaig.com>; SUR <sur@lkkauto.com>
Subject: RE: Our Ref:CLMOMVM000000508, Accident involving FBK6057 on 6/9/19 - request for survey

Dear Sir/Mdm,

Thank you for the assignment.

Best Regards

G.NIVITHA

LKK Auto Consultants Pte Ltd

From: Wong, Shery [mailto:Shery.Wong@sg.gaig.com] **On Behalf Of** Motor Claims
Sent: Thursday, 12 September 2019 2:17 PM
To: assignments@lkkauto.com; Admin-D (LKKAuto) <admin-d@lkkauto.com>
Cc: Ngian, Kelvyna <Kelvyna.Ngian@sg.gaig.com>; SUR <sur@lkkauto.com>
Subject: Our Ref:CLMOMVM000000508, Accident involving FBK6057 on 6/9/19 - request for survey

Hi Cs,

Noted on your request.

Aside to LKK,

Kindly assist to conduct OD survey.

Regards

Shery Wong, Executive, Claims | P. +65 68046077 | F. +65 62353354 | shery.wong@sg.gaig.com



Claims | 3 Temasek Avenue #16-01 Centennial Tower Singapore 039190



A+ (Superior)
Affirmed August 17, 2018

Moody's
A1 (Good)
Published December 2018

Standard & Poor's
A+ (Strong)
Affirmed February 23, 2018

For more information on our financial ratings, visit GAIG.com/FinancialStrength.

From: leongseng <leongsen@singnet.com.sg>
Sent: 12 September 2019 12:54 PM
To: Ngian, Kelvyna <Kelvyna.Ngian@sg.gaig.com>; Motor Claims <MotorClaims@sg.gaig.com>
Subject: [External] Accident involving FBK6057 on 6/9/19 - request for survey

Dear Sir/Mdm

Pls be informed that FBK6057 owner had appointed us to submit an O/D claim for them


Pls find enclosed accident report and our repair estimate.

Kindly arrange your appointed surveyor to conduct damage survey at our workshop at your early convenience.

Thanks

c s teo

The content of this e-mail message and any attachments are confidential and may be legally privileged, intended solely for the addressee. If you are not the intended recipient, be advised that any use, dissemination, distribution, or copying of this e-mail is strictly prohibited. If you receive this message in error, please notify the sender immediately by reply email and destroy the message and its attachments.



This email has been checked for viruses by AVG antivirus software.
www.avg.com

Nivitha (LKK Auto)

From: Wong, Shery <Shery.Wong@sg.gaig.com> on behalf of Motor Claims <MotorClaims@sg.gaig.com>
Sent: Thursday, 12 September 2019 2:17 PM
To: assignments@lkkauto.com; Admin-D (LKKAuto)
Cc: Ngian, Kelvyna; SUR
Subject: Our Ref:CLMOMVM000000508, Accident involving FBK6057 on 6/9/19 - request for survey
Attachments: FBK6057R_06092019.pdf; IMG_20190912_0004.pdf

Hi Cs,

Noted on your request.

Aside to LKK,

Kindly assist to conduct OD survey.

Regards

Shery Wong, Executive, Claims | P. +65 68046077 | F. +65 62353354 | shery.wong@sg.gaig.com



Claims | 3 Temasek Avenue #16-01 Centennial Tower Singapore 039190



A+ (Superior)
Affirmed August 17, 2018

Moody's
A1 (Good)
Published December 2018

Standard & Poor's
A+ (Strong)
Affirmed February 23, 2018

For more information on our financial ratings, visit GAIG.com/FinancialStrength.

From: leongseng <leongsen@singnet.com.sg>
Sent: 12 September 2019 12:54 PM
To: Ngian, Kelvyna <Kelvyna.Ngian@sg.gaig.com>; Motor Claims <MotorClaims@sg.gaig.com>
Subject: [External] Accident involving FBK6057 on 6/9/19 - request for survey

Dear Sir/Mdm

Pls be informed that FBK6057 owner had appointed us to submit an O/D claim for them

Pls find enclosed accident report and our repair estimate.

Kindly arrange your appointed surveyor to conduct damage survey at our workshop at your early convenience.

Thanks

c s teo

The content of this e-mail message and any attachments are confidential and may be legally privileged, intended solely for the addressee. If you are not the intended recipient, be advised that any use, dissemination, distribution, or copying of this e-mail is strictly prohibited. If you receive this message in error, please notify the sender immediately by reply email and destroy the message and its attachments.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	12/09/2019 09:21
Date Of Accident	06/09/2019 23:10
Exact Location Of Accident	ALONG PIONEER ROAD
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	FBK6057R
Insured/Policyholder	
Name Of Registered Owner	CERTIS CISCO AUXILIARY POLICE
Co Reg No	- 2009 00 882K
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-98595057
Alternative Phone No	OFFICE-98595057

Vehicle Particulars

Manufacturer	HONDA
Model	CB400
Exact Purpose for which vehicle was being used at time of accident	WORKING PURPOSES

Are you claiming under your own insurance policy for repair to your vehicle? YES

If No, Please state action to be taken

Vehicle Category	MOTORCYCLE
------------------	------------

Insurance Company

Name of Insurance Company	GREAT AMERICAN INSURANCE COMPANY
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	MOMVM000001011-02-000
Cover Note Number	

Driver

Name of Driver	MOHAMAD SAFRI BIN YUSOFF
NRIC No	S8112161C
Date Of Birth	07/05/1981
Occupation	OUTDOOR
Date Of Driving Pass	02/10/2007
Driving Experience	11 YEARS AND 11 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-98595057
Fax Number	
Contact Number	OTHERS-98595057
Email Address	NOEMAIL

Address	BLK 818 JURONG WEST STREET 81 #03-248
Postcode	640818
Was driver an employee of the Insured's Company	YES
If No, Relationship of the Driver with the Insured	
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	NO COLLISION
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	1
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	NO
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	


Circumstances of Accident

PLEASE REFER TO SKETCH PLAN

Attachment(s)


Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

INCIDENT REPORT FOR DUTY POST

Location of Duty Post	Type of Business (Bank/KINs/Embassy/ Residence/Factory)	Date of Incident	Time of Incident	Weather Condition				
E & E (Contriver)	Oversize cargo escort	6/9/19	2310 Hrs	Fine.				
Person(s) Involved	Particulars of Witness(es)							
CPL 21016 Mohamad Safri	CPL 59690 Ridzuan							
Details of Incident (Who, What, Where, When, Why, How and Other Essential Details)								
On the abovementioned date and time, 1 cpl 21016 was performing oversize cargo								
escort for Bok Seng logistics with cargo dimensions H: 3.8m W: 3.5m L: 31m.								
Along pioneer road the road was not well lighted and very sandy. I was								
at the lane 1 against the flow covering the turning cargo, however in								
the process my front tyre run over a curb of divider cause me to								
fall off the bike. The divider is not visible and no arrow signage.								
The bike was damage in the process, no other properties damage in								
the process. That's all. Please refer to sketch.								
Reported by : (Rank/Svc No/Name) CPL 21016 Md Safri Yusoff.		Signature 	Date 7/9	Time 0420 Hrs.				

Details of Incident (Cont'd)

Sketch



[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle****Vehicle Owner Particulars**

Owner ID Type:	Company
Owner ID:	882K

Vehicle Details

Vehicle No.:	FBK6057R
Vehicle to be Exported:	No
Intended Deregistration Date:	13 Sep 2019
Vehicle Make:	HONDA
Vehicle Model:	CB400X
Primary Colour:	White
Manufacturing Year:	2015
Engine No.:	NC47E5000439
Chassis No.:	JH2NC4796EK000435
Maximum Power Output:	-
Open Market Value:	\$6,659.00
Original Registration Date:	05 Nov 2015
First Registration Date:	05 Nov 2015
Transfer Count:	1
Actual ARF Paid:	\$999.00

Intended PARF Rebate Details

PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00

Intended COE Rebate Details

COE Expiry Date:	04 Nov 2025
COE Category:	D - Motorcycle
COE Period(Years):	10
QP Paid:	\$6,201.00
COE Rebate Amount:	\$3,809.00
Total Rebate Amount:	\$3,809.00

The information contained herein is correct as at 13 Sep 2019

OK

Leong Seng Motor Pte Ltd

Blk 1006 Bukit Merah Lane 2

#01-08 Singapore 159762

Tel: 62737469 Fax: 62727669

Veh No : FBK6057R

Model : CB400X

S/N	Parts Description	QTY	List Price	Nett Price	Remark
1	Top cowling		\$ 385.00	cut	
2	Front nose		\$ 185.00	cut	
3	Top side cover (L)		\$ 365.00	de	
4	Meter cover		\$ 175.00	cut	
5	Side panel		\$ 285.00	de	
6	Side panel inner		\$ 160.00	?	
7	Side cover		\$ 240.00	de	
8	Side cover inner		\$ 125.00	de	
9	Wind shield		\$ 280.00	cut	
10	Top stay		\$ 260.00	bt	
11	Front signal lamp		\$ 95.00	cut	
12	Front fender		\$ 225.00	KX	
13	Front fork assy		\$ 960.00	?	
14	Fork under bracket		\$ 285.00	?	
15	Front wheel rim	600	\$ 880.00	bt	
16	Wheel rim bearing	2	\$ 50.00	na	
17	Front wheel axle		\$ 120.00	bt	
18	Clutch lever		\$ 45.00	cut	
19	Mirror		\$ 95.00	cut	
20	Handle bar		\$ 235.00	bt	
21	Handle balancer		\$ 45.00	cut	
22	Gear pedal		\$ 150.00	bt	
23	Front foot rest		\$ 85.00	cut	
24	Side stand holder		\$ 165.00	dd	
25	Top crash bar		\$ 350.00	bt	
26	Bottom crash bar		\$ 340.00	bt	
27	Rear crash bar		\$ 280.00	bt	
28	Front blinker lamp		\$ 155.00	cut	
29	Siren assy		\$ 780.00	cut	
30	ERP IU		\$ 166.00	cut	
31	Side box		\$ 280.00	cut	
32	Respray side box		\$ 150.00	100.	
33	Side box reflective sticker		\$ 180.00	120.	
34	Front no plate		\$ 15.00	37	
35	Co logo sticker		\$ 180.00	150	
36	Respray top cowling, panel, fender		\$ 350.00	200	
37	Towing 2 way		\$ 120.00	80	
38	Labour		\$ 500.00	300	
39					

\$ 5,895.00 \$ 3,846.00

Less 10%

\$ 589.50

\$ 5,305.50

Leong Seng Motor Pte Ltd

Blk 1006 Bukit Merah Lane 2

#01-08 Singapore 159762

Tel: 62737469 Fax: 62727669

Veh No : FBK6057R

Model : CB400X

S/N	Parts Description	QTY	List Price	Nett Price	Remark
1	Top cowling		\$ 385.00	at	
2	Front nose		\$ 185.00	cr	
3	Top side cover (L)		\$ 365.00	de	
4	Meter cover		\$ 175.00	at	
5	Side panel		\$ 285.00	de	
6	Side panel inner		\$ 160.00	? Xnm	
7	Side cover		\$ 240.00	de	
8	Side cover inner		\$ 125.00	de	
9	Wind shield		\$ 280.00	cr	
10	Top stay		\$ 260.00	bt	
11	Front signal lamp		\$ 95.00	at	
12	Front fender		\$ 225.00	Kx	
13	Front fork assy		\$ 960.00	? bt	
14	Fork under bracket		\$ 285.00	? bt	
15	Front wheel rim	600	\$ 880.00	bt	
16	Wheel rim bearing	2	\$ 50.00	no	
17	Front wheel axle		\$ 120.00	bt	
18	Clutch lever		\$ 45.00	at	
19	Mirror		\$ 95.00	at	
20	Handle bar		\$ 235.00	bt	
21	Handle balancer		\$ 45.00	at	
22	Gear pedal		\$ 150.00	bt	
23	Front foot rest		\$ 85.00	at	
24	Side stand holder		\$ 165.00	at	
25	Top crash bar			\$ 350.00	bt
26	Bottom crash bar			\$ 340.00	bt
27	Rear crash bar			\$ 280.00	bt
28	Front blinker lamp			\$ 155.00	cr
29	Siren assy			\$ 780.00	cr
30	ERP IU			\$ 166.00	at
31	Side box			\$ 280.00	at
32	Respray side box			\$ 150.00	100
33	Side box reflective sticker			\$ 180.00	120 nu
34	Front no plate			\$ 15.00	bt
35	Co logo sticker			\$ 180.00	150 nu
36	Respray top cowling, panel, fender			\$ 350.00	200
37	Towing 2 way			\$ 120.00	80
38	Labour			\$ 500.00	300
39					

Less 10%

5230
10% - 4707
3316
8023

\$ 5,895.00 \$ 3,846.00
\$ 589.50
\$ 5,305.50

3316

A191.50

Confirm with w/s

45\$ 6400 # 5 days

UNIQUE MOTORSPORTS PTE LTD



GST REG. No. : 200907910H
UEN No. : 200907910H
Website : www.uniquemotorsports.com.sg
Email : sales@uniquemotorsports.com.sg

TAX INVOICE

UM @ Toh Guan
48 Toh Guan Road East,
#02-140 Enterprise Hub, (S) 608586
Tel : 6515 4978 Fax : 6515 4979

UM @ Kaki Bukit
1 Kaki Bukit Ave 6 #02-54/55,
Autobay @ Kaki Bukit, (S) 417883
Tel : 6844 6378 Fax : 6844 6379

UM @ Woodlands
280 Woodlands Industrial Park E5
#01-43 Harvest @ Woodlands
Singapore 757322
Tel : 6339 2178 Fax : 6339 3379

Invoice : TG1S40415
Date : 13/09/2019
Page : 1
Cashier : Chan Jia Jun
Served By : Chan Jia Jun

Mechanics:

Bill To

L0004
Leong Seng Trading & Credit Pte Ltd
Blk 1006 Bukit Merah Lane 2 #01-08
Singapore 159762
Phone : 62737469

Deliver To

Mileage :

Item Details	Qty	Unit Price	Amount (\$)
Customised Front Top Crashbar For Honda CB400X	1	480.00	480.00

Remarks : Cash And Carry

Terms : COD

Sub-Total :	\$	480.00
Discount :	\$	90.00
Incl. of GST 7.0% :	\$	25.51
Total Amount Payable :	\$	390.00
Nets :	\$	390.00

Goods sold are not returnable or exchangeable.
Cheque payment must be crossed and made payable to UNIQUE MOTORSPORTS PTE LTD

Unique Motorsports Pte Ltd

Goods received in good order and condition.

Authorised Signatory

Date :

Company Stamp & Signature

Date :

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

GREAT AMERICAN INSURANCE COMPANY

Ref : CS/GAI19016193/T1yd3e2

3 TEMASEK AVENUE
#16-01 CENTENNIAL TOWER
SINGAPORE 039190

Date : 08-10-2019



Code : GAI

1. Policy Particulars :- OWN DAMAGE

Insured Veh.		Veh. Inspected	FBK 6057R
Policy No.	MOMVM000001011-02-000	Coverage (\$)	0.00
Claim No.	CLMOMVM000000508	Excess (\$)	1,500.00
Assign From	SHERY WONG	Assign Date	12/09/2019

2. Vehicle Particulars & Condition

Make & Model	HONDA CB400X	c.c	399
Engine No.	HIDDEN	Year of Reg.	2015
Chassis No.	JH2NC4796EK000435	Colour	WHITE
Odometer	130146	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	120/70 R17	PIRELLI	5 mm
L/H Front Tyre			mm
R/H Rear Tyre	160/60 R17	PIRELLI	5 mm
L/H Rear Tyre			mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE N/S BODY AND FRONT PORTION. DAMAGES SEE DETAILS.
--

5. General Information

Accident Date	06/09/2019	Inspection Date	13/09/2019
Survey held at	LEONG SENG MOTOR PTE LTD BLK 1006, BUKIT MERAH LANE 2 #01-08 ALEXANDRA VILLAGE SINGAPORE 159762.		

5a. Remarks

A) THE MARKET VALUE IS S\$13,000.00(EST. AVERAGE) B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	5 Working Days
-------------------------------------	-----------------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. FBK 6057R

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	TOP COWLING	CUT	385.00	385.00
1	FRONT NOSE	CRACKED	185.00	185.00
1	TOP SIDE COVER (L)	DEFORMED	365.00	365.00
1	METER COVER	CUT	175.00	175.00
1	SIDE PANEL	DEFORMED	285.00	285.00
1	SIDE PANEL INNER	NOT NECESSARY	160.00	-
1	SIDE COVER	DEFORMED	240.00	240.00
1	SIDE COVER INNER	DEFORMED	125.00	125.00
1	WIND SHIELD	CRACKED	280.00	280.00
1	TOP STAY	BENT	260.00	260.00
1	FRONT SIGNAL LAMP	CUT	95.00	95.00
1	FRONT FENDER	TO REPAIR SEE LABOUR	225.00	-
1	FRONT FORK ASSY	BENT	960.00	960.00
1	FORK UNDER BRACKET	BENT	285.00	285.00
1	FRONT WHEEL RIM	BENT	880.00	600.00
2	WHEEL RIM BEARING	NECESSARY	50.00	50.00
1	FRONT WHEEL AXLE	DENTED	120.00	120.00
1	CLUTCH LEVER	CUT	45.00	45.00
1	MIRROR	CUT	95.00	95.00
1	HANDLE BAR	BENT	235.00	235.00
1	HANDLE BALANCER	CUT	45.00	45.00
1	GEAR PEDAL	BENT	150.00	150.00
1	FRONT FOOT REST	CUT	85.00	85.00
1	SIDE STAND HOLDER	DENTED	165.00	165.00
	LESS 10% DISCOUNT		-589.50	-523.00
			5,305.50	4,707.00
<u>SPECIAL NETT ITEMS</u>				
1	TOP CRASH BAR (SN)	BENT	350.00	350.00
1	BOTTOM CRASH BAR (SN)	BENT	340.00	340.00
1	REAR CRASH BAR (SN)	BENT	280.00	280.00

Report Ref No. CS/GAI19016193/T1yd3e2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	FRONT BLINKER LAMP (SN)	CRACKED	155.00	155.00
1	SIREN ASSY (SN)	CRACKED	780.00	780.00
1	ERP IU (SN)	CUT	166.00	166.00
1	SIDE BOX (SN)	CUT	280.00	280.00
1	SIDE BOX REFLECTIVE STICKER (SN)	NECESSARY	180.00	120.00
	FRONT NO PLATE (SN)	BENT	15.00	15.00
1	CO LOGO STICKER (SN)	NECESSARY	180.00	150.00
			2,726.00	2,636.00
	LABOUR			
	RESPRAY SIDE BOX.		150.00	100.00
	RESPRAY TOP COWLING, PANEL, FENDER.		350.00	200.00
	TOWING 2 WAY.		120.00	80.00
	LABOUR. INCLUSIVE OF THE REPAIR OF FRONT FENDER.		500.00	300.00
			1,120.00	680.00
GRAND TOTAL			9,151.50	8,023.00

RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			6,400.00
LESS EXCESS			-1,500.00
NETT LIABILITY			4,900.00

Report Ref No. CS/GAI19016193/T1yd3e2

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.