

HOCK WAH MOTOR WORKSHOP PTE LTD

BLK 3011 BEDOK INDUSTRIAL PARK E
BEDOK NORTH AVE 4,
#01-2008 10 12 SINGAPORE 489977
TEL: 6441 5655 FAX: 6441 5355 6243 8121
R.O.C No. 200104141D GST Reg No 20-0104141-D

JN1BBUJ3220000583

TO : SXXX8913E
ALEX YEO SIAK TEONG
BLK 9 YISHUN STREET 51
07-18
SINGAPORE 767970
TEL : FAX
PIE: 97201102
ATTN :

ESTIMATE BILL

Number : EB00005258
Date : 02-09-2019
Case No : AD00010643
Vehicle No : SGG850T
Chassis : JNABBU32Z0000583
Year of Mfr : 2008
Policy No : 5058925228-01
Model : NISSAN TEANA 2.5

Term:

Sn	DESCRIPTION	QTY	U PRICE	DISC	AMOUNT
1	HEADLAMP RH <i>SCR</i>	1.0	2,188.60	10	1,969.74
2	FRONT BUMPER <i>Deep cut ✓</i>	1.0	720.00	10	648.00
3	FRONT BUMPER RETAINER RH <i>✓</i>	1.0	55.50	10	49.95
4	FRONT BUMPER RETAINER LH <i>✓</i>	1.0	55.50	10	49.95
5	FRONT BUMPER CHROME RH <i>✓</i>	1.0	121.20	10	109.08
6	FRONT BUMPER CHROME LH <i>✓</i>	1.0	121.20	10	109.08
7	FRONT FENDER SHIELD RH <i>✓</i>	1.0	99.40	10	89.46
Nett Price - Parts Sub Total					3,025.26
8	HEADLAMP LOWER BRACKET RH <i>✓</i>	1.0	30.00	0	30.00
9	HEADLAMP NOZZLE RH <i>BVC</i>	1.0	233.90	0	233.90
10	HEADLAMP NOZZLE COVER RH <i>Cu</i>	1.0	75.60	0	75.60
11	FRONT FENDER RH - REPAIR <i>✓</i>	1.0			
12	BONNET - REPAIR <i>✓</i>	1.0			
Special Nett Price - Parts Sub Total					339.50
Parts Total					3,364.76
13	LABOUR TO REMOVE & REFIT NECESSARY PARTS	1.0	600.00	0	600.00
14	SPRAY PAINT ON THE AFFECTED AREAS	1.0	800.00	0	800.00
15	ANTI-RUST COATING	1.0	180.00	0	180.00
16	WIRING	1.0	40.00	0	40.00
Labour 1 Sub Total					1,620.00
SINGAPORE DOLLARS : FIVE THOUSAND THREE HUNDRED THIRTY-THREE AND CENTS SIXTY-NINE ONLY					5,333.69
Less Excess					0.00
SUBTOTAL					4,984.76
GST 7.00%					348.93
TOTAL					5,333.69

Date of accident : 02-08-2019 08:40 AM. Place : CARPARK OF 419A YISHUN AVE 11

E. & O. E.

HOCK WAH MOTOR WORKSHOP PTE LTD

CUSTOMER SIGNATURE

AUTHORISED SIGNATURE