

Assessor

ASS. REC. BY:

REF

CS/CTJ 19016/97/ Kq f3

n2

Special Instruction:

Surveyor

Kenneth

ASSIGNMENT (Office)

From (Person):

Chang Braa Sen

of

CTJ

Date/Time:

12.9.19 14.48p.n

Estimated Cost:

Bill to:

OD/TP/WS/TP RES/OD RES/EVA/INV/MV/CS

To Inspect Vehicle No:

SMD 7596B

Insured:

YL 6679T

at Workshop m/s

S R H motor

Tel:

64534730

of

160 sn mny drive #07-02

Policy No:

DMCVSN 30329318022

Claim No:

SMM 1910200471

Sum Insured:

Excess:

Make of Veh:

D.O.A

23.1.2019

(Client's Record)

16.9.2019

CA / REV / REP. / REV 24 HRS

I.O.D. Endorsement:

Date/Time:

13.9.19 3.54p.n

Person Contacted:

Miss Wong.

Vehicle IN

OUT

Date/Time	Action/Instruction (✓) Estimate
	SMD 7596B X
	YL 6679T - CS 3 / A16 / 4006 / 60 / 4036
	D.O.A - 01/04/2014
5/3	6502 email & confirmed CRD 8674.30, 49%

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	12 Sep 2019 Sendback Est	12 Sep 2019 12:12 S\$1,274.30	12 Sep 2019 14:48 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS									
Insured:	-, Co. Reg. No.: -								
Main Claimant:	CHAN CHEE YOON, ID: S13971822								
Vehicle Reg. No.:	SMD7596B	Date of Loss:	23/01/2019 17:00 - :59 [4 Months and 22 Days From LTA Reg Date (Mon Yr)]						
Claim Type:	TP / SNM19D200471- YL6679T-CBS	Policy/Cover Note No.:	DMCVSN30329518022						
Vehicle Reg. No. (Insured):	YL6679T	Policy No. (Claimant):	VPA/P2172020						
		Excess:	S\$0.00						
Repairer:	S & H Motor Pte Ltd (Sin Ming) 160 Sin Ming Drive #07-02, Sin Ming AutoCity, 575722 Sin Ming - Tel: 6453 4730								
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Chong Boon Sen]								
Claimant's Insurer:	AXA Insurance Pte Ltd (HQ) - Tel: 6338 7288								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 23/09/2019]								
ASSOCIATED MAIL RECEIVED									
View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS									
View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Shiau Chan (LKKAUTO)

From: Doris <doris@sh-motor.com>
Sent: Wednesday, 1 April 2020 10:58 AM
To: SUR
Subject: FW: vehicle no : SMD 7596 B-Final

From: Doris [mailto:doris@sh-motor.com]
Sent: Monday, 9 March 2020 1:00 PM
To: 'Kenneth Kong (LKKAUTO)'
Subject: RE: vehicle no : SMD 7596 B-Final

Dear Kenneth

Noted....Thank.....lump sum cot \$650.00

Thank

Doris

From: Kenneth Kong (LKKAUTO) [mailto:KennethKong@lkkauto.com]
Sent: Thursday, 5 March 2020 10:59 AM
To: Doris
Subject: RE: vehicle no : SMD 7596 B-Final

Attach finalised for SMD 7596B. Kenneth

From: Doris [mailto:doris@sh-motor.com]
Sent: Wednesday, 26 February, 2020 2:25 PM
To: Kenneth Kong (LKKAUTO)
Subject: FW: vehicle no : SMD 7596 B-Final

Can final

From: Doris [mailto:doris@sh-motor.com]
Sent: Monday, 18 November 2019 6:02 PM
To: 'Kenneth Kong (LKKAUTO)'
Subject: RE: vehicle no : SMD 7596 B-Final

Dear Kenneth

Sorry, this can

Thank

Doris

From: Kenneth Kong (LKKAUTO) [mailto:KennethKong@lkkauto.com]
Sent: Thursday, 10 October 2019 8:48 AM
To: Doris
Subject: RE: vehicle no : SMD 7596 B-Final

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	7182Z
Vehicle Details	
Vehicle No.:	SMD7596B
Vehicle to be Exported:	Yes
Intended Deregistration Date:	24 Jan 2019
Vehicle Make:	HYUNDAI
Vehicle Model:	ELANTRA AD 1.6 GLS AT (AMS)
Primary Colour:	Red
Manufacturing Year:	2018
Engine No.:	G4FGJU229304
Chassis No.:	KMHDB41CMJU717031
Maximum Power Output:	93.8 kW (125 bhp)
Open Market Value:	\$10,928.00
Original Registration Date:	01 Sep 2018
First Registration Date:	01 Sep 2018
Transfer Count:	0
Actual ARF Paid:	\$10,928.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	31 Aug 2028
PARF Rebate Amount:	\$8,196.00
Intended COE Rebate Details	
COE Expiry Date:	31 Aug 2028
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$31,997.00
COE Rebate Amount:	\$25,597.00
Total Rebate Amount:	\$33,793.00

The information contained herein is correct as at 24 Jan 2019

OK

S&H Motor Pte Ltd
160 Sin Ming Drive #07-02
Sin Ming Autocity
Singapore 575722

Insurer Reference:
Repairer Reference: 016122
Date calculated: 12/09/2019 12:06 PM

Full Report
Registration: SMD7596B
Printed: 12/09/2019 12:06 PM

Summary Information

Claim			
Location:	Singapore (SG)	Work Provider:	China Taiping Insurance (Singapore) Pte Ltd
Printed by:	SH Motor	Currency:	SGD
Claim Reference:		Date of Incident:	23/01/19
Estimated Repair Time:		Hire Car Start:	
Actual Repair Days:		Hire Car End:	

Vehicle Details

Vehicle	
Manufacturer:	HYUNDAI
Model:	ELANTRA (AD)
Sub Model:	BASE MODEL
Model Sheet Number:	30 EL 01
Registration:	SMD7596B
VIN number:	
Odometer:	
Model Specs	
TWO COAT METALLIC	PREPARE OFF VEHICLE

Not Authored
Resing B& paint
3 days
11pm @ 6501

Labour

Code	Description	Time Base 10 WU/h	Price = 42.00 SGD/h	
			WU	Price SGD
86520R00	RENEW REAR BUMPER INCLUDES: R + R OUTER TAIL LAMPS AND NECESSARY ATTACHED PARTS		9.0	37.80
3485	L/R OUT QTR PANEL REPAIR		10.0*	84.00
3571	L/R LAMP FRAME REPAIR		10.0* X	42.00 X
Labour Cost		Hrs	WU	
Panel / Mechanical Labour		3.90	39.0	163.80
Total of Labour				163.80

Paint

Paint Work		SYSTEM AZT		Time Basis 10 WU/h	
Code	Description - TWO COAT METALLIC			WU	Price SGD
	REAR BUMPER NEW PART PAINT K1R			8.0	
	L/R OUT QTR PANEL REPAIR PAINTING <50%			14.0	
	L/R LAMP FRAME REPAIR PAINTING <50%			8.0	
	L/R DOOR SURFACE PAINT			7.0	
	BOOTLID SURFACE PAINT			6.0	

S&H Motor Pte Ltd
160 Sin Ming Drive #07-02
Sin Ming Autocity
Singapore 575722

Insurer Reference:

Repairer Reference: 016122

Date calculated: 12/09/2019 12:06 PM

Paint Work

SYSTEM AZT

Full Report

Registration: SMD7596B

Printed: 12/09/2019 12:06 PM

Time Basis 10 WU/h

Code	Description - TWO COAT METALLIC	WU	Price SGD
	R/R OUT QTR PANEL SURFACE PAINT	7.0	

Paint Material Per Part

Code	Description	Price SGD
2583	REAR BUMPER NEW PART PAINT K1R	35.42
3485	L/R OUT QTR PANEL REPAIR PAINTING <50%	20.03
3571	L/R LAMP FRAME REPAIR PAINTING <50%	3.88
1781	L/R DOOR SURFACE PAINT	15.69
2931	BOOTLID SURFACE PAINT	14.44
3486	R/R OUT QTR PANEL SURFACE PAINT	15.44

Labour Cost - Paint

Factor

42.00 SGD/h

Hrs

WU

Price SGD

Time Paint

50.0

Preparation Main Work Metal

2.50

25.0

105.00

Preparation Comp. Work Plastic

0.50

5.0

21.00

Total

10 WU/h

8.00

80.0

336.00

Material Cost - Paint

Price SGD

New Part Painting - Plastic K1R

35.42

Repair Painting

23.91

Surface-/Blend Paint

45.57

Material-constant Metal Preparation

28.60

Material-constant Plastic

9.00

Total

142.50

Spare Parts

Code	Description	Part Number	Supplier	prices as at 2015-06-01	Price SGD
------	-------------	-------------	----------	-------------------------	-----------

2583	REAR BUMPER	86610F2AB1		230.00	✓
2585	L/R BUMPER BRACKET	86613F2AA0		30.00	✗
3281	L/R OUTER LAMP	92401F2500		230.00	✗

f: OEM Parts
n: Non-OEM Parts
u: Used parts

Savings

Subtotal

Fixed Sundry Parts Price

0.00

490.00

100.00

Link Auto Consultants licence notify
the Repairer of the following:
• To ensure satisfactory spray painting
• To ensure damaged areas being repaired
• Paint prices are subject to modification
• Total gap covered on a Vehicle's Repainting work
• No legal right to return, as stated
• Supplementary work items are at extra charge
It is subject to that our work is approved for pay

Authorised by Repairer

Date:

PRINT DATE 12/09/2019

S&H Motor Pte Ltd
160 Sin Ming Drive #07-02
Sin Ming Autocity
Singapore 575722

Insurer Reference:

Repairer Reference: 016122

Date calculated: 12/09/2019 12:06 PM

Full Report

Registration: SMD7596B

Printed: 12/09/2019 12:06 PM

Total

590.00

Extras

Code	Description	Price SGD
1000	Audatex fees Audatex fees	42.00*
	Total Extras	42.00

Final Calculation

	SGD	SGD
Parts	490.00	
Fixed Sundry Parts Price	100.00	
Total Parts		590.00
Labour Time Base 10 WU/h		
Total 39.0 WU X 42.00 SGD/h	163.80	
Total of Labour		163.80
Total Of Extras		42.00
Paint Work Time Base 10 WU/h		
Labour Cost 80.0 WU X 42.00 SGD/h	336.00	
Material Cost	142.50	
Total Paint Including Material		478.50
Repair Cost Excludes GST		1,274.30
GST (+7.0%)		89.20
Repair Cost Included GST		1,363.50

Comments

* - USER SUPPLIED DATA

NN - NO MANUFACTURERS CODE EXISTS

) - WU PARTIAL INCL IN OTHER POSITIONS

Assessment Note

No assessment notes entered.



TP INSURER: China Taiping Insurance (Singapore) Pte. Ltd. (HQ)

Singapore

Claimant Insurer: AXA Insurance Pte Ltd

PARTICULARS OF CLAIM

Claim Type:	THIRD PARTY	Ref. No:	
Policy No:		Date of Loss:	23/01/2019
Vehicle Reg. No.:	SMD7596B	Driveable?	
Party At Fault:	UNKNOWN		
Driver (TP):	CHAN CHEE YOON		
Make/Model:	HYUNDAI ELANTRA, 1.6 (A)	Vehicle Reg. Date:	01/09/2018
Vehicle Colour:	METALLIC RED		
Engine No:	G4FGJU229304	Chassis No:	KMHD841CMJU717031
Odometer:	0 KM		
Paint Type:			
Total Loss?	NO		
Est. Duration of Repair (day)	4		
Description of Accident/Loss	REFER ATTACHED REPORT.		
Present Location:	S & H MOTOR PTE LTD (SIN MING)		

COST OF CLAIMS	Amount
Parts	490.00
Miscellaneous Items	142.00
Paintwork Materials	142.50
Labour	163.80
Paintwork Labour	336.00
Towing	0.00
Gross Total (S\$)	1,274.30
+ GST 7.00% (S\$)	89.20
Nett Amount (S\$)	1,363.50

This claim is handled by: LUM WEE KEAT

Generated using Merimen e-Claims Internet Estimation & Adjusting System

RÉPAIR DETAILS**Reference****Part Source:** MRM-SG **Version:** 1.0 (Last Synchronised: 12 Sep 2019)**Parts:** 143 **HYUNDAI ELANTRA 1.6 (A)** (Catalogue:Merimen Singapore 1.0)**Labour:** Repairer's (Price-denominated Standard List)**Print Code:** S & H Motor Pte Ltd/SMD7596B/12/09/2019 12:12**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk *.**Estimates on Parts**

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*Parts	0.00	0.00	730 *490.00 F
Total Parts (\$\$)						490.00

F=Franchise part.

S & H Motor Pte Ltd/SMD7596B/12/09/2019 12:12. Not valid without Reference section.
Generated using **Merimen e-Claims IEAS**

Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
<u>Materials</u>			
1	1	Paintwork material	139.62 142.50
<u>Miscellaneous Items</u>			
2	1	Misc	142.00 ✓
Sub Total (S\$)			284.50

Estimates on Labour

No	Particulars	Lab.Type	Amount
<u>Paintwork Labour</u>			
1	Labour for paintwork	New	302.40 336.00
<u>Labour Items</u>			
2	Labour for parts/mechanical	New	75.80 163.80
Gross Labour Cost (S\$)			499.80

S & H Motor Pte Ltd/SMD7596B/12/09/2019 12:12, Not valid without Reference section,
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

LKK Auto Consultants
#01-25 Paya Ubi Industrial Park, 51
Ubi Avenue 1
408933

Insurer Reference:
Repairer Reference: 016122
Date calculated: 24/03/2020 12:04 PM

Full Report
Registration: SMD7596B
Printed: 24/03/2020 12:05 PM

Summary Information

Claim			
Location:	Singapore (SG)	Work Provider:	China Taiping Insurance (Singapore) Pte Ltd
Printed by:	KK LAU	Currency:	SGD
Claim Reference:		Date of Incident:	23/01/19
Estimated Repair Time:		Hire Car Start:	
Actual Repair Days:		Hire Car End:	

Vehicle Details


Vehicle	
Manufacturer:	HYUNDAI
Model:	ELANTRA (AD)
Sub Model:	BASE MODEL
Model Sheet Number:	30 EL 01
Registration:	SMD7596B
VIN number:	
Odometer:	
Model Specs	
TWO COAT METALLIC	PREPARE OFF VEHICLE

Vehicle Condition

Vehicle Status
Pre-Accident Damage:
Date of Inspection:

Damage Areas

All ☐
Underbody ☐



Labour

		Time Base 10 WU/h	Price = 42.00 SGD/h	
Code	Description		WU	Price SGD
86520R00	RENEW REAR BUMPER INCLUDES: R + R OUTER TAIL LAMPS AND NECESSARY ATTACHED PARTS		9.0	37.80
3485	L/R OUT QTR PANEL REPAIR		10.0*	42.00
Labour Cost		Hrs	WU	
Panel / Mechanical Labour		1.90	19.0	79.80
Total of Labour				79.80

Paint

Paint Work		SYSTEM AZT	Time Basis 10 WU/h	
Code	Description - TWO COAT METALLIC		WU	Price SGD
	REAR BUMPER NEW PART PAINT K1R		8.0	
	L/R OUT QTR PANEL REPAIR PAINTING <50%		14.0	
	L/R DOOR SURFACE PAINT		7.0	
	BOOTLID SURFACE PAINT		6.0	
	R/R OUT QTR PANEL SURFACE PAINT		7.0	

Paint Material Per Part

Code	Description	Price SGD
2583	REAR BUMPER NEW PART PAINT K1R	35.42
3485	L/R OUT QTR PANEL REPAIR PAINTING <50%	20.03
1781	L/R DOOR SURFACE PAINT	15.69
2931	BOOTLID SURFACE PAINT	14.44
3486	R/R OUT QTR PANEL SURFACE PAINT	15.44

Labour Cost - Paint			Hrs	WU	Price SGD
Factor		42.00 SGD/h			
Time Paint				42.0	
Preparation Main Work Metal			2.50	25.0	105.00
Preparation Comp. Work Plastic			0.50	5.0	21.00
Total		10 WU/h	7.20	72.0	302.40

Material Cost - Paint		Price SGD
New Part Painting - Plastic K1R		35.42
Repair Painting		20.03
Surface-/Blend Paint		45.57
Material-constant Metal Preparation		28.60
Material-constant Plastic		9.00
Total		138.62

Spare Parts

prices as at 2015-06-01

Code	Description	Part Number	Supplier	Price SGD
2583	REAR BUMPER	86610F2AB1		230.00
f: OEM Parts	Savings			0.00
n: Non-OEM Parts	Subtotal			230.00
u: Used parts	Fixed Sundry Parts Price			100.00
	Total			330.00

Extras

Code	Description	Price SGD
1000	Audatex fees Audatex fees	42.00*
	Total Extras	42.00

Final Calculation

	SGD	SGD
Parts	230.00	
Fixed Sundry Parts Price	100.00	
Total Parts		330.00
Labour Time Base 10 WU/h		
Total 19.0 WU X 42.00 SGD/h	79.80	
Total of Labour		79.80
Total Of Extras		42.00
Paint Work Time Base 10 WU/h		
Labour Cost 72.0 WU X 42.00 SGD/h	302.40	
Material Cost	138.62	
Total Paint Including Material		441.02
Repair Cost Excludes GST		892.82
GST (+7.0%)		62.50
Repair Cost Included GST		955.32

Comments

* - USER SUPPLIED DATA
 NN - NO MANUFACTURERS CODE EXISTS
) - WU PARTIAL INCL IN OTHER POSITIONS

Assessment Note

No assessment notes entered.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607196R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CT119016197/KQF3N2
Date: 02/04/2020

REFERENCE

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMCVSN30329518022
 Claimant Vehicle No: SMD7596B Insured Vehicle No: YL6679T
 Date of Loss: 23/01/2019 Nature of Claim: TP Claim No: SNM19D200471-
 YL6679T-CBS

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SMD7596B Engine No: G4FGJU229304
 Make & Model: HYUNDAI ELANTRA, 1.6 (A) Chassis No: KMHD841CMJU717031
 Reg. Date: 01/09/2018 (Man. Year: 2018) Odometer: 12940 km
 Colour: Metallic Red
 Engine Capacity: 1591 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/65R15 Rear Tyre Size: 195/65R15
 Front Left Side: Nexen 9 mm Rear Left Side: Nexen 9 mm
 Front Right Side: Nexen 9 mm Rear Right Side: Nexen 9 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	490.00	230.00	260.00	53.06
Miscellaneous Items	142.00	142.00	0.00	0.00
Paintwork Materials	142.50	138.62	3.88	2.72
Labour	163.80	79.80	84.00	51.28
Paintwork Labour	336.00	302.40	33.60	10.00
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	1,274.30	892.82	381.48	29.94
Approved Total (Overridden) (S\$)		650.00		
(S\$)	1,274.30	650.00	624.30	48.99
+ GST 7.00/7.00% (S\$)	89.20	45.50	43.70	48.99
Nett Amount (S\$)	1,363.50	695.50	668.00	48.99

INSPECTION

Date of Assignment: 12/09/2019 Present Location: S & H Motor Pte Ltd (Sin Ming)
 Date Inspected: 16/09/2019 Inspected At: S & H Motor Pte Ltd (Sin Ming)
 160 Sin Ming Drive #07-02, Sin Ming AutoCity
 Singapore 575722
 Estimated Period of Repair: 3.0 days

Adjuster: KENNETH KONG

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 02 Apr 2020)
Parts:	143	HYUNDAI ELANTRA 1.6 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMD7596B)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*Parts		490.00 F	*230.00 F
			Total Parts (S\$)		490.00	230.00

F=Franchise part.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
<u>Materials</u>				
1	1	Paintwork material	142.50	138.62
<u>Miscellaneous Items</u>				
2	1	Misc	142.00	142.00
Sub Total (S\$)			284.50	280.62

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Paintwork Labour</u>				
1	Labour for paintwork	New	336.00	302.40
<u>Labour Items</u>				
2	Labour for parts/mechanical	New	163.80	79.80
Gross Labour Cost (S\$)			499.80	382.20

Report was unsubmitted during this print-out.

< END OF ESTIMATES >