

Surveyor: Kelvin

REF: es/QW19016215/K1td392

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspected Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SHD 47017 Yr Regn: 3 May, 2019

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Hyundai Tucson C.C. 1500

Colour: Blue A/C: Insured / Std / NI / NA

Sp. Reading: — T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: KMHC851CCK46053

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 195/65R15

R: —

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front Rear

R/Bal. 8 mm R/Bal. 8 mm

L/Bal. 8 mm L/Bal. 8 mm

D.O.A. 5/9/19 D.O.I. 11/9/19

Survey held at CDHE (Loyang)

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Front

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	2nd opinion Report
	Independent Report to Sin Ming (CDHE)
	Front Both chassis Damaged, unable to Repair (structure)
	Recommend to Scrap.
	Veh cannot start
	Submit unsafe to repair.
	SHD 47017- NS/INC/8019759/K1td392
	DOA: 09/10/2019

RECEIVED 13 SEP 2019

Date/Time, File Pass to?

☐ : Prel. Report☒ : Final Report

1) 13/9 Typist

Date/Time, File Return to?

2)

Days Of Repair: —

Resurvey No. of Trip: —

Add Fee: ☐ : Site Insp (\$ —)☐ : Interview (\$ —)

Survey Fee:

Transportation:

S + RS, SI

Photos

Nivitha (LKK Auto)

From: Jumani Bin Masudin <jumanibm@cdge.com.sg>
Sent: Wednesday, 11 September 2019 10:54 AM
To: LKK
Subject: Fw: DOA.05.09.19 SHD4701T (IONIQ) PENDING SCRAP - Seek 2nd opinion

To

Office in charge

Please assist Doris's email

Best Regards

Jumani Masudin

Taxi Crash Repair / ComfortDelgro Engineering Pte Ltd
Tel. 6214-8315 / Fax. 6546-8156

From: Doris Lim Puay Noi <doris_lim@cdgtaxi.com.sg>
Sent: Wednesday, 11 September 2019 9:10 AM
To: Jumani Bin Masudin <jumanibm@cdge.com.sg>
Cc: Christine Tay Siew Hway <christine_tay@cdgtaxi.com.sg>; Roger How Keen Meng <rogerhow@cdge.com.sg>; Tan Pei Wei <tanpw@cdge.com.sg>
Subject: Re: DOA.05.09.19 SHD4701T (IONIQ) PENDING SCRAP - Seek 2nd opinion

Hi Jumani

Please assist to appoint LKK for 2nd opinion under our account.

Regards

Doris Lim

Fleet Safety Department

ComfortDelGro Taxi

DID: 6550 8606 / Hotline: 6550 8768



WIN \$8,888* by taking ComfortRIDE

1 SEP - 31 DEC 2019

* Prizes are in the form of ComfortPoints
Terms and conditions apply

Follow us on   

ComfortRide ComfortPoints

383 Sin Ming Drive, Singapore 575717

Members of COMFORTDELGRO

CityCab



From: Jurnani Bin Masudin <jumanibm@cdge.com.sg>

Sent: Monday, 9 September 2019 4:19 PM

To: Doris Lim Puay Noi <doris_lim@cdgtaxi.com.sg>

Cc: Christine Tay Siew Hway <christine_tay@cdgtaxi.com.sg>; Roger How Keen Meng <rogerhow@cdge.com.sg>;

Tan Pei Wei <tanpw@cdge.com.sg>

Subject: DOA.05.09.19 SHD4701T (IONIQ) PENDING SCRAP

Hi Doris

A/m taxi surveyed by VAC-DIN and recommended for scrap.

Please advise

Best Regards

Jumani Masudin

Taxi Crash Repair / ComfortDelgro Engineering Pte Ltd

Tel. 6214-8315 / Fax. 6546-8156

From: canon@comfortdelgro.com.sg <canon@comfortdelgro.com.sg>

Sent: Monday, 9 September 2019 4:14 PM

To: Jumani Bin Masudin

Subject: Scan Image

This message and any attachments may contain confidential, privileged or proprietary information. If you are not the intended recipient, kindly notify us and delete this message and its attachments immediately, and please be advised that using, copying, distributing or disclosing any contents therein is not allowed. Statements pertaining to any matter outside our business are not to be taken as endorsed by ComfortDelGro Corporation Limited or its related companies. The comments/proposals provided are for discussion purposes only and are subject to approvals. Nothing herein shall constitute a binding agreement between the parties. Neither party shall be bound in any way to any term or condition except as agreed in a written agreement signed by the duly authorised representatives of both parties.

ComfortDelGro - a Green Office certified by the Singapore Environment Council - is committed to preserving the environment. We encourage you to print this only if necessary.

ComfortDelGro Engineering Pte Ltd [Registration No. 199506048W]

Jurnal

Need Taxi Replacement

Yes / No

Date: will take 7 days

Sign: Kong Soon

COMFORT DELGRO
ENGINEERING

VARS

Welcome, Subramaniam S/O Narayanasamy

Home	New Request	Search
IsActive	IsAdmin	IsLOrFinance

VARS Reports Administration

Branch

AR Number: AR-09-19-000149
Maintenance Branch: BRADDELL

Vehicle Arrival Details

Check-In Mode: TOWED (Same Location) Tow Driver's Name: WEE
Check-In At: 5/9/2019 23:50 Tow Truck Reg. No.: YQ1675

Vehicle Details

Taxi Registration No.: SHD4701T Taxi Insurer:
Taxi Company: COMFORT TRANSP... Taxi Model: Hyundai Ioniq

Hirer Details

Status: HIRER Address: 422 HOUGANG AVENUE 6
Name: DOMINIC TAN CHIN TAK #06-128 530422
NRIC: SXXXX741D Roled in accident: No, Hirer was not the Driver
License Issued Date: Mobile Phone No: 96926671
License Expiry Date: Home Phone No: 63838859

Driver Details

Status: RELIEF Address: 571 HOUGANG ST 51
Name: SEE- TOH KENG SOON #05-115 530571
NRIC: SXXXX020B Mobile Phone No: 96497851
License Issued: Home Phone No:
License Expired:

Accident Details

Accident Date: 5/9/2019 23:50 Downtime Start: 5/9/2019 23:50
Accident Location: MCE TURN RIGHT TO CENTRAL BLVD
Location Type: X- JUNCTION Taxi Speed: 20 KM/H
Traffic Control: TRAFFIC LIGHT OPERATING CORRECT... No. of Passenger: 0
Traffic Flow: TWO WAY Collision Type: HEAD TO SIDE
Weather Condition: CLEAR Brakes Applied: Yes, brakes applied
Traffic Volume: LIGHT Reported To Police: No
Road Condition: DRY Police Report No.:
Lighting Condition: DARK, STREET LIGHT ON Ambulance Called: No
Taxi Damaged At: FRONT Scene Photo Taken: Yes, scene photo taken
Damage Severity: SERIOUS Scene Video Taken: Yes, scene video taken
Late Report Reason: - Driver Hospitalized: No


Remarks:

Third Party Property Details

Vehicle No	Involved Others	Owner Name	Owner NRIC	Damage At	Damage S...	Involved Taxi Bus
GBG3468D	-	-	-	FRONT RIGHT	MODERATE DAMAGE	

Injured Person Details

Name	NRIC	Gender	Mobile Phone	In Vehicle No.	Role In Accident	Injury Type	Remarks
No items to display.							



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 5/9/19 at about 23:50 hrs, I was turning right at above said location with traffic green light. When I approaching the other side, Veh B come out from my left hand side. As it happen too sudden, I can't react to avoid collision. Veh B front right portion collided onto the left front portion of my taxi. My taxi sustained badly damage at front portion including both front door and front windscreen. No injury reported in this accident. Thereafter I realised traffic light green is for going straight..

DECLARATION

I/We declare the foregoing particulars are true in every respect.

COMFORT TRANSPORTATION PTE LTD

POLY RES NO: 123456789

Policyholder's Signature

Date & Time:

Driver's Signature

(If driver is not the policyholder)

Date & Time:

Reporting Centre Personnel's Signature

Name:

NRIC/FIN No.:

Loke Wei Yeng

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type:

Company

Owner ID:

821R

Vehicle Details

Vehicle No.:

SHD4701T

Vehicle to be Exported:

Yes

Intended Deregistration Date:

11 Sep 2019

Vehicle Make:

HYUNDAI

Vehicle Model:

AE IONIQ HEV 1.6 DCT

Primary Colour:

Blue

Manufacturing Year:

2019

Engine No.:

G4LEKU209882

Chassis No.:

KMHC851CVKU146053

Maximum Power Output:

103.6 kW (138 bhp)

Open Market Value:

\$24,799.00

Original Registration Date:

03 May 2019

First Registration Date:

03 May 2019

Transfer Count:

0

Actual ARF Paid:

\$11,719.00

Intended PARF Rebate Details

PARF Eligibility:

Yes

PARF Eligibility Expiry Date:

02 May 2027

PARF Rebate Amount:

\$8,789.00

Intended COE Rebate Details

COE Expiry Date:

02 May 2027

COE Category:

A - Car up to 1600cc & 97kW (130bhp)

COE Period(Years):

8

PQP Paid:

\$22,309.00

COE Rebate Amount:

\$17,847.00

Total Rebate Amount:

\$26,636.00

Message

Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 11 Sep 2019

OK

REPAIR ESTIMATE*

VEHICLE NO : SHD 4701T

DATE 9/9/2019 15:35

MODEL : HYUNDAI IONIQ

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Bonnet			\$ 2,253.80
	Bonnet Hinge (LH/RH)		\$ 118.70	\$ 237.40
	Bonnet Lock			\$ 127.30
	Radiator Grille			\$ 1,227.50
	Speaker Assy- VESS			\$ 354.40
	Unit Assy-SMART CRU (Radar Sensor)			\$ 2,910.90
	Cover Assy -S.C.C.Unit			\$ 767.30
	Antenna Assy-SMARTK (LH/RH)	\$	689.50	\$ 1,379.00
	Assy BSD Blind Spot Radar (LH/RH)	\$	758.50	\$ 1,517.00
	Wiring Harness BWS Ext			\$ 988.90
	Front Bumper Cover			\$ 418.30
	Front Bumper Sponge			\$ 86.90
	Front Bumper Reinforcement			\$ 1,075.10
	Front Bumper Grille (LH/RH)	\$	186.90	\$ 373.80
	Front Bumper Towing Cover			\$ 29.00
	Front Bumper Centre Moulding			\$ 188.00
	Front Bumper Moulding	\$	93.60	\$ 187.20
	Front Bumper Lower Stiffner			\$ 85.10
	Front Bumper License Plate			\$ 17.40
	Front Bumper Lip			\$ 35.10
	Front Bumper Bracket Top (LH/RH)	\$	35.00	\$ 70.00
	Front Bumper Bracket (LH/RH)	\$	28.00	\$ 56.00
	Front Bumper Side Bracket Support	\$	12.00	\$ 24.00
	Front Bumper Clips 10 pcs			\$ 22.00
	Front Bumper Strip Assy			\$ 29.40
	Headlamp Support Panel Assy			\$ 949.30
	Headlamp (LH/RH)	\$	1,198.80	\$ 2,397.60
	Day Light, LH			\$ 642.50
	Day Light, RH			\$ 642.50
	Day Light Wire, LH/RH	\$	585.50	\$ 1,171.00
	Radiator Inverter			\$ 884.80
	Radiator			\$ 510.50
	Radiator Blower Motor			\$ 576.00
	Radiator Shroud			\$ 275.50
	Radiator Bracket			\$ 6.50
	Radiator Hose Upper			\$ 66.20
	Radiator Hose Lower			\$ 66.20
	Radiator Tank Reservoir			\$ 110.10
	Radiator Hose & Tube Assy			\$ 245.70
	Radiator Air Guard (LH/RH)	\$	26.40	\$ 52.80
	Radiator Air Guard, Upr (LH/RH)	\$	27.50	\$ 55.00
	Horn Unit (LH/RH)			\$ 72.80
	Front Fender (LH/RH)			\$ 490.70
	Front Fender Apron Panel (LH/RH)	\$	756.20	\$ 1,512.40
	Front Fender Apron Panel Upper (LH/RH)	\$	329.00	\$ 658.00
	Front Fender Shield (LH/RH)			\$ 114.70
	Front Fender Retainer	\$	41.40	\$ 82.80
	Emblem-Blue Drive (LH/RH)	\$	26.60	\$ 53.20

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Air Cleaner Assy			\$ 282.70
	Air Cleaner Cover			\$ 47.30
	Air Cleaner Body			\$ 112.30
	Aircon Expansion Valve			\$ 313.60
	Aircon Sensor Pressure - Suc/Liq			\$ 238.10
	Aircon Condenser			\$ 663.60
	Aircon Suction & Liquid Hose			\$ 679.60
	Aircon Discharge Hose			\$ 148.50
	Aircon Blower Motor			\$ 567.50
	Aircon Compressor			\$ 4,069.80
	Aircon Evaporation Coil & Heater Unit			\$ 2,077.00
	Front Windscreen Moulding			\$ 57.30
	Wiper Container			\$ 61.90
	Wiper Container Motor			\$ 75.00
	Front Chasis Member (LH/RH)		\$ 1,314.80	\$ 2,629.60
	Engine Mounting			
	Engine Under Cover			\$ 469.40
	Engine Crossmember			\$ 1,803.90
	Engine Mtg (Front)			
	Engine Mtg (Rear)			
	Engine Support Bracket Assy			
	Gearbox			\$ 23,660.40
	Gearbox Mounting			\$ 183.70
	Engine Assy			
	Pstg Hose & Bracket			
	Power Steering Pump			
	Power Steering Tank			
	Power Steering Pressure Hose Assy			
	Power Steering Outlet Hose & Bracket			
	Power Steering Pipe Assy			
	Steering Wheel			\$ 1,354.30
	Steering Shaft			
	Steering Column & Shaft Assy			\$ 4,115.50
	Steering Flexible Joint			
	Steering Wheel Horn Button Assy			
	Inverter Cooler			\$ 1,723.90
	Inter Cooler Mounting (2 PCS)			
	Hose B To Inter Cooler			
	Hose C To Inter Cooler Inlet			
	Pipe To Inter Cooler			
	Pipe To Inter Cooler Outlet			
	Airbag Control Module			\$ 1,243.70
	Curtain Airbag Module, LH			\$ 1,344.50
	Curtain Airbag Module, RH			\$ 1,344.50
	Steering Wheel Air Bag			\$ 1,090.90
	Module Assy -Knee Air Bag			\$ 578.60
	Air Bag Assy - Passenger			\$ 1,951.20
	Air Bag Sensor (LH/RH)		\$ 330.00	\$ 660.00

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	SUB TOTAL			\$ 79,645.90
	LESS 20%			\$ 15,929.18
	DISCOUNTED TOTAL			\$ 63,716.72
	Front Number Plate			\$ 25.00 Nett
	Front No Plate Trim Cover			\$ 30.00 Nett
	Front Windscreen Sealant			\$ 46.00 Nett
				\$ 101.00
	Labour Charge			
	Panel Beating			\$ 2,000.00
	Spray Painting Charge			\$ 1,600.00
	Wiring Charge			\$ 50.00
	Tuff Kote			\$ 50.00
	Towing Charge			\$ 90.00
	Front Chassis Alignment Charge			\$ 400.00
	Remove/Refix Aircon & Refill Gas			\$ 150.00
	Remove/Refix Engine			\$ 500.00
	Remove/Refix Dashboard			\$ 450.00
	Remove/Refix Fuse Box			\$ 180.00
	Remove/Refix Power Steering Pump			\$ 120.00
	R/Refix Air Bag/Steering Wheel/Dashboard/Seat			\$ 550.00
	Diagnostic & Resetting To Erase Fault Code			\$ 480.00
	TOTAL LABOUR			\$ 6,620.00
	ESTIMATE TOTAL			\$ 70,437.72
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor surveyor appointed by the insurance company.				

Report ID : ZFICV32
DATE : 11.09.2019
TIME : 12:00:20

Comfort Transportation PL
Vehicle NW for Fleet Safety Division
AS AT 31.09.2019

USER ID : CTFMEX03
PAGE : 1

Co. Code : CTFM
Licence Pl. No : S2M4701T
Old Asset No :
Veh. Model : Hyundai Ioniq Hybrid
Reg. Date : 03.05.2019
Cap. Date : 03.05.2019
Accident Date : 05.09.2019
Veh. Age : 004

Asset No	SA No	Bal. Dep. Mths	Per. Mth. Dep	Bal. Dep. Value	Asset Description 1	Cost	Op. Acc. Dep	Our. Year Dep	Accum. Dep	Net Book Value	Scrap value/Estimated P&GF Refund
10038554	0	086	317.54	29,023.44	S2M4701T HH 03.05.2019 BASIC COST W ALKIN	30,390.00	0.00	1,350.18-	1,350.18-	29,023.82	1.00
10038554	1	086	55.11	4,739.46	S2M4701T HH 03.05.2019 IMPORT DUTY 2004M24799	4,959.70	0.00	220.43-	220.43-	4,739.27	0.00
10038554	2	086	52.09	4,479.74	S2M4701T HH 03.05.2019 ARF X20M24799-CENSSISK	11,719.00	0.00	208.36-	208.36-	11,510.64	7,031.00
10038554	3	086	247.88	21,317.68	S2M4701T HH 03.05.2019 CDE 804	22,309.00	0.00	991.51-	991.51-	21,317.49	0.00
10038554	4	002	0.00	0.00	S2M4701T HH 03.05.2019 CDE TOP UP	0.00	0.00	0.00	0.00	0.00	0.00
10038554	5	086	0.00	0.00	S2M4701T HH 03.05.2019 AIR CONDITIONER	0.00	0.00	0.00	0.00	0.00	0.00
10038554	6	086	0.00	0.00	S2M4701T HH 03.05.2019 PRINTER DIGITAL THERMAL	0.00	0.00	0.00	0.00	0.00	0.00
10038554	7	086	0.00	0.00	S2M4701T HH 03.05.2019 TAXIMETER DIGITAL FI	0.00	0.00	0.00	0.00	0.00	0.00
10038554	8	086	2.44	209.84	S2M4701T HH 03.05.2019 VEH REG FEE	220.00	0.00	9.78-	9.78-	210.22	0.00
			695.06	59,775.16		69,587.70	0.00	2,780.26-	2,780.26-	66,807.44	
	CDE		247.88	21,317.68	Vehicle : Without T/M & CDE	47,278.70	0.00	1,788.75-	1,788.75-	45,489.95	
	Vehicle		447.18	38,457.48	Vehicle : Without T/M, With CDE	69,587.70	0.00	2,780.26-	2,780.26-	66,807.44	
			695.06	59,775.16	Taximeter	0.00	0.00	0.00	0.00	0.00	

SHD 47017

$$\textcircled{1} \text{ cost of taxies } 69587.70$$

$$\text{ARF } 75\% = 18599.25$$

$$\text{Re partition} = (69587.70 - 18599.25) \div 96$$
$$= 531.13$$

$$\textcircled{2} \text{ Park value} = (531.13 \times 92) + 18599.25$$
$$= 67463.21$$

$$\textcircled{3} \text{ NetH value} = 67463.21 - 26636$$
$$= 40827.21$$
