

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	524Z
Vehicle Details	
Vehicle No.:	SKR3016K
Vehicle to be Exported:	No
Intended Deregistration Date:	02 Aug 2019
Vehicle Make:	TOYOTA
Vehicle Model:	TOYOTA COROLLA ALTIS 1.6L CVT
Primary Colour:	Grey
Manufacturing Year:	2015
Engine No.:	1ZRX484039
Chassis No.:	MR053REH104525378
Maximum Power Output:	90.0 kW (120 bhp)
Open Market Value:	\$19,589.00
Original Registration Date:	29 Jan 2015
First Registration Date:	29 Jan 2015
Transfer Count:	0
Actual ARF Paid:	\$14,589.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes <input checked="" type="checkbox"/>
PARF Eligibility Expiry Date:	28 Jan 2025
PARF Rebate Amount:	\$10,941.00 $\times 50\% = \$5,470.50$
Intended COE Rebate Details	
COE Expiry Date:	28 Jan 2025
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$65,001.00
COE Rebate Amount:	\$35,663.00
Total Rebate Amount:	\$46,604.00

$\times 50\% = \$7,294.50$

$\times 50\% = \$5,470.50$

The information contained herein is correct as at 02 Aug 2019

DOA: 16/07/2019

OK

47,586

Remaining : 5years 6months 12days (66.4months)

Depri : \$9100 (Yearly) \$758.33 (monthly)

$66.4 \times \$758.33 = \50353.33

$\$50353.33 + \5470.50

$= \$55823.83$

FLY TO OVER 60 CITIES! ALL-IN FARE FROM **\$56*** ScootBiz from \$177* [Book Now](#) *Terms & conditions apply

Post an Advertisement
Sell it yourself! Advertise it at just **\$58 until it's SOLD!**

[Post an Ad](#) [Advertiser Login](#) [Ways of Selling](#)

New 5 Years Renewal Coe Honda Fit 1.3A G



5.08% up to 50 Down, Monthly From \$138.2 Year Warranty, Sta Grade, 8 No Major Damage, GV Credit Pte Ltd

KA-HUP
VALUE FOR MONEY
VALUE FOR TIME
A PEACE OF MIND
HOTLINE: 6741 9997 [View our cars](#)

Browse by Category

Back (1 2) Next

Sort by Date Posted

20 results/page

35 vehicles

Toyota Corolla

Advanced Search

Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
Search Selection								
Toyota	Corolla	Any	Any	2015	Any	Any	Any	Available
	Toyota Corolla Altis 1.6A Classic	\$60,888	\$8,430 /yr	02-Oct-2015	1,598 cc	42,000 km	Sedan	Available
1 Owner, Agent Maintained.								
Posted: 02-Aug-2019 Tags: 2015 Toyota Corolla, 2015 toyota corolla, Toyota Corolla, toyota corolla, Toyota, Corolla, corolla, Used Toyota								
	Toyota Corolla Altis 1.6A Classic	\$58,800	\$9,100 /yr	13-May-2015	1,598 cc	56,800 km	Sedan	Available
Low Mileage, No Repairs Needed, Well Maintained, Excellent Condition, Accident Free, Beautiful Interior And Exterior, Bank And In House Loan Available, Trade In Are Welcome, Powerful Engine And Smooth Transmission, A Real Joy To Drive! Buy With Confidence! Call Us N...								
Posted: 01-Aug-2019 Tags: 2015 Toyota Corolla, 2015 toyota corolla, Toyota Corolla, toyota corolla, Toyota, Corolla, corolla, Used Toyota								
	Toyota Corolla Altis 1.6A Classic	\$67,800	\$9,610 /yr	16-Sep-2015	1,598 cc	30,080 km	Sedan	Available
Borneo Unit, Full Agent Maintained, Warranty Till Sept 2020. Grey Met Metallic Colour. Most Popular Sedan In The Market. Interest Rate From 1.99%. Please Call Our Sales Consultant For More Enquiries Now.								
Inchape Pre-Owned PREMIUM AD								
Posted: 01-Aug-2019 Tags: 2015 Toyota Corolla, 2015 toyota corolla, Toyota Corolla, toyota corolla, Toyota, Corolla, corolla, Used Toyota								
	Toyota Corolla Altis 1.6A Elegance	\$64,800	\$8,770 /yr	09-Nov-2015	1,598 cc	86,365 km	Sedan	Available
Elegance Model With Push Start And Keyless Entry! Call For An Viewing Appointment Today! High Loan Welcome.								
Mayfair Motoring PREMIUM AD								
Posted: 29-Jul-2019 Tags: 2015 Toyota Corolla, 2015 toyota corolla, Toyota Corolla, toyota corolla, Toyota, Corolla, corolla, Used Toyota								
	Bullstone Grasse Diffuser - Pure Cotton (105ml)							
Contains 100% natural French oil, providing drivers with deep subtle scent for pleasant driving experience.								
Find out more!								
	Toyota Corolla Altis 1.6A Elegance	\$65,000	\$8,610 /yr	28-Dec-2015	1,598 cc	81,000 km	Sedan	Available
One Owner Only, Excellent Tip Top Car Condition, Almost Brand New, Clean And Beautiful Interior, Owner's Consignment Unit, Call To Arrange For A Viewing. CONSIGNMENT								
Posted: 28-Jul-2019 Tags: 2015 Toyota Corolla, 2015 toyota corolla, Toyota Corolla, toyota corolla, Toyota, Corolla, corolla, Used Toyota								
	Toyota Corolla Altis 1.6A Elegance	\$63,800	\$8,760 /yr	29-Sep-2015	1,598 cc	83,147 km	Sedan	Available
Well Taken Care By 1 Owner Only. 100% Accident Free & Non Private Hirer Unit. Low Fuel Consumption And Maintenance.Transparent Deal With No Gimmicks & Hidden Cost. Flexible Bank Loan Package With Low Interest From 2.28%.In House Loan Available. Welcome T...								
Ka-Hup Vehicles Trading PREMIUM AD								
Posted: 28-Jul-2019 Tags: 2015 Toyota Corolla, 2015 toyota corolla, Toyota Corolla, toyota corolla, Toyota, Corolla, corolla, Used Toyota								

Compare

MOTORCAR (Rear)

Rear Portion

NAC	INC	Item	CON	AC	Qb
1137	993626	Rear Number Plate			
1138	993627	Rear Number Plate Base			
1139	993630	Rear Number Plate Garnish			
1140	993632	Rear Number Plate Lamp			
1141	992958	Rear Bumper	cr		700
1142	993085	Rear Bumper Upper			
1143	993017	Rear Bumper Lower			
1144	993054	Rear Bumper Side			
1145	993103	Rear Bumper Tow Cover			
1146	992341	Rear Bumper Clips	nc		40
1147	992976	Rear Bumper Bracket			
1148	993068	Rear Bumper Side Retainer			
1149	993045	Rear Bumper Reinforcement			
1150	992970	Rear Bumper Beam			
1151	993077	Rear Bumper Sponge			
1152	992999	Rear Bumper Damper			
1153	993040	Rear Bumper Protector			
1154	993036	Rear Bumper Pad			
1155	993026	Rear Bumper Moulding			
1156	993044	Rear Bumper Reflector			
1157	993023	Rear Bumper Lower Spoiler			
1158	994023	Reverse Sensor	gn		300
1159	993327	Rear End Panel			
1160	993339	Rear End Panel Top Garnish			
1161	993333	Rear End Panel Inner Trim			
1162	990333	Boot Compartment Inner Trim			
1163	993851	Rear LH Taillamp			
1164	993853	Rear LH Taillamp Garnish			
1165	993859	Rear LH Taillamp Panel			
1166	995116	Rear RH Taillamp			
1167	993853	Rear RH Taillamp Garnish			
1168	993859	Rear RH Taillamp Panel			
1169	993554	Rear Apron Panel			
1170	992895	Bootlid			
1171	991328	Bootlid Emblem			
1172	990356	Bootlid Handle			
1173	995250	Bootlid Moulding			
1174	990376	Bootlid Reflector			
1175	995222	Bootlid Lamp LH			
1176	992899	Bootlid Lamp RH			
1177	995243	Bootlid Lock			
1178	990377	Bootlid Rubber			
1179	990382	Bootlid Hinge			
1180	993877	Bootlid Spoiler			
1181	994543	Tailgate			
1182	991328	Tailgate Emblem			
1183	994643	Tailgate Outer Handle			
1184	994640	Tailgate Moulding			
1185	994545	Tailgate Garnish			
1186	994648	Tailgate Reflector			
1187	994549	Tailgate Lamp			
1188	994646	Tailgate Protector			
1189	994676	Tailgate Wiper Arm			
1190	994677	Tailgate Wiper Blade			
1191	994679	Tailgate Wiper Nozzle			
1192	994555	Tailgate Wiper Motor			
1193	994602	Tailgate Glass			
1194	994606	Tailgate Glass Rubber			
1195	994604	Tailgate Glass Moulding			
1196	994607	Tailgate Glass Sealant			
1197	994629	Tailgate Lock			
1198	994651	Tailgate Rubber			
1199	994611	Tailgate Hinge			
1200	994594	Tailgate Damper			
1201	994613	Tailgate Inner Board			

Vehicle No: SKR 2016 K

NAC	INC	Item	CON	AC	Q
1202	993784	Spare Tyre Board			
1203	994328	Spare Tyre Panel			
1204	995065	Spare Tyre			
1205	994326	Spare Tyre Lock Screw			
1206	993787	Spare Tyre Cover			
1207	995323	Triangle Breakdown Sign			
1208	990507	CD Changer Assy			
1209	990164	Antenna			
1210	990534	Centre Exhaust Pipe Assy			
1211	990532	Centre Exhaust Mounting			
1212	993364	Rear Exhaust Pipe			
1213	993357	Rear Exhaust Chrome Pipe			
1214	993361	Rear Exhaust Mounting			
1215	993358	Rear Exhaust Heat Shield			
1216	995223	Rear LH Chassis Member			
1217	993165	Rear RH Chassis Member			
1218	993436	Rear LH Fender			
1219	993449	Rear LH Fender Protector			
1220	993420	Rear LH Fender Inner Panel			
1221	993431	Rear LH Fender Inner Trim			
1222	993415	Rear LH Fender Inner Garnish			
1223	993425	Rear LH Fender Inner Shield			
1224	993621	Rear LH Mudflap			
1225	993933	Rear LH Wheel Rim			
1226	994025	Rear LH Rim Cover			
1227	995065	Rear LH Tyre			
1228	993456	Rear RH Fender			
1229	993450	Rear RH Fender Protector			
1230	993420	Rear RH Fender Inner Panel			
1231	993431	Rear RH Fender Inner Trim			
1232	993415	Rear RH Fender Inner Garnish			
1233	993425	Rear RH Fender Inner Shield			
1234	993622	Rear RH Mudflap			
1235	993934	Rear RH Wheel Rim			
1236	994025	Rear RH Rim Cover			
1237	995065	Rear RH Tyre			
1238	995162	Rear Fender Extension Panel LH			
1239	993401	Rear Fender Extension Panel RH			
1240	993430	Rear Fender Inner Top Garnish			
1241	993673	Rear Fender 1/4 Glass			
1242	993452	Rear Fender 1/4 Glass Rubber			
1243	993453	Rear Fender 1/4 Glass Sealant			
1244	993949	Rear Windscreen Glass			
1245	993976	Rear Windscreen Rubber			
1246	993961	Rear Windscreen Moulding			
1247	993955	Rear Windscreen Sealant			
1248	994729	Third Brake Light			
1249	993385	Rear Fender Air Grille			
1250	992167	Fuel Lid			
1251	992168	Fuel Neck			
1252	992179	Fuel Tank			
1253	992184	Fuel Tank Bracket			
1254	992191	Fuel Tank Float			
1255	990247	Sticker			

No of Items: _____ Assessor: _____

JINGKIA CAR SERVICES

Blok 10, Ang Mo Kio Autopoint, #05-09 Ang Mo Kio Industrial Park 2A Singapore 568047
 Tel: 64814055 Fax: 64811066 H/P: 93822000

Auto Consultants hence notify
 the Repairer of the following:
 • To resurvey before/after spray painting
 • To display damaged part(s) during resurvey
 • Parts prices are subject to confirmation
 • Third party survey is on a "Without Prejudice" basis
 • No illegal modification(s) is allowed
 • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature: Jellic Toyota ATTU.
 Date:

01/08/19.

Re: Quotation of vehicle no. SKR

1 pc. Rear bumper Assy	575.50 inc ✓	\$436.50
1 pc. Rear bumper reinforcement	246.20 inc	
1 pc. Rear bumper Lt retainer	75.00 inc ✓	\$40
1 pc. Rear bumper Lt reflector	55.00 inc	
1 set Rear bumper rev. sensor	220.00 inc ✓	✓
2 pcs Bumper clips. @ 2.00	16.00 inc ✓	✓
	<hr/>	
	1,188.40	\$713.30
	25%	178.32
		<hr/>
		\$552.98
- Labour charge to repair the accident areas.	280.00	\$200
- To spraying rear bumper	280.00	\$200
- To renew sensor wiring	50.00	\$30

13/8/19
 Total: \$ 1,798.40 @ \$982.98
 43 20% = \$ 750.00 *



RAM (LXK)
 886227189

JINGKIA CAR SERVICES

Bik 10, Ang Mo Kio Autopoint, #05-09 Ang Mo Kio Industrial Park 2A Singapore 568047
Tel: 64814055 Fax: 64811066 H/P: 93822000

01/08/19.

Re: Quotation of vehicle no. JKR 3016 K Toyota AHD.

1 pc. Rear bumper assy	\$ 575.50 inc ✓	\$436.
1 pc Rear bumper reinforcement	246.20 inc ✓	
1 pc. Rear bumper Lt retainer	75.00 inc ✓	\$40
1 pc Rear bumper Lt reflector	55.00 inc ✓	
1 set Rear bumper rev. sensor	220.60 inc ✓	✓
2 pcs Bumper clips. @ 8.00	16.00 inc ✓	✓
	<hr/>	
	1,188.40	\$713.31
	25%	178.3
		<hr/>
		\$552.
- Labour charge to repair the accident areas.	280.00	\$200
- To spraying rear bumper	280.00	\$200
- To renew sensor wiring	50.00	\$30
	<hr/>	

RAM (LKIC)
+622-7189

Total: \$ 1,798.40 \$982.9

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	22 Jul 2019 Edit Reg		22 Jul 2019 00:00 Edit Adj Rpt	\$750.00 Edit Estimates	\$750.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	--------------------------

CLAIM SUBFOLDER DETAILS		[Created by adjuster]	
Insured:	-, Co. Reg. No.: -		
Main Claimant:	-		
Vehicle Reg. No.:	SKR3016K	Date of Loss:	16/07/2019 00:00 - :59 [53 Months and 17 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / 1201900020781	Policy/Cover Note No.:	PNMC2018-00005488
Vehicle Reg. No. (Insured):	FS3024R	Policy No. (Claimant):	
		Excess:	
Repairer:	Jingkia Car Services (HQ) BLK 10 AMK INDUSTRIAL PARK 2A, #05-09 AMK AUTO POINT, 568047 Ang Mo Kio - Tel: 93822000		
Handling Insurer:	FWD Singapore Pte. Ltd. (HQ) - Tel: 6727 5700 ... [Handled by Eileen Bay]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by PARASURAM SHANMUGAM] ... [Final Rpt due 31/07/2019]		

ASSOCIATED MAIL RECEIVED	View All	Compose Case Mail
There are no mail for this case.		

ALL ASSOCIATED TASKS		View All	Search Tasks	Create New Task	Complete				
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SKR3016K (1201900020781)**
[FS3024R]

TP

-
Jul 16 2019 12:00AM

[-]

Jingkia Car Services

<input type="button" value="Upload Documents"/> <input type="button" value="Upload Photos"/> <input type="button" value="Compose New Letter"/>			View <input type="button" value="View in Browser"/>	
Assessment Reports			1 per page <input type="button" value=""/>	
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	07/08/19 10:48	Adjuster Immediate Advice	Load HTM	<input type="checkbox"/>
Photos/Images			3 per page <input type="button" value=""/>	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	05/08/19 18:12	General View	Load JPG	<input checked="" type="checkbox"/>
2	05/08/19 18:12	General View	Load JPG	<input checked="" type="checkbox"/>
3	05/08/19 18:12	General View	Load JPG	<input checked="" type="checkbox"/>
4	05/08/19 18:12	General View	Load JPG	<input checked="" type="checkbox"/>
5	05/08/19 18:12	General View	Load JPG	<input checked="" type="checkbox"/>
6	05/08/19 18:12	General View	Load JPG	<input checked="" type="checkbox"/>
7	05/08/19 18:12	General View	Load JPG	<input checked="" type="checkbox"/>
8	05/08/19 18:12	General View	Load JPG	<input checked="" type="checkbox"/>
9	05/08/19 18:12	General View	Load JPG	<input checked="" type="checkbox"/>
10	05/08/19 18:12	General View	Load JPG	<input checked="" type="checkbox"/>
11	05/08/19 18:12	General View	Load JPG	<input checked="" type="checkbox"/>
12	05/08/19 18:12	General View	Load JPG	<input checked="" type="checkbox"/>
13	05/08/19 18:12	General View	Load JPG	<input checked="" type="checkbox"/>
14	05/08/19 18:12	General View	Load JPG	<input checked="" type="checkbox"/>
15	05/08/19 18:12	General View	Load JPG	<input checked="" type="checkbox"/>
16	05/08/19 18:12	General View	Load JPG	<input checked="" type="checkbox"/>
17	05/08/19 18:12	General View	Load JPG	<input checked="" type="checkbox"/>
18	05/08/19 18:12	General View	Load JPG	<input checked="" type="checkbox"/>
19	05/08/19 18:12	General View	Load JPG	<input checked="" type="checkbox"/>
20	05/08/19 18:12	General View	Load JPG	<input checked="" type="checkbox"/>
21	05/08/19 18:12	General View	Load JPG	<input checked="" type="checkbox"/>
22	05/08/19 18:12	General View	Load JPG	<input checked="" type="checkbox"/>
23	05/08/19 18:12	General View	Load JPG	<input checked="" type="checkbox"/>
24	05/08/19 18:12	General View	Load JPG	<input checked="" type="checkbox"/>
25	05/08/19 18:12	General View	Load JPG	<input checked="" type="checkbox"/>
26	05/08/19 18:12	General View	Load JPG	<input checked="" type="checkbox"/>
27	05/08/19 18:12	General View	Load JPG	<input checked="" type="checkbox"/>
28	05/08/19 18:12	General View	Load JPG	<input checked="" type="checkbox"/>
29	05/08/19 18:12	General View	Load JPG	<input checked="" type="checkbox"/>
30	05/08/19 18:12	General View	Load JPG	<input checked="" type="checkbox"/>
31	05/08/19 18:12	General View	Load JPG	<input checked="" type="checkbox"/>
32	05/08/19 18:12	General View	Load JPG	<input checked="" type="checkbox"/>

Assessment Reports			1 per page ▼	☑
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
33	05/08/19 18:12	General View	Load JPG	☑
34	05/08/19 18:12	General View	Load JPG	☑
35	05/08/19 18:12	General View	Load JPG	☑
36	05/08/19 18:13	Photographs of Damaged Parts	Load JPG	☑
37	05/08/19 18:13	Photographs of Damaged Parts	Load JPG	☑
38	05/08/19 18:13	Photographs of Damaged Parts	Load JPG	☑
39	05/08/19 18:13	Photographs of Damaged Parts	Load JPG	☑
40	05/08/19 18:13	Photographs of Damaged Parts	Load JPG	☑
41	05/08/19 18:13	Photographs of Damaged Parts	Load JPG	☑
42	05/08/19 18:13	Photographs of Damaged Parts	Load JPG	☑
43	05/08/19 18:13	Photographs of Damaged Parts	Load JPG	☑
44	05/08/19 18:13	Photographs of Damaged Parts	Load JPG	☑
45	05/08/19 18:13	Photographs of Damaged Parts	Load JPG	☑
46	05/08/19 18:13	Photographs of Damaged Parts	Load JPG	☑
47	05/08/19 18:13	Photographs of Damaged Parts	Load JPG	☑
48	05/08/19 18:13	Photographs of Damaged Parts	Load JPG	☑
49	05/08/19 18:13	Photographs of Damaged Parts	Load JPG	☑
50	05/08/19 18:13	Photo After Spray	Load JPG	☑
51	05/08/19 18:13	Photo After Spray	Load JPG	☑
52	05/08/19 18:13	Photo After Spray	Load JPG	☑
53	05/08/19 18:13	Photo After Spray	Load JPG	☑
54	05/08/19 18:13	Photo After Spray	Load JPG	☑
55	05/08/19 18:13	Photo After Spray	Load JPG	☑
56	05/08/19 18:13	Photo After Spray	Load JPG	☑
57	05/08/19 18:13	Photo After Spray	Load JPG	☑
58	05/08/19 18:13	Photo After Spray	Load JPG	☑
59	05/08/19 18:13	Photo After Spray	Load JPG	☑
Documentation			1 per page ▼	☑
No	Finalized On	FWD Singapore Pte. Ltd. (HQ)	Thumbnail	Print
1	22/08/19 11:14	OI GIA	Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST

Reset Save Print

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/FWD19012890/FQF3S2
Date: 27/08/2019

REFERENCE

Handling Insurer: FWD Singapore Pte. Ltd. Policy No: PNMC2018-00005488
Claimant Vehicle No : SKR3016K **Insured Vehicle No :** FS3024R
 Date of Loss: 16/07/2019 Nature of Claim: TP Claim No: 1201900020781

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SKR3016K**
 Make & Model: TOYOTA COROLLA ALTIS, 1.6 (A) Engine No: 1ZR484039
 Reg. Date: 29/01/2015 (Man. Year: 2015) Chassis No: MR053REH104525378
 Colour: Grey Odometer: 36776 km
 Engine Capacity: 1598 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Good Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/55 R16 Rear Tyre Size: 205/55 R16
 Front Left Side: Michelin 6 mm Rear Left Side: Michelin 5 mm
 Front Right Side: Michelin 6 mm Rear Right Side: Michelin 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,188.40	534.82	653.58	55.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	610.00	430.00	180.00	29.51
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	1,798.40	964.82	833.58	46.35
Approved Total (Overridden) (S\$)		750.00		
Nett Amount (S\$)	1,798.40	750.00	1,048.40	58.30

INSPECTION

Date of Assignment: 22/07/2019
 Date Inspected: 01/08/2019 Inspected At: Jingkia Car Services (HQ)
 BLK 10 AMK INDUSTRIAL PARK 2A, #05-09 AMK
 AUTO POINT
 Singapore 568047
 Estimated Period of Repair: 2.0 days

Adjuster: PARASURAM SHANMUGAM

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

MARKET VALUE: \$55,000.00 - PAPER VALUE: \$46,604.00 = NETT VALUE: \$8,000.00

REPAIR DETAILS**Reference****Part Source:** MRM-SG Version: 1.0 (Last Synchronised: 27 Aug 2019)**Parts:** 143 TOYOTA COROLLA ALTIS 1.6 (A) (Catalogue:Merimen Singapore 1.0)**Labour:** Repairer's (Price-denominated Standard List)**Print Code:** (Unsubmitted, no print-code for SKR3016K)**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk *.**Recommended Parts**

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER ASSY	Cracked	575.50 F	*436.50 FL
2	1		*REAR BUMPER REINFORCEMENT	Not Necessary	246.20 F	*- FL
3	1		*REAR BUMPER LH RETAINER	Necessary	75.10 F	*40.00 FL
4	1		*REAR BUMPER LH REFLECTOR	Not Necessary	55.00 F	*- FL
5	1		*SET REAR BUMPER REVERSE SENSOR	Short Circuit	220.60 F	*220.60 FL
6	2		*BUMPER CLIPS	Necessary	16.00 F	*16.00 FL

F=Franchise part. L=ListItemDisc.

Sub Total (S\$)	1,188.40	713.10
- List Item Discount on L Items 0.00/25.00% (S\$)	0.00	178.28
Total Parts (S\$)	1,188.40	534.82

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	LABOUR CHARGE TO REPAIR THE ACCIDENT AREAS.	New	280.00	200.00
2	TO SPRAYING REAR BUMPER.	New	280.00	200.00
3	TO RENEW SENSOR WIRING.	New	50.00	30.00
			Gross Labour Cost (\$\$)	610.00
				430.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >