Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To:

AIG Asia Pacific Insurance Pte. Ltd.

AIG Building

78 Shenton Way #08-16 Singapore 079120

From:

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park

Singapore 408933

Attn:

Date:

16 Sep 2019

Preliminary Advice

Vehicle No

: SKW634U

Accident Date

: 07/09/2019

Make

: AUDI Q7

Policy No.

: 1900097236

Assignment Date

: 13/09/2019

Excess

:S\$

: \$\$0.00

Date of Inspection

: 12/09/2019

Est. Duration of Repair

: 5.00

Inspection At

: PREMIUM AUTOMOBILES PTE LTD (UBI)

55 UBI ROAD 1

SINGAPORE 408699

Point of Impact / General Description of Damages

The vehicle sustained impact / damages FRONT O/S portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	37,123.00
Revised Amount	:S\$	18,129.00°
Check Items (Estimated)	:S\$	6,137.00
Total	:S\$	24,266.00

Lump Sum Repair

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	180,000.00
COE / PARF Rebate	:S\$	90,627.00
Salvage Value	:\$\$	
Margin for Repair	:S\$	89.373.00

Remarks

(Х)	The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
()	The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
(3)	Other comments :