



BAN HOCK HIN
Co., Pte Ltd

Co.Reg.No: 197000288K

MOTORCYCLE ACCESSORIES | SERVICE CENTRE
MODIFICATIONS | SPRAY PAINTING AND BODY WORK | METAL
WORKS | LEASING & RENTALS | FLEET SALES | INSURANCE SALES

QUOTATION

Customer :

INDIA INTERNATIONAL INSURANCE P.L.
64 CECIL STREET
#04-00 & #06-00
IOB BUILDING
SINGAPORE 049711
INDIA INTERNATIONAL INSURANCE P.L.

NO. : 34804

DATE : 02/09/2019
CLAIM NO. : 11424
POLICY NO. : AVFMSB0000591904
FROM : RAYMOND

VEHICLE NO. : FBM3973E
MAKE/MODEL : YAM / YBR125

*not added
clear
2/58
13/9/19
Sdr.
take the order up.*

(Page 1 of 3)

S/N	Description	Action	Qty	Unit Price	Amount
1	ALIGNMENT BODY P/N: 29561	REPLACE	1.00	\$350.00	350.00 ?
2	AXLE WHEEL FRONT P/N: 25363	REPLACE	1.00	\$22.00	22.00 X
3	BAR HANDLE P/N: 42062	REPLACE	1.00	\$68.00	68.00
4	BRACKET UNDER FORK P/N: 27458	REPLACE	1.00	\$180.00	180.00
5	CAP RESERVOIR P/N: 45629	REPLACE	1.00	\$7.00	7.00 ?
6	COCK FUEL P/N: 24361	REPLACE	1.00	\$16.00	16.00 X
7	COVER MAGNETO P/N: 28564	REPLACE	1.00	\$120.00	120.00 ?
8	COVER SIDE LH (BLACK) P/N: 50007	REPLACE	1.00	\$98.00	98.00
9	COVER TAIL RH (BLACK) P/N: 50004	REPLACE	1.00	\$87.00	87.00
10	COVER TANK SIDE LH (BLACK) P/N: 54458	REPLACE	1.00	\$98.00	98.00
11	COWLING FRONT (BLACK) P/N: 50000	REPLACE	1.00	\$282.00	282.00
12	CRASH BAR P/N: 35878	REPLACE	1.00	\$195.00	195.00
13	CROWN HANDLE P/N: 28100	REPLACE	1.00	\$75.00	75.00



bizSAFE₃



CERT NO: 2002-1-0363
ISO 9001:2015

S/N	Description	Action	Qty	Unit Price	Amount
14	FORK FRONT ASSY LH P/N: 56248	REPLACE	1.00	\$625.00	625.00 <i>Self</i>
15	FORK FRONT ASSY RH P/N: 53204	REPLACE	1.00	\$625.00	625.00 <i>Self</i>
16	GASKET EXHAUST PIPE P/N: 21453	REPLACE	1.00	\$5.00	5.00 <i>17</i> X
17	GASKET MAGNETO COVER P/N: 26824	REPLACE	1.00	\$12.00	12.00 <i>11</i> X
18	GRIP HANDLE SET (GPR) F2 P/N: 45347	REPLACE	1.00	\$13.00	13.00 <i>7.11</i>
19	GUIDE AIR LH P/N: 48403	REPLACE	1.00	\$22.00	22.00 <i>one</i>
20	HANDLE SEAT P/N: 42567	REPLACE	1.00	\$98.00	98.00 <i>500</i> X
21	HEADLIGHT ASSY P/N: 50950	REPLACE	1.00	\$490.00	490.00 <i>500</i>
22	LABOUR P/N: 06766 - FOR DISMANTLING AND ASSEMBLING OF PARTS QUOTED.	Supply/Install	16.00	\$35.00	560.00 <i>300</i>
23	LAMP SIGNAL FRONT RH P/N: 42003	REPLACE	1.00	\$54.00	54.00 <i>800</i> X
24	LAMP SIGNAL REAR RH P/N: 45419	REPLACE	1.00	\$63.00	63.00 <i>272</i>
25	LEVER BRAKE P/N: 50001	REPLACE	1.00	\$23.00	23.00 <i>500</i>
26	METER ASSY P/N: 50954	REPLACE	1.00	\$328.00	328.00 <i>11</i> X
27	MIRROR RH P/N: 58187	REPLACE	1.00	\$35.00	35.00 <i>510</i>
28	MUDGUARD FRONT (BLACK) P/N: 45203	REPLACE	1.00	\$85.00	85.00 <i>wyrd</i>
29	O-RING P/N: 21455	REPLACE	1.00	\$3.00	3.00 <i>.</i> ?
30	O-RING (CAP MAGNETO COVER) P/N: 21456	REPLACE	1.00	\$8.00	8.00 ?
31	PEDAL GEAR P/N: 50002	REPLACE	1.00	\$20.00	20.00 <i>Self</i>
32	PIPE EXHAUST ASSY P/N: 50025	REPLACE	1.00	\$1,655.00	1,655.00 <i>12</i> X
33	RUBBER FOOTREST FRONT P/N: 26136	REPLACE	1.00	\$14.00	14.00 <i>7061</i>
34	STAY HEADLAMP P/N: 45750	REPLACE	1.00	\$68.00	68.00 <i>Self</i>



bizSAFE₃



CERT NO : 2002-1-0363
ISO 9001:2015

S/N	Description	Action	Qty	Unit Price	Amount
35	STEERING CONE SET P/N: 41793	REPLACE	1.00	\$66.00	66.00
36	STICKER (MCDONALDS) ACCIDENTAL P/N: 57420	REPLACE	1.00	\$14.00	14.00
37	STICKER (MCDONALDS) SIDECOVER/WINDSHEILD P/N: 56222	REPLACE	1.00	\$18.00	18.00
38	STICKER NUMBER PLATE FRONT (BLACK) STRAIGHT P/N: 32921	REPLACE	1.00	\$12.00	12.00
39	TANK FUEL ASSY (BLACK) P/N: 56129	REPLACE	1.00	\$550.00	550.00
40	TRANSPORT CHARGES (MOTORCYCLE/SCOOTER) STD P/N: 45833 - FOR COLLECTION OF ACCIDENT BIKE AND DELIVER BIKE BACK TO OUTLET ONCE REPAIR DONE.		2.00	\$56.00	112.00

SUB TOTAL

\$7,176.00

GST @ 7 %

\$502.32

GRAND TOTAL

\$7,678.32

50% deposit required before ordering of parts.

Validity: 30 days

For & on Behalf of

Acknowledge & Accepted By

BAN HOCK HIN CO PTE LTD



RAYMOND

This quotation is sent via email / LAN-Fax and will bear a computer generated signature.

Let Auto Consultants hence notify the Reparer of the following:

- * To be done before spray painting
- * To be done on damaged part(s) during resurvey
- * All work must be subject to confirmation
- * Third party survey is on a "Without Prejudice" basis
- * Resurvey confirmation is allowed
- * Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

bizSAFE₃CERT NO: 2002-1-0383
ISO 9001: 2015

Address: No. 6, Defu lane 4, Singapore 539410 | Telephone: +65 6281 6520 | Web: www.bhh.com.sg

Fax: (Main) +65 6281 2830, (Spare Parts) +65 6285 7530, (Insurance/Project) +65 6284 2969, (Accounts) +65 6281 6759