

BH AUTO SERVICES PTE LTD

Blk 1, Sector C, Sin Ming Industrial Estate #01-111 / 113 / 115 / 117 Singapore 575636

Tel: 6559 8944 / Fax: 6269 2404

India International Insurance Pte Ltd

64 Cecil Street

#04-05 IOB Building

Singapore 049711

ATTN: MOTOR CLAIM DEPARTMENT

Tel : 63476100 Fax : 62244174

DEAR SIR / MADAM :

Not Authorized
11 Days @ 7
Resony After Paint
4-5 days

ACCIDENT REPAIR ON: SKX252H

MODEL : TOYOTA WISH 1.8A

POLICY NO : MPC19A00111900

CHASSIS NO : ZNE100311955

YEAR OF MANUFACTURE : 2006

DATE / TIME OF ACCIDENT: 08/09/2019 Time: 1225Hrs at ALONG YISHUN AVE 11 &

THIRD PARTY VEHICLE NO: SH7102B

Date: 13/09/2019

Page : 1 of 2

YISHUN RING ROAD.

Appended below are the estimated cost of repair and parts to be replaced for the above vehicle: -

Replacement Of Parts

S/N	Quantity	Unit Price	Condition	Amount
		S\$		S\$
1 Tailgate	1	1,492.30	Dented	1,492.30 ✓
2 Tailgate weatherstrip	1	352.30	Torn	352.30 X
3 Tailgate stopper LH	1	15.60	Necessary	15.60 X
4 Tailgate stopper RH	1	15.60	Necessary	15.60 X
5 Tailgate hinge LH	1	88.75	Bented	88.75 ✓
6 Tailgate hinge RH	1	88.75	Bented	88.75 ✓
7 Tailgate lock assy	1	470.40	Cracked	470.40 X
8 Tailgate lock striker	1	45.17	Bented	45.17 X
9 Tailgate handle chrome moulding	1	291.45	To Check	291.45 X
10 Rear windscreen moulding set	1	70.20	Necessary	70.20 ✓
11 Rear wiper motor	1	699.60	Malfunction	699.60 X
12 Rear tail lamp assy RH	1	574.90	Cracked	574.90 ?
13 Rear tail lamp clip	2	4.22	Necessary	8.44 ?
14 Rear bumper	1	525.30	Torn	525.30 ✓
15 Rear bumper side retainer LH	1	67.80	Necessary	67.80 X
16 Rear bumper side retainer RH	1	67.80	Necessary	67.80 ✓
17 Rear bumper clip	12	3.89	Necessary	46.68 ✓
18 Rear bumper reflector RH	1	59.70	Cracked	59.70 ✓
19 Rear end panel	1	522.60	Dented	522.60 ?
20 Rear end panel top garnish	1	295.40	Kinked	295.40 X
21 Rear exhaust silencer assy	1	780.15	Bented	780.15 X
22 Rear exhaust silencer mounting	2	45.80	Necessary	91.60 X

Sub-Total: 6,670.49

Less: 25% discount - 1,667.62

Total Parts after 25% discount: 5,002.87

Special Nett Items

1 Anti-rust coating	2	80.00	na	160.00 301
2 Windscreen sealant	1	100.00	na	100.00 405n
3 Rear bumper sensor set	1	250.00	mis	250.00 2005n
				510.00

Total Parts: 5,512.87

Labour Charges For Rear RH Portion

1	Provide skill labour to remove all damaged parts, panel beat , cut & weld if necessary and align all panel and reinstall all damaged parts.	1,250.00	7
2	Provide skill labour & material to putty all damaged parts & panel & to respray with 2K paint with oven spray booth facilities	1,250.00	600
3	Provide skill labour to disconnect and check electrical wiring	60.00	201
4	Remove and reinstall cushions, seats, backrest, inner trim, garnish, roof lining and or upholstery to facilitate repairs	150.00	7
5	Dismantle and transfer tailgate fittings and mechanism to new/facilitate repair	100.00	601
6	Provide skill labour to remove and refit rear windscreen	200.00	1201
7	Provide skill labour to remove and replace bumper sensors	60.00	501
8	Provide skill labour to remove and replace exhaust pipe/system to facilitate repair	nn 120.00	x
9	Provide skill labour to mount vehicle onto chassis alignment bench	nn 250.00	x

Total Labour:

3,440.00

Total Parts & Labour:

8,952.87

GST 7%

626.70

Grand Total:

9,579.57

Estimate Repair Duration

10 days

ACCIDENT VEHICLE OF : SKX252H

Page : 2 of 2

4-5 days

Remark: Supplementary estimate will be raised in the event additional damaged parts are found in the course of repair.

Yours sincerely,

ESTIMATOR: WEN ZHENG

Survey attended by:

Name : Kenneth
Company : LKK
Date : 16/9/19
Time : 11.45am
Contact No : 96910663
Email : _____

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: