

15/02/10

INS. CASE OWNER:

CC 4/1111901 6234, EP 63%

LKK:
IDAC:

Surveyor:

STBW

ASSIGNMENT
DOI: 17/1/19

Date / Time: 12/1/19

Registered in Meritrix: 12/1/19

Pre-assign / CCU / FTE



Insured Vehicle No. : SHA 6575T

Claim No. :

Name of Insured : CTP

Policy No. : MLOMPOW

Insured Tel No. : HP:

Make / Model : HONDA

Excess Sec II : SS D.O.A. : 11/1/19

Place of Accident : MEONG WEST HWY

Is driver the owner? (YES / NO) Nature of Accident :

If NO, Driver Name / Age : KOH SENG TENG

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Driver Tel No. : (V/L: YES / NO)

Insured Liability : % Final ? Yes / No

SLX 74040



INSRS: CMZ
WSP: WMTD
Tel :
Liability :
RMKS :



INSRS:
WSP:
Tel :
Liability :
RMKS :



INSRS:
WSP:
Tel :
Liability :
RMKS :



INSRS:
WSP:
Tel :
Liability :
RMKS :

Date/ Time	STAGE	DATE/ PIC
17/1/19	File -> type mandate	
17/1/19	File -> Sumatra to send BV.	
	* TP had sent original docs to III directly.	
	Documentation Check List:	Handler Typist
	Notification ltr (if non-pickup)	<input type="checkbox"/>
	After call ltr to OI	<input checked="" type="checkbox"/>
	Authorisation To Act:	<input checked="" type="checkbox"/>
	Release Voucher:	<input checked="" type="checkbox"/>
	Final Repair Bill:	<input checked="" type="checkbox"/>
	Car Rental Invoice:	<input checked="" type="checkbox"/>
	Towing Invoice	<input checked="" type="checkbox"/>
	LTA / GIA :	<input checked="" type="checkbox"/>
	Medical Bill:	<input type="checkbox"/>
	PIR:	<input type="checkbox"/>
	Mandate/Reject Instruction:	<input checked="" type="checkbox"/>
	LOD	<input type="checkbox"/>
	Payment Breakdown Form:	<input type="checkbox"/>
	Post-Repair Photos:	<input type="checkbox"/>
	Others:	<input type="checkbox"/>
PRELIMINARY ADVICE Date/Time:	Sent By:	
FINALIZATION Date/Time:	Confirm with:	Confirm by:
Repair Cost: S\$	(days) Reduction: %	Email <input type="checkbox"/> Call <input type="checkbox"/>
FINAL SETTLEMENT Date/Time:	Confirm with: Jerdin	Email <input checked="" type="checkbox"/> Call <input type="checkbox"/>
Final Liability: %	(Agreed / Assessed) BOLA S/N No. : 5.	If NO or 28, Ask Lia
Repair Cost: w/hm S\$ 30774.00		<div style="border: 2px solid black; padding: 5px; display: inline-block;"> COPY SENT 4/11/19 </div>
Loss of Rental (LOR): S\$ 1600.00 (16 days) x \$100		
Loss of Use (LOU): S\$ - (5 x days)		
Loss of Income (LOI): S\$ - (5 x days)		
LOR only <input checked="" type="checkbox"/> LOU only <input type="checkbox"/> LOR + LOU <input type="checkbox"/> LOR + LO <input type="checkbox"/> (Tick only one)		
GIA/LTA Search S\$ 2.45		
Medical: S\$ -		1) Claim status: Normal/Reject/Private Settle
Disbursement: S\$ -	(e.g. Tow/ Independent)	2) Report Format: <input checked="" type="checkbox"/>
Legal Cost S\$ -		3) Survey fee: \$600.00
Total: S\$ 31701.45	Global Sum S\$: 31700.00	
FINAL PAYMENT Date/Time:	Confirm with:	Email <input checked="" type="checkbox"/> Call <input type="checkbox"/>
Payee 1: S\$ 31700.00	Name 1: Carz Auto Services Pte Ltd	
Payee 2: (Strike if N.A.) S\$	Name 2:	
Payee 3: (Strike if N.A.) S\$	Name 3:	

ASS. REC. BY:

Steve

REP:

TJ

ASSIGNMENT

From:

Date

13.9.2019

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

SLX 7404D

at Workshop n/s

Car 2 Auto

of

61 Woodland Industrial Park E9

Insured:

Policy No

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

		X	X
N/S	O/S		

Val. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

14.

days

Res.: Yes or No

Lum Sum:

20

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

mp

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No

SLX 7404D

yr Regn: 09/Apr/2018

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Toyota C-HR Hybrid

cc 1797

Colour

Silver.

A/C: Insured / Std / NI / NA

Sp Reading

N/A

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

ZYX102103121

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modl: Nil / S/Rim / STD A/Rim or

Tyre Size:

F: 215 / 60 R17

R: 215 / 60 R17

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

5

mm

R/Bal.

5

mm

L/Bal.

5

mm

L/Bal.

5

mm

D.O.A

11/04/2019

D.O.I

13/9/2019

Survey held at

Car 2 Auto.

Des. of Damages Frt / Rear / O/S / N/S / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

MV = 90,000

PV = 19,842

NV = 70,158.

U S # 2020 (Red) \$ 21777.01 / 43%

Date/Time, File Pass to?

: Preli. Report

Days Of Repair:

1)

: Final Report

Resurvey No. of Trip:

Survey Fee:

Date/Time, File Return to?

Transportation:

2)

Add Fee:

: Site Insp (\$

\$ + RS, \$

: Interview (\$

Phone

: Tech. Invs (\$

Other

: West end (\$

Form Format:

Lump Sum / Bill of

TOTAL



CARZ AUTO SERVICES PTE LTD

UEN/ GST 201409457D

61 WOODLANDS IND PARK E9 (E9 PREMIUM) #04-04 Singapore 757047

Email: alex@carzauto.com.sg

Tel: 65 6493 1924

Fax: 65 6493 1928

Insurance Company: INDIA INTERNATIONAL INSURANCE SINGAPORE
 Address: 64 Cecil Street #04, #05 IOB Building Singapore 049711
 Telephone: 6347 6100 Fax: 6224 4174 Email:

Make/ Model : TOYOTA CHR Date: 12/9/2019
 Chassis No : ZYX10-2103121 Vehicle No: SLX 7404 D
 Date/Time of Accident : 11/9/2019 18:50

Stork
 Resung 17/9/19

Materials Cost/ Spare Parts Cost

TO BE COMPLETED BY SERVICE ADVISOR

ITEMS	PARTS DESCRIPTION	QTY	LIST PRICE \$	PARTS DISCOUNT	FINAL PRICE \$
1	BONNET ✓ DD	1	\$ 1,321.80	25%	\$ 991.35
2	BONNET LOCK ✓ BT	1	\$ 115.25	25%	\$ 86.44
3	BONNET LOCK BRACE PANEL ? ✓ BT	1	\$ 185.35	25%	\$ 139.01
4	BONNET HINGE ✓ BT	2	\$ 129.10	25%	\$ 96.83
5	BONNET INSULATOR ✓ CR4	1	\$ 281.15	25%	\$ 210.86
6	BONNET STAND x NN	1	\$ 195.15	25%	\$ 146.36
7	BONNET STAND BRACKET x ✓ BT	1	\$ 58.55	25%	\$ 43.91
8	FRONT NUMBER PLATE GARNISH x ✓ (Retain net (tan))	1	\$ 155.65	25%	\$ 116.74
9	FRONT BUMPER ✓ DD	1	\$ 584.25	25%	\$ 438.19
10	FRONT BUMPER LOWER ✓ CR4	1	\$ 505.15	25%	\$ 378.86
11	FRONT BUMPER CENTER GRILLE ✓ CR4	1	\$ 183.65	25%	\$ 137.74
12	FRONT BUMPER SIDE RETAINER ✓ B.br.	2	\$ 230.36	25%	\$ 172.77
13	FRONT BUMPER SIDE AIR SCOOP (RH) ✓ RR	2	\$ 85.70 / 171.40	25%	\$ 128.63
14	FRONT BUMPER TOW COVER ✓ BT	1	\$ 28.90	25%	\$ 21.68
15	FRONT BUMPER TOP BEAM ? ✓ BT	1	\$ 145.75	25%	\$ 109.31
16	FRONT BUMPER REINFORCEMENT ✓ DD	1	\$ 296.85	25%	\$ 222.64
17	FRONT BUMPER REINFORCEMENT SPONGE ✓ BR	1	\$ 109.25	25%	\$ 81.94
18	FRONT BUMPER REINFORCEMENT BRACKET ✓ BT	2	\$ 402.10	25%	\$ 301.58
19	FRONT BUMPER LOWER BEAM ? ✓ DD	1	\$ 465.35	25%	\$ 349.01
20	FRONT BUMPER LOWER BEAM SPONGE ✓ BR	1	\$ 98.15	25%	\$ 73.61
21	FRONT BUMPER LOWER BEAM BRACKET ? ✓ DD	2	\$ 176.90	25%	\$ 132.68
22	FRONT BUMPER UNDER COVER ? ✓ RR	2	\$ 171.36 / 342.72	25%	\$ 266.07
23	FRONT BUMPER FOG LAMP COVER ✓ BR	1	\$ 270.92	25%	\$ 203.19
24	FRONT NBUMPER SIDE LOWER RETAINER x NN	2	\$ 113.66	25%	\$ 85.25
25	FRONT RADIATOR GRILLE ✓ CR4	1	\$ 434.21	25%	\$ 325.66
26	FRONT RADIATOR GRILLE LOGO ✓ NEC	1	\$ 283.63	25%	\$ 212.72
27	FRONT RADIATOR GRILLE INNER BASE ? x NN	1	\$ 183.72	25%	\$ 137.79
28	FRONT IMPACT SENSOR ? x NN	1	\$ 1,195.67	25%	\$ 896.75
29	FRONT IMPACT SENSOR WIRE HARNESS ✓ CR4 / TA	1	\$ 1,455.83	25%	\$ 1,091.87
30	FRONT HEAD LAMP ✓ CR4 (R) (L) ? ✓ RR	2	\$ 3,293.06	25%	\$ 6,594.80
31	FRONT HEAD LAMP BLUB (HID) RH ✓ Br 1pc	1	\$ 355.71	25%	\$ 266.78

17 496.38

32	FRONT HEAD LAMP HID MODULE RH	✓ Br	1	\$ 581.45	25%	\$ 436.09
33	FRONT HEAD LAMP LOWER PANEL RH	✓ BT	1	\$ 110.15	25%	\$ 82.61
34	FRONT SUPPORT PANEL TOP CENTER	? / DD	1	\$ 232.33	25%	\$ 174.25
35	FRONT SUPPORT PANEL TOP GARNISH	✓ CR4	1	\$ 195.89	25%	\$ 146.92
36	FRONT SUPPORT PANEL STAND	? (CR4) DD	21	\$ 285.71	25%	\$ 428.57
37	FRONT SUPPORT PANEL BOTTOM	? / TWB	1	\$ 288.63	25%	\$ 216.47
38	FRONT SUPPORT PANEL BOTTOM GARNISH	? / CR4	1	\$ 135.18	25%	\$ 101.39
39	FRONT A/C CONDENSER	✓ BT	1	\$ 1245.9	25%	\$ 977.78
40	FRONT A/C CONDENSER LIQUID PIPE WITH LOCK	✓ BT	1	\$ 565	25%	\$ 530.41
41	FRONT A/C CONDENSER SIDE GARNISH	✓ CR4	21	\$ 98.35	25%	\$ 147.53
42	FRONT A/C FAN BLADE	? X NN	1	\$ 158.11	X 25%	\$ 118.58
43	FRONT RADIATOR	? / TWB	1	\$ 1716.8	25%	\$ 1,380.86
44	FRONT RADIATOR COWLING	? X NN	1	\$ 291.38	X 25%	\$ 218.54
45	FRONT RADIATOR FAN BLADE	? X NN	1	\$ 233.45	X 25%	\$ 175.09
46	FRONT RADIATOR FAN MOTOR	? X NN	1	\$ 585.60	X 25%	\$ 439.20
47	FRONT RADIATOR RESERVOIR TANK	? / DR	1	\$ 177	25%	\$ 144.34
48	FRONT RADIATOR TOP HOSE	X NN	1	\$ 45.15	X 25%	\$ 33.86
49	FRONT RADIATOR TOP EXTANSION HOSE	X NN	1	\$ 69.70	X 25%	\$ 52.28
50	FRONT WASHER TANK	✓ CR4	1	\$ 165	25%	\$ 148.84
51	FRONT WASHER TANK MOTOR	? X NN	1	\$ 185.85	X 25%	\$ 139.39
52	FRONT WASHER TANK PANEL SIDE RH	? / DD	1	\$ 255.78	25%	\$ 191.84
53	FRONT FENDER RH	✓ CR4	1	\$ 691	25%	\$ 619.58
54	FRONT FENDER SPLASHIELD RH	✓ CR4	1	\$ 189.25	25%	\$ 141.94
55	FRONT FENDER INNER PANEL RH	? / DD	1	\$ 545.8	25%	\$ 511.37
56	FRONT FENDER WHEEL ARCH GARNISH RH	✓ Br.	1	\$ 155.75	25%	\$ 116.81
57	FRONT FENDER EMBLEM HYBRID RH	✓ Nec	1	\$ 68.15	25%	\$ 51.11
58	FRONT FENDER SPLASHIELD SPOILER RH	? X NN	1	\$ 58.35	X 25%	\$ 43.76
59	FRONT AIR BAG IMPACT SENSOR	✓ Nec	2	\$ 384.86	25%	\$ 288.65
60	FRONT DOOR RH	X R ✓ DD	1	\$ 1256	25%	\$ 1,012.69
61	FRONT DOOR PROTECTOR RH	X ✓ DD	1	\$ 281.85	25%	\$ 211.39
62	FRONT WIPER GARNISH	? X NN	1	\$ 635.45	X 25%	\$ 476.59
63	FRONT WIPER GARNISH SIDE RH	? / CR4	1	\$ 88.05	25%	\$ 66.04
64	FRONT WINDSCREEN GLASS WITH SENSOR	✓ Br.	1	\$ 1821	25%	\$ 2,033.74
65	FRONT WINDSCREEN GLASS MOULDING	✓ Nec	2	\$ 220.80	25%	\$ 165.60
66	FRONT WINDSCREEN INNER SEAL	✓ Nec	1	\$ 65.30	25%	\$ 48.98
67	FRONT WHEEL SHOCK ABSORBER RH	? / DD	1	\$ 441.85	25%	\$ 331.39
68	FRONT WHEEL KNUCKLE ARM RH	? / DD	1	\$ 479.15	25%	\$ 359.36
69	FRONT WHEEL KNUCKLE BEARING WITH HUB RH	? / R	1	\$ 574	25%	\$ 311.51
70	FRONT WHEEL LOWER ARM RH	? / BT	1	\$ 471.35	25%	\$ 353.51
71	FRONT WHEEL LOWER ARM LINK RH	? X NN	1	\$ 196.20	X 25%	\$ 147.15
72	FRONT ENGINE MOUNTING TOP RH	X NN	1	\$ 198.10	X 25%	\$ 148.58
73	FRONT DASHBOARD	✓ Br.	1	\$ 1211	25%	\$ 1,463.48
74	FRONT DASHBOARD AIR BAG	✓ Br.	1	\$ 821	25%	\$ 2,340.53
75	FRONT STREEING AIR BAG	✓ Br.	1	\$ 771	25%	\$ 2,112.98
76	FRONT STREEING AIR BAG CONTACT PIECE	✓ Nec	1	\$ 770	25%	\$ 771.34
77	FRONT AIR BAG CONTROL MODULE	✓ Nec.	1	\$ 970	25%	\$ 910.24
78	FRONT SAFETY BELT	✓ Jame	2	\$ 550.25	25%	\$ 412.69
79	FRONT ROOF-TOP LINING	✓ CR4	1	\$ 1680	25%	\$ 1,581.53
80	FRONT ROOF-TOP AIR BAG	✓ Br.	2	\$ 870	25%	\$ 2,329.28
81	REAR SAFETY BELT	✓ Im	2	\$ 640	25%	\$ 1,180.95

40,829.46
- 25%
30,622.08

SPECIAL ITEMS	PARTS DESCRIPTION	QTY	PRICE \$	FINAL PRICE \$	
1	BONNET INSULATOR CLIP ✓ NEC	8	\$ 44.00	\$ 44.00 15	
2	FRONT NUMBER PLATE with ✓ Gurnish ✓ Nec	1	\$ 50.00	\$ 50.00 40	
3	FRONT BUMPER CLIP ✓ NEC	8	\$ 44.00	\$ 44.00 30	
4	FRONT SUPPORT PANEL TOP GARNISH CLIP ✓ NEC	5	\$ 27.50	\$ 27.50 10	
5	FRONT FENDER SPLASHIELD CLIP RH ✓ ? / B.C. NEC	8	\$ 44.00	\$ 44.00 20	
6	FRONT FENDER WHEEL ARCH GARNISH CLIP RH ✓ NEC	8	\$ 44.00	\$ 44.00 20	
7	FRONT WINDSCREEN SEALANT ✓ NEC	1	\$ 50.00	\$ 50.00 40	
8	FRONT ERP BRACKET ✓ NEC	1	\$ 25.00	\$ 25.00 20	
9	FRONT WHEEL TYRE RH ✓ B.C.	1	\$ 250.00	\$ 250.00 200	
10	FRONT WHEEL TYRE RIM RH ✓ SCH	1	\$ 700.00	\$ 700.00 600	
Total Cost				\$ 42,567.01	895

Labour Works/ Panel Beating Related Works	
Job Scope	Quotation
TO RENEW FRONT DAMAGED PARTS, REPLACED AND REALIGNED HYDRAULIC, ALIGNED ALL PARTS	\$ 1,800.00 1200
Spray Painting	
Job Scope	Quotation
TO RESPRAY AFFECTED AREAS	\$ 1,600.00 1100
Others Cost (Accident Repair Related Expenses)	
Job Scope	Quotation
TOWING	\$ 50.00 ✓
TO TUFFCOAT AFFECTED AREA	\$ 250.00 200
TO REPLACE FRONT WINDSCREEN	\$ 120.00 ✓
TO REPLACE ENGINE MOUNTING/ GEAR BOX MOUNTING	\$ 250.00 3 X
TO REMOVE/ REPLACE AIRCON CONDENSOR, VACUUM, TOP UP AIRCON GAS	\$ 120.00 ✓
TO REMOVE/ REFIX/ REPLACE DASHBOARD	\$ 350.00 150
TO REMOVE/ REFIX INTERIOR UPHOLSTERY	\$ 100.00 50
TO REMOVE/ REPLACE FRONT UNDERCARRIAGE	\$ 350.00 150
TO REMOVE/ REFIX WIRING CHECKS	\$ 60.00 30
TO REMOVE/ REPLACE DOOR MECHANISM	\$ 100.00 50
TO REPROGRAM ALL RELATED HYBRID SYSTEM	\$ 250.00 300
TO REMOVE AND REPLACE AIRBAG	\$ 450.00 200
TO RESET ALL AIRBAG NECESSARY SYSTEM	\$ 480.00 100
TO COMPUTERISED FOUR WHEEL ALIGNMENT	\$ 80.00 60
TO REMOVE AND REPLACE ROOF-TOP LINING	\$ 200.00 X
Total Others Cost	\$ 3,310.00
GRAND TOTAL	\$ 49,277.01

Sun Pm / Steve
 Thirty Party
 without Prejudice
 Repair day - 14 days
 Lum sum

DOI - 17/04/2014 @ 12.30 pm
 P- 30,622.98
 N- 895
 L- 3710
 35,227.08
 L/S- 28,181.66
 = 28,200.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	190E
Vehicle Details	
Vehicle No.:	SLX7404D
Vehicle to be Exported:	No
Intended Deregistration Date:	13 Sep 2019
Vehicle Make:	TOYOTA
Vehicle Model:	C-HR HYBRID 1.85 CVT
Primary Colour:	Silver
Manufacturing Year:	2018
Engine No.:	2ZR8361746
Chassis No.:	ZYX102103121
Maximum Power Output:	90.0 kW (120 bhp)
Open Market Value:	\$27,586.00
Original Registration Date:	09 Apr 2018
First Registration Date:	09 Apr 2018
Transfer Count:	0
Actual ARF Paid:	\$10,621.00 ✓
Intended PARF Rebate Details	
PARF Eligibility:	Yes ✓
PARF Eligibility Expiry Date:	08 Apr 2028
PARF Rebate Amount:	\$7,965.00
Intended COE Rebate Details	
COE Expiry Date:	08 Apr 2028
COE Category:	E - Open - all except motorcycle
COE Period(Years):	10
QP Paid:	\$38,000.00
COE Rebate Amount:	\$31,719.00
Total Rebate Amount:	\$39,684.00

The information contained herein is correct as at 13 Sep 2019

OK

$$MV = 90,000$$

$$PV = 19,842$$

$$NV = 75,468.5$$

Steve Chen (LKK Auto)

From: jeslyn@carzauto.com.sg
Sent: Tuesday, October 01, 2019 10:42 AM
To: Steve Chen (LKK Auto)
Cc: 'alex'
Subject: RE: SLX 7404 D Finalize

Hi Mr Steve

Good Morning

We accept the amount as \$28,200.00 (L/S, before GST) and 14 repair days.
Please advise us the document need to mail out to who.

Thank You.

With Regards,
Jeslyn Chua
HP: 8322 7418

-----Original Message-----

From: alex@carzauto.com.sg [mailto:alex@carzauto.com.sg]
Sent: Tuesday, 1 October 2019 10:33 AM
To: 'jeslyn' <jeslyn@carzauto.com.sg>
Subject: FW: SLX 7404 D Finalize

hi

-----Original Message-----

From: Steve Chen (LKK Auto) <SteveChen@lkkauto.com>
Sent: Tuesday, October 1, 2019 9:28 AM
To: alex@carzauto.com.sg
Subject: SLX 7404 D Finalize

Dear Alex,

Kindly refer our finalize \$28,200.00 (L/S, before GST). 14 repair days.

Kindly confirm.

Thanks

Best Regards,



CARZ AUTO SERVICES PTE LTD

UEN/ GST 201409457D

61 WOODLANDS IND PARK E9 (E9 PREMIUM) #04-04 Singapore 757047

Email: alex@carzauto.com.sg

Tel: 65 6493 1924

Fax: 65 6493 1928

Insurance Company:	INDIA INTERNATIONAL INSURANCE SINGAPORE		
Address:	64 Cecil Street #04, #05 IOB Building Singapore 049711		
Telephone:	6347 6100	Fax:	6224 4174
		Email:	
Make/ Model :	TOYOTA CHR	Date:	12/9/2019
Chassis No :	ZYX10-2103121	Vehicle No:	SLX 7404 D
Date/Time of Accident :	11/9/2019 18:50		

Materials Cost/ Spare Parts Cost

TO BE COMPLETED BY SERVICE ADVISOR

ITEMS	PARTS DESCRIPTION	QTY	LIST PRICE \$	PARTS DISCOUNT	FINAL PRICE \$
1	BONNET ✓ DD	1	\$ 1,321.80	25%	\$ 991.35
2	BONNET LOCK ✓ BT	1	\$ 115.25	25%	\$ 86.44
3	BONNET LOCK BRACE PANEL ?	1	\$ 185.35	25%	\$ 139.01
4	BONNET HINGE ✓ BT	2	\$ 129.10	25%	\$ 96.83
5	BONNET INSULATOR ✓ CR4	1	\$ 281.15	25%	\$ 210.86
6	BONNET STAND *	1	\$ 195.15	25%	\$ 146.36
7	BONNET STAND BRACKET x	1	\$ 58.55	25%	\$ 43.91
8	FRONT NUMBER PLATE GARNISH x x (Refer part list)	1	\$ 155.65	25%	\$ 116.74
9	FRONT BUMPER ✓ DD	1	\$ 584.25	25%	\$ 438.19
10	FRONT BUMPER LOWER ✓ cut	1	\$ 505.15	25%	\$ 378.86
11	FRONT BUMPER CENTER GRILLE ✓ cut hr	1	\$ 183.65	25%	\$ 137.74
12	FRONT BUMPER SIDE RETAINER ✓ B.br.	2	\$ 230.36	25%	\$ 172.77
13	FRONT BUMPER SIDE AIR SCOOP	2	\$ 171.50	25%	\$ 128.63
14	FRONT BUMPER TOW COVER ✓ BT	1	\$ 28.90	25%	\$ 21.68
15	FRONT BUMPER TOP BEAM ?	1	\$ 145.75	25%	\$ 109.31
16	FRONT BUMPER REINFORCEMENT ✓ DP	1	\$ 296.85	25%	\$ 222.64
17	FRONT BUMPER REINFORCEMENT SPONGE ✓ BR	1	\$ 109.25	25%	\$ 81.94
18	FRONT BUMPER REINFORCEMENT BRACKET ✓ BT	2	\$ 402.10	25%	\$ 301.58
19	FRONT BUMPER LOWER BEAM ?	1	\$ 465.35	25%	\$ 349.01
20	FRONT BUMPER LOWER BEAM SPONGE ✓ BR	1	\$ 98.15	25%	\$ 73.61
21	FRONT BUMPER LOWER BEAM BRACKET ?	2	\$ 176.90	25%	\$ 132.68
22	FRONT BUMPER UNDER COVER ?	2	\$ 354.76	25%	\$ 266.07
23	FRONT BUMPER FOG LAMP COVER ✓ BR	2	\$ 270.92	25%	\$ 203.19
24	FRONT NBUMPER SIDE LOWER RETAINER x	2	\$ 113.66	25%	\$ 85.25
25	FRONT RADIATOR GRILLE ✓ CR4	1	\$ 434.21	25%	\$ 325.66
26	FRONT RADIATOR GRILLE LOGO ✓ NEC	1	\$ 283.63	25%	\$ 212.72
27	FRONT RADIATOR GRILLE INNER BASE ?	1	\$ 183.72	25%	\$ 137.79
28	FRONT IMPACT SENSOR ?	1	\$ 1,195.67	25%	\$ 896.75
29	FRONT IMPACT SENSOR WIRE HARNESS ✓ cut	1	\$ 1,455.83	25%	\$ 1,091.87
30	FRONT HEAD LAMP ✓ CR4 (R) (L) ?	2	\$ 8,793.06	25%	\$ 6,594.80
31	FRONT HEAD LAMP BLUB (HID) RH ✓ Br 1pc	1	\$ 355.71	25%	\$ 266.78

32	FRONT HEAD LAMP HID MODULE RH ✓ Br	1	\$	581.45	25%	\$	436.09
33	FRONT HEAD LAMP LOWER PANEL RH ✓ BT	1	\$	110.15	25%	\$	82.61
34	FRONT SUPPORT PANEL TOP CENTER ?	1	\$	232.33	25%	\$	174.25
35	FRONT SUPPORT PANEL TOP GARNISH ✓ CR4	1	\$	195.89	25%	\$	146.92
36	FRONT SUPPORT PANEL STAND ?	2	\$	571.42	25%	\$	428.57
37	FRONT SUPPORT PANEL BOTTOM ?	1	\$	288.63	25%	\$	216.47
38	FRONT SUPPORT PANEL BOTTOM GARNISH ?	1	\$	135.18	25%	\$	101.39
39	FRONT A/C CONDENSER ✓ BT	1	\$	1,303.70	25%	\$	977.78
40	FRONT A/C CONDENSER LIQUID PIPE WITH LOCK ✓ AT	1	\$	707.21	25%	\$	530.41
41	FRONT A/C CONDENSER SIDE GARNISH ✓ CR4	2	\$	196.70	25%	\$	147.53
42	FRONT A/C FAN BLADE ?	1	\$	158.11	25%	\$	118.58
43	FRONT RADIATOR ?	1	\$	1,841.15	25%	\$	1,380.86
44	FRONT RADIATOR COWLING ?	1	\$	291.38	25%	\$	218.54
45	FRONT RADIATOR FAN BLADE ?	1	\$	233.45	25%	\$	175.09
46	FRONT RADIATOR FAN MOTOR ?	1	\$	585.60	25%	\$	439.20
47	FRONT RADIATOR RESERVOIR TANK ?	1	\$	192.45	25%	\$	144.34
48	FRONT RADIATOR TOP HOSE X	1	\$	45.15	25%	\$	33.86
49	FRONT RADIATOR TOP EXTANSION HOSE X	1	\$	69.70	25%	\$	52.28
50	FRONT WASHER TANK ✓ CR4	1	\$	198.45	25%	\$	148.84
51	FRONT WASHER TANK MOTOR ?	1	\$	185.85	25%	\$	139.39
52	FRONT WASHER TANK PANEL SIDE RH ?	1	\$	255.78	25%	\$	191.84
53	FRONT FENDER RH ✓ CR4	1	\$	826.10	25%	\$	619.58
54	FRONT FENDER SPLASHIELD RH ✓ CR4	1	\$	189.25	25%	\$	141.94
55	FRONT FENDER INNER PANEL RH ?	1	\$	681.83	25%	\$	511.37
56	FRONT FENDER WHEEL ARCH GARNISH RH ✓ Br	1	\$	155.75	25%	\$	116.81
57	FRONT FENDER EMBLEM HYBRID RH ✓ NEC	1	\$	68.15	25%	\$	51.11
58	FRONT FENDER SPLASHIELD SPOILER RH ?	1	\$	58.35	25%	\$	43.76
59	FRONT AIR BAG IMPACT SENSOR ✓ NEC	2	\$	384.86	25%	\$	288.65
60	FRONT DOOR RH X R ✓ DD	1	\$	1,350.25	25%	\$	1,012.69
61	FRONT DOOR PROTECTOR RH X ✓ DD	1	\$	281.85	25%	\$	211.39
62	FRONT WIPER GARNISH ?	1	\$	635.45	25%	\$	476.59
63	FRONT WIPER GARNISH SIDE RH ?	1	\$	88.05	25%	\$	66.04
64	FRONT WINDSCREEN GLASS WITH SENSOR ✓ Br	1	\$	2,711.65	25%	\$	2,033.74
65	FRONT WINDSCREEN GLASS MOULDING ✓ NEC	2	\$	220.80	25%	\$	165.60
66	FRONT WINDSCREEN INNER SEAL ✓ NEC	1	\$	65.30	25%	\$	48.98
67	FRONT WHEEL SHOCKABSOBER RH ?	1	\$	441.85	25%	\$	331.39
68	FRONT WHEEL KNUCKLE ARM RH ?	1	\$	479.15	25%	\$	359.36
69	FRONT WHEEL KNUCKLE BEARING WITH HUB RH ?	1	\$	415.35	25%	\$	311.51
70	FRONT WHEEL LOWER ARM RH ?	1	\$	471.35	25%	\$	353.51
71	FRONT WHEEL LOWER ARM LINK RH ?	1	\$	196.20	25%	\$	147.15
72	FRONT ENGINE MOUNTING TOP RH X	1	\$	198.10	25%	\$	148.58
73	FRONT DASHBOARD ✓ Br	1	\$	1,951.30	25%	\$	1,463.48
74	FRONT DASHBOARD AIR BAG ✓ Br	1	\$	3,120.70	25%	\$	2,340.53
75	FRONT STREEING AIR BAG ✓ Br	1	\$	2,817.30	25%	\$	2,112.98
76	FRONT STREEING AIR BAG CONTACT PIECE ✓ NEC	1	\$	1,028.45	25%	\$	771.34
77	FRONT AIR BAG CONTROL MODULE ✓ NEC	1	\$	1,213.65	25%	\$	910.24
78	FRONT SAFETY BELT ✓ Jane	2	\$	550.25	25%	\$	412.69
79	FRONT ROOF-TOP LINING ✓ CR4	1	\$	2,108.70	25%	\$	1,581.53
80	FRONT ROOF-TOP AIR BAG ✓ Br	2	\$	3,105.70	25%	\$	2,329.28
81	REAR SAFETY BELT ✓ Im	2	\$	1,574.60	25%	\$	1,180.95

SPECIAL ITEMS	PARTS DESCRIPTION	QTY	PRICE \$	FINAL PRICE \$
1	BONNET INSULATOR CLIP ✓ NEC	8	\$ 44.00	\$ -44.00 15
2	FRONT NUMBER PLATE with ✓ Garnish ✓	1	\$ 50.00	\$ -50.00 40
3	FRONT BUMPER CLIP ✓ NEC	8	\$ 44.00	\$ -44.00 30
4	FRONT SUPPORT PANEL TOP GARNISH CLIP ✓ NEC	5	\$ 27.50	\$ -27.50 10
5	FRONT FENDER SPLASHIELD CLIP RH ✓ ?	8	\$ 44.00	\$ 44.00
6	FRONT FENDER WHEEL ARCH GARNISH CLIP RH ✓ NEC	8	\$ 44.00	\$ -44.00 20
7	FRONT WINDSCREEN SEALANT ✓ NEC	1	\$ 50.00	\$ -50.00 40
8	FRONT ERP BRACKET ✓ NEC	1	\$ 25.00	\$ 25.00
9	FRONT WHEEL TYRE RH ✓ B.C.	1	\$ 250.00	\$ -250.00 200
10	FRONT WHEEL TYRE RIM RH ✓ SCH	1	\$ 700.00	\$ -700.00 600
Total Cost				\$ 42,567.01

Labour Works/ Panel Beating Related Works

Job Scope	Quotation
TO RENEW FRONT DAMAGED PARTS, REPLACED AND REALIGNED HYDRAULIC, ALIGNED ALL PARTS	\$ -1,800.00 1200

Spray Painting

Job Scope	Quotation
TO RESPRAY AFFECTED AREAS	\$ 1,600.00 1600

Others Cost (Accident Repair Related Expenses)

Job Scope	Quotation
TOWING	\$ 50.00 ✓
TO TUFFCOAT AFFECTED AREA	\$ -250.00 250 ✓
TO REPLACE FRONT WINDSCREEN	\$ -120.00 ✓
TO REPLACE ENGINE MOUNTING/ GEAR BOX MOUNTING	\$ 250.00 ?
TO REMOVE/ REPLACE AIRCON CONDENSOR, VACUUM, TOP UP AIRCON GAS	\$ 120.00 ✓
TO REMOVE/ REFIX/ REPLACE DASHBOARD	\$ -350.00 350 150
TO REMOVE/ REFIX INTERIOR UPHOLSTERY	\$ -100.00 50
TO REMOVE/ REPLACE FRONT UNDERCARRIAGE	\$ -350.00 350 150
TO REMOVE/ REFIX WIRING CHECKS	\$ -60.00 30
TO REMOVE/ REPLACE DOOR MECHANISM	\$ -100.00 50
TO REPROGRAM ALL RELATED HYBRID SYSTEM	\$ -250.00 250
TO REMOVE AND REPLACE AIRBAG	\$ -450.00 200
TO RESET ALL AIRBAG NECESSARY SYSTEM	\$ -480.00 100
TO COMPUTERISED FOUR WHEEL ALIGNMENT	\$ -80.00 60
TO REMOVE AND REPLACE ROOF-TOP LINING	\$ -200.00 X
Total Others Cost	\$ 3,310.00
GRAND TOTAL	\$ 49,277.01

Sun Pm / Steve DOZ - 17/04/2014 @ 12.30 pm

Thirty Party
without prejudice.

Repair day - 12 days.

Lump sum

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

> [Back to OneMotoring](#)

Enquire Transfer Fee

Vehicle Details

Vehicle No.:	SLX7404D
Vehicle Type:	P11 - Passenger Station Wagon/Jeep/Land Rover
Vehicle Attachment 1:	No Attachment
Vehicle Scheme:	Normal
Vehicle Make:	TOYOTA
Vehicle Model:	C-HR HYBRID 1.8S CVT
Chassis No.:	ZYX102103121
Propellant:	Petrol-Electric
Engine No.:	2ZR8361746
Motor No.:	07WA17M06161
Engine Capacity:	1797 cc
Power Rating:	53.0 kW
Maximum Power Output:	90.0 kW (120 bhp)
Maximum Laden Weight:	1715 kg
Unladen Weight:	1440 kg
Year Of Manufacture:	2018
Original Registration Date:	09 Apr 2018
Lifespan Expiry Date:	-
COE Category:	E - Open - all except motorcycle
Quota Premium:	\$38,000.00
COE Expiry Date:	08 Apr 2028
Road Tax Expiry Date:	08 Apr 2020
PARF Eligibility Expiry Date:	08 Apr 2028
Inspection Due Date:	08 Apr 2021
Intended Transfer Date:	13 Sep 2019
CO2 Emission:	87.00 (g/km)
CEV/VES Rebate Utilised Amount:	\$20,000.00
CO Emission:	0.052000 (g/km)
HC Emission:	0.012000 (g/km)
NOx Emission:	0.005000 (g/km)
PM Emission:	0.900000 (mg/km)

Late renewal fee(s) will be imposed if road tax / lay-up has expired. Please use Enquire Road Tax Payable for fee(s) payable.

Road tax, including Over Payment (if any), of a vehicle will follow the vehicle to the new registered owner when its ownership is being transferred.

Amount Payable

	Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
Transfer Fee:	25.00	-	25.00
Total Amount Payable:			25.00

You may print this page for reference.

OK

Print

Nivitha (LKK Auto)

From: Motor Claim - III <motorclaim@iii.com.sg>
Sent: Thursday, 12 September 2019 1:59 PM
To: jeslyn@carzauto.com.sg; 'sur@lkkauto.com'; Admin-D (LKKAuto)
Cc: 'alex'; Manivel Priyadarshini
Subject: RE: Request Surveyor for pre-repair inspection Our Ref: SLX7404D Your Ref: SHA6575T
Attachments: Reporting SLX7404D.PDF; PRI SLX7404D.PDF

Dear Sir / Mdm,

Please conduct a survey on TP vehicle SLX7404D and let us have your report urgently.

This claim will be handled by Ms Priya.

*Kindly upload this survey request email to merimen.

Thank You.

Best Regards,
Gabriel Wee



64 Cecil Street; #05 - IOB Building
Singapore 049711
Tel: 6347 6100, Ext - 248

P. Jeslyn

T. 2.4 p.m

v.l.y

E. ✓

From: jeslyn@carzauto.com.sg [mailto:jeslyn@carzauto.com.sg]
Sent: 12 September, 2019 12:07 PM
To: Motor Claim - III <motorclaim@iii.com.sg>
Cc: 'alex' <alex@carzauto.com.sg>
Subject: RE: Request Surveyor for pre-repair inspection Our Ref: SLX7404D Your Ref: SHA6575T

Hi Mr Gabriel Wee

Good Afternoon

We choose LKK Auto Consultants Pte Ltd to conduct the PRI.
Please arrange as soon as possible.

Thank You.

With Regards,
Jeslyn Chua
HP: 8322 7418



CARZ AUTO SERVICES PTE LTD

MAIN OFFICE & ACCESSORIES WORKSHOP:
CAR GRINDING WORKSHOP:
SPRAY PAINTING WORKSHOP:
ACCIDENT REPAIR & SERVICE WORKSHOP:
ACCIDENT REPORTING & SERVICE WORKSHOP:

TEL: 6709 3080
FAX: 6709 3081
HP: 9022 2226

1 KAKI BUKIT AVE 6, #02-26, (AUTOMAX@KAKI BUKIT), SINGAPORE 412882
1 KAKI BUKIT AVE 6, #02-25, (AUTOMAX@KAKI BUKIT), SINGAPORE 412882
1 KAKI BUKIT AVE 6, #01-14, (AUTOMAX@KAKI BUKIT), SINGAPORE 412882
41 WOODLANDS INDUSTRIAL PARK 9S, #06-04, (PREMIUM @ ES), SINGAPORE 757047
259 MACPHERSON ROAD, (MARTY SHELL SERVICE STATION), SINGAPORE 248244

EMAIL: SALES@CARZAUTO.COM.SG
FB: FACEBOOK.COM/CARZAUTOSERVICES
WEB: HTTP://WWW.CARZAUTO.COM.SG

From: Motor Claim - III [mailto:motorclaim@iii.com.sg]

Sent: Thursday, 12 September 2019 11:45 AM

To: jeslyn@carzauto.com.sg

Cc: 'alex' <alex@carzauto.com.sg>

Subject: RE: Request Surveyor for pre-repair inspection Our Ref: SLX7404D Your Ref: SHA6575T

Dear Sir / Mdm,

We acknowledge receipt of your email.

We propose using one of the following motor surveyors:

- LKK Auto Consultants Pte Ltd
- Vicom Assessment Centre Pte Ltd

Please notify us within 02 days of receipt of this letter for surveyor agreed on or if you have any objections to the above list.

Best Regards,
Gabriel Wee



64 Cecil Street; #05 - IOB Building
Singapore 049711
Tel: 6347 6100, Ext - 248

From: jeslyn@carzauto.com.sg [mailto:jeslyn@carzauto.com.sg]

Sent: 12 September, 2019 11:23 AM

To: Motor Claim - III <motorclaim@iii.com.sg>

Cc: 'alex' <alex@carzauto.com.sg>

Subject: Request Surveyor for pre-repair inspection Our Ref: SLX7404D Your Ref: SHA6575T

Hi Ms/Sir

Good Morning

Please arrange surveyor for pre-repair inspection.

Thank You.

With Regards,
Jeslyn Chua
HP: 8322 7418



CARZ AUTO SERVICES PTE LTD

MAIN OFFICE & ACCESSORIES WORKSHOP:
CAR GROOMING WORKSHOP:
SPRAY PAINTING WORKSHOP:
ACCIDENT REPAIR & SERVICE WORKSHOP:
ACCIDENT REPORTING & SERVICE WORKSHOP:

TEL: 6509 3080
FAX: 6509 3081
HP: 9022 2226

1 KARI BUKIT AVE S, #02-20, (AUTOSBAY@KARI BUKIT), SINGAPORE 417883
1 KARI BUKIT AVE S, #02-15, (AUTOSBAY@KARI BUKIT), SINGAPORE 417883
1 KARI BUKIT AVE S, #02-1A, (AUTOSBAY@KARI BUKIT), SINGAPORE 417883
81 WOODLANDS INDUSTRIAL PARK EX, #04-06, (PREMIER @ IRL), SINGAPORE 737947
216 MACPHERSON ROAD, (SMART SHELL SERVICE STATION), SINGAPORE 348584

EMAIL: SALES@CARZAUTO.COM.SG
FB: FACEBOOK.COM/CARZAUTOSERVICES
WEB: HTTP://WWW.CARZAUTO.COM.SG

Kindly note that by submitting this claim to us, you are deemed to have agreed to us collecting, using, disclosing and processing your personal data, sharing your personal data with our service providers (located both inside and outside Singapore) and/or with other insurers in the general insurance industry, including the General Insurance Association of Singapore. This enables us to ensure proper processing, handling and/or dealing with your claim, which includes investigating the said claim, and complying with applicable laws. If you do not agree to the same, kindly let us know immediately.

DISCLAIMER:

This email is intended solely for the person to whom it has been addressed.

It may contain confidential and/or legally privileged information.

If you are not the person for whom this e-mail was intended, or if this e-mail has reached you by mistake, please delete it immediately and inform us of the error and also be hereby notified that any use, distribution, transmission, printing, copying or dissemination of this information in any way or in any manner is strictly prohibited and may be unlawful. Internet communications may not be entirely secure or accurate as information could be intercepted, corrupted, lost, delayed or contain viruses.

Therefore, we do not accept liability for any errors or omissions in the content of this message or any delay in delivery which may arise as a result of Internet transmission or any modification.

Print this email only if it is absolutely necessary and help in preservation of environment.

India International Insurance Pte Ltd.

Registration No. 198703792-K

Kindly note that by submitting this claim to us, you are deemed to have agreed to us collecting, using, disclosing and processing your personal data, sharing your personal data with our service providers (located both inside and outside Singapore) and/or with other insurers in the general insurance industry, including the General Insurance Association of Singapore. This enables us to ensure proper processing, handling and/or dealing with your claim, which includes investigating the said claim, and complying with applicable laws. If you do not agree to the same, kindly let us know immediately.

DISCLAIMER:

This email is intended solely for the person to whom it has been addressed.

It may contain confidential and/or legally privileged information.

If you are not the person for whom this e-mail was intended, or if this e-mail has reached you by mistake, please delete it immediately and inform us of the error and also be hereby notified that any use, distribution, transmission, printing, copying or dissemination of this information in any way or in any manner is strictly prohibited and may be unlawful. Internet communications may not be entirely secure or accurate as information could be intercepted, corrupted, lost, delayed or contain viruses.

Therefore, we do not accept liability for any errors or omissions in the content of this message or any delay in delivery which may arise as a result of Internet transmission or any modification.

Print this email only if it is absolutely necessary and help in preservation of environment.

India International Insurance Pte Ltd.

Registration No. 198703792-K

Claim Audit

AUDIT TRAIL				
No.	On	Audit	Remarks	By
1	13 Sep 2019 14:21	Cim Dtl Modified	Claimant's Name: -> V VELAUTHAM S/O VALAKRISHNAN, Claimant's ID: -> S6876190E.	[A] Lau Shu Pel
2	13 Sep 2019 14:21	Cim Veh Model Changed	(205388) TOYOTA C-HR HYBRID 1.8 S CVT (A).	[A] Lau Shu Pel
3	13 Sep 2019 14:21	Cim Created	Reg No: SLX7404D, Acct Date: 2019/09/11. Claim Type: TP. Insurer: India International Insurance Pte Ltd (HQ). TP Insurer: MSIG Insurance (Singapore) Pte. Ltd. (HQ). Worksh op: Carz Auto Services Pte Ltd (HQ)	[A] Lau Shu Pel
4	13 Sep 2019 14:21	Adj Co Assigned	LKK Auto Consultants Pte Ltd (HQ):	[A] Lau Shu Pel
5	13 Sep 2019 14:21	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2019/09/24	[A] Lau Shu Pel
6	13 Sep 2019 14:21	Adj Mandate Set	Approved:0.00.Reinsp:Adj decides.	[A] Lau Shu Pel
7	13 Sep 2019 14:21	Label Added	(30653):Direct Settlement.	[A] Lau Shu Pel
8	13 Sep 2019 14:21	Adj Adjuster Assigned	[None] -> ADRIAN LING	[A] Lau Shu Pel
9	16 Sep 2019 15:34	Adj Adjuster Assigned	ADRIAN LING -> CHEN TSUE YEE	[A] Lau Shu Pel
10	17 Sep 2019 09:47	Cim Dtl Modified	Insured Name: -> COMFORT TRANSPORTATION PTE LTD.	[A] Lau Shu Pel
11	19 Sep 2019 13:53	Adj Mandate Request	Cur.Reg:0.00:PODS Liability: 100% Remark: Insured driver made right turn and collided with third party who was driving straight on the opposite direction.	[A] CHEW HSIAO TONG

Date From



Date To



Audit Type

None

Go

ACTIVITY

No record

Merimen Billing for this case - Transaction History

Bill Ref No	Bill Date	Bill Type	Acc Type	Acc Name	Co Name (Branch)	Ref 1	Ref 2	Amount
2280258	16 Sep 2019 08:51:52	TP Case (Insurer)	Motor	LKK Auto Consultants Pte Ltd	India International Insurance Pte Ltd (HQ)	SLX7404D	SHA6575T	11.77

Claim Audit

AUDIT TRAIL				
No.	On	Audit	Remarks	By
1	13 Sep 2019 14:21	Cim Dtl Modified	Claimant's Name: -> V VELAUTHAM S/O VALAKRISHNAN. Claimant's ID: -> S6876190E.	[A] Lau Shu Pei
2	13 Sep 2019 14:21	Cim Veh Model Changed	(205388) TOYOTA C-HR HYBRID 1.8 S CVT (A).	[A] Lau Shu Pei
3	13 Sep 2019 14:21	Cim Created	Reg No: SLX7404D. Acct Date: 2019/09/11. Claim Type: TP. Insurer: India International Insurance Pte Ltd (HQ). TP Insurer: MSIG Insurance (Singapore) Pte. Ltd. (HQ). Worksh op: Carz Auto Services Pte Ltd (HQ)	[A] Lau Shu Pei
4	13 Sep 2019 14:21	Adj Co Assigned	LKK Auto Consultants Pte Ltd (HQ):	[A] Lau Shu Pei
5	13 Sep 2019 14:21	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2019/09/24	[A] Lau Shu Pei
6	13 Sep 2019 14:21	Adj Mandate Set	Approved:0.00.Reinsp:Adj decides.	[A] Lau Shu Pei
7	13 Sep 2019 14:21	Label Added	(30653):Direct Settlement.	[A] Lau Shu Pei
8	13 Sep 2019 14:21	Adj Adjuster Assigned	[None] -> ADRIAN LING	[A] Lau Shu Pei
9	16 Sep 2019 15:34	Adj Adjuster Assigned	ADRIAN LING -> CHEN TSUE YEE	[A] Lau Shu Pei
10	17 Sep 2019 09:47	Cim Dtl Modified	Insured Name: -> COMFORT TRANSPORTATION PTE LTD.	[A] Lau Shu Pei
11	19 Sep 2019 13:53	Adj Mandate Request	Cur.Reg:0.00:PODS Liability: 100% Remark: Insured driver made right turn and collided with third party who was driving straight on the opposite direction.	[A] CHEW HSIAO TONG
12	19 Sep 2019 17:22	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2019/09/24	[I] Priya
13	19 Sep 2019 17:22	Adj Mandate Set	Approved:0.00.	[I] Priya

Date From Date To Audit Type

ACTIVITY

No record

Merimen Billing for this case - Transaction History

Bill Ref No	Bill Date	Bill Type	Acc Type	Acc Name	Co Name (Branch)	Ref 1	Ref 2	Amount
2280258	16 Sep 2019 08:51:52	TP Case (Insurer)	Motor	LKK Auto Consultants Pte Ltd	India International Insurance Pte Ltd (HQ)	SLX7404D	SHA6575T	11.77

Hsiao Tong (LKKAuto)

From: Hsiao Tong (LKKAuto)
Sent: Tuesday, 24 September 2019 8:59 AM
To: jeslyn@carzauto.com.sg; 'alex'
Cc: Admin A
Subject: Your Ref: SLX7404D *Our Ref: CC4/III19016234/Epb3 [ACCIDENT INVOLVING SHA 6575T(III) AND SLX 7404D ON 11/09/2019]

Your Ref: **SLX7404D** Without Prejudice
Our Ref: CC4/III19016234/Epb3

Dear Sirs/Mdm,

ACCIDENT INVOLVING SHA 6575T(III) AND SLX 7404D ON 11/09/2019

We refer to the above matter.

Please be informed that basing on the accident statements submitted by both parties, the liability is clear / under BOLA (subject to BOLA guideline settlement) and shall proceed with direct settlement for the above mentioned case.

Please note that this e-mail is on without prejudice basis which does not amount to an authorisation of repair to your client's vehicle and admission of any liability to our Insured's part. The final repair cost is subjected to the consistency of the damages according to the nature of the accident. And the days of LOU/ LOR will be based on the number of days of repair as recommended by our surveyor and approved by our principal.

Thank you.

"Kindly note that this negotiation between parties on this matter is purely on a without prejudice basis with the sole intention of resolving the matter amicably without parties resorting to legal proceedings. No admission of liability, whatsoever, should be deemed / inferred from this negotiation of terms/settlement.

In the event of new evidence being discovered or subsequently produced by either party that will materially affect/influence on the issues of liability/damages, either party is not bound, thereafter, by the negotiation terms/settlement."

Best Regards,

Hsiao Tong, Chew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6742-3197 | email: chewht@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Claim Audit

AUDIT TRAIL				
No	On	Audit	Remarks	By
1	13 Sep 2019 14:21	Clm Dtl Modified	Claimant's Name: -> V VELAUTHAM S/O VALAKRISHNAN, Claimant's ID: -> S6876190 E.	[A] Lau Shu Pei
2	13 Sep 2019 14:21	Clm Veh Model Changed	(205388) TOYOTA C-HR HYBRID 1.8 S CVT (A).	[A] Lau Shu Pei
3	13 Sep 2019 14:21	Clm Created	Reg No: SLX7404D, Acct Date: 2019/09/11, Claim Type: TP, Insurer: India International Insurance Pte Ltd (HQ), TP Insurer: MSI Insurance (Singapore) Pte. Ltd. (HQ), Workshop: Carz Auto Services Pte Ltd (HQ)	[A] Lau Shu Pei
4	13 Sep 2019 14:21	Adj Co Assigned	LKK Auto Consultants Pte Ltd (HQ):	[A] Lau Shu Pei
5	13 Sep 2019 14:21	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2019/09/24	[A] Lau Shu Pei
6	13 Sep 2019 14:21	Adj Mandate Set	Approved:0.00.Reinsp:Adj decides.	[A] Lau Shu Pei
7	13 Sep 2019 14:21	Label Added	(30653):Direct Settlement.	[A] Lau Shu Pei
8	13 Sep 2019 14:21	Adj Adjuster Assigned	[None] -> ADRIAN LING	[A] Lau Shu Pei
9	16 Sep 2019 15:34	Adj Adjuster Assigned	ADRIAN LING -> CHEN TSUE YEE	[A] Lau Shu Pei
10	17 Sep 2019 09:47	Clm Dtl Modified	Insured Name: -> COMFORT TRANSPORTATION PTE LTD.	[A] Lau Shu Pei
11	19 Sep 2019 13:53	Adj Mandate Request	Cur.Req:0.00:PODS Liability: 100% Remark: Insured driver made right turn and collided with third party who was driving straight on the opposite direction.	[A] CHEW HSIAO TONG
12	19 Sep 2019 17:22	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2019/09/24	[I] Priya
13	19 Sep 2019 17:22	Adj Mandate Set	Approved:0.00.	[I] Priya
14	06 Nov 2019 10:20	Adj Rpt Initiated		[A] JOANNE LEE KHANG MIN
15	06 Nov 2019 10:20	Clm Dtl Modified	Insured ID: -> -.	[A] JOANNE LEE KHANG MIN
16	06 Nov 2019 10:20	Clm Dtl Modified	IPJ Reg. Date: -> 2018/04/09.	[A] JOANNE LEE KHANG MIN
17	06 Nov 2019 10:20	Clm Details Notified		[A] JOANNE LEE KHANG MIN
18	09 Nov 2019 14:43	Adj Mandate Request	Cur.Req:31781.45:PODS Liability: 100% *Quantum: (a)CORw/GST: \$30,174.00 + (b)LOR(16days x \$100.00): \$1,600.00 + (c)LTA/GIA search fee: \$7.45 = Total: \$31,781.45 *Vehicle Model: Toyota C-HR Hybrid (1797cc) *14 recommendation repair days 2Sunday =	[A] CHEW HSIAO TONG

Date From



Date To



Audit Type

None

Go

ACTIVITY

No record

Merimen Billing for this case - Transaction History

Bill Ref No	Bill Date	Bill Type	Acc. Type	Acc. Name	Co Name (Branch)	Ref 1	Ref 2	Amount
2280258	16 Sep 2019 08:51:52	TP Case (Insurer)	Motor	LKK Auto Consultants Pte Ltd	India International Insurance Pte Ltd (HQ)	SLX7404D	SHA6575T	11.77
2336985	06 Nov 2019 10:20:19	OD/TP Case (Adjuster)	Motor	LKK Auto Consultants Pte Ltd	LKK Auto Consultants Pte Ltd (HQ)	SLX7404D	SHA6575T	11.77

Print Received Message

This mail is associated with :

***SLX7404D (MCT19090238)**

[SHA6575T]

TP

V VELAUTHAM S/O VALAKRISHNAN

Sep 11 2019 6:00AM

[COMFORT TRANSPORTATION PTE LTD]

Carz Auto Services Pte Ltd

From India International Insurance Pte Ltd (HQ) (III_SG), sent on 12/11/2019 18:03 PM.
To LKK_HQ
Subject Alert - Adj Mandate Approved (S\$31781.45) - SLX7404D - Claim Handler: Priya

Approved:31781.45.

Hsiao Tong (LKKAUTO)

From: jeslyn@carzauto.com.sg
Sent: Monday, 18 November 2019 10:24 AM
To: Hsiao Tong (LKKAUTO); alex@carzauto.com.sg
Cc: Admin A
Subject: RE: Your Ref: SLX7404D *Our Ref: CC4/III19016234/Epb3 [ACCIDENT INVOLVING SHA 6575T(III) AND SLX 7404D ON 11/09/2019]

Hi Ms Hsiao Tong

Good Morning

We accept the offer at amount **\$31,700.00(all-in)**.
Please email the discharge voucher for us as soon as possible.

Thank You.

With Regards,
Jeslyn Chua
HP: 8322 7418



CARZ AUTO SERVICES PTE LTD

MAIN OFFICE & ACCESSORIES WORKSHOP:
CAR GROOMING WORKSHOP:
SPRAY PAINTING WORKSHOP:
ACCIDENT REPAIR & SERVICE WORKSHOP:
ACCIDENT REPORTING & SERVICE WORKSHOP:

TEL: 8322 7418
FAX: 8322 7418
HP: 8322 7418

1 KAKI BUKIT AVE S, #02-26, (AUTOBAY@KAKI BUKIT), SINGAPORE 457882
1 KAKI BUKIT AVE S, #02-25, (AUTOBAY@KAKI BUKIT), SINGAPORE 457883
1 KAKI BUKIT AVE S, #01-14, (AUTOBAY@KAKI BUKIT), SINGAPORE 457883
43 WOODLANDS INDUSTRIAL PARK ES, #04-04, (PREMIUM @ ES), SINGAPORE 757947
219 MACPHERSON ROAD, (MARTIN'S SERVICE STATION), SINGAPORE 348344

EMAIL: SALES@CARZAUTO.COM.SG
FACEBOOK: CARZAUTO SERVICES
WEB: HTTP://WWW.CARZAUTO.COM.SG

From: Hsiao Tong (LKKAUTO) [mailto:chewht@lkkauto.com]
Sent: Monday, 18 November 2019 9:57 AM
To: jeslyn@carzauto.com.sg; alex@carzauto.com.sg
Cc: Admin A <admin-a@lkkauto.com>
Subject: RE: Your Ref: SLX7404D *Our Ref: CC4/III19016234/Epb3 [ACCIDENT INVOLVING SHA 6575T(III) AND SLX 7404D ON 11/09/2019]

Without Prejudice
(save as to costs)

Dear Sirs/Mdm,

We refer to the above matter.

We have our principal instruction to offer at a global sum of **\$31,700.00(all-in)**.

Please confirm acceptance.

"Kindly note that this negotiation between parties on this matter is purely on a without prejudice basis with the sole intention of resolving the matter amicably without parties resorting to legal proceedings. No admission of liability, whatsoever, should be deemed / inferred from this negotiation of terms/settlement.

In the event of new evidence being discovered or subsequently produced by either party that will materially affect/influence on the issues of liability/damages, either party is not bound, thereafter, by the negotiation terms/settlement."

Best Regards,

Hsiao Tong, Chew (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6742-3197 | email: chewht@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: jeslyn@carzauto.com.sg <jeslyn@carzauto.com.sg>

Sent: Monday, 4 November 2019 12:20 PM

To: alex@carzauto.com.sg; Hsiao Tong (LKKAuto) <chewht@lkkauto.com>

Cc: Admin A <admin-a@lkkauto.com>

Subject: RE: Your Ref: SLX7404D *Our Ref: CC4/III19016234/Epb3 [ACCIDENT INVOLVING SHA 6575T(III) AND SLX 7404D ON 11/09/2019]

Hi Ms Hsiao Tong

Good Afternoon

Please give the offer for us as soon as possible.

Thank You.

With Regards,

Jeslyn Chua

HP: 8322 7418



CARZ AUTO SERVICES PTE LTD

MAIN OFFICE & ACCESSORIES WORKSHOP:
CAR GROOMING WORKSHOP:
SPRAY PAINTING WORKSHOP:
ACCIDENT REPAIR & SERVICE WORKSHOP:
ACCIDENT REPORTING & SERVICE WORKSHOP:

TEL: 6742 3197
FAX: 6741 4108
HP: 8322 7418

1 KARI BURST AVE S, #02-26, (AUTOBAY@KARI BURST), SINGAPORE 451663
1 KARI BURST AVE S, #02-25, (AUTOBAY@KARI BURST), SINGAPORE 451663
1 KARI BURST AVE S, #02-24, (AUTOBAY@KARI BURST), SINGAPORE 451663
41 WOODLANDS INDUSTRIAL PARK DR, #04-04, (SPRINT@WIP @ 25), SINGAPORE 751047
279 KUALAHERIOM ROAD, (MART SHELL SERVICE STATION), SINGAPORE 540044

EMAIL: [SALES@CARZAUTO.COM.SG](mailto:sales@carzauto.com.sg)
FB: [FACEBOOK.COM/CARZAUTOSERVICES](https://www.facebook.com/carzautoservices)
WEB: [HTTP://WWW.CARZAUTO.COM.SG](http://www.carzauto.com.sg)

From: jeslyn@carzauto.com.sg [<mailto:jeslyn@carzauto.com.sg>]

Sent: Friday, 1 November 2019 1:01 PM

To: 'alex@carzauto.com.sg' <alex@carzauto.com.sg>; Hsiao Tong (LKKAuto) <chewht@lkkauto.com>

Cc: 'Admin A' <admin-a@lkkauto.com>

Subject: RE: Your Ref: SLX7404D *Our Ref: CC4/III19016234/Epb3 [ACCIDENT INVOLVING SHA 6575T(III) AND SLX 7404D ON 11/09/2019]

Hi Ms Hsiao Tong

Good Afternoon

Please give the offer for us as soon as possible.

Thank You.

With Regards,
Jeslyn Chua
HP: 8322 7418



CARZ AUTO SERVICES PTE LTD

MAIN OFFICE & ACCESSORIES WORKSHOP:
CAR GROOMING WORKSHOP:
SPRAY PAINTING WORKSHOP:
ACCIDENT REPAIR & SERVICE WORKSHOP:
ACCIDENT REPORTING & SERVICE WORKSHOP:

TEL: 8322 2226
FAX: 8322 2226
HP: 8322 2226

1 KARI BUKIT AVE S, #02-24, (AUTORAY@KARI BUKIT), SINGAPORE 417881
1 KARI BUKIT AVE S, #02-25, (AUTORAY@KARI BUKIT), SINGAPORE 417883
1 KARI BUKIT AVE S, #01-14, (AUTORAY@KARI BUKIT), SINGAPORE 417883
43 WOODLANDS INDUSTRIAL PARK ES, #04-04, (PENTAGON @ ES), SINGAPORE 757841
210 MACPHERSON ROAD, (MART SHELL SERVICE STATION), SINGAPORE 348384

EMAIL: SALES@CARZAUTO.COM.SG
FACEBOOK.COM/CARZAUTOSERVICES
WEB: HTTP://WWW.CARZAUTO.COM.SG

From: alex@carzauto.com.sg [mailto:alex@carzauto.com.sg]

Sent: Tuesday, 24 September 2019 10:22 AM

To: 'Hsiao Tong (LKKAuto)' <chewht@lkkauto.com>; jeslyn@carzauto.com.sg

Cc: 'Admin A' <admin-a@lkkauto.com>

Subject: RE: Your Ref: SLX7404D *Our Ref: CC4/III19016234/Epb3 [ACCIDENT INVOLVING SHA 6575T(III) AND SLX 7404D ON 11/09/2019]

Hi Hsiao Tong

Thanks you for your information

Subject to BOLA Guideline , we will proceed with direct settlement about mentioned

Thanks Regards

Alex

From: Hsiao Tong (LKKAuto) <chewht@lkkauto.com>

Sent: Tuesday, September 24, 2019 8:59 AM

To: jeslyn@carzauto.com.sg; 'alex' <alex@carzauto.com.sg>

Cc: Admin A <admin-a@lkkauto.com>

Subject: Your Ref: SLX7404D *Our Ref: CC4/III19016234/Epb3 [ACCIDENT INVOLVING SHA 6575T(III) AND SLX 7404D ON 11/09/2019]

Your Ref: **SLX7404D**

Without Prejudice

Our Ref: CC4/III19016234/Epb3

Dear Sirs/Mdm,

ACCIDENT INVOLVING SHA 6575T(III) AND SLX 7404D ON 11/09/2019

We refer to the above matter.

Please be informed that basing on the accident statements submitted by both parties, the liability is clear / under BOLA (subject to BOLA guideline settlement) and shall proceed with direct settlement for the above mentioned case.

Please note that this e-mail is on without prejudice basis which does not amount to an authorisation of repair to your client's vehicle and admission of any liability to our Insured's part. The final repair cost is subjected to the consistency of the damages according to the nature of the accident. And the days of LOU/ LOR will be based on the number of days of repair as recommended by our surveyor and approved by our principal.

Thank you.

"Kindly note that this negotiation between parties on this matter is purely on a without prejudice basis with the sole intention of resolving the matter amicably without parties resorting to legal proceedings. No admission of liability, whatsoever, should be deemed / inferred from this negotiation of terms/settlement.

In the event of new evidence being discovered or subsequently produced by either party that will materially affect/influence on the issues of liability/damages, either party is not bound, thereafter, by the negotiation terms/settlement."

Best Regards,

Hsiao Tong, Chew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6742-3197 | email: chewht@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

...CLAIM SUBFOLDER...(Pending for Survey Report)

Direct Settlement

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	13 Sep 2019 Edit Reg		12 Sep 2019 00:00 Edit Adj Rpt	S\$28,200.00 Edit Estimates	S\$28,200.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured:	COMFORT TRANSPORTATION PTE LTD , Co. Reg. No.: -								
Main Claimant:	V VELAUTHAM S/O VALAKRISHNAN , ID: S6876190E								
Vehicle Reg. No.:	SLX7404D	Date of Loss:	11/09/2019 06:00 - :59 [17 Months and 2 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / MCT19090238	Policy/Cover Note No.:	MCOM0015						
Vehicle Reg. No. (Insured):	SHA6575T	Policy No. (Claimant):							
		Excess:							
Repairer:	Carz Auto Services Pte Ltd - Woodlands (HQ) NO 61, WOODLANDS INDUSTRIAL PARK E9, #04-04 E9 PREMIUM SINGAPORE 757047, 757047 Woodlands - Tel:								
Handling Insurer:	India International Insurance Pte Ltd (HQ) - Tel: 63476100 ... [Handled by Priya]								
Claimant's Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by CHEN TSUE YEE] ... [Final Rpt due 24/09/2019]								
ASSOCIATED MAIL RECEIVED			View All	Compose Case Mail					
<ul style="list-style-type: none"> III_SG (12/11/2019): Alert - Adj Mandate Approved (S\$31781.45) - SLX7404D - Claim Handler: Priya III_SG (19/09/2019): Alert - Adj Mandate Approved (S\$0.00) - SLX7404D - Claim Handler: Priya 									
ALL ASSOCIATED TASKS			View All	Search Tasks					
			Create New Task	Complete					
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SLX7404D (MCT19090238)
[SHA6575T]
TP
V VELAUTHAM S/O VALAKRISHNAN
Sep 11 2019 6:00AM
[COMFORT TRANSPORTATION PTE LTD]
Carz Auto Services Pte Ltd - Woodlands

Upload Documents			Upload Photos		Compose New Letter		View <input type="button" value="View in Browser"/>	
Photos/Images							3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print			
1	19/09/19 12:58	General View		Load JPG	<input checked="" type="checkbox"/>			
2	19/09/19 12:58	General View		Load JPG	<input checked="" type="checkbox"/>			
3	19/09/19 12:58	General View		Load JPG	<input checked="" type="checkbox"/>			
4	19/09/19 12:58	General View		Load JPG	<input checked="" type="checkbox"/>			
5	19/09/19 12:58	General View		Load JPG	<input checked="" type="checkbox"/>			
6	19/09/19 12:58	General View		Load JPG	<input checked="" type="checkbox"/>			
7	19/09/19 12:58	General View		Load JPG	<input checked="" type="checkbox"/>			
8	19/09/19 12:58	General View		Load JPG	<input checked="" type="checkbox"/>			
9	19/09/19 12:58	General View		Load JPG	<input checked="" type="checkbox"/>			
10	19/09/19 12:58	General View		Load JPG	<input checked="" type="checkbox"/>			
11	19/09/19 12:58	General View		Load JPG	<input checked="" type="checkbox"/>			
12	19/09/19 12:58	General View		Load JPG	<input checked="" type="checkbox"/>			
13	19/09/19 12:58	General View		Load JPG	<input checked="" type="checkbox"/>			
14	19/09/19 12:58	General View		Load JPG	<input checked="" type="checkbox"/>			
15	19/09/19 12:58	General View		Load JPG	<input checked="" type="checkbox"/>			
16	19/09/19 12:58	General View		Load JPG	<input checked="" type="checkbox"/>			
17	19/09/19 12:58	General View		Load JPG	<input checked="" type="checkbox"/>			
18	19/09/19 12:58	General View		Load JPG	<input checked="" type="checkbox"/>			
19	19/09/19 12:58	General View		Load JPG	<input checked="" type="checkbox"/>			
20	19/09/19 12:58	General View		Load JPG	<input checked="" type="checkbox"/>			
21	19/09/19 12:58	General View		Load JPG	<input checked="" type="checkbox"/>			
22	19/09/19 12:58	General View		Load JPG	<input checked="" type="checkbox"/>			
23	19/09/19 12:58	General View		Load JPG	<input checked="" type="checkbox"/>			
24	19/09/19 12:58	General View		Load JPG	<input checked="" type="checkbox"/>			
25	19/09/19 12:58	General View		Load JPG	<input checked="" type="checkbox"/>			
26	19/09/19 12:58	General View		Load JPG	<input checked="" type="checkbox"/>			
27	19/09/19 12:58	General View		Load JPG	<input checked="" type="checkbox"/>			
28	19/09/19 12:58	General View		Load JPG	<input checked="" type="checkbox"/>			
29	19/09/19 12:58	General View		Load JPG	<input checked="" type="checkbox"/>			
30	27/09/19 17:35	General View		Load JPG	<input checked="" type="checkbox"/>			
31	27/09/19 17:35	General View		Load JPG	<input checked="" type="checkbox"/>			
32	27/09/19 17:35	General View		Load JPG	<input checked="" type="checkbox"/>			
33	27/09/19 17:35	General View		Load JPG	<input checked="" type="checkbox"/>			
34	27/09/19 17:35	General View		Load JPG	<input checked="" type="checkbox"/>			
35	27/09/19 17:35	General View		Load JPG	<input checked="" type="checkbox"/>			
36	27/09/19 17:35	General View		Load JPG	<input checked="" type="checkbox"/>			
37	27/09/19 17:35	General View		Load JPG	<input checked="" type="checkbox"/>			
38	27/09/19 17:35	General View		Load JPG	<input checked="" type="checkbox"/>			
39	27/09/19 17:35	General View		Load JPG	<input checked="" type="checkbox"/>			
40	27/09/19 17:35	General View		Load JPG	<input checked="" type="checkbox"/>			
41	27/09/19 17:35	General View		Load JPG	<input checked="" type="checkbox"/>			
42	27/09/19 17:35	General View		Load JPG	<input checked="" type="checkbox"/>			
43	27/09/19 17:35	General View		Load JPG	<input checked="" type="checkbox"/>			

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
44	27/09/19 17:35	General View		Load JPG <input checked="" type="checkbox"/>
45	27/09/19 17:35	General View		Load JPG <input checked="" type="checkbox"/>
46	27/09/19 17:35	General View		Load JPG <input checked="" type="checkbox"/>
47	27/09/19 17:35	General View		Load JPG <input checked="" type="checkbox"/>
48	27/09/19 17:35	General View		Load JPG <input checked="" type="checkbox"/>
49	27/09/19 17:35	General View		Load JPG <input checked="" type="checkbox"/>
50	27/09/19 17:35	General View		Load JPG <input checked="" type="checkbox"/>
51	27/09/19 17:35	General View		Load JPG <input checked="" type="checkbox"/>
52	27/09/19 17:35	General View		Load JPG <input checked="" type="checkbox"/>
53	27/09/19 17:35	General View		Load JPG <input checked="" type="checkbox"/>
54	27/09/19 17:35	General View		Load JPG <input checked="" type="checkbox"/>
55	27/09/19 17:35	General View		Load JPG <input checked="" type="checkbox"/>
56	27/09/19 17:35	General View		Load JPG <input checked="" type="checkbox"/>
57	27/09/19 17:35	General View		Load JPG <input checked="" type="checkbox"/>
58	27/09/19 17:35	General View		Load JPG <input checked="" type="checkbox"/>
59	27/09/19 17:35	General View		Load JPG <input checked="" type="checkbox"/>
60	27/09/19 17:35	General View		Load JPG <input checked="" type="checkbox"/>
61	27/09/19 17:35	General View		Load JPG <input checked="" type="checkbox"/>
62	27/09/19 17:35	General View		Load JPG <input checked="" type="checkbox"/>
63	27/09/19 17:35	General View		Load JPG <input checked="" type="checkbox"/>
64	27/09/19 17:35	General View		Load JPG <input checked="" type="checkbox"/>
65	27/09/19 17:35	General View		Load JPG <input checked="" type="checkbox"/>
66	27/09/19 17:35	General View		Load JPG <input checked="" type="checkbox"/>
67	27/09/19 17:35	General View		Load JPG <input checked="" type="checkbox"/>
68	27/09/19 17:35	General View		Load JPG <input checked="" type="checkbox"/>
69	27/09/19 17:35	General View		Load JPG <input checked="" type="checkbox"/>
70	27/09/19 17:35	General View		Load JPG <input checked="" type="checkbox"/>
71	27/09/19 17:35	General View		Load JPG <input checked="" type="checkbox"/>
72	27/09/19 17:35	General View		Load JPG <input checked="" type="checkbox"/>
73	27/09/19 17:35	General View		Load JPG <input checked="" type="checkbox"/>
74	27/09/19 17:35	General View		Load JPG <input checked="" type="checkbox"/>
75	27/09/19 17:35	General View		Load JPG <input checked="" type="checkbox"/>
76	27/09/19 17:35	General View		Load JPG <input checked="" type="checkbox"/>
77	27/09/19 17:35	General View		Load JPG <input checked="" type="checkbox"/>
78	27/09/19 17:35	General View		Load JPG <input checked="" type="checkbox"/>
79	27/09/19 17:35	General View		Load JPG <input checked="" type="checkbox"/>
80	27/09/19 17:35	General View		Load JPG <input checked="" type="checkbox"/>
81	27/09/19 17:35	General View		Load JPG <input checked="" type="checkbox"/>
82	27/09/19 17:35	General View		Load JPG <input checked="" type="checkbox"/>
83	27/09/19 17:35	General View		Load JPG <input checked="" type="checkbox"/>
84	27/09/19 17:35	General View		Load JPG <input checked="" type="checkbox"/>
85	27/09/19 17:35	General View		Load JPG <input checked="" type="checkbox"/>
86	27/09/19 17:35	General View		Load JPG <input checked="" type="checkbox"/>
87	27/09/19 17:35	General View		Load JPG <input checked="" type="checkbox"/>
88	27/09/19 17:35	General View		Load JPG <input checked="" type="checkbox"/>
89	27/09/19 17:35	General View		Load JPG <input checked="" type="checkbox"/>
90	27/09/19 17:35	General View		Load JPG <input checked="" type="checkbox"/>
91	27/09/19 17:35	General View		Load JPG <input checked="" type="checkbox"/>
92	27/09/19 17:35	General View		Load JPG <input checked="" type="checkbox"/>
93	27/09/19 17:35	Odometer Reading		Load JPG <input checked="" type="checkbox"/>
94	27/09/19 17:35	Chassis Number		Load JPG <input checked="" type="checkbox"/>
95	27/09/19 17:35	General View		Load JPG <input checked="" type="checkbox"/>
96	27/09/19 17:35	General View		Load JPG <input checked="" type="checkbox"/>
97	27/09/19 17:35	General View		Load JPG <input checked="" type="checkbox"/>
98	27/09/19 17:35	General View		Load JPG <input checked="" type="checkbox"/>
99	27/09/19 17:35	General View		Load JPG <input checked="" type="checkbox"/>

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
100	27/09/19 17:35	General View	 Load JPG	<input checked="" type="checkbox"/>
101	27/09/19 17:35	General View	 Load JPG	<input checked="" type="checkbox"/>
102	27/09/19 17:35	General View	 Load JPG	<input checked="" type="checkbox"/>
103	27/09/19 17:35	General View	 Load JPG	<input checked="" type="checkbox"/>
104	27/09/19 17:35	General View	 Load JPG	<input checked="" type="checkbox"/>
105	27/09/19 17:35	General View	 Load JPG	<input checked="" type="checkbox"/>
106	27/09/19 17:35	General View	 Load JPG	<input checked="" type="checkbox"/>
107	27/09/19 17:35	General View	 Load JPG	<input checked="" type="checkbox"/>
108	27/09/19 17:35	General View	 Load JPG	<input checked="" type="checkbox"/>
109	27/09/19 17:35	General View	 Load JPG	<input checked="" type="checkbox"/>
110	27/09/19 17:35	General View	 Load JPG	<input checked="" type="checkbox"/>
111	27/09/19 17:35	General View	 Load JPG	<input checked="" type="checkbox"/>
112	27/09/19 17:35	General View	 Load JPG	<input checked="" type="checkbox"/>
113	27/09/19 17:35	General View	 Load JPG	<input checked="" type="checkbox"/>
114	27/09/19 17:35	General View	 Load JPG	<input checked="" type="checkbox"/>
115	27/09/19 17:35	General View	 Load JPG	<input checked="" type="checkbox"/>
116	27/09/19 17:36	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
117	27/09/19 17:36	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
118	27/09/19 17:36	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
119	27/09/19 17:36	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
120	27/09/19 17:36	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
121	27/09/19 17:36	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
122	27/09/19 17:36	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
123	27/09/19 17:36	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
124	27/09/19 17:36	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
125	27/09/19 17:36	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
126	27/09/19 17:36	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
127	27/09/19 17:36	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
128	27/09/19 17:36	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
129	27/09/19 17:36	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
130	27/09/19 17:36	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
131	27/09/19 17:36	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
132	27/09/19 17:36	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
133	27/09/19 17:36	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
134	27/09/19 17:36	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
135	27/09/19 17:36	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
136	27/09/19 17:36	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
137	27/09/19 17:36	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
138	27/09/19 17:36	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
139	27/09/19 17:36	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
140	27/09/19 17:36	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
141	27/09/19 17:36	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
142	27/09/19 17:36	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
143	27/09/19 17:36	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
144	27/09/19 17:36	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
145	27/09/19 17:36	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
146	27/09/19 17:36	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
147	27/09/19 17:36	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
148	27/09/19 17:36	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
149	27/09/19 17:36	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
150	27/09/19 17:36	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
151	27/09/19 17:36	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
152	27/09/19 17:36	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
153	27/09/19 17:36	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
154	27/09/19 17:36	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
155	27/09/19 17:36	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
156	27/09/19 17:36	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
157	27/09/19 17:36	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
158	27/09/19 17:36	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
159	27/09/19 17:36	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
160	27/09/19 17:36	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
161	27/09/19 17:36	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
162	27/09/19 17:36	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
163	27/09/19 17:36	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
164	27/09/19 17:36	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
165	27/09/19 17:36	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
166	27/09/19 17:36	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
167	27/09/19 17:36	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
168	27/09/19 17:36	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
169	27/09/19 17:36	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
170	27/09/19 17:36	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
171	27/09/19 17:36	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
172	27/09/19 17:36	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
173	27/09/19 17:36	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
174	27/09/19 17:36	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
175	27/09/19 17:36	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
176	27/09/19 17:36	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
177	27/09/19 17:36	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
178	27/09/19 17:36	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
179	27/09/19 17:36	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
180	27/09/19 17:36	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
181	27/09/19 17:36	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
182	27/09/19 17:36	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
183	27/09/19 17:36	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
184	27/09/19 17:36	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
185	27/09/19 17:36	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
186	27/09/19 17:36	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
187	27/09/19 17:36	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
188	27/09/19 17:36	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
189	27/09/19 17:36	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
190	27/09/19 17:36	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
191	27/09/19 17:36	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
192	27/09/19 17:36	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
193	27/09/19 17:36	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
194	27/09/19 17:36	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
195	27/09/19 17:36	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
196	27/09/19 17:36	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
197	27/09/19 17:36	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
198	27/09/19 17:36	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
199	27/09/19 17:36	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
200	27/09/19 17:36	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
201	27/09/19 17:36	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
202	27/09/19 17:36	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
203	27/09/19 17:36	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
204	27/09/19 17:36	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
205	27/09/19 17:36	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
206	27/09/19 17:36	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
207	27/09/19 17:36	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
208	27/09/19 17:36	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
209	27/09/19 17:36	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
210	27/09/19 17:36	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
211	27/09/19 17:36	Photographs of Damaged Parts		<input checked="" type="checkbox"/>

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
212	27/09/19 17:36	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
213	27/09/19 17:36	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
214	27/09/19 17:36	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
215	27/09/19 17:36	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
216	27/09/19 17:36	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
217	27/09/19 17:36	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
218	27/09/19 17:36	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
219	27/09/19 17:36	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
220	27/09/19 17:36	After Repair Photo		<input checked="" type="checkbox"/>
221	27/09/19 17:36	After Repair Photo		<input checked="" type="checkbox"/>
222	27/09/19 17:36	After Repair Photo		<input checked="" type="checkbox"/>
223	27/09/19 17:36	After Repair Photo		<input checked="" type="checkbox"/>
224	27/09/19 17:36	After Repair Photo		<input checked="" type="checkbox"/>
225	27/09/19 17:36	After Repair Photo		<input checked="" type="checkbox"/>
226	27/09/19 17:36	After Repair Photo		<input checked="" type="checkbox"/>
227	27/09/19 17:36	After Repair Photo		<input checked="" type="checkbox"/>
228	27/09/19 17:36	After Repair Photo		<input checked="" type="checkbox"/>
229	27/09/19 17:36	After Repair Photo		<input checked="" type="checkbox"/>
230	27/09/19 17:36	After Repair Photo		<input checked="" type="checkbox"/>
231	27/09/19 17:36	After Repair Photo		<input checked="" type="checkbox"/>
232	27/09/19 17:36	After Repair Photo		<input checked="" type="checkbox"/>
233	27/09/19 17:36	After Repair Photo		<input checked="" type="checkbox"/>
234	27/09/19 17:36	After Repair Photo		<input checked="" type="checkbox"/>
235	27/09/19 17:36	After Repair Photo		<input checked="" type="checkbox"/>
236	27/09/19 17:36	After Repair Photo		<input checked="" type="checkbox"/>
237	27/09/19 17:36	After Repair Photo		<input checked="" type="checkbox"/>
238	27/09/19 17:36	After Repair Photo		<input checked="" type="checkbox"/>
239	27/09/19 17:36	After Repair Photo		<input checked="" type="checkbox"/>
240	27/09/19 17:36	After Repair Photo		<input checked="" type="checkbox"/>
241	27/09/19 17:36	After Repair Photo		<input checked="" type="checkbox"/>
242	27/09/19 17:36	After Repair Photo		<input checked="" type="checkbox"/>
243	27/09/19 17:36	After Repair Photo		<input checked="" type="checkbox"/>
244	27/09/19 17:36	After Repair Photo		<input checked="" type="checkbox"/>
245	27/09/19 17:36	After Repair Photo		<input checked="" type="checkbox"/>
246	27/09/19 17:36	After Repair Photo		<input checked="" type="checkbox"/>
247	27/09/19 17:36	After Repair Photo		<input checked="" type="checkbox"/>
248	27/09/19 17:36	After Repair Photo		<input checked="" type="checkbox"/>
249	27/09/19 17:36	After Repair Photo		<input checked="" type="checkbox"/>
250	27/09/19 17:36	After Repair Photo		<input checked="" type="checkbox"/>
251	27/09/19 17:36	After Repair Photo		<input checked="" type="checkbox"/>
252	27/09/19 17:36	After Repair Photo		<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	13/09/19 14:22	EMAIL FROM III DD 12092019		<input type="checkbox"/>
2	13/09/19 14:22	TP GIA REPORT.		<input type="checkbox"/>
3	16/09/19 16:40	TP ESTIMATE- MARKED.		<input type="checkbox"/>
4	09/11/19 14:38	LOD		<input type="checkbox"/>
5	09/11/19 14:38	Authorisation to Act		<input type="checkbox"/>
6	09/11/19 14:39	Workshop Invoice		<input type="checkbox"/>
7	09/11/19 14:39	Rental Invoice & Agreement.		<input type="checkbox"/>
8	09/11/19 14:39	LTA Search Fee		<input type="checkbox"/>
9	09/11/19 14:41	PARF_COE REBATE		<input type="checkbox"/>
10	04/12/19 11:44	DISCHARGE VOUCHER		<input type="checkbox"/>
11	04/12/19 11:44	GIRO FORM		<input type="checkbox"/>
No	Finalized On	India International Insurance Pte Ltd (HQ)	Thumbnail	Print
1	16/09/19 08:51	Singapore Accident Statement		<input type="checkbox"/>
2	05/11/19 18:23	Letter of Demand from Third Party TPD LOD FROM CARZ AUTO (SLX7484B)		<input type="checkbox"/>

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
<div style="border: 1px solid black; height: 40px; width: 100%;"></div>			
Show Remarks To: <input type="checkbox"/> Handling Insurer			
<small>Note: Remarks are private unless you show it to other parties.</small>			

LKK Auto Consultants Pte Ltd (Co Reg No: 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/III19016234/EPB3Q2

Date: 04/12/2019

REFERENCE

Handling Insurer: India International Insurance Pte Ltd	Policy No:	MCOM0015	
Claimant			
Vehicle No : SLX7404D	Insured Vehicle No :	SHA6575T	
Date of Loss: 11/09/2019	Nature of Claim:	TP	Claim No: MCT19090238

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLX7404D		
Make & Model:	TOYOTA C-HR HYBRID, 1.8 S CVT (A)	Engine No:	2ZR8361746
Reg. Date:	09/04/2018 (Man. Year: 2018)	Chassis No:	ZYX102103121
Colour:	Silver	Odometer:	0 km
Engine Capacity:	1797 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/60 R17	Rear Tyre Size:	215/60 R17
Front Left Side:	Bridgestone 5 mm	Rear Left Side:	Bridgestone 5 mm
Front Right Side:	Bridgestone 5 mm	Rear Right Side:	Bridgestone 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	42,567.01	31,517.15	11,049.86	25.96
Miscellaneous Items	0.00	0.00	0.00	
Labour	6,710.00	3,710.00	3,000.00	44.71
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	49,277.01	35,227.15	14,049.86	28.51
Approved Total (Overridden) (S\$)		28,200.00		
(S\$)	49,277.01	28,200.00	21,077.01	42.77
+ GST 7.00/7.00% (S\$)	3,449.39	1,974.00	1,475.39	42.77
Nett Amount (S\$)	52,726.40	30,174.00	22,552.40	42.77
+ Car Rental (16.0 x S\$100.00/day) (S\$)		1,600.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		31,781.45		
Global Sum Settlement (S\$)		31,700.00		

INSPECTION

Date of Assignment:	12/09/2019	
Date Inspected:	13/09/2019	Inspected At:
		Carz Auto Services Pte Ltd (HQ) NO 61, WOODLANDS INDUSTRIAL PARK E9, #04-04 E9 PREMIUM SINGAPORE 75704
Estimated Period of Repair:	14.0 days	

Adjuster: CHEN TSUE YEE

Manager: CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

SPECIAL REMARKS

Market Value: \$90,000.00(est) less LTA Rebate: \$19,842.00(est) = Nett Value :\$70,158.00(est)

REPAIR DETAILS

Reference		
Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 06 Nov 2019)	
Parts: M1-SUV	TOYOTA C-HR HYBRID 1.8 S CVT (A) (Catalogue:Merimen Singapore 1.0)	
Labour: Repairer's	(Price-denominated Standard List)	
Print Code:	(Unsubmitted, no print-code for SLX7404D)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.		

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BONNET	Dented	1,321.80 FL	*1,321.80 FL
2	1		*BONNET LOCK	Bent	115.25 FL	*115.25 FL
3	1		*BONNET LOCK BRACE PANEL	Bent	185.35 FL	*185.35 FL
4	2		*BONNET HINGE	Bent	129.10 FL	*129.10 FL
5	1		*BONNET INSULATOR	Crushed	281.15 FL	*281.15 FL
6	1		*BONNET STAND	Not Necessary	195.15 FL	*-FL
7	1		*BONNET STAND BRACKET	Bent	58.55 FL	*58.55 FL
8	1		*FRONT NUMBER PLATE GARNISH	Not Necessary	155.65 FL	*-FL
9	1		*FRONT BUMPER	Dented	584.25 FL	*584.25 FL
10	1		*FRONT BUMPER LOWER	Cut	505.15 FL	*505.15 FL
11	1		*FRONT BUMPER CENTER GUIDE	Broken	183.65 FL	*183.65 FL
12	2		*FRONT BUMPER SIDE RETAINER	Broken	230.36 FL	*230.36 FL
13	1		*FRONT BUMPER SIDE AIR SCOOP	O/S Broken	171.50 FL	*85.70 FL
14	1		*FRONT BUMPER TOW COVER	Bent	28.90 FL	*28.90 FL
15	1		*FRONT BUMPER TOP BEAM	Bent	145.75 FL	*145.75 FL
16	1		*FRONT BUMPER REINFORCEMENT	Dented	296.85 FL	*296.85 FL
17	1		*FRONT BUMPER REINFORCEMENT SPONGE	Broken	109.25 FL	*109.25 FL
18	2		*FRONT BUMPER REINFORCEMENT BRACKET	Bent	402.10 FL	*402.10 FL
19	1		*FRONT BUMPER LOWER BEAM	Dented	465.35 FL	*465.35 FL
20	1		*FRONT BUMPER LOWER BEAM SPONGE	Broken	98.15 FL	*98.15 FL
21	2		*FRONT BUMPER LOWER BEAM BRACKET	Dented	176.90 FL	*176.90 FL
22	2		*FRONT BUMPER UNDER COVER	Broken (1 PCS ONLY)	354.76 FL	*177.38 FL
23	2		*FRONT BUMPER FOG LAMP COVER	Broken (1 PCS ONLY)	270.92 FL	*89.20 FL
24	2		*FRONT NUMBER SIDE LOWER RETAINER	Not Necessary	113.66 FL	*-FL
25	1		*FRONT RADIATOR GRILLE	Cracked	434.21 FL	*434.21 FL
26	1		*FRONT RADIATOR GRILLE LOGO	Necessary	283.63 FL	*283.63 FL
27	1		*FRONT RADIATOR GRILLE INNER BASE	Not Necessary	183.72 FL	*-FL
28	1		*FRONT IMPACT SENSOR	Not Necessary	1,195.67 FL	*-FL
29	1		*FRONT IMPACT SENSOR WIRE HARNESS	Cut / Torn	1,455.83 FL	*1,019.89 FL
30	2		*FRONT HEAD LAMP	O/S Crushed / N/S Broken	8,793.06 FL	*5,642.80 FL
31	1		*FRONT HEAD LAMP BULB (HID)RH	Broken	355.71 FL	*355.71 FL
32	1		*FRONT HEAD LAMP HID MODULE RH	Broken	581.45 FL	*581.45 FL
33	1		*FRONT HEAD LAMP LOWER PANEL RH	Bent	110.15 FL	*110.15 FL
34	1		*FRONT SUPPORT PANEL TOP CENTER	Dented	232.33 FL	*232.33 FL
35	1		*FRONT SUPPORT PANEL TOP GARNISH	Crushed	195.89 FL	*195.89 FL
36	1		*FRONT SUPPORT PANEL STAND	O/S Dented	571.42 FL	*285.71 FL
37	1		*FRONT SUPPORT PANEL BOTTOM	Twisted	288.63 FL	*288.63 FL
38	1		*FRONT SUPPORT PANEL BOTTOM GARNISH	Crushed	135.18 FL	*135.18 FL
39	1		*FRONT A/C CONDENSER	Bent	1,303.70 FL	*1,218.59 FL
40	1			Bent	707.21 FL	*565.00 FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
			*FRONT A/C CONDENSER LIQUID PIPE WITH LOCK			
41	1		*FRONT A/C CONDENSER SIDE GARNISH (2 PCS)	Crushed (1 PCS ONLY)	196.70 FL	*98.35 FL
42	1		*FRONT A/C FAN BLADE	Not Necessary	158.11 FL	*- FL
43	1		*FRONT RADIATOR	Twisted	1,841.15 FL	*1,718.80 FL
44	1		*FRONT RADIATOR COWLING	Not Necessary	291.38 FL	*- FL
45	1		*FRONT RADIATOR FAN BLADE	Not Necessary	233.45 FL	*- FL
46	1		*FRONT RADIATOR FAN MOTOR	Not Necessary	585.60 FL	*- FL
47	1		*FRONT RADIATOR RESERVOIR TANK	Broken	192.45 FL	*177.00 FL
48	1		*FRONT RADIATOR TOP HOSE	Not Necessary	45.15 FL	*- FL
49	1		*FRONT RADIATOR TOP EXTANSION HOSE	Not Necessary	69.70 FL	*- FL
50	1		*FRONT WASHER TANK	Crushed	198.45 FL	*165.00 FL
51	1		*FRONT WASHER TANK MOTOR	Not Necessary	185.85 FL	*- FL
52	1		*FRONT WASHER TANK PANEL SIDE RH	Dented	255.78 FL	*255.78 FL
53	1		*FRONT FENDER RH	Crushed	826.10 FL	*691.00 FL
54	1		*FRONT FENDER SPLASHIELD RH	Crushed	189.25 FL	*189.25 FL
55	1		*FRONT FENDER INNER PANEL RH	Dented	681.83 FL	*545.80 FL
56	1		*FRONT FENDER WHEEL ARCH GARNISH RH	Bent	155.75 FL	*155.75 FL
57	1		*FRONT FENDER EMBLEM HYBRID RH	Necessary	68.15 FL	*68.15 FL
58	1		*FRONT FENDER SPLASHIELD SPOILER RH	Not Necessary	58.35 FL	*- FL
59	2		*FRONT AIR BAG IMPACT SENSOR	Necessary	384.86 FL	*384.86 FL
60	1		*FRONT DOOR RH	Dented	1,350.25 FL	*1,256.00 FL
61	1		*FRONT DOOR PROTECTOR RH	Dented	281.85 FL	*281.85 FL
62	1		*FRONT WIPER GARNISH	Not Necessary	635.45 FL	*- FL
63	1		*FRONT WIPER GARNISH SIDE RH	Crushed	88.05 FL	*88.05 FL
64	1		*FRONT WINDSCREEN GLASS WITH SENSOR	Bent	2,711.65 FL	*1,821.00 FL
65	2		*FRONT WINDSCREEN GLASS MOULDING	Necessary	220.80 FL	*220.80 FL
66	1		*FRONT WINDSCREEN INNER SEAL	Necessary	65.30 FL	*65.30 FL
67	1		*FRONT WHEEL SHOCK ABSORBER RH	Dented	441.85 FL	*441.85 FL
68	1		*FRONT WHEEL KNUCKLE ARM RH	Dented	479.15 FL	*479.15 FL
69	1		*FRONT WHEEL KNUCKLE BEARING WITH HUB RH	Necessary	415.35 FL	*374.00 FL
70	1		*FRONT WHEEL LOWER ARM RH	Bent	471.35 FL	*471.35 FL
71	1		*FRONT WHEEL LOWER ARM LINK RH	Not Necessary	196.20 FL	*- FL
72	1		*FRONT ENGINE MOUNTING TOP RH	Not Necessary	198.10 FL	*- FL
73	1		*FRONT DASHBOARD	Broken	1,951.30 FL	*1,218.00 FL
74	1		*FRONT DASHBOARD AIR BAG	Broken	3,120.70 FL	*2,821.00 FL
75	1		*FRONT STEERING AIR BAG	Broken	2,817.30 FL	*2,721.00 FL
76	1		*FRONT STEERING AIR BAG CONTACT PIECE	Necessary	1,028.45 FL	*390.00 FL
77	1		*FRONT AIR BAG CONTROL MODULE	Necessary	1,213.65 FL	*970.88 FL
78	1		*FRONT SAFETY BELT (2 PCS)	Jammed	550.25 FL	*550.25 FL
79	2		*FRONT ROOF-TOP AIR BAG	Broken	3,105.70 FL	*2,870.00 FL
80	2		*REAR SAFETY BELT	Jammed	1,574.60 FL	*640.00 FL
81	1		*FRONT ROOF-TOP LINING	Crushed	2,108.70 FL	*1,680.00 FL
82	1		*BONNET INSULATOR CLIP (8 PCS)	Necessary	44.00 FS	*15.00 FS
83	1		*FRONT NUMBER PLATE WITH GARNISH	Necessary	50.00 FS	*40.00 FS
84	8		*FRONT BUMPER CLIP	Necessary	44.00 FS	*30.00 FS
85	5		*FRONT SUPPORT PANEL TOP GARNISH CLIP	Necessary	27.50 FS	*10.00 FS
86	8		*FRONT FENDER SPLASHIELD CLIP RH	Necessary	44.00 FS	*20.00 FS
87	8		*FRONT FENDER WHEEL ARCH GARNISH CLIP RH	Necessary	44.00 FS	*20.00 FS
88	1		*FRONT WINDSCREEN SEALANT	Necessary	50.00 FS	*40.00 FS
89	1		*FRONT ERP BRACKET	Necessary	25.00 FS	*20.00 FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount	
90	1		*FRONT WHEEL TYRE RH	Broken	250.00 FS	*200.00 FS	
91	1		*FRONT WHEEL TYRE RIM RH	Scratched	700.00 FS	*500.00 FS	
					Sub Total (S\$)	56,329.85	41,724.53
					- List Item Discount on L Items 25.00/25.00% (S\$)	13,762.84	10,207.38
					Total Parts (S\$)	42,567.01	31,517.15

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO RENEW FRONT DAMAGED PARTS ,REPLACED AND REALIGNED HYDRAULIC ,ALIGNED ALL PARTS	New	1,800.00	1,200.00
2	TO RESPRAY AFFECTED AREAS	New	1,600.00	1,100.00
3	TOWING	New	50.00	50.00
4	TO TUFFCOAT AFFECTED AREA	New	250.00	30.00
5	TO REPLACE FRONT WINDSCREEN	New	120.00	120.00
6	TO REPLACE ENGINE MOUNTING /GEAR BOX MOUNTING	New	250.00	0.00
7	TO REMOVE/REPLACE AIRCON CONDENSOR ,VACUUM ,TOP UP AIRCON GAS	New	120.00	120.00
8	TO REMOVE/REFIX /REPLACE DASHBOARD	New	350.00	150.00
9	TO REMOVE/REFIX INTERIOR UPHOLSTERY	New	100.00	50.00
10	TO REMOVE/REPLACE FRONT UNDERCARRIAGE	New	350.00	150.00
11	TO REMOVE/REFIX WIRING CHECKS	New	60.00	30.00
12	TO REMOVE/REPLACE DOOR MECHANISM	New	100.00	50.00
13	TO REPROGRAM ALL REPLATED HYBRID SYSTEM	New	350.00	300.00
14	TO REMOVE AND REPLACE AIRBAG	New	450.00	200.00
15	TO RESET ALL AIRBAG NECESSARY SYSTEM	New	480.00	100.00
16	TO COMPUTERISED FOUR WHEEL ALIGNMENT	New	80.00	60.00
17	TO REMOVE AND REPLACE ROOF-TOP LINING	New	200.00	0.00
Gross Labour Cost (S\$)			6,710.00	3,710.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >