

Vehicle: SJY3788R

Make & Model: Suzuki SX4

Chassis No: _____

S/N	Parts/Labour	QTY	Unit Price	Price	Recommend
1	Left Front Head Lamp			380.00	120 /
2	Left Front Fender			282.00	12 X
3	Left Front Fender Inner Shield Chips			25.00SN	12 / S.N
4	Left Front Fender VVT word			20.00	12 X
5	Front Bumper 652			790.00	12 / 12 /
6	Front Bumper Chips	152		30.00SN	12 / S.N
7	Front Bumper Retainer Left			25.00	12 X
8	Front Bumper Fog Lamp (Left)			160.00	12 X
9	Front Bumper Fog Lamp Garnish (Left)			28.00	12 X
10	Front Bumper Lower Lip			356.00	12 X
11					
12					
13					
14					P-1032
15					152.
16					P-877.20
17					S.N-55.00
18					L-1020.00
19					1952.2
20					
21					
22					
23					

Labour					
1	Anti Rust Proofing			\$ 60.00	11X
2	Check Wiring			\$ 60.00	20
3	Panel Beating			\$ 600.00	400
4	Paint Work			\$ 1,000.00	600

STYTECH AUTO PTE. LTD.
 2 Kaki Bukit Ave 2 #02-00 01-03
 Kaki Bukit Autohub Singapore 417921
 Tel: 6444 8125 Fax: 6445 3310
 GST Reg. No.: 201601539K
 Co. Reg. No.: 201601539K

not added
 2/8 ~~1550~~
 82
 13/8/19

LKK Auto Consultants hence notify
 the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: