

Ash



TeamWork Garage Pte Ltd
 53 Ubi Avenue 1 #01-23/24 Spore 408934
 Paya Ubi Industrial Park
 Tel : 6844 2475
 E-mail : claims@teamworkgarage.com
 ROC number : 201015366H
REPAIR PERFORMA INVOICE

AIG Singapore
 78 Shenton Way
 Singapore 079120

Vehicle number	SLK2004B	2017
Make / Model	TOYOTA/ALTIS	
Chassis number	MR053REH104562204	
Accident date	05 September 2019	
Reference	1909-21	

Qty Particulars Unit Price - SGD \$

Qty	Particulars	Unit Price - SGD \$
<u>PARTS REPLACEMENT - LIST ITEMS</u>		
1	BONNET X <i>svc</i>	1059.67 X
1	BONNET LOCK X <i>svc</i>	144.38 X
1	BONNET LOCK STRIKER X <i>svc</i>	98.10 X
1	FRONT BUMPER de <i>svc</i>	645.84 <i>581</i>
<i>1 pc</i>	FRONT BUMPER RETAINER <i>acc / RH / LH - X @ 81</i>	126.50 <i>81</i>
1	FRONT BUMPER REINFORCEMENT X <i>svc</i>	454.20 X
1	FRONT BUMPER SPONGE X <i>svc</i>	185.84 X
1	FRONT BUMPER LOWER GRILLE X <i>svc</i>	178.25 X
1	FRONT GRILLE CR <i>svc</i>	439.19 /
1	FRONT GRILLE EMBLEM acc <i>svc</i>	162.63 <i>43</i>
1	FRONT RH FOG LAMP COVER X <i>svc</i>	116.15 X
1	FRONT RH FOG LAMP X <i>svc</i>	373.75 X
1	FRONT RH HEADLAMP CR <i>svc</i>	977.50 <i>850</i>
1	FRONT RH FENDER bt <i>svc</i>	914.25 <i>781</i>
1	FRONT RH FENDER INNER SHIELD de <i>svc</i>	253.00 <i>182</i>
1	FRONT RH FENDER EMBLEM LOGO-VVTI acc <i>svc</i>	45.00 /
1	FRONT RH SHOCK ABSORBER X <i>svc</i>	557.70 X
1	FRONT RH KNUCKLE ARM st <i>svc</i>	603.75 <i>521</i>
1	FRONT RH LOWER ARM X <i>svc</i>	616.40 X
1	FRONT RH KNUCKLE BEARING bt <i>svc</i>	155.25 /
		8107.35
	Less 25 %	2026.84
	Subtotal	6080.51
	Balance C/F	6080.51
<u>PARTS REPLACEMENT - SPECIAL NETT ITEMS</u>		
1 SET	FRONT BUMPER CLIP acc <i>svc</i>	40.00
1 SET	FRONT FENDER INNER SHIELD CLIP acc <i>svc</i>	30.00
1 BOT	BRAKE FUILD X <i>acc</i>	50.00
1	RIM svc <i>acc</i>	600.00 <i>300</i>
	Subtotal	720.00
	Balance C/F	6800.51
<u>LABOUR AND MISCELLANEOUS CHARGES</u>		
	Balance B/F	6800.51
1	CHECK WIRING AND LIGHTNING SYSTEM	60.00 <i>30</i>
2	COMPUTERISED AND CHECK FRONT WHEEL ALIGNMENT	150.00 <i>60</i>
3	REMOVE AND REPLACE FRONT UNDERCARRIAGE PARTS	200.00 <i>80</i>

3678.44
 258
2758.83

} 420

4	PANEL BEATING ON AFFECTED AREAS	1000.00	400	500
5	SPRAY PAINTING ON AFFECTED AREAS	1000.00	400	500
6	APPLY ANTI RUST ON AFFECTED AREAS	150.00	0	
Subtotal		2560.00		
Grand total		9360.51		<u>1210</u>

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Rasul
Hp 90010068
4 days
Hs

13/09/19 @ 1500

Ready after repair

2758.83
420.00
1210.00
4388.83
20%
3511.06
42-3,500

4 days