



**TeamWork Garage Pte Ltd**  
 53 Ubi Avenue 1 #01-23/24 Spore 408934  
 Paya Ubi Industrial Park  
 Tel : 6844 2475  
 E-mail : claims@teamworkgarage.com  
 ROC number : 201015366H  
**REPAIR PERFORMA INVOICE**

**AIG Singapore**  
 78 Shenton Way  
 Singapore 079120

|                |                   |
|----------------|-------------------|
| Vehicle number | SLK2004B          |
| Make / Model   | TOYOTA/ALTIS      |
| Chassis number | MR053REH104562204 |
| Accident date  | 05 September 2019 |
| Reference      | 1909-21           |

| Qty   | Particulars                                  | Unit Price - SGD \$ |
|---|--|---------------------|
| <u>PARTS REPLACEMENT - LIST ITEMS</u>         |  |                     |
| 1   | BONNET ✕                                     | 1059.67             |
| 1   | BONNET LOCK ✕                                | 144.38              |
| 1   | BONNET LOCK STRIKER ✕                        | 98.10               |
| 1   | FRONT BUMPER de -                            | 645.84              |
| 1/c/2   | FRONT BUMPER RETAINER nee / RH / LH - X      | 126.50              |
| 1   | FRONT BUMPER REINFORCEMENT ✕                 | 454.20              |
| 1   | FRONT BUMPER SPONGE ✕                        | 185.84              |
| 1   | FRONT BUMPER LOWER GRILLE ✕                  | 178.25              |
| 1   | FRONT GRILLE ✕ cra /                         | 439.19              |
| 1   | FRONT GRILLE EMBLEM ✕ nee /                  | 162.63              |
| 1   | FRONT RH FOG LAMP COVER ✕                    | 116.15              |
| 1   | FRONT RH FOG LAMP ✕                          | 373.75              |
| 1   | FRONT RH HEADLAMP cra /                      | 977.50              |
| 1   | FRONT RH FENDER bt -                         | 914.25              |
| 1   | FRONT RH FENDER INNER SHIELD de /            | 253.00              |
| 1   | FRONT RH FENDER EMBLEM LOGO-VVTI nee /       | 45.00               |
| 1   | FRONT RH SHOCK ABSORBER ✕                    | 557.70              |
| 1   | FRONT RH KNUCKLE ARM ?                       | 603.75              |
| 1   | FRONT RH LOWER ARM ✕                         | 616.40              |
| 1   | FRONT RH KNUCKLE BEARING ?                   | 155.25              |
|   |  | 8107.35             |
|   | Less 25 %                                    | 2026.84             |
|   | Subtotal                                     | 6080.51             |
|   | Balance C/F                                  | 6080.51             |
| <u>PARTS REPLACEMENT - SPECIAL NETT ITEMS</u> |  |                     |
| 1 SET   | FRONT BUMPER CLIP nee /                      | 40.00               |
| 1 SET   | FRONT FENDER INNER SHIELD CLIP nee /         | 30.00               |
| 1 BOT   | BRAKE FUILD ✕                                | 50.00               |
| 1   | RIM sur /                                    | 600.00 300          |
|   | Subtotal                                     | 720.00              |
|   | Balance C/F                                  | 6800.51             |
| <u>LABOUR AND MISCELLANEOUS CHARGES</u>       |  |                     |
|   | Balance B/F                                  | 6800.51             |
| 1   | CHECK WIRING AND LIGHTNING SYSTEM            | 60.00 30            |
| 2   | COMPUTERISED AND CHECK FRONT WHEEL ALIGNMENT | 150.00 60           |
| 3   | REMOVE AND REPLACE FRONT UNDERCARRIAGE PARTS | 200.00 80           |

|   |                                   |         |                |     |
|---|-----------------------------------|---------|----------------|-----|
| 4 | PANEL BEATING ON AFFECTED AREAS   | 1000.00 | <del>400</del> | 500 |
| 5 | SPRAY PAINTING ON AFFECTED AREAS  | 1000.00 | <del>400</del> | 500 |
| 6 | APPLY ANTI RUST ON AFFECTED AREAS | 150.00  | 40             |     |
|   | Subtotal                          | 2560.00 |                |     |
|   | Grand total                       | 9360.51 |                |     |

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
 Signature:  
 Date:

Resur  
 Hp 90010068  
 4 days  
 H/s  
 13/09/19 @ 1500  
 Ready after repair