

ESTEEM PERFORMANCE PTE LTD

Bik 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536.
Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

Repair Estimates

SME 9172 Y

| | | | | |
|------------------|-----------------------------|----|-----------|----------|
| Parts | (a) Cost / List Price Items | \$ | 8,384.98 | 5,140.13 |
| | Plus/Less 25% | \$ | 2,096.25 | |
| | Total of Cost / List | \$ | 6,288.74 | 4,080.10 |
| | (b) Nett Price Items | | | |
| | Less | | | |
| | Total of Nett Item | | | |
| | (c) Special Nett Items | \$ | 1,490.00 | 560.00 |
| Total Parts Cost | | \$ | 7,778.74 | 4,630.10 |
| Labour | | \$ | 4,150.00 | 1,690.00 |
| Total | | \$ | 11,928.74 | 6,320.10 |

Not Authorized
Resurvey By pain

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

86320.10

The above total will be subjected to 7% G.S.T.

Name of Surveyor

Kenneth

Company

LKK

Survey conducted on

13/9/11

at

Remarks By Surveyor

(a) The repair of this vehicle is ~~authorized~~ / is not authorized until further notice.

(b) Recommended Days of Repair : 6 day(s)


(c) Resurvey : Required / ~~Not Required~~

(d) Excess : \$

(e) Signature of surveyor

Le

Date: 13/9/11



ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536.

Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

Spare Parts

Vehicle No. : SME 9172 Y
Make & Model : TOYOTA PRIUS ALPHA
Chassis No : ZVW400030063

Submit By : JENNY
Year Manufacture : 2018
Engine No. :

Cost / List

| S/No. | Part Description | Qty | Unit Price | Price | Disposition by Surveyor |
|-------|---|-----|------------|-------|-------------------------|
| 1 | Rear windscreen <i>Shattered</i> | 1 | \$1,473.80 | | ✓ |
| 2 | Rear windscreen solar film <i>na</i> | 1 | \$450.00 | S.N | 2 cosn |
| 3 | Private hirer sticker <i>na</i> | 1 | \$20.00 | S.N | ✓ |
| 4 | Rear windscreen moulding <i>na</i> | 1 | \$70.20 | | ✓ |
| 5 | Rear windscreen sealant <i>na</i> | 1 | \$50.00 | S.N | 4 cosn |
| 6 | Reverse sensor <i>Shan</i> | 1 | \$200.00 | S.N | ✓ |
| 7 | Rear number plate <i>na</i> | 1 | \$45.00 | S.N | ✓ |
| 8 | Rear bumper <i>Ry</i> | 1 | \$459.20 | | ✓ |
| 9 | Rear bumper clip <i>na</i> | 1 | \$38.90 | | ✓ |
| 10 | Rear bumper side retainer LH <i>sn</i> | 1 | \$121.70 | | X |
| 11 | Rear bumper side retainer RH <i>Dis</i> | 1 | \$121.70 | | ✓ |
| 12 | Rear bumper reflector LH <i>sn</i> | 1 | \$58.70 | | X |
| 13 | Rear bumper reflector RH <i>sn</i> | 1 | \$58.70 | | X |
| 14 | Tail door <i>Ry</i> | 1 | \$1,022.50 | | ✓ |
| 15 | Tail door lock <i>R</i> | 1 | \$391.60 | | X |
| 16 | Tail door plate garnish <i>wap</i> | 1 | \$498.30 | | ✓ |
| 17 | Tail door emblem <i>na</i> | 1 | \$67.10 | | ✓ |
| 18 | Wording "PRIUSCX" <i>na</i> | 1 | \$72.66 | | ✓ |
| 19 | Wording "HYBRID SYNERGY" <i>na</i> | 1 | \$48.57 | | ✓ |
| 20 | Tail door trim <i>sn</i> | 1 | \$577.85 | | X |
| 21 | Tail door trim clip <i>na</i> | 10 | \$42.10 | | X |
| 22 | Tail end panel <i>Ry</i> | 1 | \$678.10 | | ✓ |
| 23 | Tail end panel garnish <i>n.i</i> | 1 | \$154.60 | | ✓ |

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

Spare Parts


Vehicle No. : SME 9172 Y
Make & Model : TOYOTA PRIUS ALPHA
Chassis No : ZVW400030063ZVW400030063

Submit By : Carmen Lim
Year Manufacture : 2018
Engine No. :

Cost / List

| S/No. | Part Description | Qty | Unit Price | Price | Disposition by Surveyor |
|-------|---------------------------------------|-----|------------|-------|-------------------------|
| 24 | Tail end panel garnish clip <i>me</i> | 10 | \$39.20 | | <i>X</i> |
| 25 | Boot weatherstrip <i>Sn</i> | 1 | \$342.70 | | <i>X</i> |
| 26 | Tail lamp LH <i>Sn</i> | 1 | \$653.20 | | <i>X</i> |
| 27 | Tail lamp RH <i>CM</i> | 1 | \$653.20 | | <i>✓</i> |
| 28 | Tail lamp clip <i>me</i> | 10 | \$42.10 | | <i>✓</i> |
| 29 | Rear camara <i>Sn</i> | 1 | \$680.00 | S.N | <i>X</i> |
| 30 | Spare tyre board <i>Sn</i> | 1 | \$698.30 | | <i>X</i> |
| 31 | Front number plate <i>Sn</i> | 1 | \$45.00 | S.N | <i>✓</i> |
| 32 | | | | | |
| 33 | | | | | |
| 34 | | | | | |
| 35 | | | | | |
| 36 | | | | | |
| 37 | | | | | |
| 38 | | | | | |
| 39 | | | | | |
| 40 | | | | | |
| 41 | | | | | |
| 42 | | | | | |
| 43 | | | | | |
| 44 | | | | | |
| 45 | | | | | |
| 46 | | | | | |

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.



ESTEEM PERFORMANCE PTE LTD

Bik 5033 Ang Mo Kio, Ind Park 2 #01-251/259, 569536.
Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

Labour

Vehicle No. : **SME 9172 Y** Submit By : **Carmen Lim**
Make & Model : **TOYOTA PRIUS ALPHA** Year of Manufacture : **2018**

| S/No | Labour Description | Estimated Price | Adjusted Price |
|------|--|-----------------|----------------|
| 1 | TO RENEW DAMAGED PARTS & KNOCK OUT ACCIDENT REPAIR AREA. (REAR BUMPER, TAILDOOR, END PANEL, SPARE TYRE WELL PANEL, LHR FENDER, RHR FENDER, FRONT BUMPER) | \$1,600.00 | 800 |
| 2 | TO PUTTY, RESPRAY PAINT FOR AFFECTED ACCIDENT REPAIR AREA. (REAR BUMPER, TAILDOOR, END PANEL, SPARE TYRE WELL PANEL, LHR FENDER, RHR FENDER, FRONT BUMPER) | \$1,600.00 | 860 |
| 3 | To check wiring | \$50.00 | 20 |
| 4 | To remove & refit reverse sensor | \$120.00 | 50 |
| 5 | To remove & refit spare tyre, spare tyre board, carpet trim to assist work load. | \$150.00 | 60 |
| 6 | To remove & refit rear windscreen. | \$120.00 | ✓ |
| 7 | To tuff coat. | \$150.00 | 80 |
| 8 | To transfer boot mechanism to new boot | \$120.00 | 60 |
| 9 | To conduct water leakage tests to ensure proper air and sealing | \$120.00 | 20 |

Note: The above estimate of repair is based on visual assessment of the external affected areas. Any additional damages observed during the course of repair will be quote accordingly as a supplementary.

Labour

Vehicle No. : SME 9172 Y

Submit By : Carmen Lim

Make & Model : TOYOTA PRIUS ALPHA

Year of Manufacture : 2018

[illegible]

Note: The above estimate of repair is based on visual assessment of the external affected areas. Any additional damages observed during the course of repair will be quote accordingly as a supplementary.