

ALG



## ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536.  
Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

### Repair Estimates

SME 9172 Y

Parts	(a) Cost / List Price Items	\$	8,384.98
	Plus/Less 25%	\$	2,096.25
	<b>Total of Cost / List</b>	<b>\$</b>	<b>6,288.74</b>
	(b) Nett Price Items		
	Less		
	<b>Total of Nett Item</b>		
	(c) Special Nett Items	\$	1,490.00
<b>Total Parts Cost</b>		<b>\$</b>	<b>7,778.74</b>
<b>Labour</b>		<b>\$</b>	<b>4,150.00</b>
<b>Total</b>		<b>\$</b>	<b>11,928.74</b>

*Not Authorized  
Resurvey By pain*

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date:

The above total will be subjected to 7% G.S.T.

Name of Surveyor : Kenneth  
Company : LKK  
Survey conducted on : 13/9/11 at \_\_\_\_\_

#### Remarks By Surveyor

- (a) The repair of this vehicle is authorized / is not authorized until further notice.
- (b) Recommended Days of Repair : 5-6 day(s)
- (c) Resurvey : Required / Not Required
- (d) Excess : \$ \_\_\_\_\_
- (e) Signature of surveyor : Le Date: 13/9/11



## ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536.  
Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

### Spare Parts

Vehicle No. : **SME 9172 Y**  
Make & Model : **TOYOTA PRIUS ALPHA**  
Chassis No : **ZVW400030063**

Submit By : **JENNY**  
Year Manufacture : **2018**  
Engine No. :

### Cost / List

S/No.	Part Description	Qty	Unit Price	Price	Disposition by Surveyor
1	Rear windscreen <i>Shattered</i>	1	\$1,473.80		✓
2	Rear windscreen solar film	1	\$450.00	S.N	?
3	Private hirer sticker <i>nu</i>	1	\$20.00	S.N	✓
4	Rear windscreen moulding <i>nu</i>	1	\$70.20		✓
5	Rear windscreen sealant <i>nu</i>	1	\$50.00	S.N	<i>4052</i>
6	Reverse sensor <i>short</i>	1	\$200.00	S.N	✓
7	Rear number plate <i>nu</i>	1	\$45.00	S.N	✓
8	Rear bumper <i>Ry</i>	1	\$459.20		✓
9	Rear bumper clip <i>nu</i>	1	\$38.90		✓
10	Rear bumper side retainer LH	1	\$121.70		?
11	Rear bumper side retainer RH <i>nu</i>	1	\$121.70		✓
12	Rear bumper reflector LH <i>nu</i>	1	\$58.70		X
13	Rear bumper reflector RH <i>nu</i>	1	\$58.70		X
14	Tail door <i>Ry</i>	1	\$1,022.50		✓
15	Tail door lock	1	\$391.60		?
16	Tail door plate garnish <i>warp</i>	1	\$498.30		✓
17	Tail door emblem <i>nu</i>	1	\$67.10		✓
18	Wording "PRIUSCX" <i>nu</i>	1	\$72.66		✓
19	Wording "HYBRID SYNERGY" <i>nu</i>	1	\$48.57		✓
20	Tail door trim	1	\$577.85		?
21	Tail door trim clip	10	\$42.10		?
22	Tail end panel	1	\$678.10		?
23	Tail end panel garnish	1	\$154.60		?

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

**Spare Parts**

Vehicle No. : **SME 9172 Y**  
Make & Model : **TOYOTA PRIUS ALPHA**  
Chassis No : **ZVW400030063ZVW400030063**

Submit By : **Carmen Lim**  
Year Manufacture : **2018**  
Engine No. :

**Cost / List**

S/No.	Part Description	Qty	Unit Price	Price	Disposition by Surveyor
24	Tail end panel garnish clip	10	\$39.20		7
25	Boot weatherstrip	1	\$342.70		7
26	Tail lamp LH	1	\$653.20		7
27	Tail lamp RH <i>CM</i>	1	\$653.20		✓
28	Tail lamp clip <i>nu</i>	10	\$42.10		✓
29	Rear camara	1	\$680.00	S.N	7
30	Spare tyre board	1	\$698.30		7
31	Front number plate <i>RT</i>	1	\$45.00	S.N	✓
32					
33					
34					
35					
36					
37					
38					
39					
40					
41					
42					
43					
44					
45					
46					

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.



## ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536.  
Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

### Labour

Vehicle No. : **SME 9172 Y** Submit By : **Carmen Lim**  
Make & Model : **TOYOTA PRIUS ALPHA** Year of Manufacture : **2018**

S/No	Labour Description	Estimated Price	Adjusted Price
1	TO RENEW DAMAGED PARTS & KNOCK OUT ACCIDENT REPAIR AREA. (REAR BUMPER, TAILDOOR, END PANEL, SPARE TYRE WELL PANEL, LHR FENDER, RHR FENDER, FRONT BUMPER)	\$1,600.00	?
2	TO PUTTY, RESPRAY PAINT FOR AFFECTED ACCIDENT REPAIR AREA. (REAR BUMPER, TAILDOOR, END PANEL, SPARE TYRE WELL PANEL, LHR FENDER, RHR FENDER, FRONT BUMPER)	\$1,600.00	8601
3	To check wiring	\$50.00	201
4	To remove & refit reverse sensor	\$120.00	501
5	To remove & refit spare tyre, spare tyre board, carpet trim to assist work load.	\$150.00	601
6	To remove & refit rear windscreen.	\$120.00	✓
7	To tuff coat.	\$150.00	?
8	To transfer boot mechanism to new boot	\$120.00	601
9	To conduct water leakage tests to ensure proper air and sealing	\$120.00	201

*Note: The above estimate of repair is based on visual assessment of the external affected areas. Any additional damages observed during the course of repair will be quote accordingly as a supplementary.*

Labour

Vehicle No. : **SME 9172 Y**

Submit By : Carmen Lim

Make & Model : TOYOTA PRIUS ALPHA

Year of Manufacture : 2018

[illegible]

*Note: The above estimate of repair is based on visual assessment of the external affected areas. Any additional damages observed during the course of repair will be quote accordingly as a supplementary.*