

**Trans-cab Auto Services Pte Ltd**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

**SHD 755P**

561•7+  
411•9+  
547•8+  
1,677•2+  
82•4+  
95•8+  
313•1+  
745•8+  
404•56=  
4,840•26\*

Vehicle No.:

Chassis No.:

12 SEP 2019

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration:

4,840•26 x  
90•%  
4,356•234\*  
0•c

**PART**

1	1	BUMPER COVER REAR		30•+
2	1	BUMPER LOWER REAR		30•+
3	1	BUMPER BRACKET CTR REAR		5•+
4	1	BUMPER BRACKET SIDE RH REAR		40•=
5	1	BUMPER RETAINER RH REAR		270•*
6	1	BUMPER REFLECTOR RH		0•c
7	1	BUMPER BRACKET SIDE LH REAR		660•+
8	1	BUMPER RETAINER LH REAR		600•+
9	1	BUMPER REFLECTOR LH		60•+
10	1	BUMPER BEAM REAR		60•+
11	1	BUMPER BEAM BRACKET LH REAR		60•+
12	1	BUMPER BEAM BRACKET RH REAR		20•=
13	1	BOOT REAR		1,520•*
14	1	BOOT FINISHER		0•c
15	1	BOOT WHEATERSTRIP		
16	1	BOOT REFLECTOR LAMP LH		4,356•23+
17	1	BOOT REFLECTOR LAMP RH		270•+
18	1	BOOT BADGE 'RENAULT'		1,520•=
19	1	BOOT BADGE		6,146•23*
20	1	BOOT STRUT LH	+	145.10
21	1	BOOT STRUT RH	\$	145.10
22	1	BOOT HINGE LH	\$	254.20
23	1	BOOT HINGE RH	\$	253.80
24	1	BOOT INNER TRIM BOARD	\$	611.00
25	1	BOOT SWITCH	\$	113.00
26	1	BOOT LOCK	\$	246.60
27	1	BOOT LOCK CATCH	\$	41.70

P/P

} X