

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 755P

AAD1909-108

Not Authorized

Reserving B4 paint

Vehicle No.:
 Chassis No.: 12 SEP 2019
 Vehicle Make:
 Vehicle Model:
 Date of Accident :
 Third Party Insurer :
 Date of Registration:

SHD 755P
 VF1ABL15AUC283418
 RENAULT
 LATITUDE
 11.9.19
CHINA TAIPING
 15/12/2017

PART		LIST
1	1 BUMPER COVER REAR	\$ Bu 561.70 ✓
2	1 BUMPER LOWER REAR	\$ Na 411.90 ✓
3	1 BUMPER BRACKET CTR REAR	\$ S ₂ 98.10
4	1 BUMPER BRACKET SIDE RH REAR	\$ S ₂ 82.10
5	1 BUMPER RETAINER RH REAR	\$ S ₂ 59.80
6	1 BUMPER REFLECTOR RH	\$ S ₂ 16.60
7	1 BUMPER BRACKET SIDE LH REAR	\$ S ₂ 80.80
8	1 BUMPER RETAINER LH REAR	\$ S ₂ 54.20
9	1 BUMPER REFLECTOR LH	\$ S ₂ 16.60
10	1 BUMPER BEAM REAR	\$ B ₂ 547.80 ✓
11	1 BUMPER BEAM BRACKET LH REAR	\$ R 114.50 X
12	1 BUMPER BEAM BRACKET RH REAR	\$ R 100.90 X
13	1 BOOT REAR	\$ B ₂ 1,677.20 ✓
14	1 BOOT FINISHER	\$ S ₂ 344.70 X
15	1 BOOT WHEATERSTRIP	\$ S ₂ 178.20 X
16	1 BOOT REFLECTOR LAMP LH	\$ S ₂ 277.70 X
17	1 BOOT REFLECTOR LAMP RH	\$ S ₂ 277.70 X
18	1 BOOT BADGE 'RENAULT'	\$ Na 82.40 ✓
19	1 BOOT BADGE	\$ Na 95.80 ✓
20	1 BOOT STRUT LH	\$ S ₂ 145.10
21	1 BOOT STRUT RH	\$ S ₂ 145.10
22	1 BOOT HINGE LH	\$ R 254.20
23	1 BOOT HINGE RH	\$ R 253.80
24	1 BOOT INNER TRIM BOARD	\$ S ₂ 611.00
25	1 BOOT SWITCH	\$ S ₂ 113.00
26	1 BOOT LOCK	\$ R 246.60
27	1 BOOT LOCK CATCH	\$ R 41.70

Trans-cab Auto Services Pte Ltd

AAD1909-108

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 755P

28	2	LICENCE PLATE LAMP	\$	Sn	26.30	X
29	2	BOOT RUBBER PLUG	\$	Sn	139.30	X
30	1	TAILLAMP RH	\$	Sn	313.10	X
31	1	TAILLAMP PANEL RH	\$	R	401.40	X
32	1	TAILLAMP LH	\$	Mjcm	401.40	313.10
33	1	TAILLAMP PANEL LH	\$	R	401.40	X
34	1	OUTER PANEL REAR (End Panel)	\$	R	745.80	✓
35	1	OUTER PANEL REAR (End Panel)TRIM	\$	nd	404.56	✓
36	1	SPARE WHEEL PANEL (Luggage Floor Panel)	\$	R	1,229.40	X
37	1	SPARE WHEEL PANEL TRIM	\$	Sn	612.21	X
38	1	EXHAUST CAP REAR	\$	R	125.40	X

TOTAL	\$	11,689.47
10%	\$	1,168.95
	\$	10,520.52

Special Nett

1	1SET	PARKING AID	\$	Sn	700.00	X
2	1SET	REAR BUMPER CLIP	\$	R	66.00	✓
3	1SET	BUMPER BRACKET CTR CLIP	\$	R	33.00	✓
4	1SET	BUMPER BRACKET SIDE CLIP RH RR	\$	na	10.00	X
5	1SET	BUMPER RETAINER RH CLIP RR	\$	na	20.00	X
6	1SET	BUMPER BRACKET SIDE CLIP LH RR	\$	na	10.00	X
7	1SET	BUMPER RETAINER CLIP LH RR	\$	na	20.00	X
8	1SET	BUMPER LOWER REAR RIVET	\$	na	22.00	X
9	1SET	BUMPER LOWER REAR CLIP	\$	na	66.00	✓
10	1	EXHAUST MOUNTING REAR	\$	na	16.00	X
11	1SET	BOOT FINISHER CLIP	\$	na	24.20	X
12	1	BOOT STICKER "Trans-cab"	\$	na	30.00	✓
13	1	BOOT STICKER "6555-3333"	\$	na	30.00	✓
14	1	BOOT INNER TRIM CLIP	\$	na	45.00	X
15	1	SPARE TYRE RIM (ROUE 7J 16H 2547)	\$	Sn	385.00	X
16	1	SPARE TYRE	\$	Sn	330.00	X
17	1	TAILLAMP CLIP RH	\$	na	5.00	X
18	2	REAR WINDSCREEN SEALANT	\$	na	80.00	X
19	1	WINDSCREEN MOULDING	\$	na	100.00	X

Trans-cab Auto Services Pte Ltd

AAD1909-108

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 755P

20	1	REAR WINDSCREEN INNER SPONGE SEAL	\$	<i>nn</i> 100.00 X
21	1	TAILLAMP CLIP LH	\$	<i>nn</i> 5.00 ✓
22	1	Rear Bumper Protector	\$	<i>nn</i> 100.00 <i>gain</i>
TOTAL			\$	2,197.20
TOTAL PARTS			\$	12,717.72

LABOUR

Putty And Spray Painting Of The Affected Portion.	\$	6,000.00	<i>6001</i>
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	6,000.00	<i>6001</i>
To supply and re-do rear luggage floor panel insulation padding.	\$	<i>nn</i> 380.00	X
To transfer of bootlid fittings, attachments and perform water seepage test.	\$	170.00	<i>601</i>
To drop rear exhaust box, renew the same, to repair and realign centre exhaust pipe.	\$	<i>nn</i> 170.00	X
To transfer of rear end panel fittings, attachment and perform water seepage test.	\$	170.00	} <i>601</i>
To transfer of rear luggage floor panel fittings, attachment and perform water seepage test.	\$	170.00	
To Rust-Proofing Of The Affected Areas.	\$	170.00	<i>601</i>
To check steering geometry and computer wheel alignment	\$	<i>nn</i> 220.00	X
To repair and realign rear exhaust pipe.	\$	<i>nn</i> 170.00	X

Trans-cab Auto Services Pte Ltd

AAD1909-108

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 755P

To transfer of tire, rim and on wheel balancing.	\$	<i>nn</i> 170.00 X
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	<i>nn</i> 380.00 X
To transfer of rear windscreen glass to facilitate bodywork repair.	\$	<i>nn</i> 170.00 X
To transfer of rear bumper fittings, attachment and perform water seepage test.	\$	<i>nn</i> 380.00 X
To reinstall rear bumper parking sensor.	\$	170.00 <i>601</i>
To Check Electrical Lighting Concerned.	\$	170.00 <i>201</i>
Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.	\$	<i>nn</i> 380.00 X
TOTAL	\$	15,440.00
Over All Total	\$	28,157.72

(PART BY PART) Repair Days

20 DAYS

5 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: