

22/03/2007

ASS. REC. BY:

REF:

CS3/A1419016244/Acd3br

Special Instruction:

Surveyor:

Adnan

ASSIGNMENT (Office)

Murnan

Person (Person):

Chinlee Ying

of

A14

Date/Time:

12/9/19 @ 2:57pm

Estimated Cost:

Bill to:

OD ☒ / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

FBH 5138M

Insured:

GBH 7538D

at Workshop m/s

Coindymotor Workshop

Tel:

9636 6740

of

25 kaki Bukit Road 4 # 01-83 Synergy

Policy No:

1800110409

Claim No:

935135025436

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

06/09/2019

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

9:29am @ 13/9/19

Person Contacted:

Kent

Vehicle ☒ IN ☐ OUT

Date/Time	Action/Instruction
	FBH 5138 M - X
	GBH 7538D - X
	Dismantle: 19/9/2019.
	After repair: 27/9/2019.

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: _____
 at Workshop m/s _____
 of _____
 Insured: _____
 Policy No. _____
 Claims No. _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
 repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____
 IDAC Accident Rpt: _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: 4 days Res.: Yes or No
 Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: FBH5138M Yr Regn: 2013 July
 Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or
 Make: Honda CB400 c.c. 399
 Colour: white A/C: Insured / Std / NI / NA
 Sp. Reading: - T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: JH2NC4291BK300483
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: Inorder / Jammed / Leaked / Burnt or
 Brake: Inorder / Jammed / Leaked / Burnt or
 Modi: Nil / S/Rim / STD A/Rim or
 Tyre Size: F: 120/60 R17
 R: 160/60 R17
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or Diablo
 Front Rear
 R/Bal. 06 mm R/Bal. 06 mm
 L/Bal. _____ mm L/Bal. _____ mm
 D.O.A. _____ D.O.I. 13/09/19
 Survey held at Randy
 Des. of Damages: Frnt / Rear / O/S / N/S / UIC / Rooftop or
 The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction
TP ALG PRS.

RECEIVED 24 OCT 2019

MV :
 PV :
 Nett:

Date/Time, File Pass to? ☐ : Preli. Report

1) ☐ : Final Report

Date/Time, File Return to?

2)

Report Format: DAR

Report Sent / Mkt Co

Days Of Repair: 4

Resurvey No. of Trip: 2

Add Fee: ☐ Site Insp (\$) ☐ Interview (\$) ☐ Tech. Insp (\$) ☐ Travel and

Survey Fee: 180

Transportation: 3 + RS \$

Flores


Other

Total

180
11
191

Your password will expire in 3 days. [Click here to change it.](#)

PR-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHIC...

From: Chin, Lee-Ying
To: assignments, Admin A
Cc: Fong, Andy-SY
Sent: 9/12/2019 2:57:28 PM
Attachments:  190926.pdf

Hi LKK,

Kindly assist to survey by today if possible, bike in workshop.

Thanks.

Best Regards
Lee Ying, Chin
AIG
Claims | AIG Asia Pacific Insurance Pte. Ltd.
78 Shenton Way #08-16 Singapore 079120
Tel +(65) 6419 1947
Lee-Ying.Chin@aig.com | www.aig.sg

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

CATHERINE LIM LLC

林 ADVOCATES & SOLICITORS
翠 NOTARY PUBLIC - 公证官
玲 COMMISSIONER FOR OATHS- 宣誓官
律
師 CATHERINE C.L.LIM
馆 DIRECTOR
LL.B (HONS) SINGAPORE-法律系-律師
M.B.A. (BUSINESS LAW)-商业系-碩士

20 Havelock Road #03-01
Central Square Singapore 059765
UEN No. 201310922K

Tel: (65) 6438 5500
Fax: (65) 6438 0111
www.catherinelimllc.com
Email: info@catherinelimllc.com
CATHERINE LIM LLC is a law corporation
with limited liability

Your Ref: GBH 7538D
Our Ref: CL/190926/T/CMW.sg

10 September 2019

AIG Asia Pacific Insurance Pte Ltd
AIG Building
78 Shenton Way
#07-16
Singapore 079120
Attn: Motor Claims Department

via fax: 6415 3727 & By Hand

Muhammad Haikal Bin Zainol
382 Tampines Street 32
#03-121
Singapore 520382

CERTIFICATE OF POSTING
(Please be informed that all supporting documents
have been forwarded to your insurer.)

Dear Sir

**RE: NOTICE TO CONDUCT PRE-REPAIR INSPECTION WITHIN 2 WORKING DAYS PURSUANT TO
PRE-ACTION PROTOCOL FOR NON-INJURY MOTOR ACCIDENT CLAIMS (NIMA)**

**ACCIDENT INVOLVING FBH 5138M / GBH 7538D ON 6.9.2019 AT NEAR BLK 469 TAMPINES
STREET 44**

We are instructed by **Muhammad Haikal Bin Zainol** to notify you of a road traffic accident involving our client's vehicle No. FBH 5138M and vehicle No. GBH 7538D driven by you at the material time. A copy of the Singapore Accident Statement and/or Police Report is enclosed.

As a result of the accident, our client's motor vehicle has been damaged. Before our client proceed to repair the damaged motor vehicle, please let us know within **2 working days** of your receipt of this notice whether you/your insurer would like to conduct a pre-repair survey of the motor vehicle. If we do not receive any reply from you/your insurer within the stipulated timeline, our client shall proceed to repair the vehicle without further reference to you.

Please let us know your appointed surveyor.

Venue: Candymotor Workshop Pte Ltd
25 Kaki Bukit Road 4
#01-83
Singapore 417800

Contact: Ken @ 91559496

Yours faithfully


cc: client

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle**

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	886B
Vehicle Details	
Vehicle No.:	FBH5138M
Vehicle to be Exported:	No
Intended Deregistration Date:	18 Sep 2019
Vehicle Make:	HONDA
Vehicle Model:	CB400
Primary Colour:	White
Manufacturing Year:	2013
Engine No.:	NC42E1124622
Chassis No.:	JH2NC4291BK300483
Maximum Power Output:	-
Open Market Value:	\$7,182.00
Original Registration Date:	05 Jul 2013
First Registration Date:	05 Jul 2013
Transfer Count:	4
Actual ARF Paid:	\$1,078.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	04 Jul 2023
COE Category:	D - Motorcycle
COE Period(Years):	10
QP Paid:	\$1,610.00
COE Rebate Amount:	\$610.00
Total Rebate Amount:	\$610.00

The information contained herein is correct as at 18 Sep 2019

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	09/09/2019 12:45
Date Of Accident	06/09/2019 11:15
Exact Location Of Accident	NEAR BLK 469 TAMPINES STREET 44
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	FBH5138M
Insured/Policyholder	
Name Of Registered Owner	LIM KANG JIE MASON
NRIC No	S9206886B
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-96395253
Alternative Phone No	OFFICE-96395253

Vehicle Particulars

Manufacturer	HONDA
Model	CB400
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	MOTORCYCLE

Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	THIRD PARTY
Fleet Policy	NO
Policy Number	5108538348 TP
Cover Note Number	

Driver

Name of Driver	LIM KANG JIE MASON
NRIC No	S9206886B
Date Of Birth	03/03/1992
Occupation	OUTDOOR
Date Of Driving Pass	18/07/2016
Driving Experience	3 YEARS AND 1 MONTH
Gender	MALE
Mobile Number	(LOCAL) +65-96395253
Fax Number	
Contact Number	OFFICE-96395253
EEmail Address	NOEMAIL

Address	BLK 469 #11-172 TAMPINES STREET 44
Postcode	520469
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-

General Information of the Accident

Type Of Accident	SIDE SWIPE
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	0

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO SKETCH PLAN ATTACHED

Attachment(s)


Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	GBH7538D
Vehicle Make/Model/Colour	MINI COOPER / L200 DOUBLE CAB 2.4 AT
Details Of Properties	
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

Sketch Plan #2

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

My motorbike got hit by a pickup at my house carpark. I was not at the location when the accident happened. When I arrived at the scene, my motorbike was upright and there was a note left on my motorbike. The letter has the driver's number and name. My motorbike was damaged and needs to be repaired.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time

- 9 SEP 2019

Driver's Signature
(If driver is not the policyholder)
Date & Time

IDAC KAKI BUKIT (VAC)
23 Kaki Bukit Ave 4
Singapore 415933
Tel: 67416697 Fax: 67492305
Email: yackb@singnet.com.sg

Reporting Centre Personnel's Signature
Name
NRIC/FIN No

* (01)Bent (2)Dented (3)Distorted (4)Cracked (5)Cut (6)Scratched
(07)Deformed (08)Shifted (09)Buckled (10)Broken (11)Necessary
(12)Missing (13)Torn (14)Unconfirmed (15)Not Working

1. Replace (✓) 2. Repair (X) 3. Check (?)
4. Not Consistent (NC)

FOR MOTORCYCLE

Vehicle No: FBH 5138M.

Motorcycle

[illegible][illegible]

No of Items:

Assessor: _____

Adrian King. 04 Days.
Sl. S. - 24/10/19.

...CLAIM SUBFOLDER...(Pending for Survey Report)

PRI

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	13 Sep 2019 Edit Reg		12 Sep 2019 00:00 Edit Adj Rpt	\$S\$0.00 Edit Estimates	\$S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
-------------	------------------	----------------------	------------------	--------------------------

CLAIM SUBFOLDER DETAILS		[Created by adjuster]			
Insured:	Muhammad Haikal Bin Zainol, Co. Reg. No.: -				
Main Claimant:	LIM KANG JIE MASON, ID: S9206886B				
Vehicle Reg. No.:	FBH5138M	Date of Loss:	06/09/2019 11:00 - :59 [74 Months and 1 Days From LTA Reg Date (Man Yr)]		
Claim Type:	TP / 9351350254SG	Policy/Cover Note No.:	1800110409		
Vehicle Reg. No. (Insured):	GBH7538D	Policy No. (Claimant):			
		Excess:			
Repairer:	Candymotor Workshop (HQ) 25 KAKIT BUKIT RD 4 #01-83 SP 417800 KEN: 91559496, 417800 Kaki Bukit - Tel:				
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Chan, Kian Meng] kianmeng.chan@aig.com				
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by ADRIAN LING] ... [Final Rpt due 24/09/2019]				
Claimant's Solicitor:	CATHERINE LIM LLC - Tel: 6438 5500				


































ASSOCIATED MAIL RECEIVED	View All	Compose Case Mail
<ul style="list-style-type: none"> AIG_SG (17/09/2019): NO OI GIA REPORT AIG_SG (17/09/2019): TP GIA REPORT 		

ALL ASSOCIATED TASKS	View All	Search Tasks	Create New Task	Complete					
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*FBH5138M (9351350254SG)
[GBH7538D]
TP
LIM KANG JIE MASON
Sep 6 2019 11:00AM
[Muhammad Haikal Bin Zainol]
Candymotor Workshop

Upload Documents			Upload Photos			Compose New Letter			Upload Video			Upload Audio			View		View in Browser	
Photos/Images															3 per page		<input checked="" type="checkbox"/>	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)														Thumbnail	Print	
1	18/09/19 15:52	General View														Load JPG	<input checked="" type="checkbox"/>	
2	18/09/19 15:52	General View														Load JPG	<input checked="" type="checkbox"/>	
3	18/09/19 15:52	General View														Load JPG	<input checked="" type="checkbox"/>	
4	18/09/19 15:52	General View														Load JPG	<input checked="" type="checkbox"/>	
5	18/09/19 15:52	General View														Load JPG	<input checked="" type="checkbox"/>	
6	18/09/19 15:52	General View														Load JPG	<input checked="" type="checkbox"/>	
7	18/09/19 15:52	General View														Load JPG	<input checked="" type="checkbox"/>	
8	18/09/19 15:52	General View														Load JPG	<input checked="" type="checkbox"/>	
9	18/09/19 15:52	General View														Load JPG	<input checked="" type="checkbox"/>	
10	18/09/19 15:52	General View														Load JPG	<input checked="" type="checkbox"/>	
11	18/09/19 15:52	General View														Load JPG	<input checked="" type="checkbox"/>	
12	18/09/19 15:52	General View														Load JPG	<input checked="" type="checkbox"/>	
13	18/09/19 15:52	General View														Load JPG	<input checked="" type="checkbox"/>	
14	18/09/19 15:52	General View														Load JPG	<input checked="" type="checkbox"/>	
15	18/09/19 15:52	General View														Load JPG	<input checked="" type="checkbox"/>	
16	18/09/19 15:52	General View														Load JPG	<input checked="" type="checkbox"/>	
17	18/09/19 15:52	General View														Load JPG	<input checked="" type="checkbox"/>	
18	18/09/19 15:52	General View														Load JPG	<input checked="" type="checkbox"/>	
19	18/09/19 15:52	General View														Load JPG	<input checked="" type="checkbox"/>	
20	26/09/19 16:43	Photographs of Damaged Parts														Load JPG	<input checked="" type="checkbox"/>	
21	26/09/19 16:43	Photographs of Damaged Parts														Load JPG	<input checked="" type="checkbox"/>	
22	26/09/19 16:43	Photographs of Damaged Parts														Load JPG	<input checked="" type="checkbox"/>	
23	26/09/19 16:43	Photographs of Damaged Parts														Load JPG	<input checked="" type="checkbox"/>	
24	26/09/19 16:43	Photographs of Damaged Parts														Load JPG	<input checked="" type="checkbox"/>	
25	26/09/19 16:43	Photographs of Damaged Parts														Load JPG	<input checked="" type="checkbox"/>	
26	26/09/19 16:43	Photographs of Damaged Parts														Load JPG	<input checked="" type="checkbox"/>	
27	26/09/19 16:43	Photographs of Damaged Parts														Load JPG	<input checked="" type="checkbox"/>	
28	26/09/19 16:43	Photographs of Damaged Parts														Load JPG	<input checked="" type="checkbox"/>	
29	26/09/19 16:43	Photographs of Damaged Parts														Load JPG	<input checked="" type="checkbox"/>	
30	26/09/19 16:43	Photographs of Damaged Parts														Load JPG	<input checked="" type="checkbox"/>	
31	26/09/19 16:43	Photographs of Damaged Parts														Load JPG	<input checked="" type="checkbox"/>	
32	26/09/19 16:43	Photographs of Damaged Parts														Load JPG	<input checked="" type="checkbox"/>	
33	26/09/19 16:43	Photographs of Damaged Parts														Load JPG	<input checked="" type="checkbox"/>	
34	26/09/19 16:43	Photographs of Damaged Parts														Load JPG	<input checked="" type="checkbox"/>	
35	26/09/19 16:43	Photographs of Damaged Parts														Load JPG	<input checked="" type="checkbox"/>	
36	26/09/19 16:43	Photographs of Damaged Parts														Load JPG	<input checked="" type="checkbox"/>	
37	26/09/19 16:43	Photographs of Damaged Parts														Load JPG	<input checked="" type="checkbox"/>	
38	26/09/19 16:43	Photographs of Damaged Parts														Load JPG	<input checked="" type="checkbox"/>	
39	26/09/19 16:43	Photographs of Damaged Parts														Load JPG	<input checked="" type="checkbox"/>	
40	26/09/19 16:43	Photographs of Damaged Parts														Load JPG	<input checked="" type="checkbox"/>	
41	26/09/19 16:43	Photographs of Damaged Parts														Load JPG	<input checked="" type="checkbox"/>	
42	26/09/19 16:43	Photographs of Damaged Parts														Load JPG	<input checked="" type="checkbox"/>	
43	26/09/19 16:43	Photographs of Damaged Parts														Load JPG	<input checked="" type="checkbox"/>	

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
44	26/09/19 16:43	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
45	26/09/19 16:43	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
46	26/09/19 16:43	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
47	26/09/19 16:43	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
48	26/09/19 16:43	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
49	26/09/19 16:43	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
50	26/09/19 16:43	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
51	26/09/19 16:43	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
52	26/09/19 16:43	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
53	26/09/19 16:43	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
54	26/09/19 16:43	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
55	26/09/19 16:43	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
56	26/09/19 16:43	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
57	26/09/19 16:43	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
58	26/09/19 16:43	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
59	26/09/19 16:43	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
60	26/09/19 16:43	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
61	26/09/19 16:43	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
62	26/09/19 16:43	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
63	26/09/19 16:43	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
64	26/09/19 16:43	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
65	26/09/19 16:43	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
66	26/09/19 16:43	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
67	26/09/19 16:43	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
68	10/10/19 12:53	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
69	10/10/19 12:53	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
70	10/10/19 12:53	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
71	10/10/19 12:53	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
72	10/10/19 12:53	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
73	10/10/19 12:53	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
74	10/10/19 12:53	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
75	10/10/19 12:53	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
76	10/10/19 12:53	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
77	10/10/19 12:53	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
78	10/10/19 12:53	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
79	10/10/19 12:53	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
80	10/10/19 12:53	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
81	10/10/19 12:53	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
82	10/10/19 12:53	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
83	10/10/19 12:53	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
84	10/10/19 12:53	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/AIG19016244/ACD3E2

Date: 29/10/2019

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1800110409
Claimant
Vehicle No : FBH5138M **Insured Vehicle No :** GBH7538D
Date of Loss: 06/09/2019 **Nature of Claim:** TP **Claim No:** 9351350254SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **FBH5138M**
 Make & Model: HONDA CB400, 399cc Engine No: NC42E1124622
 Reg. Date: 05/07/2013 (Man. Year: 2013) Chassis No: JH2NC4291BK300483
 Colour: White Odometer: 0 km
 Engine Capacity: 399 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 120/60 R17 Rear Tyre Size: 160/60 R17
 Front Left Side: DIABLO 6 mm Rear Left Side: DIABLO 6 mm
 Front Right Side: 0 mm Rear Right Side: 0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 12/09/2019
 Date Inspected: 13/09/2019 Inspected At: Candymotor Workshop (HQ)
 25 KAKIT BUKIT RD 4 #01-83 SP
 417800 KEN: 91559496
 Singapore 417800
 Estimated Period of Repair: 4.0 days

Adjuster: ADRIAN LING

Manager: CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT FENDER WHEEL GUARD	Repair	0.00 F	*- F
2	1		*FRONT WING MIRROR LH	Damaged	0.00 F	*- F
3	1		*METER CASING	Cracked	0.00 F	*- F
4	1		*HANDLE BAR	Bent	0.00 F	*- F
5	1		*FUEL TANK	Dented	0.00 F	*- F
6	1		*CLUTCH LEVER	Cut	0.00 F	*- F
7	1		*REAR FAIRING LH	Cut	0.00 F	*- F
8	1		*FRONT FOOT REST	Broken	0.00 F	*- F
9	1		*REAR LH SIGNAL LAMP	Cracked	0.00 F	*- F
10	1		*SIDE GUARD LH	Bent	0.00 F	*- F
11	1		*SLIDER LH	Cut	0.00 F	*- F
F=Franchise part.						
				Total Parts (S\$)	0.00	0.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >