

(09/2011)

INS. CASE OWNER:

CC 6 /AIG1901 6248, Uda...

LKK:
IDAC:

Surveyor:

Markus

DOI:

ASSIGNMENT

12/11/19

Date / Time:

12/11/19

Registered in Merimen:

12/11/19

Pre-assign / CCU / FTE



Insured Vehicle No.:

SLH 10829

Name of Insured:

NG Ho Henry

Insured Tel No.:

HP:

Excess Sec II :\$S

D.O.A.:

8/11/19

Is driver the owner?

(YES / NO)

Nature of Accident:

Claim No.:

333884121056

Policy No.:

2006870501

Make / Model:

Toyota

Place of Accident:

PVB

If NO, Driver Name / Age: NG Hen Henry

Driver Tel No.:

(VA: YES / NO)

OI GIA REPORT: YES / NO : TP GIA REPORT: YES / NO

Insured Liability:

%

Final ? Yes / No

SMF 86790

INSRS:
WSP:
Tel:
Liability:
RMKS:Hup
MotorINSRS:
WSP:
Tel:
Liability:
RMKS:INSRS:
WSP:
Tel:
Liability:
RMKS:INSRS:
WSP:
Tel:
Liability:
RMKS:

Date/ Time	STAGE	DATE / PIC
14/10/19	Non-Reporting Itr (1st):	
	Non-Reporting Itr (2nd):	
	Non-Reporting Itr (Final):	
	Notification Itr (if non-pickup):	
	Call OI:	
	After call Itr to OI:	
	Documentation Check List:	Handler Typist
	Notification Itr (if non-pickup)	
	After call Itr to OI:	
	Authorisation To Act:	
	Release Voucher:	
	Final Repair Bill:	
	Car Rental Invoice:	
	Towing Invoice:	
	LTA / GIA:	
	Medical Bill:	
	PIR:	
	Mandate/Reject Instruction:	
	LOD:	
	Payment Breakdown Form:	
	Post-Repair Photos:	
	Others:	

PRELIMINARY ADVICE		Date/Time:	Sent By:	Confirm by:
Repair Cost:	\$S	(days) Reduction:	%	Email <input type="checkbox"/> Call <input type="checkbox"/>
FINAL SETTLEMENT		Date/Time: 9/10/19	Confirm with: David	Email <input type="checkbox"/> Call <input type="checkbox"/>
Final Liability:	% 100	(Agreed / Assessed) BOLA S/N No.:	27	If NO or B 28, Ass. Lia:
Repair Cost:	\$S 3200.00			
Loss of Rental (LOR):	\$S -	(days)		
Loss of Use (LOU):	\$S 420.00	(3 70 x 6 days)		
Loss of Income (LOI):	\$S -	(3 x days)		
LOR only <input type="checkbox"/> LOU only <input checked="" type="checkbox"/>	LOR + LOU <input type="checkbox"/> LOR + LO <input type="checkbox"/>	(Tick only one)		
GIA/LTA Search	\$S 2.00			
Medical:	\$S -			
Disbursement:	\$S -	(e.g. Tow/ Independent)		
Legal Cost:	\$S -			
Total:	\$S 3622.00	Global Sum \$S:		
FINAL PAYMENT		Date/Time:	Confirm with:	Email <input type="checkbox"/> Call <input type="checkbox"/>
Payee 1:	\$S 3622.00	Name 1:	Hup Motor Trading & Service	
Payee 2: (Strike if N.A.)	\$S	Name 2:		
Payee 3: (Strike if N.A.)	\$S	Name 3:		

QAN 1/13) Waf
ASS. REC. BY: MCR 65

REF:

A16/

ASSIGNMENT

From: _____ Date: _____
Estimated Cost: _____
OD / TP / WS / TP RES / OD RES / EVA / INV / MV
To Inspect Vehicle No: SMF 8679D
at Workshop m/s hyndai
of _____
Insured: SLH 110824
Policy No. _____
Claims No. _____
Sum Insured: _____ Excess: _____
(Client's Record)
Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____
IDAC Accident Report: _____ Consistent? : Yes or No
GIA / PR Seen: _____ Consistent? : Yes or No
Est. Repairs: 6 days Res: Yes or No
Lum Sum: 20 % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SMF 8679D Yr Regn: 11 18
Type: Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
Truck / Trailer or CA
Make: Toyota Vios C.C. 1496
Colour: Grey A/C: Insured / Std / NI / NA
Sp. Reading: 3701 T/Radio: Insured / Std / NI / NA
Eng/No: _____
C/No: MR2B23F3701155430
Gen. Cond: Good / Fair / Poor / Burnt
Steering: Good / Jammed / Leaked / Burnt or
Brake: Good / Jammed / Leaked / Burnt or
Mod: Nil / S/Rim / STD A/Rim or
Tyre Size: F: 185-160R15
R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front: S mm Rear: S mm
R/Bal: S mm L/Bal: S mm
D.O.A: 8/9/19 D.O.I: 13/9/19
Survey held at: _____

Des. of Damages: Fnt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

21A 36507

U/S - \$3200 (Red \$3258.30 / 507.)

Date/Time, File Pass to?

☐ : Prel. Report
☐ : Final Report

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

Date/Time, File Return to?

2)

Add Fee: ☐ : Site Insp (\$ _____)
☐ : Interview (\$ _____)
☐ : Tech. Invs (\$ _____)
☐ : Weekend (\$ _____)

Photo

Other

Report Format :

Lump Sum / I.B.I: (\$ _____)

TOTAL

哈 汽 車 貿 易 服 務

HUP MOTOR TRADING & SERVICE

Blk 9004 Tampines Street 93 #01-120 Singapore 528838 Tel: 6784 0039 Fax: 6784 0076 Email: hupmotor@gmail.com Reg. No. 378091/00W

Our Ref: TP 2961/09/19

Your Ref: Date: 13th SEP 2019

Madam Ong Alice
Blk 3, Bedok Reservoir View,
#06-04, Singapore 478927

Estimate cost of repair to TOYOTA VIOS 1.5 (A) Saloon - SMF 8679 D

1 pc rear bumper		20/12	\$ 542.70	—
8 pcs rear bumper top clips	@ \$ 3.80	rec	30.40	—
2 pcs rear bumper o/s & n/s side retainer	@ \$ 131.90	11	263.80	α
2 pcs rear bumper o/s & n/s side clips & stopper	@ \$ 3.80	rec	7.60	—
1 set rear bumper reverse sensor		shd	283.90	—
1 pc rear bumper sponge damper		nt	75.00	α
1 pc rear bumper reinforcement		20	361.60	—
2 pcs rear bumper reinforcement o/s & n/s stay	@ \$ 114.80	11	229.60	α
2 pcs rear bumper o/s & n/s reflector	@ \$ 87.10	shd	174.20	1 pc
2 pcs rear bumper o/s & n/s top screw & stopper	@ \$ 5.80	11	11.60	α
1 pc boot lid		2	684.80	α
1 pc boot lid 'VIOS' emblem		rec	43.60	—
1 pc boot lid 'E' emblem		rec	40.20	—
1 pc boot lid logo emblems		rec	52.10	—
2 pcs boot lid o/s & n/s hinge	@ \$ 60.20	11	120.40	α
1 pc boot lid lock		twi	360.40	—
1 pc boot lid lock straiacker		11	29.90	α
1 pc boot lid weatherstrip		twi	166.40	—
12 pcs boot lid insulator clips	@ \$ 4.10	11	49.20	α
1 pc rear end panel		DD/Bent	620.10	—
1 pc rear end panel top garnish		out/m	252.20	—
6 pcs rear end panel top garnish clips	@ \$ 4.20	11	25.20	α
1 pc rear number plate & frame		suc	60.00	α
1 pc o/s tail lamp assy		11	299.50	α
			\$ 4,784.40	2848.30
	Less 25%		\$ 1,196.10	2136.22
			\$ 3,588.30	

To remove & refix carpet, floor mat, garnish, floor board cover, tool set, spare tyre & necessary parts.

150.00 60

To wiring check up for affected wiring system.

50.00 20

To respray Tuff-Kote on all affected accident parts.

120.00 40

Labour charge to remove & cut out damaged parts, to jack, straighten & knocking out rear floor board panel & necessary parts, to weld, renew & align above parts.

1,200.00 800

To putty & respray painting on all affected accident parts.

1,350.00 950

\$ 6,458.30

=====

Dollars : Six Thousand Four Hundred Fifty Eight And Cents Thirty Only.

3204.

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type:	Singapore NRIC
Owner ID:	835D

Vehicle Details

Vehicle No.:	SMF8679D
Vehicle to be Exported:	No
Intended Deregistration Date:	16 Sep 2019
Vehicle Make:	TOYOTA
Vehicle Model:	VIOS 1.5 E (AUTO)
Primary Colour:	Grey
Manufacturing Year:	2018
Engine No.:	2NR5292031
Chassis No.:	MR2B23F3701155430
Maximum Power Output:	79.0 kW (105 bhp)
Open Market Value:	\$13,781.00
Original Registration Date:	28 Nov 2018
First Registration Date:	28 Nov 2018
Transfer Count:	0
Actual ARF Paid:	\$13,781.00

Intended PARF Rebate Details

PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	27 Nov 2028
PARF Rebate Amount:	\$10,335.00

Intended COE Rebate Details

COE Expiry Date:	27 Nov 2028
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$28,457.00
COE Rebate Amount:	\$26,172.00
Total Rebate Amount:	\$36,507.00

The information contained herein is correct as at 16 Sep 2019

OK

Jia Le

哈 汽 車 貿 易 服 務

HUP MOTOR TRADING & SERVICE Email : hupmotor@gmail.com

Blk 9004 Tampines Street 93 #01-120 Singapore 528838 Tel: 6784 0039 Fax: 6784 0076 WEB SITE: http://hupmotor.com.sg Reg. No. 378091/00W

Our Ref: TF 2961/09/19 Your Ref: _____ Date: 23rd SEP 2019

The Claim's Manager
Motor Claims Dept.
AIG ASIA PACIFIC INSURANCE PTE. LTD.
78, Shenton Way, #07-16, Chartis Bldg.
Singapore 079120

Dear Sirs,

RE : ACCIDENT ON 08/09/19 ALONG P.I.E. TOWARDS JALAN BUROS
INVOLVING : SMP 8679 D & YOUR INSURED : SLH 1082 Y

We act for Madam Ong Alice., NRIC No : S1427835D
Who is the registered owner of Veh. No : SMP 8679 D Which was involved
in the above accident with Veh. No : SLH 1082 Y Which we understand
is insured with you.

Your appointed surveyor had surveyed our client's damaged vehicle and
we had repaired the vehicle.

The accident was clearly caused by your insured's negligence, I am,
therefore, seeking compensation from you for my financial losses as
itemised below : -

Cost of repair	\$ 3,200.00
Loss of Use for 6 days (1 day X \$ 70.00)	420.00
LTA Search Fee & GIA-RMC Search Fee	2.00
Survey Fee	0.00
	<hr/>
	\$ 3,622.00
	=====

We have enclosed copies of relevant documents to support my client's
claim, There was no receipt enclosed, as my client's did not pay us
any single amount.

Your prompt settlement of our claim would be much appreciated.

Yours faithfully,

HUP MOTOR TRADING & SERVICE

Mr David Ang B. Y.

Encl : Final Bill, Car Rental Bill, LTA Search Fee, Owner Authorisation
Letter, GIA Report, Survey Report & Ins. Cert.

Remark : Kindly acknowledge receipt.

Jia Le (LKK Auto)

From: Jia Le (LKK Auto)
Sent: Wednesday, 18 September 2019 10:51 AM
To: nghh9196@gmail.com
Subject: ACCIDENT INVOLVING SLH 1082Y & SMF 8679D ALONG/AT PIE(TUAS) BEFORE THE 9KM MARK ON 08/09/2019

Our Ref: CC6/AIG19016248/Udb3

NG HO HENG
BLK 414 COMMONWEALTH AVENUE WEST
#18-3007
SINGAPORE 120414

Dear Sir/Madam,

ACCIDENT INVOLVING SLH 1082Y & SMF 8679D ALONG/AT PIE(TUAS) BEFORE THE 9KM MARK ON 08/09/2019

We refer to the above subject matter. We write to inform you that we are the loss adjuster appointed by your motor insurer, AIG Asia Pacific Insurance Pte Ltd to deal with the third party claim against your policy.

We have received a claim from SMF 8679D against your motor insurance policy.

Based on the accident report and accident scenario, we are of the view that liability is not in your favour as it is head to rear collision. We will therefore proceed to negotiate for an amicable settlement with the Third Party.

Should you however wish to further discuss on the matter prior to our negotiations and settlement, please contact us within 10 days from the date of this letter.

Please note that your No-Claim Discount (NCD) (if any) will be affected and reduced by 30% (20% for commercial vehicles) upon next renewal due to this Third Party claim. However, if your policy has a NCD protector feature, it will be deemed utilized for this claim and your NCD will be protected.

Please call us if you have further queries.

Best Regards,

Chan Jia Le | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6749 5792 | email: Jiale@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

TO : AIG ASIA PACIFIC INSURANCE PTE LTD


AUTHORIZATION TO ACT

I, MDM ONG ALICE (S1427835D) ("the third party claimant")
of BLK 3, #06-04, BEDOK RESERVOIR VIEW, S (478927) (address),
owner of SMV 8679 D (vehicle no.) hereby authorize
Hup Motor Trading & Service,
("The workshop") to act for me with respect to my claim for
repair costs and/or rental and/or loss of use ("claim") for my
Vehicle No. SMG 8679 D that was damaged pursuant to the
accident which occurred on 08/09/19 (date) along P.I.E. TWDS
JALAN BUNOS (location)
involving Vehicle No/s SLH 1082 Y
("The accident").

I further authorize the workshop to settle my above mentioned
claim in a manner that they deem fit and the workshop is further
authorized to receive payment further to settlement of my claim
with payment cheque/s being made in favour of the workshop.

I further acknowledge that any settlement the workshop may reach
on my behalf is on a without prejudice and without admission of
liability basis insofar as the driver/owner/insurers of the
other vehicle/s is concerned.

Dated this 23rd day of September (month) 20 19 (year)



Owner Of SMV 8679 D (S1427835D)
Signed by "the third party claimant"

HUP MOTOR TRADING & SERVICE



Signed by "the workshop"

RELEASE VOUCHER
(AIG Asia Pacific - Express Third Party Claim)

"We/I, **HUP MOTOR TRADING & SERVICE** ("the workshop") hereby confirm that we/I have reached an agreement with the appointed surveyor of AIG Asia Pacific Insurance Pte Ltd **LKK AUTO CONSULTANTS PTE LTD** (name of surveyor) with respect to the amount claimed for **S\$3,200.00** (Repair Cost), **S\$420.00** (Loss of Use/Rental), **S\$2.00** (Disbursement) for vehicle no. **SMF 8679D** that was damaged pursuant to the accident which occurred on **08/09/2019** (date) along **PIE TOWARDS JALAN EUNOS** (location) involving vehicle no/s **SLH 1082Y**. This is pursuant to the inspection conducted on **13/09/2019** (date) at "the workshop".

We/I confirm that we/I are/am authorized by the owner **ONG ALICE** ("the third party claimant") of vehicle no. **SMF 8679D** make the claim as set out in the above paragraph and we/I have full authority to settle the matter on his/her behalf in a manner that we/I deem fit. We/I enclose herein the letter of authority given by "the third party claimant".

We/I further confirm that we/I will indemnify AIG Asia Pacific Insurance Pte Ltd for all damages, loss and/or expense that they will or have already incurred in the event that "the third party claimant" after the above said agreement lodges a further claim against the former for any loss and expenses suffered pertaining to costs of repairs and/or rental and/or loss of use pursuant to the damage to **SMF 8679D** (vehicle no.) as a result of the accident.

We/I confirm that the agreement reached above is in full and final settlement of any claim of "the third party claimant" pursuant to the accident and that further this settlement is reached on a without prejudice and without admission of liability basis.

This agreement is subject to the application of Singapore law and the Singapore Courts have exclusive jurisdiction over any dispute arising out of the same.

Dated this 9th (day) of October (month) 2019 (year)



Signed by appointed surveyor

HUP MOTOR TRADING & SERVICE

Signed by "the workshop" (with chop)

哈 汽 車 貿 易 服 務

HUP MOTOR TRADING & SERVICE

Blk 9004 Tampines Street 93 #01-120 Singapore 528838 Tel: 6784 0039 Fax: 6784 0076 Email: hupmotor@gmail.com Reg. No. 378091/00W

Our Ref: TF 2961/09/19 Your Ref: _____ Date: 23rd SEP 2019

MDM ONG ALICE
BLK 3, #06-04,
BEDOK RESERVOIR VIEW
SINGAPORE 478927

INVOICE For cost of repair to TOYOTA VIOS 1.5 (A) Saloon - SWP 8679 D

To supply rear bumper, clips, reverse sensor, reinforcement,
boot lid emblems, lock, rear end panel, top garnish & necessary
parts.

To remove & refix carpet, floor board cover, garnish, floor mat,
tool set, spare tyre & necessary parts, including wiring check up
for affected wiring system.

Labour charge to remove & cut out damaged parts, to jack, straighten
& knocking out boot lid, rear floor board panel & necessary parts,
to weld, renew & align above parts.

To putty & respray painting on all affected accident parts,
including respray Tuff-Kote on all affected accident parts.

Lump Sum Repair : \$ 3,200.00

=====

Dollars : Three Thousand And Two Hundred Only.

HUP MOTOR TRADING & SERVICE



RECORDS MANAGEMENT CENTRE

**GENERAL INSURANCE ASSOCIATION OF SINGAPORE
RECORDS MANAGEMENT CENTRE**

6 Raffles Quay #18-00, Singapore 048580

Phone: +65 6224 0010 Fax: +65 6224 0030

Operating Hours: Monday to Friday 9am to 5pm

GST Registration No: M400017735

Third Party Insurer Enquiry

Our Ref No: GR-19-150765

Date of Request: 13/09/2019

Your Ref No:

Online Purchase

Hup Motor Trading & Service

Blk 9004 Tampines Street 93

#01-120

Singapore 528838

Dear Sir/Madam,

Enquiry Date 13/09/2019

Enquiry By David Ang Beng Yeow

TP Vehicle No. SLH1082Y

Accident Date 08/09/2019

Enquiry Result

TP Vehicle No.	Insurer	Period of Insurance	Insurer Tel. No.
SLH1082Y	AIG Asia Pacific Insurance Pte. Ltd.	25/10/2018-24/10/2019	65-6419-3000

Thank You.

The images provided to you are taken from the original reports forwarded to the centre by the members of the General Insurance Association of Singapore and we take no responsibility for their accuracy or contents and shall be under no liability whatsoever for any loss or damage arising out of or in connection with the reports or their images.

This is a computer generated document and requires no signature.

You are returning to a previous page. This page may be outdated.
Please click 'Refresh' to refresh the page.

...CLAIM SUBFOLDER...(Pending for Survey Report)

Fastlane

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	10 Sep 2019 Edit Reg		13 Sep 2019 00:00 Edit Adj Rpt	S\$3,200.00 Edit Estimates	S\$3,200.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured: NG HO HENG , ID: S1396373H									
Main Claimant: ONG ALICE , ID: S1427835D									
Vehicle Reg. No.: SMF8679D		Date of Loss: 08/09/2019 00:00 - :59 [9 Months and 11 Days From LTA Reg Date (Man Yr)]							
Claim Type: TP / 7338541310SG		Policy/Cover Note No.: 2100487605 (Comprehensive)							
Vehicle Reg. No. (Insured): SLH1082Y		Policy No. (Claimant): VPA/P2214740							
		Excess:							
Repairer: Hup Motor Trading & Service (HQ) Bk 9004 Tampines Street 93, #01-120, 528838 Tampines - Tel: 67840039/98154655									
Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by MdNoor, Norsiah] Norsiah.MdNoor@aig.com									
Claimant's Insurer: AXA Insurance Pte Ltd (HQ) - Tel: 6338 7288									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MARCUS CHUA] ... [Final Rpt due 24/09/2019]									
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
<ul style="list-style-type: none"> AIG_SG_EXPRESS (25/09/2019): Alert - Adj Mandate Approved (S\$3622.00) - SMF8679D - Claim Handler: MdNoor, Nor... 									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SMF8679D (7338541310SG)
[SLH1082Y]
TP
ONG ALICE
Sep 8 2019 12:00AM
[NG HO HENG]
Hup Motor Trading & Service

[Upload Documents](#)
[Upload Photos](#)
[Compose New Letter](#)
[Upload Video](#)
[Upload Audio](#)

View View in Browser

Letters/Correspondences				1 per page	<input checked="" type="checkbox"/>
No	Finalized On			Thumbnail	Print
1	(Draft)	LKK Auto Consultants Pte Ltd (HQ)			
		Third Party Express Settlement – Payment Breakdown		Edit	

Assessment Reports				1 per page	<input checked="" type="checkbox"/>
No	Finalized On			Thumbnail	Print
1	24/09/19 15:15	LKK Auto Consultants Pte Ltd (HQ)			
		Adjuster Immediate Advice		Load HTM	

Photos/Images				3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder			Thumbnail	Print
1	13/09/19 19:08	LKK Auto Consultants Pte Ltd (HQ)			
		Chassis Number		Load JPG	<input checked="" type="checkbox"/>
2	13/09/19 19:08	Odometer Reading		Load JPG	<input checked="" type="checkbox"/>
3	13/09/19 19:09	General View		Load JPG	<input checked="" type="checkbox"/>
4	13/09/19 19:09	General View		Load JPG	<input checked="" type="checkbox"/>
5	13/09/19 19:09	General View		Load JPG	<input checked="" type="checkbox"/>
6	13/09/19 19:09	General View		Load JPG	<input checked="" type="checkbox"/>
7	13/09/19 19:09	General View		Load JPG	<input checked="" type="checkbox"/>
8	13/09/19 19:09	General View		Load JPG	<input checked="" type="checkbox"/>
9	13/09/19 19:09	General View		Load JPG	<input checked="" type="checkbox"/>
10	13/09/19 19:09	General View		Load JPG	<input checked="" type="checkbox"/>
11	13/09/19 19:09	General View		Load JPG	<input checked="" type="checkbox"/>
12	13/09/19 19:09	General View		Load JPG	<input checked="" type="checkbox"/>
13	13/09/19 19:09	General View		Load JPG	<input checked="" type="checkbox"/>
14	13/09/19 19:09	General View		Load JPG	<input checked="" type="checkbox"/>
15	13/09/19 19:09	General View		Load JPG	<input checked="" type="checkbox"/>
16	13/09/19 19:09	General View		Load JPG	<input checked="" type="checkbox"/>
17	13/09/19 19:09	General View		Load JPG	<input checked="" type="checkbox"/>
18	13/09/19 19:09	General View		Load JPG	<input checked="" type="checkbox"/>
19	13/09/19 19:09	General View		Load JPG	<input checked="" type="checkbox"/>
20	13/09/19 19:09	General View		Load JPG	<input checked="" type="checkbox"/>
21	13/09/19 19:09	General View		Load JPG	<input checked="" type="checkbox"/>
22	13/09/19 19:09	General View		Load JPG	<input checked="" type="checkbox"/>
23	13/09/19 19:09	General View		Load JPG	<input checked="" type="checkbox"/>
24	13/09/19 19:09	General View		Load JPG	<input checked="" type="checkbox"/>
25	13/09/19 19:09	General View		Load JPG	<input checked="" type="checkbox"/>
26	13/09/19 19:09	General View		Load JPG	<input checked="" type="checkbox"/>
27	13/09/19 19:09	General View		Load JPG	<input checked="" type="checkbox"/>
28	13/09/19 19:09	General View		Load JPG	<input checked="" type="checkbox"/>
29	13/09/19 19:09	General View		Load JPG	<input checked="" type="checkbox"/>
30	13/09/19 19:09	General View		Load JPG	<input checked="" type="checkbox"/>
31	13/09/19 19:09	General View		Load JPG	<input checked="" type="checkbox"/>
32	13/09/19 19:09	General View		Load JPG	<input checked="" type="checkbox"/>
33	13/09/19 19:09	General View		Load JPG	<input checked="" type="checkbox"/>
34	13/09/19 19:09	General View		Load JPG	<input checked="" type="checkbox"/>
35	13/09/19 19:09	General View		Load JPG	<input checked="" type="checkbox"/>
36	13/09/19 19:09	General View		Load JPG	<input checked="" type="checkbox"/>

Letters/Correspondences			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
37	13/09/19 19:09	General View		<input checked="" type="checkbox"/>
38	13/09/19 19:09	General View		<input checked="" type="checkbox"/>
39	13/09/19 19:09	General View		<input checked="" type="checkbox"/>
40	13/09/19 19:09	General View		<input checked="" type="checkbox"/>
41	13/09/19 19:09	General View		<input checked="" type="checkbox"/>
42	13/09/19 19:09	General View		<input checked="" type="checkbox"/>
43	13/09/19 19:09	General View		<input checked="" type="checkbox"/>
44	13/09/19 19:09	General View		<input checked="" type="checkbox"/>
45	13/09/19 19:09	General View		<input checked="" type="checkbox"/>
46	13/09/19 19:09	General View		<input checked="" type="checkbox"/>
47	13/09/19 19:09	General View		<input checked="" type="checkbox"/>
48	13/09/19 19:09	General View		<input checked="" type="checkbox"/>
49	13/09/19 19:09	General View		<input checked="" type="checkbox"/>
50	13/09/19 19:09	General View		<input checked="" type="checkbox"/>
51	13/09/19 19:09	General View		<input checked="" type="checkbox"/>
52	13/09/19 19:09	General View		<input checked="" type="checkbox"/>
53	13/09/19 19:09	General View		<input checked="" type="checkbox"/>
54	19/09/19 17:34	Reinspection Photo		<input checked="" type="checkbox"/>
55	19/09/19 17:34	Reinspection Photo		<input checked="" type="checkbox"/>
56	19/09/19 17:34	Reinspection Photo		<input checked="" type="checkbox"/>
57	19/09/19 17:34	Reinspection Photo		<input checked="" type="checkbox"/>
58	19/09/19 17:34	Reinspection Photo		<input checked="" type="checkbox"/>
59	19/09/19 17:34	Reinspection Photo		<input checked="" type="checkbox"/>
60	19/09/19 17:34	Reinspection Photo		<input checked="" type="checkbox"/>
61	19/09/19 17:34	Reinspection Photo		<input checked="" type="checkbox"/>
62	19/09/19 17:34	Reinspection Photo		<input checked="" type="checkbox"/>
63	19/09/19 17:34	Reinspection Photo		<input checked="" type="checkbox"/>
64	19/09/19 17:34	Reinspection Photo		<input checked="" type="checkbox"/>
65	19/09/19 17:34	Reinspection Photo		<input checked="" type="checkbox"/>
66	19/09/19 17:34	Reinspection Photo		<input checked="" type="checkbox"/>
67	19/09/19 17:34	Reinspection Photo		<input checked="" type="checkbox"/>
68	23/09/19 08:22	After Repair Photo		<input checked="" type="checkbox"/>
69	23/09/19 08:22	After Repair Photo		<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	16/09/19 09:45	TP EST & GIA REPORT.		<input checked="" type="checkbox"/>
2	24/09/19 15:06	GIA SEARCH FEE		<input checked="" type="checkbox"/>
3	24/09/19 15:06	LOD		<input checked="" type="checkbox"/>
4	24/09/19 15:07	TP ESTIMATE - MARKED		<input checked="" type="checkbox"/>
5	24/09/19 15:10	LETTER TO OI		<input checked="" type="checkbox"/>
6	17/10/19 10:20	WORKSHOP INVOICE		<input checked="" type="checkbox"/>
7	17/10/19 10:20	AUTHORISATION TO ACT FORM		<input checked="" type="checkbox"/>
8	17/10/19 10:20	Release Voucher		<input checked="" type="checkbox"/>
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
1	17/09/19 14:43	OI GIA REPORT		<input checked="" type="checkbox"/>

Documents Checklist

DOCUMENTS CHECKLIST

Reset

Save

Print

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM _____

THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

Vehicle No:	SLH1082Y (Insd veh)	Model:	TOYOTA VIOS 1.5 E (A)
	SMF8679D (TP veh)		
Date of Accident:	08/09/2019		

Global Sum Settlement	: [] Yes	: [X] No	
Repair Estimate	: \$	6,458.30	
Final Repair Cost	: \$	3,200.00	
Loss of Use	: \$	420.00	6.00 days at \$70.00 per day
Rental (if any)	: \$	0.00	days
LTA / GIA Search Fee	: \$	2.00	
Others:	: \$	0.00	
	: \$		
Final Settlement Sum	: \$	3,622.00	

Is Third Party Workshop GIA Registered? [] YES [X] NO (Kindly indicate below)

A) For Non GIA Registered Workshop: Agreed Liability ____ 100 ____ (%)

B) For GIA Registered Workshop: BOLA Applicable: Yes/ No BOLA Scenario No: ____

BOLA Liability: ____ (%) Assessed Liability (*): ____ (%)

** Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.*

Remarks _____

Payment Instruction: Payee's Breakdown			
1)	Hup Motor Trading & Service	: \$	3,622.00
2)		: \$	
3)		: \$	

JOANNE LEE KHANG MIN

17 Oct
2019

LKK Auto Consultants Pte Ltd

Date

Please attach all the supporting documents to the form.
(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report;
Medical Report/ Bill (if any))

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/AIG19016248/UDB3Q2

Date: 17/10/2019

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2100487605
 Claimant SMF8679D Insured Vehicle No: SLH1082Y
 Vehicle No: SMF8679D Nature of Claim: TP Claim No: 7338541310SG
 Date of Loss: 08/09/2019

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SMF8679D Engine No: 2NR5292031
 Make & Model: TOYOTA VIOS, 1.5 E (A) Chassis No: MR2B23F3701155430
 Reg. Date: 28/11/2018 (Man. Year: 2018) Odometer: 3701 km
 Colour: Grey
 Engine Capacity: 1496 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 185/60 R15 Rear Tyre Size: 185/60 R15
 Front Left Side: Yokohama 8 mm Rear Left Side: Yokohama 8 mm
 Front Right Side: Yokohama 8 mm Rear Right Side: Yokohama 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,588.30	2,136.22	1,452.08	40.47
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,870.00	1,870.00	1,000.00	34.84
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	6,458.30	4,006.22	2,452.08	37.97
Approved Total (Overridden) (S\$)		3,200.00		
Nett Amount (S\$)	6,458.30	3,200.00	3,258.30	50.45
+ Loss of Use (6.0 x S\$70.00/day) (S\$)		420.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		3,622.00		

INSPECTION

Date of Assignment: 13/09/2019
 Date Inspected: 13/09/2019 Inspected At: Hup Motor Trading & Service (HQ)
 Blk 9004 Tampines Street 93, #01-120
 Singapore 528838
 Estimated Period of Repair: 6.0 days

Adjuster: MARCUS CHUA

Manager: CHAN JIA LE

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Dented / Deformed	542.70 FL	*542.70 FL
2	8		*REAR BUMPER TOP CLIPS	Necessary	30.40 FL	*30.40 FL
3	2		*REAR BUMPER O/S & N/S SIDE RETAINER	Not Necessary	263.80 FL	*- FL
4	2		*REAR BUMPER O/S & N/S SIDE CLIPS & STOPPER	Necessary	7.60 FL	*7.60 FL
5	1		*SET REAR BUMPER REVERSE SENSOR	Shorted	283.90 FL	*283.90 FL
6	1		*REAR BUMPER SPONGE DAMPER	Not fitted	75.00 FL	*- FL
7	1		*REAR BUMPER REINFORCEMENT	Dented	361.60 FL	*361.60 FL
8	2		*REAR BUMPER REINFORCEMENT O/S & N/S STAY	Not Necessary	229.60 FL	*- FL
9	1		*REAR BUMPER O/S & N/S REFLECTOR	O/S Cracked	174.20 FL	*87.10 FL
10	2		*REAR BUMPER O/S & N/S TOP SCREW & STOPPER	Not Necessary	11.60 FL	*- FL
11	1		*BOOT LID	Repair	684.80 FL	*- FL
12	1		*BOOT LID VIOS EMBLEM	Necessary	43.60 FL	*43.60 FL
13	1		*BOOT LID E EMBLEM	Necessary	40.20 FL	*40.20 FL
14	1		*BOOT LID LOGO EMBLEMS	Necessary	52.10 FL	*52.10 FL
15	2		*BOOT LID O/S & N/S HINGE	Not Necessary	120.40 FL	*- FL
16	1		*BOOT LID LOCK	Twisted	360.40 FL	*360.40 FL
17	1		*BOOT LID LOCK STRAICKER	Not Necessary	29.90 FL	*- FL
18	1		*BOOT LID WEATHERSTRIP	Twisted	166.40 FL	*166.40 FL
19	12		*BOOT LID INSULATOR CLIPS	Not Necessary	49.20 FL	*- FL
20	1		*REAR END PANEL	Dented / Bent	620.10 FL	*620.10 FL
21	1		*REAR END PANEL TOP GARNISH	Deformed / Twisted	252.20 FL	*252.20 FL
22	6		*REAR END PANEL TOP GARNISH CLIPS	Not Necessary	25.20 FL	*- FL
23	1		*REAR NUMBER PLATE & FRAME	Serviceable	60.00 FL	*- FL
24	1		*O/S TAIL LAMP ASSY	Not Necessary	299.50 FL	*- FL

F=Franchise part. L=ListItemDisc.

Sub Total (S\$)	4,784.40	2,848.30
- List Item Discount on L Items 25.00/25.00% (S\$)	1,196.10	712.08
Total Parts (S\$)	3,588.30	2,136.22

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE & REFIX CARPET ,FLOOR MAT ,GARNISH ,FLOOR BOARD COVER ,TOOL SET ,SPARE TYRE & NECESSARY PARTS	New	150.00	60.00
2	TO WIRING CHECK UP FOR AFFECTED WIRING SYSTEM	New	50.00	20.00
3	TO RESPRAY TUFF-KOTE ON ALL AFFECTED ACCIDENT PARTS	New	120.00	40.00
4	LABOUR CHARGE TO REMOVE & CUT OUT DAMAGED PARTS ,TO JACK,STRAIGHTEN & KNOCKING OUT REAR FLOOR BOARD PANEL & NECESSARY PARTS ,TO WELD ,RENEW & ALIGN ABOVE PARTS	New	1,200.00	800.00
5	TO PUTTY & RESPRAY PAINTING ON ALL AFFECTED ACCIDENT PARTS	New	1,350.00	950.00
Gross Labour Cost (\$\$)			2,870.00	1,870.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >