

哈 汽 車 貿 易 服 務

HUP MOTOR TRADING & SERVICE

Blk 9004 Tampines Street 93 #01-120 Singapore 528838 Tel: 6784 0039 Fax: 6784 0076 Email: hupmotor@gmail.com Reg. No. 378091/00W

Our Ref: TP 2961/09/19

Your Ref: Date: 13th SEP 2019

Madam Ong Alice
Blk 3, Bedok Reservoir View,
#06-04, Singapore 478927

Estimate cost of repair to TOYOTA VIOS 1.5 (A) Saloon - SMF 8679 D

1 pc rear bumper	20/12	\$ 542.70	—
8 pcs rear bumper top clips	@ \$ 3.80	30.40	—
2 pcs rear bumper o/s & n/s side retainer	@ \$ 131.90	263.80	α
2 pcs rear bumper o/s & n/s side clips & stopper	@ \$ 3.80	7.60	—
1 set rear bumper reverse sensor	shd	283.90	—
1 pc rear bumper sponge damper	nt	75.00	α
1 pc rear bumper reinforcement	nt	361.60	—
2 pcs rear bumper reinforcement o/s & n/s stay	@ \$ 114.80	229.60	α
2 pcs rear bumper o/s & n/s reflector	@ \$ 87.10	174.20	α
2 pcs rear bumper o/s & n/s top screw & stopper	@ \$ 5.80	11.60	α
1 pc boot lid	nt	684.80	α
1 pc boot lid 'VIOS' emblem	nt	43.60	—
1 pc boot lid 'E' emblem	nt	40.20	—
1 pc boot lid logo emblems	nt	52.10	—
2 pcs boot lid o/s & n/s hinge	@ \$ 60.20	120.40	α
1 pc boot lid lock	nt	360.40	—
1 pc boot lid lock straiter	nt	29.90	α
1 pc boot lid weatherstrip	nt	166.40	—
12 pcs boot lid insulator clips	@ \$ 4.10	49.20	α
1 pc rear end panel	DP/Bnt	620.10	—
1 pc rear end panel top garnish	nt	252.20	—
6 pcs rear end panel top garnish clips	@ \$ 4.20	25.20	α
1 pc rear number plate & frame	nt	60.00	α
1 pc o/s tail lamp assy	nt	299.50	α
		\$ 4,784.40	2848.30
	Less 25%	\$ 1,196.10	2136.22
		\$ 3,588.30	

To remove & refix carpet, floor mat, garnish, floor board cover, tool set, spare tyre & necessary parts. 150.00 60

To wiring check up for affected wiring system. 50.00 20

To respray Tuff-Kote on all affected accident parts. 120.00 40

Labour charge to remove & cut out damaged parts, to jack, straighten & knocking out rear floor board panel & necessary parts, to weld, renew & align above parts. 1,200.00 800

To putty & respray painting on all affected accident parts. 1,350.00 950

\$ 6,458.30

Dollars : Six Thousand Four Hundred Fifty Eight And Cents Thirty Only. 3204.