

AES REC BY:

REF: CS/FCE19016309 / Kyd3 n2

Special Instruction:

Author: Kenneth
aws

ASSIGNMENT (Office)

From (Person): Siffherer of FEI Date/Time: 2:36pm @ 16/9/19

Estimated Cost: Bill to:

OD / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SLQ 9987L Insured: SHC 7442B

at Workshop m/s: Estem Performance Tel: 879910066

of 385 Sirming Drive

Policy No: Claim No: D19003665MPSH

Sum Insured: Excess:

Make of Veh: D.O.A. 01/06/2019

(Client's Record)

CA / REV / REP. / REV 24 HRS (up)

H.O.D. Endorsement:

Date/Time: 2:43pm @ 16/9/19 Person Contacted: Cammen Vehicle: IN/OUT

Date/Time	Action/Instruction	Estimate	
	SLQ 9987L - X		
	SHC 7442B - NA/INC 1100173/w		DUV: 26/01/2011
18/9/19	Sent Preli Revise by email		
23/10	8906.95 Confirm (Red = \$3527.98, 79%)		

ASS. REC. BY:

REF: 1021


Kenneth

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: _____
 at Workshop m/s: Estem
 of _____
 Insured: _____
 Policy No. _____
 Claims No. _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: 878k
 IDAC Accident Rpt: _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: 02 days Res.: Yes or No
 Lum Sum: 1.B.1 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS
 Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: SLG 9987L Yr Regn: 07, 17
 Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or _____
 Make: Toy Prius c.c. 1798
 Colour: M.P. White A/C: Insured / Std / NI / NA
 Sn. Plating: 97873 T/Radio: Insured / Std / NI / NA
 Eng/Mod: _____
 C.No: JTOKB31FU 403562495
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: E Inorder / Jammed / Leaked / Burnt or
 Brake: E Inorder / Jammed / Leaked / Burnt or
 Mod: Nil / S/R / STD / Rim or
 Tyre Size: Coelander 195/65R15
 R: Rovelo
 BS / DM / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or _____
 Front: _____ mm Rear: _____ mm
 R/Bal: 7 mm
 L/Bal: 7 mm
 D.O.A: 1/6/19 D.O.I: 17/9/19
 Survey held at: _____
 Des. of Damages: Fnt / Rear / O/S / N/S / UIC / Rooftop or
 The W/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
<u>1</u>	<u>File pass to</u>
RECEIVED: 23 OCT 2019	

Date/Time, File Pass to? : Prell. Report
 : Final Report

Days Of Repair: 2

Resurvey No. of Trlp: 1

Date/Time, File Return to?
 2) 23/10/19 Typist

Add Fee: Site Insp (\$)
 Interview (\$)
 For. Days (\$)
 Workshop (\$)

Survey Fee:	135
Transportation:	50
S - RS - SI	50
Fees	13
Others	
TOTAL	248

Report Format :
 Lump Sum / I.B.I. (\$)

PIP \$906-95



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D19003665MFSH

Date: 18 Sep 2019

Our Ref: CS/FCI19016309/Kyd3

The Motor Claims Department
MS First Capital Insurance Ltd

Dear Sir/Madam,


INITIAL INSPECTION REPORT OF VEHICLE NO. SLO9987L .

Please be informed that we had conducted the inspection of the abovementioned vehicle on 17/09/2019 at the premises of M/s ESTEEM PERFORMANCE PTE LTD. and have the following to report:-

Workshop Estimate Amount	: S\$	<u>4,434.93</u>	.
Revised Estimate Amount	: S\$	<u>931.95</u>	.
"Check" Items Amount	: S\$	<u>702.30</u>	.
Market Value	: S\$	<u>-</u>	.
LTA Reimbursement Value	: S\$	<u>-</u>	.
Nett Value	: S\$	<u>-</u>	.

Description of Damage:

The vehicle sustained damages at the rear portion.



Yours faithfully

KONG SENG CHEONG
Licensed Appraiser

MOTOR SURVEY ASSIGNMENT

Date	04-06-2019	Our Ref No. D19003665MFSH
Accident Date	01-06-2019	Claim Type. Third Party
Insured Vehicle	SHC7442B	Third Party Vehicle. SLQ9987L
Survey Location	385, SIN MING DRIVE (INSIDE VICOM)	
Contact Person.	SERENCE CHEE	
Contact No.	65662112/ 87990066	Fax No. 62593326
Survey Type	WITHOUT PREJUDICE:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	ESTEEM PERFORMANCE PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	SITHARA	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.

This is a computer generated letter, no signature required.

Yvonne Wong (LKK Auto)

From: Yvonne Wong (LKK Auto)
Sent: Wednesday, September 18, 2019 8:22 PM
To: 'CWS Motor Claims'
Cc: 'Sithara'; SUR
Subject: RE: SURVEY ASSESSMENT - D19003665MFSH/1
Attachments: SLQ9987L DOA 01062019 REVERT.pdf

Dear Sir/ Madam

Enclosed preliminary revised of vehicle SLQ9987L
Date of survey : 17/09/2019
Number of days : 2 days
Thank you.

Best Regards,

Yvonne Wong (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: yvonnewong@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto)
Sent: Monday, September 16, 2019 3:07 PM
To: 'CWS Motor Claims' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: 'Sithara' <Sithara@msfirstcapital.com.sg>; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D19003665MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

Please be informed that vehicle is not in the workshop, repairer will arrange.

Best Regards

G.NIVITHA

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

From: CWS Motor Claims [mailto:cwsmotorclaims@msfirstcapital.com.sg]
Sent: Monday, 16 September 2019 2:36 PM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWS Motor Claims <cwsmotorclaims@msfirstcapital.com.sg>; Sithara <Sithara@msfirstcapital.com.sg>
Subject: PRI: SURVEY ASSESSMENT - D19003665MFSH/1

Dear Sir/Mdm,

We refer to the above reference.


Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Note: All the accident reports are uploaded into CWS for your perusal.

Best Regards,
Admin Team
Claim Workflow System
Motor Claims Department
MS First Capital Insurance Limited
Tel : 6507 3848
Fax : 6507 3849

PS: This is a system generated mail. Please do not reply to this mail.



This email has been checked for viruses by AVG antivirus software.
www.avg.com

CONFIDENTIAL

Annex E

NOTICE OF COMPLIANCE

This is to confirm that Sivanandam Ravi NRIC/FIN S7367360G, has reported to the Police a non-injury traffic accident

which occurred at Along Scotts Rd, before Orchard Road, beside FarEast Plaza on 01/06/2019 at 1515hrs

involving the following vehicles:

- SLQ9987L (Toyota Prius, White)
- SHC7442B (Honda, Yellow)
- GBF9426R (Yellow)

- 2 If this accident was reported to the Police within 24 hours of its occurrence, Then he/she has complied with Sec 84(2) of the Road Traffic Act, Cap 276.



Rank/Name of Issuing Officer: SSgt T130117 Haziq

Date: 01/06/2019 Time: 1934hrs

S/D Ref: 172

Police Post/Unit: Sembawang NPC

SEMBAWANG NPC
4 Sembawang Crescent
Singapore 757633
Tel: 1800-5549999
Fax: 68522499

Original -- to be issued to informant
Duplicate -- to be submitted to Traffic Police

CONFIDENTIAL

Version as of 15 Jan 2002

FC | Kenneth



ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536.
Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

Repair Estimates

SLQ 9987 L

*Not Authorized
Resurvey B4print*

Parts	(a) Cost / List Price Items	\$	<u>2,819.90</u>
	Plus/Less 25%	\$	<u>704.98</u>
	Total of Cost / List	\$	<u><u>2,114.93</u></u>
	(b) Nett Price Items		_____
	Less		_____
	Total of Nett Item		_____
	(c) Special Nett Items	\$	<u>200.00</u>
Total Parts Cost		\$	<u><u>2,314.93</u></u>
Labour		\$	<u><u>2,120.00</u></u>
Total		\$	<u><u>4,434.93</u></u>

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature: _____
Date: _____

The above total will be subjected to 7% G.S.T.

Name of Surveyor : Kenneth

Company : LKK

Survey conducted on : 17/9/19 at _____

Remarks By Surveyor

(a) The repair of this vehicle is Not authorized / is not authorized until further notice.

(b) Recommended Days of Repair : 02 day(s)

(c) Resurvey : Required / ~~Not Required~~

(d) Excess : \$ _____

(e) Signature of surveyor : Lc Date: 17/9/19



ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259. 569536.
 Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

Spare Parts

Vehicle No. : SLQ 9987 L
 Make & Model : TOYOTA PRIUS
 Chassis No : JTDKB3FU403562495

Submit By : SERENCE
 Year Manufacture : 2017
 Engine No. :

Cost / List

S/No.	Part Description	Qty	Unit Price	Price	Disposition by Surveyor
1	Reverse sensor	1	\$200.00	S.N	X
2	Rear bumper	1	\$497.50		X
3	Rear bumper clip	10	\$40.00		X
4	Rear bumper side retainer LH	1	\$112.70		X
5	Rear bumper side retainer RH	1	\$112.70		X
6	Rear bumper reinforcement	1	\$398.90		X
7	Rear bumper lower garnish centre	1	\$582.60		✓
8	Rear bumper lower garnish LH	1	\$149.70		X
9	Rear bumper lower garnish RH	1	\$149.70		X
10	Rear bumper tow cover	1	\$31.70		X
11	Rear bumper under cover	1	\$355.20		X
12	Rear bumper under cover LH	1	\$187.60		X
13	Rear bumper under cover RH	1	\$187.60		X
14	Rear bumper under cover clip	4	\$14.00		X
15					
16					
17					
18					
19					
20					
21					
22					
23					

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.



ESTEEM PERFORMANCE PTE LTD

Blok 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536.
 Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

Labour

Vehicle No. : SLQ 9987 L Submit By : SERENCE
 Make & Model : TOYOTA PRIUS Year of Manufacture : 2017

S/No	Labour Description	Esimated Price	Adjusted Price
1	TO RENEW DAMAGED PARTS & KNOCK OUT ACCIDENT REPAIR AREA. (REAR BUMPER, END PANEL, SPARE TYRE COMPARTMENT)	\$800.00	2001
2	TO PUTTY, RESPRAY PAINT FOR AFFECTED ACCIDENT REPAIR AREA. (REAR BUMPER, END PANEL, SPARE TYRE COMPARTMENT)	\$800.00	2201
3	To tuff coat. <i>nn</i>	\$50.00	X
4	TO Check wiring <i>nn</i>	\$50.00	X
5	To remove & refit reverse sensor	\$150.00	501
6	To conduct water leakage tests to ensure proper air and sealing <i>nn</i>	\$120.00	X
7	To remove & refit spare tyre, spare tyre board, carpet trim to assist work load. <i>nn</i>	\$150.00	X

Note: The above estimate of repair is based on visual assessment of the external affected areas. Any additional damages observed during the course of repair will be quote accordingly as a supplementary.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
MS FIRST CAPITAL INSURANCE LTD		Ref : CS/FCI19016309/Kyd3n2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 25-10-2019	
		Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SHC 7442B	Veh. Inspected	SLQ 9987L
Policy No.		Coverage (\$)	0.00
Claim No.	D19003665MFSH	Excess (\$)	0.00
Assign From	SITHARA	Assign Date	16/09/2019
2. Vehicle Particulars & Condition			
Make & Model	TOYOTA PRIUS (A)	c.c	1798
Engine No.	HIDDEN	Year of Reg.	2017
Chassis No.	JTDKB3FU403562495	Colour	METALLIC PEARL WHITE
Odometer	97673	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	195/65 R15	GRELANDER	8 mm
L/H Front Tyre	195/65 R15	GRELANDER	8 mm
R/H Rear Tyre	195/65 R15	ROVELO	7 mm
L/H Rear Tyre	195/65 R15	ROVELO	7 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	01/06/2019	Inspection Date	17/09/2019
Survey held at	385 SIN MING DRIVE		
Repairer	ESTEEM PERFORMANCE PTE LTD		
5a. Remarks			
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		2 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLQ 9987L

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	REAR BUMPER	SERVICEABLE	497.50	-
10	REAR BUMPER CLIP	NOT NECESSARY	40.00	-
1	REAR BUMPER SIDE RETAINER LH	SERVICEABLE	112.70	-
1	REAR BUMPER SIDE RETAINER RH	SERVICEABLE	112.70	-
1	REAR BUMPER REINFORCEMENT	TO REPAIR SEE LABOUR	398.90	-
1	REAR BUMPER LOWER GARNISH CENTRE	DENTED / CUT	582.60	582.60
1	REAR BUMPER LOWER GARNISH LH	SERVICEABLE	149.70	-
1	REAR BUMPER LOWER GARNISH RH	SERVICEABLE	149.70	-
1	REAR BUMPER TOW COVER	SERVICEABLE	31.70	-
1	REAR BUMPER UNDER COVER	SERVICEABLE	355.20	-
1	REAR BUMPER UNDER COVER LH	SERVICEABLE	187.60	-
1	REAR BUMPER UNDER COVER RH	SERVICEABLE	187.60	-
4	REAR BUMPER UNDER COVER CLIP	NOT NECESSARY	14.00	-
	LESS 25% DISCOUNT		-704.98	-145.65
			2,114.92	436.95
SPECIAL NETT ITEMS				
1	REVERSE SENSOR (SN)	SERVICEABLE	200.00	-
			200.00	-
LABOUR				
	TO RENEW DAMAGED PARTS & KNOCK OUT ACCIDENT REPAIR AREA.(REAR BUMPER,END PANEL,SPARE TYRE COMPARTMENT).INCLUSIVE OF THE REPAIR OF REAR BUMPER REINFORCEMENT.		800.00	200.00
	TO PUTTY,RESPRAY PAINT FOR AFFECTED ACCIDENT REPAIR AREA.(REAR BUMPER,END PANEL,SPARE TYRE COMPARTMENT).		800.00	220.00
	TO TUFF COAT.	NOT NECESSARY	50.00	-
	TO CHECK WIRING.	NOT NECESSARY	50.00	-
	TO REMOVE & REFIT REVERSE SENSOR.		150.00	50.00
	TO CONDUCT WATER LEAKAGE TESTS TO ENSURE PROPER AIR AND SEALING.	NOT NECESSARY	120.00	-

Report Ref No. CS/FC119016309/Kyd3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO REMOVE & REFIT SPARE TYRE, SPARE TYRE BOARD, CARPET TRIM TO ASSIST WORK LOAD.	NOT NECESSARY	150.00	-
			2,120.00	470.00
GRAND TOTAL			4,434.92	906.95
RECOMMENDED COST OF REPAIRS				906.95

Report Ref No. CS/FC119016309/Kyd3n2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.