

ASS. REC. BY:

REF: CS/FCI/19016310/T25 d3n2

Special Instructions:

Supervisor: Taufiq

CWS ASSIGNMENT (Office)

From (Person): Melina chira

of PCF

Date/Time: 12.14pm @ 16/9/19

Estimated Cost:

Bill to:

OD TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: 8MM 3213K

Insured: SHC 0086S

at Workshop n/s Performance

Tel: 63190174

of 303 Aile Xandra Road

Policy No:

Claim No: D19005938M78H

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A. 08/09/2019

CA / REV / REP. / REV 24 HRS 1up

H.O.D. Endorsement:

Date/Time: 12.26pm @ 16/9/19

Person Contacted: Caroline

Vehicle IN OUT

Date/Time

Action/Instruction Isimuld ✓

8MM3213K-X

SHC 0086S-NS/INC/602486S/H/19/1912

BOA: 27/12/2016

21/10/19 @ 14:21 pm revised PA to ~~Melina~~ Melina V.a email.

ASS. REG. BY:

REF:

FCI

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of:

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: days Res.: Yes or No

Lum Sum: % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: Person Contacted:

Veh No:

SMM 3213K Yr Reg: 20/9, June

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

BMW X3

C.C.

1998

Colour:

Blue

A/C:

Insured / Std / NI / NA

Sp. Reading:

1930

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

WHA TR/2080L550948

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

245/50 R19

R:

7 -

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

7

mm

R/Bal.

7

mm

L/Bal.

7

mm

L/Bal.

7

mm

D.O.A.

D.O.I.

18/10/19 12/11/19

Survey held at

PME

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

Frt o/s

The UIC / Chassis frame / Body Structure affected due to collision

Date / Time

Action / Instruction

Tanbleh Carried P/P \$ 3,857.10 @ 3 days with Sharon.
(\$ 6,011.50 ~~Red~~ - Red - 61%)

RECEIVED 16 DEC 2019

Date/Time, File Pass to?

16/12/19

1)

Type

Date/Time, File Return to?

2)

Pop. Format

Lump Sum / P/P:

\$ 3,857.10 P/P



Prel. Report



Final Report

Days Of Repair:

3

Resurvey No. of Trip:

1

Add Fee:



Site Insp (\$



Interview (\$



Tech. Invs (\$



Week end (\$

Survey Fee:

170

Transportation:

50

S + RS \$

50

Phone

18

Other

TOTAL

288



Auto
Consultants
Pte Ltd

Company Registration No. 199607188R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D19005938MFSH

Date: 21 October 2019

Our Ref: CS/FCI19016310/T1sd3

The Motor Claims Department
First Capital Insurance Ltd

Dear Sir/Madam,


INITIAL INSPECTION REPORT OF VEHICLE NO. SMM 3213K

Please be informed that we had conducted the inspection of the abovementioned vehicle on 18/10/2019 at the premises of M/s Performance Motors Limited and have the following to report:-

Workshop Estimate Amount	: S\$ 9,854.60
Revised Estimate Amount	: S\$ 3,763.10
"Check" Items Amount	: S\$ 5,010.50
Market Value	: S\$ -
LTA Reimbursement Value	: S\$ -
Nett Value	: S\$ -

Description of Damage:

The vehicle sustained damages at the front o/s portion.



Comments/ Present Status:

Damages Consistent.

Repair days: 3 days

Yours faithfully

Mohamad Taufikh
Automotive Assessor

MOTOR SURVEY ASSIGNMENT

Date	13-09-2019	Our Ref No. D19005938MFSH
Accident Date	08-09-2019	Claim Type. Third Party
Insured Vehicle	SHC0086S	Third Party Vehicle. SMM3213K
Survey Location	303 ALEXANDRA ROAD SIME DARBY PERFORMANCE CENTRE	
Contact Person.	CAROLINE	
Contact No.	63190174/ 0	Fax No. 64794601
Survey Type	WITHOUT PREJUDICE: ACCIDENT NOT REPORTED:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	PERFORMANCE MOTORS LIMITED	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	MERINA CHIA SAN SAN	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Shirley Hiew (LKK Auto)

From: Shirley Hiew (LKK Auto)
Sent: Monday, 16 December 2019 3:22 pm
To: Sharon Heng L K
Cc: SUR
Subject: RE: DIRECT SETTLEMENT FINAL REPORT - SMM3213K

Dear Sharon,

Finalize amount confirmed.

Final invoice and all supporting documents sent over to First Capital Ins Ltd.

"Best Wishes for Merry Christmas & Happy New Year 2020"

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

-----Original Message-----

From: Sharon Heng L K <sharon.heng.leekun@simedarby.com.sg>

Sent: Monday, 16 December 2019 11:08 am

To: Taufikh (LKKAuto) <Taufikh@lkkauto.com>

Subject: RE: DIRECT SETTLEMENT FINAL REPORT - SMM3213K

Dear Taufikh

Please find photos as per your request :

Best Regards

Sharon Heng

Performance Motors Ltd

Body & Paint

DID : 63190123

Fax : 64743229

Shirley Hiew (LKK Auto)

From: Shirley Hiew (LKK Auto)
Sent: Monday, 21 October 2019 2:21 pm
To: 'Merina Chia'; 'CWS Motor Claims'
Cc: SUR; assignments
Subject: RE: SURVEY ASSESSMENT - D19005938MFSH/1
Attachments: PRELI ADVISE - SMM 3213K.pdf

Dear Merina,

Enclosed preliminary revised of vehicle SMM 3213K.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto) <admin-d@lkkauto.com>
Sent: Monday, 16 September 2019 3:06 pm
To: 'CWS Motor Claims' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: 'Merina Chia' <MerinaChia@msfirstcapital.com.sg>; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D19005938MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

Please be informed that vehicle is not in the workshop, repairer will arrange.

Best Regards

G.NIVITHA

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: CWS Motor Claims [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]

Sent: Monday, 16 September 2019 12:14 PM

To: ASSIGNMENTS@LKKAUTO.COM

Cc: CWS Motor Claims <cwsmotorclaims@msfirstcapital.com.sg>; Merina Chia <MerinaChia@msfirstcapital.com.sg>

Subject: PRI: SURVEY ASSESSMENT - D19005938MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Note: All the accident reports are uploaded into CWS for your perusal.

Best Regards,

Admin Team

Claim Workflow System

Motor Claims Department

MS First Capital Insurance Limited

Tel : 6507 3848

Fax : 6507 3849

PS: This is a system generated mail. Please do not reply to this mail.



This email has been checked for viruses by AVG antivirus software.
www.avg.com

Performance Motors Limited

A Sime Darby Motors Company
Co. Reg. No. 197401559M GST Reg. No M2-0020081-X
Toll-Free Number (1800-2255269)

303, Alexandra Road
Sime Darby Performance Centre
Singapore 159944
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Fax. 64796601 (AfterSales)
64796624 (Motorrad)



GST REG. NO : M2 - 0020081 - X

13 SEP 2019

ESTIMATE

Estimate No. : b1 52729
Date Estimated : 13/09/2019
Prepared By : Inthiran A/L Thurasamy

Page No. : 1 of 4

- ESTIMATE REPAIR FOR -

Ye Chengzhong
53 Holland Road
#02-04
Singapore
Singapore 258859

- ACCOUNT - 303

MS First Capital Insurance Limited
6 Raffles Quay
#21-00
Singapore 048580

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SMM3213K	LS30998	25/06/2019	X3 sDrive20i	0

DESCRIPTION

To replace front bumper and attachments.

850 1,700.00

Painting front bumper.

934 1,038.00

To check electrical wiring systems at the front section
for proper function including adjustments of headlights.

150 177.00

To remove old PDC assembly, replace damaged parts and
reconnect to new bumper including conduct checks for
proper function.

150 177.00

To replace right headlight.

nn-X? 408 481.00

Sundries.

nc ✓ 80 ? 150.00

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Total Labour 1: 3,723.00

DESCRIPTION

FRT RH FOG LAMP SUPPORT
FRT BUMPER PANEL PRIMED (M/PMA)
SET MOUNTING PDC/PMA SENSOR FRT (M)
RH HEADLIGHT LED AHL HIGH (ICON LIG

Acknowledged by Repairer

Signature:

QTY	PRIC
1	64.70
1	1,679.10
1	135.05
1	4,252.75

VALUE
nn-X? 64.70
u- 1,679.10
nn-X? 135.05
mx? 4,252.75

Total Parts : 6,131.60

Claims OD / 3rd Party / Uninsured losses / Direct Settlement

Reg No. 18/10/19 C 355
Date & Time 18/10/19 C 355
Surveyor's Name Tanjika
Surveyor's Tel 97495249
Authorised Yes / No
Signature
Time
PML Yes / No
Signature

Labour 1	: 3,723.00
Parts	: 9368.60 6,131.60
Labour 2	: 0.00
Excess	: 0.00
Total GST @ 7%	: 689.82
Grand Total	: 10,544.42

** THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY **
** PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE **



Supplementary

Estimate No. : **b1 52729**
Date Estimated : **13/09/2019**
Prepared By : **Inthiran A/L Thurasamy**

- ESTIMATE REPAIR FOR -

Ye Chengzhong
53 Holland Road
#02-04
Singapore
Singapore 258859

- ACCOUNT - 303

MS First Capital Insurance Limited
6 Raffles Quay
#21-00
Singapore 048580

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SMM3213K	WBATR12080LS3099	25/06/2019	X3 sDrive20i	0

DESCRIPTION	ORIGINAL PRICE	DISC. %	NETT
-------------	----------------	---------	------

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
-------------	------------	-----	---------	------

# EXPANDING RIVET BLACK <i>A</i>	1.40	10.00	0	14.00	REL ✓
----------------------------------	------	-------	---	-------	-------

SUPPLEMENTARY ITEMS

Total Labour :	
Total Parts :	14.00
Total Labour & Parts :	14.00



Final Report

Estimate No. : b1 52729
Date Estimated : 13/09/2019
Prepared By : Inthiran A/L Thurasamy

- ESTIMATE REPAIR FOR -

Ye Chengzhong
53 Holland Road
#02-04
Singapore
Singapore 258859

- ACCOUNT - 303
MS First Capital Insurance Limited
6 Raffles Quay
#21-00
Singapore 048580

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SMM3213K	WBATR12080LS3099	25/06/2019	X3 sDrive20i	0

DESCRIPTION	ORIGINAL PRICE	DISC. %	NETT
To replace front bumper panel including to remove and install body parts in order to carry out painting job.	850.00	0	850.00
To respray front bumper.	934.00	0	934.00
To check electrical wiring systems at the front section for proper function including adjustments of headlights.	150.00	0	150.00
To remove old PDC assembly, replace damaged parts and reconnect to new bumper including conduct checks for proper function.	150.00	0	150.00
Sundries.	80.00	0	80.00

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
FRT BUMPER PANEL PRIMED (M/PMMA)	1,679.10	1.00	0	1,679.10
# EXPANDING RIVET BLACK	1.40	10.00	0	14.00

SUPPLEMENTARY ITEMS

	QTY	DATE	COMPLETION DAY/S
FAX TO FAX NO	Tanfiah LKK	13/12/19	3
FAX TO FAX NO			
FAX TO FAX NO			
CONFIRMED DATE			
PLEASE SIGNATURE			

Total Labour :	2,164.00
Total Parts :	1,693.10
Total Labour & Parts :	3,857.10
GST @7%:	270.00
Grand Total :	4,127.10

CAR RENTAL = \$450.00 (3 DAYS)

Note : Please seek MANDATE from your Principle ASAP.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD		Ref : CS/FCI19016310/T1sd3n2		
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 23-12-2019		
		Code : FCI2		
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SHC 86S	Veh. Inspected	SMM 3213K
	Policy No.		Coverage (\$)	0.00
	Claim No.	D19005938MFSH	Excess (\$)	0.00
	Assign From	MERINA CHIA	Assign Date	16/09/2019
2. Vehicle Particulars & Condition				
	Make & Model	BMW X3	c.c	1998
	Engine No.	HIDDEN	Year of Reg.	2019
	Chassis No.	WBATR12080LS30998	Colour	BLUE
	Odometer	1930	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	245/50 R19	BRIDGESTONE	7 mm
	L/H Front Tyre	245/50 R19	BRIDGESTONE	7 mm
	R/H Rear Tyre	245/50 R19	BRIDGESTONE	7 mm
	L/H Rear Tyre	245/50 R19	BRIDGESTONE	7 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE FRONT O/S PORTION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	08/09/2019	Inspection Date	18/10/2019
	Survey held at	PERFORMANCE MOTORS LTD 303 ALEXANDRA ROAD SINGAPORE 159941		
5a. Remarks				
	A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMM 3213K

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	FRT RH FOG LAMP SUPPORT (SN)	NOT NECESSARY	64.70	-
1	FRT BUMPER PANEL PRIMED (M/PMA)(SN)	DEFORMED	1,679.10	1,679.10
1	SET MOUNTING PDC/PMA SENSOR FRT (M)(SN)	NOT NECESSARY	135.05	-
1	RH HEADLIGHT LED AHL HIGH (ICON LIG)(SN)	NOT NECESSARY	4,252.75	-
1	SUNDRIES (SN)	NECESSARY	150.00	80.00
10	EXPANDING RIVET BLACK (ADDITIONAL)(SN)	NECESSARY	14.00	14.00
			6,295.60	1,773.10
	LABOUR			
	TO REPLACE FRONT BUMPER AND ATTACHMENTS.		1,700.00	850.00
	PAINTING FRONT BUMPER.		1,038.00	934.00
	TO CHECK ELECTRICAL WIRING SYSTEMS AT THE FRONT SECTION FOR PROPER FUNCTION INCLUDING ADJUSTMENTS OF HEADLIGHTS.		177.00	150.00
	TO REMOVE OLD PDC ASSEMBLY, REPLACE DAMAGED PARTS AND RECONNECT TO NEW BUMPER INCLUDING CONDUCT CHECKS FOR PROPER FUNCTION.		177.00	150.00
	TO REPLACE RIGHT HEADLIGHT.	NOT NECESSARY	481.00	-
			3,573.00	2,084.00
	GRAND TOTAL		9,868.60	3,857.10
	RECOMMENDED COST OF REPAIRS			3,857.10

Report Ref No. CS/FCI19016310/T1sd3n2

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.