

...CLAIM SUBFOLDER...(Pending for Survey Report)

Revoked / No settlement

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	16 Sep 2019 Edit Reg		18 Sep 2019 00:00 Edit Adj Rpt	S\$4,616.00 Edit Estimates	S\$4,616.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured: FAN FOO WAH , ID: S0135581C									
Main Claimant: KOH POH TIN ANGELINE , ID: S7443843A									
Vehicle Reg. No.: SJV5105P		Date of Loss: 14/09/2019 10:00 - :59 [13 Months and 12 Days From LTA Reg Date (Man Yr)]							
Claim Type: TP / 4356165818SG		Policy/Cover Note No.: 1700062721 (Comprehensive) Coverage: 24/10/2018 - 23/10/2019							
Vehicle Reg. No. (Insured): SLT230E		Policy No. (Claimant): MT100672837							
		Excess:							
Repairer: Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1, 408699 Ubi - Tel: 67689828/9827/9911									
Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Syed-Yusoff, Saliha] Saliha.Syed-Yusoff@aig.com									
Claimant's Insurer: Direct Asia Insurance (Singapore) Pte Ltd (HQ) - Tel: 65322888									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by ADRIAN LING] ... [Final Rpt due 25/09/2019]									
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SJV5105P (4356165818SG)
[SLT230E]
TP
KOH POH TIN ANGELINE
Sep 14 2019 10:00AM
[FAN FOO WAH]
Premium Automobiles Pte Ltd

Upload Documents			Upload Photos			Compose New Letter			Upload Video			Upload Audio			View		View in Browser		
Video															1 per page				
No	Finalized On		LKK Auto Consultants Pte Ltd (HQ)												Thumbnail	Print			
1	16/09/19 19:30		Video - Accident TP VIDEO												Load MP4				
Photos/Images															3 per page				
No	Relabel/Reorder		LKK Auto Consultants Pte Ltd (HQ)												Thumbnail	Print			
1	23/09/19 09:31		General View												Load JPG				
2	23/09/19 09:31		General View												Load JPG				
3	23/09/19 09:31		General View												Load JPG				
4	23/09/19 09:31		General View												Load JPG				
5	23/09/19 09:31		General View												Load JPG				
6	23/09/19 09:31		General View												Load JPG				
7	23/09/19 09:31		General View												Load JPG				
8	23/09/19 09:31		General View												Load JPG				
9	23/09/19 09:31		General View												Load JPG				
10	23/09/19 09:31		General View												Load JPG				
11	23/09/19 09:31		General View												Load JPG				
12	23/09/19 09:31		General View												Load JPG				
13	23/09/19 09:31		General View												Load JPG				
14	23/09/19 09:31		General View												Load JPG				
15	23/09/19 09:31		General View												Load JPG				
16	23/09/19 09:31		General View												Load JPG				
17	23/09/19 09:31		General View												Load JPG				
18	23/09/19 09:31		General View												Load JPG				
Documentation															1 per page				
No	Relabel/Reorder		LKK Auto Consultants Pte Ltd (HQ)												Thumbnail	Print			
1	16/09/19 16:05		TP GIA REPORT												Load PDF				
2	19/09/19 17:25		TP ESTIMATE- MARKED												Load PDF				
3	23/09/19 09:58		LETTER TO OI												Load PDF				
4	24/10/19 11:46		SJV 5105P HEIGHT MEASUREMENT REPORT												Load PDF				
5	24/02/20 20:28		EMAIL FROM PREMIUM DD 24.02.2020												Load PDF				
6	20/07/20 11:55		HEIGHT MEASUREMENT REPORT (1)												Load PDF				
7	20/07/20 12:09		HEIGHT MEASUREMENT REPORT (2)												Load PDF				
No	Finalized On		AIG Asia Pacific Insurance Pte. Ltd. (SG)												Thumbnail	Print			
1	17/09/19 17:11		OI GIA REPORT												Load PDF				

Documents Checklist

DOCUMENTS CHECKLIST															Reset Save Print		
There are no document checklists configured.																	

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC3/AIG19016320/AKA3S2**Date:** 20/07/2020REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1700062721
Claimant Vehicle No :	SJV5105P	Insured Vehicle No :	SLT230E
Date of Loss:	14/09/2019	Nature of Claim:	TP
		Claim No:	4356165818SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJV5105P	Engine No:	DAX038052
Make & Model:	AUDI Q5 SPORT, 2.0 TFSI QU S TRONIC (A)	Chassis No:	WAUZZZF4J2170329
Reg. Date:	02/08/2018 (Man. Year: 2018)	Odometer:	14942 km
Colour:	Black		
Engine Capacity:	1984 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Good	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	235/55 R19	Rear Tyre Size:	235/55 R19
Front Left Side:	Continental 6 mm	Rear Left Side:	Continental 6 mm
Front Right Side:	Continental 6 mm	Rear Right Side:	Continental 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	8,963.00	2,144.00	6,819.00	76.08
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,072.00	2,472.00	1,600.00	39.29
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	13,035.00	4,616.00	8,419.00	64.59
+ GST 7.00/7.00% (S\$)	912.45	323.12	589.33	64.59
Nett Amount (S\$)	13,947.45	4,939.12	9,008.33	64.59

INSPECTION

Date of Assignment:	18/09/2019		Premium Automobiles Pte Ltd (UBI)
Date Inspected:	18/09/2019	Inspected At:	55 Ubi Road 1
			Singapore 408699
Estimated Period of Repair:	3.0 days		

Adjuster: ADRIAN LING**Manager:** Khanchna Pothuraj

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

7/20/2020

Adjuster Report

(REPAIR COST NOT CONCLUDE)

(EXCLUDE CHECK ITEMS S\$300.00 NETT)

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	3		*FRONT BUMPER	Repair	2,364.00 FS	*- FS
2	1		*FRONT BUMPER SPOILER	Repair	685.00 FS	*- FS
3	1		*FRONT BUMPER UNDERRUN BAR	Cut	431.00 FS	*431.00 FS
4	1		*FRONT BUMPER AIR GUIDE GRILLE - RH	Cut	519.00 FS	*519.00 FS
5	1		*FRONT BUMPER END CAP - RH	Not Necessary	83.00 FS	*- FS
6	1		*RADIATOR GRILLE	Not Necessary	3,258.00 FS	*- FS
7	1		*FRONT BUMPER GRILLE - CENTRE	Not Necessary	129.00 FS	*- FS
8	2		*FRONT WHEEL COVER - LH / RH	Necessary	1,154.00 FS	*1,154.00 FS
9	1		*FRONT NO PLATE	Dented	40.00 FS	*40.00 FS
10	1		*SUNDRIES	*Check	300.00 FS	*- FS

F=Franchise part. S=SpcNett.

Total Parts (\$)	8,963.00	2,144.00
------------------	----------	----------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, FOG LAMPS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID.	New	480.00	480.00
2	TO DISMANTLE AND RENEW FRONT BUMPER ASSY. RE-ORGANISE FRONT CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	New	1,200.00	500.00
3	TO RESPRAY FRONT BUMPER, LOWER SPOILER AND WHEEL ARCH TRIMS.	New	2,200.00	1,300.00
4	TO CARRY OUT DIAGNOSTIC CHECKS.	New	192.00	192.00
Gross Labour Cost (\$\$)			4,072.00	2,472.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >