

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

WIP : 12430

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/TP/1122/2019/NS
Date : 17-Sep-19

Vehicle NOT IN workshop. Please arrange for survey.

Your insured veh no : SLT 230 E

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Ms Koh Poh Tin Angeline
Address : 12A Cairnhill Rise
#12-03
Singapore 229746
Telephone : (HP) +65 97505506
Type of Claim : Third Party Claims
Policy No. : MT 100672837
Vehicle No : **SJV 5105 P**
Model Code : Q5 SPORT 2.0 TFSI QU
Model / Year : 2/8/2018
Engine No : DAX 038052
Chassis No : WAUZZZF4J2170329
Mileage :
Date In :
Estimated By : Johnny Boo / Allan Wu
Accident Date : 14-Sep-19
Place of Accident : Kensington Park Road Service Road

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle. SJV 5105 P

S/n	Nature of Jobs	Estimated Charges	Surveyor's Recommendation
1	To remove and transfer front wire harness for headlights, horns, fog lamps, outside temperature sensor, headlight washer assy and front parking aid.	S/N \$ 480.00 ✓	
2	To dismantle and renew front bumper assy. Re-organise front crash management components. Reinstall all parts removed.	\$ 1,200.00 500	
3	To respray front bumper, lower spoiler and wheel arch trims.	\$ 2,200.00 1300.	Bumper 550 spoiler 350. Arch x 2 = 200 x 2 = 400. <u>1300.</u>
4	To carry out diagnostic checks.	S/N \$ 192.00 ✓	
TOTAL LABOUR CHARGES		: <u>\$ 4,072.00</u>	

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SJV 5105 P

S/N	Parts Description	<u>Damaged Parts & Prices</u>	
		S/Nett	Remarks
1	FRONT BUMPER <i>Regis</i>	3 \$ 2,364.00	X
2	FRONT BUMPER SPOILER <i>Regis</i>	\$ 685.00	X
3	FRONT BUMPER UNDERRUN BAR <i>cut</i>	\$ 431.00	✓
4	FRONT BUMPER AIR GUIDE GRILLE - RH <i>cut</i>	\$ 519.00	✓
5	FRONT BUMPER END CAP - RH <i>new</i>	\$ 83.00	+
6	RADIATOR GRILLE <i>new</i>	\$ 3,258.00	X
7	FRONT BUMPER GRILLE - CENTRE <i>new</i>	\$ 129.00	X
8	FRONT WHEEL COVER - LH / RH <i>new</i>	2 \$ 1,154.00	✓
9	FRONT NO PLATE <i>Painted</i>	S/N \$ 40.00	✓
10	SUNDRIES <i>?</i>	\$ 300.00	?
TOTAL SPARE PARTS		: \$ 8,963.00	
TOTAL LABOUR CHARGES		\$ 4,072.00	
GRAND TOTAL		\$ 13,035.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Name : Adrian King
Surveyed Date : 18/09/19.
Authorised Date :
Excess Cost :
Liability :
Remarks : Not Authorised, 03 Days

Please Note : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant