LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: FWD Singapore Pte. Ltd. 6 Temasek Boulevard #18-01 Suntec Tower 4 Singapore 038986 From: LKK Auto Consultants Pte Ltd 51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park Singapore 408933

Attn: Eileen Bay Date: 18 Sep 2019

Preliminary Advice

Insured Vehicle No : SJV2970C

TP Vehicle No : SJL5196D Accident Date : 13/09/2019

Make : HONDA VEZEL Assignment Date : 16/09/2019

Date of Inspection : 17/09/2019 Est. Duration of Repair : 5 days

Inspection At : Rally Pitstop (HQ)

176 SIN MING DRIVE #04-17 SINMING AUTO CARE

Singapore 787525

Point of Impact / General Description of Damages

The vehicle sustained impact / damagesN/S front... portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	4,598.53
Revised Amount	:S\$	3,476.20
Check Items (Estimated)	:S\$	0.00
Total	:S\$	3,476.20

Lump Sum Repair :S\$

Total Loss Consideration

New for Old Value :\$\$
Pre-Accident Value :\$\$
COE / PARF Rebate :\$\$
Salvage Value :\$\$
Margin for Repair :\$\$

Remarks

()	The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
()	The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.

(X) Other comments : We have not authorized repairs.