Shirley Hiew (LKK Auto)

From: Shirley Hiew (LKK Auto)

Sent: Friday, 4 December 2020 11:47 am

To: Boo seng yak

Cc: 'Carrine Leong'; jiayee.yap@premiumauto.com.sg; SUR; Rasul (LKKAuto)

Subject: RE: FINAL REVISION - SMG733C - OD AIG - SURVEYED 16 SEP 19

Dear Mr. Boo,

Confirmed final figure \$38,821.92 instead of \$40,623.84 @ 28 days before excess \$1,600/- & GST.

Kindly expedite the discharge voucher and tax invoice to us for close case.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: <u>Sur@lkkauto.com</u> | fax: 6256-4315 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Note: We are on work from home arrangement. All correspondence should be made via email. Submission of claim related documents will be in softcopy. Any inconvenience caused is much regretted.

From: Rasul (LKKAuto) < Rasul@lkkauto.com> Sent: Wednesday, 21 October 2020 9:22 am

To: Boo seng yak <boojohnny@gmail.com>; Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>

Cc: Celine Fong (LKKAuto) < celinefong@lkkauto.com>

Subject: RE: FINAL REVISION - SMG733C - OD AIG - SURVEYED 16 SEP 19

Hi Mr Boo,

As spoken to Adrian, these are the breakdown of the labour and spray paint that was highlighted to me by Adrian:

Labour :-

- 2 rear fender 10 days
- 4 doors 4 days
- Front fender RH 1 day
- Front bumper 1day

Total number of labour is 16 days = \$8000

Spray:-

- 4 doors 2200
- 2 rear fenders 1100
- 1 front fender 550
- 1 rear end panel 550
- 1 roof channel / door entrance etc , sill panel 550
- 4 door handle 400
- 1 wing mirror 150

Total cost of spray panel is \$ 5500

Aside to Shirley, kindly assist to seek mandate.

Note: We are on work from home arrangement. All correspondence should be made via email. Submission of claim related documents will be in softcopy. Any inconvenience caused is much regretted.

Best Regards,

Rasul | Assessor

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: <u>Rasul@lkkauto.com</u> | fax: 6841-4315 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



From: Boo seng yak [<u>mailto:boojohnny@gmail.com</u>]

Sent: Thursday, 8 October, 2020 2:50 PM

To: Rasul (LKKAuto)

Subject: Re: FINAL REVISION - SMG733C - OD AIG - SURVEYED 16 SEP 19

Hi Rasul,

I wish to inform you that I have spoken with Adrian few weeks ago, following from last year November 2019.

Please refer to Adrian and ask him to expedite closure with you for the labour charges.

Thank you!

Regards

Jb

On Thu, 8 Oct 2020, 14:15 Rasul (LKKAuto), <Rasul@lkkauto.com> wrote:

Hi Mr Boo,

Kindly assist

Note: We are on work from home arrangement. All correspondence should be made via email. Submission of claim related documents will be in softcopy. Any inconvenience caused is much regretted.

Best Regards,

Rasul | Assessor

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Rasul@lkkauto.com | fax: 6841-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



From: Rasul (LKKAuto)

Sent: Friday, 25 September, 2020 1:22 PM

To: 'Boo seng yak'

Subject: RE: FINAL REVISION - SMG733C - OD AIG - SURVEYED 16 SEP 19

Hi Mr Boo,

Kindly do the breakdown for the labour

Note: We are on work from home arrangement. All correspondence should be made via email. Submission of claim related documents will be in softcopy. Any inconvenience caused is much regretted.

Best Regards,

Rasul | Assessor

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: <u>Rasul@lkkauto.com</u> | fax: 6841-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



From: Boo seng yak [mailto:boojohnny@gmail.com]

Sent: Friday, 12 June, 2020 3:37 PM

To: Rasul (LKKAuto)

Subject: Re: FINAL REVISION - SMG733C - OD AIG - SURVEYED 16 SEP 19

1. RHS front fender \$550.00

2. LHS/RHS front door \$1100.00

3. LHS/RHS rear door \$1100.00

4. LHS/RHS rear fender \$1100.00 (Discounted from \$1600)

5. Rear panel \$550.00

6. LHS/RHS drain channel \$550.00 (Discounted from \$1100)

7 LHS/RHS sill panel and door entrance \$1100.00

8. LHS/RHS roof channel \$550.00 (Discounted from \$1100)

9 Sealant/stonechip work \$100.00 (Discounted from \$3000

10. Wing mirror \$100.00

TOTAL : \$6,800.00

Please take note that additional \$400.00 for 4 new door's internal respray is also not added in and how am I able to accept your offer of \$5500 for respray. Is it a reasonable offer?

I await your favourable reply.	
Best regards - jb	
On Thu, Jun 4, 2020 at 11:25 AM Rasul (LKKAuto) < Rasul@lkkauto.com > wrote:	
Hi Mr Boo,	
Kindly refer to the email below	
Note: We are on work from home arrangement. All correspondence should be made via email. Submission of claim related documents will be in softcopy. Any inconvenience caused is much regretted.	
Best Regards,	
Rasul Assessor	
LKK Auto Consultants Pte Ltd	
Phone: 6256-3561 email: <u>Rasul@lkkauto.com</u> fax: 6841-4315	
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 S(408933)	
Save the Earth. Print only when necessary.	
From: Rasul (LKKAuto) Sent: Friday, 13 March, 2020 9:50 AM To: Boo seng yak Subject: RE: FINAL REVISION - SMC723C - OD AIC - SURVEYED 16 SED 10	
Subject: RE: FINAL REVISION - SMG733C - OD AIG - SURVEYED 16 SEP 19	
Hi Mr Boo,	
With regards to this case, insurance query on the labour and the spray paint. To breakdown the labour and the spray paint.	
Based on the figure, it was 8500 on the labour and 6700 for the spray paint. Can you assist to re-check again this labour and the spray paint again?	

I did consult to Adrian and his opinion is labour 8000 and the spray paint is 5500. Kindly assist on this matter

Rasul Assessor
LKK Auto Consultants Pte Ltd
Phone: 6256-3561 email: <u>Rasul@lkkauto.com</u> fax: 6841-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 S(408933)
Save the Earth Print only when necessary
From: Boo seng yak [mailto:boojohnny@gmail.com] Sent: Wednesday, 12 February, 2020 3:34 PM To: Rasul (LKKAuto) Subject: Re: FINAL REVISION - SMG733C - OD AIG - SURVEYED 16 SEP 19
Hi Rasul, Shirley and all,,
A new set of revised estimate is attached. I have deleted the parts where photographs is not available.
Please confirm revised repair cost of \$40,521.92
Best regards - jb
On Wed, Feb 12, 2020 at 12:10 PM Rasul (LKKAuto) < Rasul@lkkauto.com > wrote:
Hi Mr Boo,
There are a few damage items photos not received
1) FENDER LEDGE COVER RH INNER
2) FENDER TOP LEDGE COVER RH OUTER
3) DOOR HANDLE TRIM PLATE DRIVER DOOR
4) REAR DOOR CATCH

Best Regards,

Kindly assist

Best Regards, Rasul | Assessor LKK Auto Consultants Pte Ltd Phone: 6256-3561 | email: Rasul@lkkauto.com | fax: 6841-4315 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933) Save the Earth. Print only when necessary. From: Shirley Hiew (LKK Auto) Sent: Wednesday, 12 February, 2020 10:05 AM To: Rasul (LKKAuto) Subject: FW: FINAL REVISION - SMG733C - OD AIG - SURVEYED 16 SEP 19 Thank you. Best Regards, Shirley Hiew | Case Handler LKK Auto Consultants Pte Ltd Phone: 6256-3561 | email: <u>Sur@lkkauto.com</u> | fax: 6256-4315 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Boo seng yak <<u>boojohnny@gmail.com</u>> Sent: Wednesday, 15 January 2020 6:14 pm

To: Adrian Ling (LKKAuto)
