

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

WIP : 12186

Telefax

Estimate	:	Accident Repairs
Workshop	:	Ubi Road 1
Contact No	:	6366 2323
Fax No	:	6841 1183
Reference	:	PA/OD/1108/2019/NS
Date	:	12-Sep-19

Vehicle IN workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name	:	Mr Howe Wen Lee Christopher Mark
Address	:	Blk 781 Pasir Ris Street 71 #06-556 Singapore 510781
Telephone	:	HP +65 94912484
Type of Claim	:	Own Damage Claims
Policy No.	:	1800143688
Vehicle No	:	SMG 733 C
Model Code	:	A4 Sedan 2.0 TFSI 8W
Model / Year	:	Nov-18
Engine No	:	CVK 068759
Chassis No	:	WAUZZZF48JA232124
Mileage	:	10178KM
Date In	:	12-Sep-19
Estimated By	:	Johnny Boo / Allan Wu
Accident Date	:	11-Sep-19
Place of Accident	:	TPE/PIE Just Before Exit 5

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle. SMG 733 C

S/n	Nature of Jobs		Estimated Charges	Surveyor's Recommendation
1	To remove and reinstall front wire harness for headlights, horns, outside temperature sensor, headlight washer assy and front parking aid.	S/N	\$ 480.00 ✓	
2	To remove and reinstall rear parking aid and rear lid kick sensor.	S/N	\$ 360.00 ✓	
3	To renew rear windscreen and both 1/4 glass to facilitate fender renewal.	S/N	\$ 900.00 ✓	
4	To install rear windscreen film.	S/N	\$ 400.00 ✓ ? ✓	
5	To remove and transfer both rhs front and rear door and both lhs front and rear door's multi-lock system and power window devices. Inspect for damages.	S/N	\$ 1,120.00 ✓	
SUB TOTAL LABOUR CHARGES		:	<u>\$ 3,260.00</u>	

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel: 6366 2323 Fax: 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle. SMG 733 C

S/n	Nature of Jobs	Estimated Charges	Surveyor's Recommendation
6	To dislodge and reinstall rear wire harness for lights, battery manager, fuse and relay trays, electrical and audio equipments.	S/N \$ 1,400.00	
7	To remove and reinstall rear seat, back rest, hat tray, abcd pillar trims, luggage compartment trims. Dislodge roof liner and disengage curtain airbag etc.	S/N \$ 1,400.00	
8	To dismantle front bumper, rhs front fender, rhs front door, rhs rear door, lhs front door, lhs rear door, rear bumper and lid. Cut out and weld both rear fender and rhs side inner panel. Renew rhs front fender, rhs front door, rhs rear door, lhs front door, lhs rear door and lhs wing mirror assy. to repair front bumper, lhs front fender, bonnet and rear bumper, re-organise crash management components. reinstall all parts removed.	\$ 16,800.00	2000.00 8,000.00
9	To respray front bumper, bonnet, both front fenders, both front doors, both rear doors, lhs wing mirror cover, door handles, both rear fenders, rear bumper, rhs rear side inner panel, door entrances, roof channel, drain panel and end panelling. To carry out stone chip treatment and joint sealer works.	\$ 14,800.00	8 x 550 = 4400 Mirror = 150 Handle 100. 3850 4550 5,500.00
10	To renew rhs front rim and rhs rear rim. To carry out wheel alignment.	S/N \$ 320.00	
11	To carry out diagnostic checks.	S/N \$ 384.00	192
TOTAL LABOUR CHARGES		: \$ 38,364.00	

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel: 6366 2323 Fax: 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SMG 733 C

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remark
1	FRONT FENDER - RH <i>bt</i>	\$ 700.00	<i>559.60</i>
2	FRONT FENDER ATTACHMENT PARTS <i>? Xsu</i>	\$ 183.00	X
3	FRONT FENDER CLOSING ELEMENT - RH <i>? Xsu</i>	\$ 45.00	X
4	FRONT FENDER BRACKET - RH <i>? Xsu</i>	\$ 32.00	X
5	FRONT FENDER DEFORMATION ELEMENT BRACKET - RH <i>? Xsu</i>	\$ 45.00	X
6	FRONT FENDER BRACKET <i>? Xsu</i>	\$ 29.00	X
7	FRONT FENDER BRACE - RH <i>? Xsu</i>	\$ 107.00	X
8	FRONT FENDER CLOSING ELEMENT - RH <i>? Xsu</i>	\$ 30.00	X
9	WHEEL HOUSING LINER - RH <i>? Xsu</i>	\$ 220.00	X
10	WHEEL HOUSING LINER ATTACHMENT PARTS - FRONT AND REAR <i>? Xsu</i>	\$ 82.00	X
11	FRONT FENDER END PLATE - RH <i>? Xsu</i>	\$ 33.00	X
12	STONE CHIP GUARD - RH <i>cut</i>	\$ 46.00	<i>36.64</i>
13	FENDER LEDGE COVER - RH INNER <i>Xsu</i>	\$ 28.00	<i>X 22.24</i>
14	FENDER TOP LEDGE COVER - RH OUTER <i>Xsu</i>	\$ 21.00	<i>X 16.16</i>
15	FRONT DOOR - RH <i>bt</i>	\$ 2,152.00	<i>✓ 1721.60</i>
16	OUTER DOOR SEAL - RH <i>na</i>	NEC \$ 185.00	<i>147.60</i>
17	BONDING AGENT <i>na</i>	NEC \$ 45.00	<i>35.92</i>
18	CLEANING SOLUTION <i>na</i>	NEC \$ 65.00	<i>51.68</i>
19	FRONT DOOR - LH <i>bt</i>	\$ 2,152.00	<i>1721.60</i>
20	FRONT DOOR OUTER SEAL - LH <i>na</i>	NEC \$ 185.00	<i>147.60</i>
SUB TOTAL SPARE PARTS CHARGES		<u>\$ 6,385.00</u>	

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel: 6366 2323 Fax: 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SMG 733 C

S/N	Parts Description	Damaged Parts & Prices			Remark
		S/Nett			
21	BONDING AGENT <i>ne</i>	NEC	\$ 45.00		35.92
22	CLEANING SOLUTION <i>ne X an</i>	NEC	\$ 65.00		
23	FRONT DOOR ATTACHMENT PARTS <i>? an X</i>	2	\$ 975.00	X	
24	FRONT DOOR CATCH <i>? su</i>	2	\$ 191.00	X	
25	DOOR HANDLE TRIM PLATE - DRIVER DOOR <i>? X su</i>		\$ 80.00	X	62.52
26	DOOR HANDLE SENSOR - RH <i>? X su</i>		\$ 208.00	X	
27	FRONT PERIPHERAL LIGHT - RH <i>? X su</i>		\$ 66.00	X	
28	EXTERIOR DOOR HANDLE - RH <i>ca</i>		\$ 35.00		27.52
29	FRONT DOOR - LOCK CYLINDER <i>? X su</i>		\$ 492.00	X	
30	FRONT DOOR MOUNTING BAR - DRIVER DOOR <i>? X su</i>		\$ 149.00	X	
31	EXTERIOR MIRROR MOUNTING - LH <i>ca</i>		\$ 999.00		799.20
32	MIRROR CAP - LH <i>ca</i>		\$ 220.00		175.60
33	MIRROR GLASS - LH <i>ca</i>		\$ 1,132.00		905.60
34	FRONT DOOR CORNER TRIM - LH / RH <i>X su</i>	2	\$ 82.00		
35	WINDOW GUIDE TRIM STRIP - LH / RH <i>X su</i>	2	\$ 470.00		
36	WINDOW SLOT SEAL WITH TRIM STRIP - LH / RH <i>X su</i>	2	\$ 560.00		
37	FRONT DOOR WINDOW - LH <i>X su</i>		\$ 265.00		
38	REAR DOOR - LH <i>bt</i>		\$ 2,152.00		1721.60
39	REAR DOOR OUTER SEAL - LH <i>ne</i>	NEC	\$ 185.00		147.60
40	BONDING AGENT <i>ne</i>	NEC	\$ 45.00		35.92
SUB TOTAL SPARE PARTS CHARGES			<u>\$ 8,416.00</u>		

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel: 6366 2323 Fax: 6841 1183

Telefax

Material List for Accident Vehicle Regn No.SMG 733 C

S/N	Parts Description	Damaged Parts & Prices		Remark
		S/Nett		
41	CLEANING SOLUTION <i>new</i>	NEC	\$ 65.00	
42	FRONT DOOR SEALING STRIP <i>? x su</i>		\$ 15.00	X
43	REAR DOOR - RH <i>bt</i>		\$ 2,152.00	1721.60
44	REAR OUTER DOOR SEAL - RH <i>nee</i>	NEC	\$ 185.00	147.60
45	BONDING AGENT <i>nee</i>	NEC	\$ 45.00	35.92
46	CLEANING SOLUTION <i>new x nn</i>	NEC	\$ 65.00	X
47	REAR DOOR SEALING STRIP <i>? x su</i>		\$ 15.00	X
48	REAR DOOR ATTACHMENT PARTS <i>? x nn</i>	2	\$ 1,030.00	X
49	REAR DOOR CATCH <i>? x su</i>	2	\$ 218.00	X 82.70
50	REAR FENDER SIDE PANEL - LH / RH <i>bt</i>	2	\$ 4,886.00	3908.80
51	REAR WINDOW <i>nee - photo? - nee</i>		\$ 1,049.00	✓ 839.20
52	PRIMER <i>nee</i>		\$ 19.00	14.88
53	SIDE WINDOW - LH / RH <i>nee - photo? - nee</i>	2	\$ 1,122.00	✓ 896.80
54	WHEEL HOUSING LINER - LH / RH <i>? su x</i>	2	\$ 446.00	X
55	WHEEL HOUSING LINER ATTACHMENT PARTS <i>? nn</i>	2	\$ 164.00	X
56	C-PILLAR REINFORCEMENT - RH LOWER <i>? x su</i>		\$ 183.00	X
57	WINDOW SLOT SEAL WITH TRIM STRIP - LH / RH <i>x su</i>	2	\$ 670.00	
58	B-PILLAR TRIM - LH / RH <i>x su</i>	2	\$ 254.00	
59	FRONT RIM - RH <i>su</i>		TBC	200
60	REAR RIM - RH <i>su</i>		TBC	200
61	TYRE PRESSURE DATA PLATE <i>nee</i>		\$ 35.00	27.36
62	ACRYLIC SEALANT <i>nee</i>	S/N	\$ 360.00	
63	CAVITY WAX <i>nee</i>	S/N	\$ 280.00	
64	STONE CHIP <i>nee</i>	S/N	\$ 360.00	
65	METAL FILLER POWDER <i>nee</i>	S/N	\$ 560.00	
66	REAR WINDSCREEN SEALANT <i>nee</i>	S/N	\$ 200.00	
67	BOTH 1/4 GLASS SEALANT <i>nee x2</i>	S/N	\$ 200.00	
68	SUNDRIES <i>?</i>		\$ 800.00	✓ 50.16 137.36
TOTAL SPARE PARTS CHARGES		:	\$ 30,179.00	
TOTAL LABOUR CHARGES		:	\$ 38,364.00	
GRAND TOTAL		:	\$ 68,543.00	69430

All charges are not inclusive of GST.

Legend: Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Name

Surveyed Date

Authorised Date

Excess Cost

Liability

Remarks

15/9/19
: *Rashid - Hp 90010068*
: *16/02/19 @ 1600 hrs*
: *28 days*
: *EXCESS: TBA*
: *REVERT*
: *Re-survey before paint*
: *To check repair limit*

Please Note

- : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel: 6768 9828 for appointment.

Yours faithfully,

Premium Automobiles Pte Ltd

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during the survey
- Parts prices are subject to confirmation
- Third party survey is on a "No Fault Found" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be approved and
is subject to final approval from LKK Auto Consultants

Acknowledged by Repairer

Signature:

Date:

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant

Premium Automobiles Pte Ltd

55 Ubi Road 1, Singapore 408699

Tel : (65) 6366 2323 Fax : (65) 6841 1183

Supplementary Estimate 1

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd 78 Shenton Way #07-16 AIG Building Singapore 079120 Attn: Mr. Adrian Ling - Motor Claims Dept Tel: 6841 0055 - Fax: 6256 4315		Estimate No. Date Service Advisor Pages Regn No Model No	PA/OD/1108/2019/NS 10-Oct-19 Glory Tan 1 of 1 SMG 733 C A4 Sedan 2.0 TFSI 8W
Quantity	Description	Unit Price	Amount
<u>Parts</u> 1	Door lock rhs front cut ✓	\$ 487.00	\$ 389.20 A
TOTAL		\$ 487.00	\$ 389.20

For Premium Automobiles Pte Ltd

Authorised Signature