

Trans-cab Auto Services Pte Ltd

AAD1908-095

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5588C

Not Authored
11 Sep @ 1300h

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration:

SHC 5588C

VF1ABL15AUC279380

RENAULT

LATITUDE

8.8.19

AIG

30/9/2014

PART		LIST	
1	BOOT REFLECTOR LAMP RH	\$	<i>Sh</i> 277.70 <i>X</i>
1	BOOT REAR	\$	<i>N</i> 1,677.20 <i>X</i>
1	BUMPER COVER REAR	\$	<i>Bu</i> 561.70 <i>✓</i>
1	BUMPER LOWER REAR	\$	<i>nd/cm</i> 411.90 <i>✓</i>
1	BUMPER BRACKET CTR REAR	\$	<i>Sh</i> 98.10
1	BUMPER BRACKET SIDE RH REAR	\$	<i>Sh</i> 82.10
1	BUMPER RETAINER RH REAR	\$	<i>Sh</i> 59.80
1	BUMPER REFLECTOR RH	\$	<i>Sh</i> 16.60
1	BUMPER BEAM REAR	\$	<i>N</i> 547.80
1	BUMPER BEAM BRACKET RH REAR	\$	<i>N</i> 100.90
1	TAILLAMP RH	\$	<i>Sh</i> 313.10
1	TAILLAMP PANEL RH	\$	<i>N</i> 401.40
1	EXHAUST REAR	\$	<i>N</i> 5,263.60
1	EXHAUST CAP REAR	\$	<i>N</i> 125.40
TOTAL		\$	9,937.30
10%		\$	993.73
		\$	8,943.57

Special Nett

1	REAR BUMPER ADVERTISEMENT STICKER	\$	<i>Nr</i> 300.00 <i>100%N</i>
1	FENDER INNER TRIM CLIP RH	\$	<i>nn</i> 28.00 <i>X</i>
1	TAILLAMP CLIP RH	\$	<i>nn</i> 5.00 <i>X</i>
1SET	FENDER WHEELARCH REAR RH CLIP	\$	<i>nn</i> 35.00 <i>X</i>
2	REAR WINDSCREEN SEALANT	\$	<i>nn</i> 80.00 <i>X</i>
1	WINDSCREEN MOULDING	\$	<i>nn</i> 100.00 <i>X</i>
1	REAR WINDSCREEN INNER SPONGE SEAL	\$	<i>nn</i> 100.00 <i>X</i>
1	REAR RIGHT TYRE	\$	<i>Sh</i> 300.00 <i>X</i>
1	REAR RIGHT TYRE RIM	\$	<i>Sh</i> 380.00 <i>X</i>

Trans-cab Auto Services Pte Ltd**AAD1908-095**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5588C

1SET	PARKING AID	\$	700.00	X
1SET	REAR BUMPER CLIP	\$	66.00	—
1SET	BUMPER BRACKET CTR CLIP	\$	33.00	—
1SET	BUMPER BRACKET SIDE CLIP RH RR	\$	10.00	X
1SET	BUMPER RETAINER CLIP RH RR	\$	20.00	X
1SET	BUMPER LOWER REAR RIVET	\$	22.00	X
1SET	BUMPER LOWER REAR CLIP	\$	66.00	✓
1	EXHAUST MOUNTING REAR	\$	16.00	X
1	REAR BOOT ADVERTISEMENT STICKER	\$	300.00	X
TOTAL		\$	2,561.00	

TOTAL PARTS	\$	11,504.57
--------------------	-----------	------------------

LABOUR

Panel beating, knocking and straightening the necessary portion, remove and renewal of parts, adjust and realign the same	\$	4,500.00	200/
Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.	\$	380.00	X
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	380.00	X
To check steering geometry and computer wheel alignment	\$	220.00	X
To transfer of rear windscreen fittings and conduct water seepage test.	\$	170.00	X
To rust-proofing of the affected areas.	\$	170.00	X
To transfer of Rear bumper fittings, attachment and perform water seepage test.	\$	380.00	X
Putty and spray painting of the affected portion.	\$	4,500.00	220/
To transfer of tire, rim and on wheel balancing.	\$	170.00	X

Trans-cab Auto Services Pte Ltd**AAD1908-095**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5588C

To Check Electrical Lighting Concerned.	\$	<i>nn</i> 170.00 <i>X</i>
To reinstall rear bumper parking sensor.	\$	170.00 <i>601</i>
To drop rear exhaust box, renew the same, to repair and realign centre exhaust pipe.	\$	<i>nn</i> 170.00 <i>X</i>
To repair and realign rear exhaust pipe.	\$	<i>nn</i> 170.00 <i>X</i>
TOTAL	\$	11,550.00
Over All Total	\$	23,054.57

LUMP SUM (REPAIR DAY)~~15 DAYS~~*2 days*

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: