

ASSIGNMENT

Surveyor: MARCUSDOI: 17/09/2019Date / Time: 17/09/2019Registered in Merimen:

Pre-assign / CCU / FTE

Insured Vehicle No.: SJH 8184PClaim No.: 19/19/19/VP05/022390Name of Insured: FOO CHUAN TECKPolicy No.: Z19VP05022862Insured Tel No.: HP: +65-96620087Make / Model: MAZDA BIANTE-2.0 5DR S/WAGON (A)Excess Sec II :S\$ D.O.A: 17/09/2019 05:50Place of Accident: JUNCTION OF TAMPINES AVENUE 9Is driver the owner? (YES / NO) Nature of Accident: If NO, Driver Name / Age: OI GIA REPORT: YES / NO: TP GIA REPORT: YES / NO: Driver Tel No.: (V/L: YES / NO) Insured Liability: % Final ? Yes / No: SJH 2120MINSRS:
WSP: HOCK WAH
Tel: MOTOR
Liability:
RMKS: INSRS:
WSP:
Tel:
Liability:
RMKS: INSRS:
WSP:
Tel:
Liability:
RMKS: INSRS:
WSP:
Tel:
Liability:
RMKS:

Date/ Time		STAGE	DATE / PIC
	SJH 8184P - CS/TP10010175/Ucn; DOA: 21/5/10	Non-Reporting ltr (1st):	
	SJH 2120M - CC4/AIG08023599/UDh; DOA: 24/8/08	Non-Reporting ltr (2nd):	
	MINORISED	Non-Reporting ltr (Final):	
	TP LOD IN BY BMAIL	Notification ltr (if non-pickup):	
		Call OI:	
20/09/19	FILE REVIEWED. OI REKE-ENDED. TP.	After call ltr to OI:	
	BMAIL CABILITY CLEAR	Documentation Check List: Handler Typist	
		Notification ltr (if non-pickup)	☐
		After call ltr to OI:	☐
		Authorisation To Act:	☒
		Release Voucher:	☒
		Final Repair Bill:	☒
		Car Rental Invoice:	☒
		Towing Invoice:	☐
		LTA / GIA:	☐
		Medical Bill:	☐
		PIR:	☐
		Mandate/Reject Instruction:	☒
		LOD	☒
		Payment Breakdown Form:	☐
		Post-Repair Photos:	☐
		Others:	☐

PRELIMINARY ADVICE Date/Time: 19/09/19 Sent By: 03

FINALIZATION		Date/Time:	Confirm with:	Confirm by:
Repair Cost:	<u>LIS</u>	S\$ <u>3,650.00</u> (<u>5</u> days) Reduction: <u>A3</u> %		Email ☐ Call ☐
FINAL SETTLEMENT		Date/Time:	Confirm with:	Email ☐ Call ☐
Final Liability:	% <u>100</u> (Agreed / Assessed) BOLA S/N No.: <u>27</u>			
Repair Cost: (w/Gen)	S\$ <u>3,905.50</u>			
Loss of Rental (LOR):	S\$ <u>500.00</u> (<u>5</u> days) x <u>100.00</u>			
Loss of Use (LOU):	S\$ <u>—</u> (<u>5</u> x days)			
Loss of Income (LOI):	S\$ <u>—</u> (<u>5</u> x days)			
LOR only ☒ LOU only ☐	LOR + LOU ☐ LOR + LOI ☐ [Tick only one]			
GIA/LTA Search	S\$ <u>—</u>			
Medical:	S\$ <u>—</u>			
Disbursement:	S\$ <u>—</u> (e.g. Tow/ Independent)			
Legal Cost	S\$ <u>—</u>			
Total:	S\$ <u>4,405.50</u> Global Sum S\$: <u>—</u>			
FINAL PAYMENT		Date/Time:	Confirm with:	Email ☐ Call ☐
Payee 1:	S\$ <u>4,405.50</u> Name 1: <u>HOCK WAH MOTOR WORKSHOP PTE LTD</u>			
Payee 2: (Strike if N.A.)	S\$ <u>—</u> Name 2: <u>—</u>			
Payee 3: (Strike if N.A.)	S\$ <u>—</u> Name 3: <u>—</u>			



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: 19/19/19/VP05/022390
Our ref: CC6/LPC19016389/Uha3

Date: 19/9/19

The Motor Claims Department
M/s LONPAC INSURANCE BHD

Dear Sir/Madam,

PRELIMINARY ADVICE OF VEHICLE NO.

SJH 2120M

We refer to the above matter.

Please be informed that we had conducted the inspection of the above mentioned vehicle on 17/09/2019 at the premises of M/s Hock Wah Motor Workshop Pte Ltd - Tampines and have the following to report:-

Workshop Estimate Amount	: S\$	6,502.41
Revised Estimate Amount	: S\$	3,650.00
"Check" Items Amount	: S\$	-
Total (Including Check Items)	: S\$	3,650.00
Market Value	: S\$	- (est.)
LTA Reimbursement Value	: S\$	- (est.)
Nett Value	: S\$	- (est.)

Description of Damage:

The vehicle sustained damages at the
Rear Portion



Comments/Present Status:

Damages Consistent

Estimated normal period for repairs: 5.0 days

Yours faithfully,

MARCUS CHUA
Licensed Appraiser

SGCARMART.COM

Login

Sign up

New Cars

Used Cars

Sell My Car

Directory

Products

Insurance

Articles

Forum

Resources

SingPost Centre, Main Atrium

16 - 22 Sep 2019 - 10am to 10pm





Volkswagen

Terms and conditions apply.

vios

Price Range

Depreciation

> 10 year

Vehicle Type

Submit

Advanced Search

Home > Used Cars > Bz Carz Pte Ltd > Toyota Vios 1.5A E (COE till 04/2023)

Toyota Vios 1.5A E (COE till 04/2023)

- Overview
- Financial
- Insurance
- Accessories
- Similar
- Research
- Photos
- Map

PREMIUM AD

Price	\$24,500		
Depreciation	\$6,780 /yr	Reg Date	28-Apr-2008 (3yrs 7mths 10days COE left)
Mileage	90,389 km (7.9k /yr)	Manufactured	2008
Road Tax	\$752 /yr	Transmission	Auto
Dereg Value	\$13,959 as of today (change)	OMV	\$12,344
COE	\$19,328	ARF	\$12,289
Engine Cap	1,497 cc	Power	80.0 kW (107 bhp)
Curb Weight	1,095 kg	No. of Owners	2
Type of Vehicle	Mid-Sized Sedan		

Features
1.5litre VVT-I 16 Valves Inline DOHC Engine, Auto Transmission, ABS, EBD, Dual SRS Airbags, Superb Fuel Efficiency 15km/Litre! View specs of the Toyota Vios (2007-2013).

Accessories
Full Bodykit! Audio System, Solar Film, Retractable Side Mirror. Clean And Tidy Interior Upholstery. No Torn, Knockdown Rear Seat.

Description
Full Hot Bodykit! Beautiful Inside Out Toyota All Time Favourite Model Vios! Guarantee You This Will Be The Best Maintained Vios You Can Ever Find In The Market Available! Selling Cheapest In The Market! Most Suitable For Grab/Gojek Users Or Even Personal Usage! Not A Single Repair Needed! Servicing Just Done Up! Call Now Quick To Grab This Hot Deal Before It's Gone!

Category
COE Car, Premium Ad Car, Low Mileage Car

Status
Available

Resources



Car Valuation - Free
Find out the market value of your existing car for free. Get started



Vehicle Evaluation
Afraid of lemons? Request to have this car evaluated professionally. Find out more



- Shortlist
- Report Error
- Compare
- More Actions
- Add note

Seller Information		
Company	Bz Carz Pte Ltd	
	» dealer's pricelist	
	» 32 vehs sold 6 vehs available	
Address	1 Bukit Batok Crescent #04-43	
	Search cars nearby this location	
Location	WCEGA Plaza	
Contact Person(s)	Mr Ang	92233102
	Mr Liang	88768886

Compare

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle****Vehicle Owner Particulars**

Owner ID Type: Singapore NRIC

Owner ID: 740C

Vehicle Details

Vehicle No.: SJH2120M

Vehicle to be Exported: No

Intended Deregistration Date: 17 Sep 2019

Vehicle Make: TOYOTA

Vehicle Model: VIOS E AUTO

Primary Colour: Green

Manufacturing Year: 2008

Engine No.: 1NZX785125

Chassis No.: MR053HY9305074031

Maximum Power Output: 80.0 kW (107 bhp)

Open Market Value: \$11,834.00

Original Registration Date: 30 Jul 2008

First Registration Date: 30 Jul 2008

Transfer Count: 3

Actual ARF Paid: \$11,683.00

Intended PARF Rebate Details

PARF Eligibility: Forfeited

PARF Eligibility Expiry Date: -

PARF Rebate Amount: \$0.00

Intended COE Rebate Details

COE Expiry Date: 29 Jul 2023

COE Category: A - Car (1600cc & below)

COE Period(Years): 5

PQP Paid: \$18,583.00

COE Rebate Amount: \$14,366.00

Total Rebate Amount: \$14,366.00**Message**

Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 17 Sep 2019

HOCK WAH MOTOR WORKSHOP PTE LTD

BLK 9006 TAMPINES ST 93 #01-204
SINGAPORE 528840
TEL: 67853933 FAX: 67883933
R.O.C No. 200104141D GST Reg No. 20-0104141-D

TO : S8729740C

JORDANN SANTANNA APPADURAI
BLK 253 TAMPINES ST 21
06-40
SINGAPORE 521253
TEL : FAX :
PH : 98758549
ATTN :

ESTIMATE BILL

Number : EBK0000284
Date : 17/09/2019
Case No : ADK0000358
Vehicle No : SJH2120M
Chassis : MR035HY9305074031
Year of Mfr : 2008
Policy No :
Model : TOYOTA VIOS

Term:

Sn	DESCRIPTION	QTY	U_PRICE	DISC	AMOUNT
1	RR BUMPER	1.0	589.90	20	471.92
2	RR BUMPER SKIRT	1.0	493.50	20	394.80
3	RR BUMPER SIDE RETAINER LH RH	2.0	76.84	20	122.94
4	RR BUMPER CLIPS	10.0	5.50	20	44.00
5	RR BUMPER BRACKET LH RH	2.0	62.18	20	99.49
6	RR END PANEL	1.0	597.90	20	478.32
7	RR END PANEL TOP GARNISH	1.0	200.70	20	160.56
8	RR END PANEL TOP GARNISH CLIPS	8.0	5.90	20	37.76
9	RR BOOTLID	1.0	697.80	20	558.24
10	RR BOOTLID LOGO VIOS	1.0	85.54	20	68.43
11	RR BOOTLID LOGO SPORT	1.0	81.81	20	65.45
12	RR BOOTLID EMBLEM	1.0	75.20	20	60.16
13	RR TAILLAMP LH RH	2.0	247.96	20	396.74
14	RR BOOTLID LOCK TOP	1.0	152.80	20	122.24
15	RR BOOTLID LOCK BOTTOM	1.0	75.20	20	60.16
16	RR BOOTLID HINGE LH RH	2.0	88.20	20	141.12
17	RR BOOTLID INNER RUBBER	1.0	275.10	20	220.08
List Price - Parts Sub Total					3,502.41
18	RR BUMPER REVERSE SENSOR	1.0	300.00	0	300.00
Special Nett Price - Parts Sub Total					300.00
Parts Total					3,802.41
19	RR SPARE TYRE PANEL REPAIR	1.0			
20	RR FENDER LH RH REPAIR	1.0			
21	LABOUR TO REMOVE AND REFIT NECESSARY PARTS	1.0	1,200.00	0	1,200.00
22	SPRAY PAINT ON THE AFFECTED AREAS	1.0	1,000.00	0	1,000.00
23	WIRING	1.0	80.00	0	80.00
24	LABOUR TO TRANSFER INNER COMPONENTS FROM OLD BOOTLID TO NEW BOOTLID	1.0	150.00	0	150.00
25	ANTI RUST COATING	1.0	120.00	0	120.00
26	LABOUR TO INSTALL REVERSE SENSOR	1.0	150.00	0	150.00
Labour 1 Sub Total					2,700.00

E. & O. E.

HOCK WAH MOTOR WORKSHOP PTE LTD

CUSTOMER SIGNATURE

AUTHORISED SIGNATURE

not authorized
dehan
2/s #3650
17/9/19
Tokephat Akkay
54.

180f

180f

180f

200

600

850

30

60

60

50

2-3672-31

253

275423

4604-23

3683

HOCK WAH MOTOR WORKSHOP PTE LTD

BLK 9006 TAMPINES ST 93 #01-204
SINGAPORE 528840
TEL : 67853933 FAX: 67883933
R.O.C No. 200104141D GST Reg No. 20-0104141-D

TO : S8729740C
JORDANN SANTANNA APPADURAI
BLK 253 TAMPINES ST 21
06-40
SINGAPORE 521253
TEL : FAX :
PH : 98758549
ATTN :

ESTIMATE BILL

Number : EBK0000284
Date : 17/09/2019
Case No : ADK0000358
Vehicle No : SJH2120M
Chassis : MR035HY9305074031
Year of Mfr : 2008
Policy No
Model : TOYOTA VIOS

Term:

Sn	DESCRIPTION	QTY	U_PRICE	DISC	AMOUNT
SINGAPORE DOLLARS : SIX THOUSAND NINE HUNDRED FIFTY-SEVEN AND CENTS FIFTY-EIGHT ONLY			Less Excess		0.00
			SUBTOTAL		6,502.41
			GST 7.00%		455.17
			TOTAL		6,957.58

Date of accident : 17/09/2019 05:50 AM. Place : T-JUNCTION AT TAMPINES AVE 9 AND AVE 7

E. & O. E.

HOCK WAH MOTOR WORKSHOP PTE LTD

CUSTOMER SIGNATURE

AUTHORISED SIGNATURE

Mei Kwan (LKKAUTO)

From: Mei Kwan (LKKAUTO)
Sent: Thursday, 19 September, 2019 4:49 PM
To: ONG LI LI; MT_Claim_SG
Cc: GERALD POH WEE BIN; KENNY LIM CHING GHEE; Vic (LKKAUTO); CS A Team; Admin A
Subject: RE: Direct Settlement - Accident Involving SJH8184P (OI : LPC - 19/19/19/VP05/022390) AND SJH2120M (TP : LKK REF - CC6/LPC19016389/Uha3) on 17/09/2019
Attachments: TP ESTIMATE - MARKED.pdf; Preliminary Advice.pdf
Categories: HMK

'WITHOUT PREJUDICE'
SAVE AS TO COSTS

LPC ref: 19/19/19/VP05/022390
LKK REF: CC6/LPC19016389/Uha3

Dear Sir / Madam,

We refer to the above matter.

Enclosed revert of vehicle: SJH 2120M

We have not authorized repairs.

Enclosed for your perusal is:

- TP estimated cost of repair
- Preliminary advice

Thank you.

Best Regards,

Mei Kwan | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366 0055 | email: MeiKwan@lkkauto.com | fax: 67414108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: ONG LI LI <llong@lonpac.com>
Sent: Wednesday, 18 September, 2019 8:52 AM
To: Mei Kwan (LKKAUTO) <Meikwan@lkkauto.com>; MT_Claim_SG <mt_claim@lonpac.com>
Cc: GERALD POH WEE BIN <geraldpoh@lonpac.com>; KENNY LIM CHING GHEE <kennylim@lonpac.com>; Vic (LKKAUTO) <vicalpeh@lkkauto.com>; CS A Team <cs-a@lkkauto.com>; Admin A <admin-a@lkkauto.com>
Subject: RE: Direct Settlement - Accident Involving SJH8184P (OI : LPC - 19/19/19/VP05/022390) AND SJH2120M (TP : LKK REF - CC6/LPC19016389/Uha3) on 17/09/2019

Dear Mei Kwan

Please see attached for our Insured's GIA report.

Regards,
Ong Li Li
Senior Claims Executive | Lonpac Insurance Bhd
300 Beach Road #17-04/07 The Concourse
Singapore 199555
Tel : (65) 6250 7388 Ext. 254 Fax: (65) 6296 2706



From: Mei Kwan (LKKAuto) [mailto:Meikwan@lkkauto.com]
Sent: Tuesday, 17 September 2019 6:18 PM
To: MT_Claim_SG
Cc: ONG LI LI; GERALD POH WEE BIN; KENNY LIM CHING GHEE; Vic (LKKAuto); CS A Team; Admin A
Subject: Direct Settlement - Accident Involving SJH8184P (OI : LPC - TBA) AND SJH2120M (TP : LKK REF - CC6/LPC19016389/Uha3) on 17/09/2019

'WITHOUT PREJUDICE'
SAVE AS TO COSTS

Dear Sir / Madam,

We refer to the above matter.

We have inspected TP vehicle SJH 2120M at M/s Hock Wah Motor Workshop Pte Ltd – Tampines on a WP basis and TP repairer proposed for a direct settlement.

Enclosed for your perusal is:
- TP GIA report

Please be informed that the estimated cost of repair is not ready yet.

We will revert to you on preliminary advice in due course.

Meanwhile, kindly assist to verify validity of our insured's policy and let us have a copy of insured's accident report for our necessary action.

Kindly take note that the case handler in-charge is Vic and he can be contacted at DID: 6841 2096.

To check availability of the case handler, you may contact the undersigned.

Thank you.

Best Regards,

Mei Kwan | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366 0055 | email: MeiKwan@lkkauto.com | fax: 67414108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
LONPAC INSURANCE BHD		Ref : CC6/LPC19016389/Uha3n2	
300 BEACH ROAD #17-04/07 THE CONCOURSESINGAPORE 199555		Date : 26-02-2020	
		Code : LPC2	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SJH 8184P	Veh. Inspected	SJH 2120M
Policy No.	Z19VP05022862	Coverage (\$)	0.00
Claim No.	19/19/19/VP05/022390	Excess (\$)	0.00
Assign From		Assign Date	17/09/2019
2. Vehicle Particulars & Condition			
Make & Model	TOYOTA VIOS (A)	c.c	1497
Engine No.	HIDDEN	Year of Reg.	2008
Chassis No.	MR053HY9305074031	Colour	GOLD
Odometer	148265	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	195/55 R15	CONTINENTAL	6 mm
L/H Front Tyre	195/55 R15	CONTINENTAL	6 mm
R/H Rear Tyre	195/55 R15	CONTINENTAL	6 mm
L/H Rear Tyre	195/55 R15	CONTINENTAL	6 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	17/09/2019	Inspection Date	17/09/2019
Survey held at	BLK 9002 TAMPINES ST 93 #01-70 SINGAPORE 528836		
Repairer	HOCK WAH MOTOR WORKSHOP PTE LTD		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		5 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJH 2120M

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	RR BUMPER	DEFORMED / TORN	589.90	589.90
1	RR BUMPER SKIRT	CRACKED / DEFORMED	493.50	493.50
2	RR BUMPER SIDE RETAINER LH/RH @\$76.84	N/S BENT	153.68	76.84
10	RR BUMPER CLIPS @\$5.50	NECESSARY	55.00	50.00
2	RR BUMPER BRACKET LH RH @\$62.18	NOT NECESSARY	124.36	-
1	RR END PANEL	DENTED / BENT	597.90	597.90
1	RR END PANEL TOP GARNISH	NOT NECESSARY	200.70	-
8	RR END PANEL TOP GARNISH CLIPS @\$5.90	NOT NECESSARY	47.20	-
1	RR BOOTLID	BENT / BUCKLED	697.80	697.80
1	RR BOOTLID LOGO VIOS	NECESSARY	85.54	85.54
1	RR BOOTLID LOGO SPORT	NECESSARY	81.81	81.81
1	RR BOOTLID EMBLEM	NECESSARY	75.20	75.20
2	RR TAILLAMP LH RH @\$247.96	CRACKED	495.92	495.92
1	RR BOOTLID LOCK TOP	TWISTED	152.80	152.80
1	RR BOOTLID LOCK BOTTOM	NOT NECESSARY	75.20	-
2	RR BOOTLID HINGE LH RH @\$88.20	NOT NECESSARY	176.40	-
1	RR BOOTLID INNER RUBBER	TWISTED	275.10	275.10
	LESS 20% DISCOUNT		-875.60	-
	LESS 25% DISCOUNT		-	-918.08
			3,502.41	2,754.23
<u>SPECIAL NETT ITEMS</u>				
1	SET RR BUMPER REVERSE SENSOR (SN)	CRACKED	300.00	200.00
1	RR SPARE TYRE PANEL (SN) (NPA)	TO REPAIR SEE LABOUR	-	-
2	RR FENDET LH RH (SN) (NPA)	TO REPAIR SEE LABOUR	-	-
			300.00	200.00
<u>LABOUR</u>				
	LABOUR TO REMOVE AND REFIT NECESSARY PARTS.INCLUSIVE OF THE REPAIR OF RR SPARE TYRE PANEL AND RR FENDET LH RH		1,200.00	600.00

Report Ref No. CC6/LPC19016389/Uha3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	SPRAY PAINT ON THE AFFECTED AREAS.		1,000.00	850.00
	WIRING.		80.00	30.00
	LABOUR TO TRANSFER INNER COMPONENTS FROM OLD BOOTLID TO NEW BOOTLID.		150.00	60.00
	ANTI RUST COATING.		120.00	60.00
	LABOUR TO INSTALL REVERSE SENSOR .		150.00	50.00
			2,700.00	1,650.00
	GRAND TOTAL		6,502.41	4,604.23
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			3,650.00

Report Ref No. CC6/LPC19016389/Uha3n2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.