

HOCK WAH MOTOR WORKSHOP PTE LTD

BLK 9006 TAMPINES ST 93 #01-204
SINGAPORE 528840
TEL : 67853933 FAX: 67883933
R.O.C No. 200104141D GST Reg No. 20-0104141-D

TO : S8729740C
JORDANN SANTANNA APPADURAI
BLK 253 TAMPINES ST 21
06-40
SINGAPORE 521253
TEL : FAX :
PH : 98758549
ATTN :

ESTIMATE BILL

Number : EBK0000284
Date : 17/09/2019
Case No : ADK0000358
Vehicle No : SJH2120M
Chassis : MR035HY9305074031
Year of Mfr : 2008
Policy No :
Model : TOYOTA VIOS

Term:

Sn	DESCRIPTION	QTY	U_PRICE	DISC	AMOUNT
1	RR BUMPER	1.0	589.90	20	471.92
2	RR BUMPER SKIRT	1.0	493.50	20	394.80
3	RR BUMPER SIDE RETAINER LH RH	2.0	76.84	20	122.94
4	RR BUMPER CLIPS	10.0	5.50	20	44.00
5	RR BUMPER BRACKET LH RH	2.0	62.18	20	99.49
6	RR END PANEL	1.0	597.90	20	478.32
7	RR END PANEL TOP GARNISH	1.0	200.70	20	160.56
8	RR END PANEL TOP GARNISH CLIPS	8.0	5.90	20	37.76
9	RR BOOTLID	1.0	697.80	20	558.24
10	RR BOOTLID LOGO VIOS	1.0	85.54	20	68.43
11	RR BOOTLID LOGO SPORT	1.0	81.81	20	65.45
12	RR BOOTLID EMBLEM	1.0	75.20	20	60.16
13	RR TAILLAMP LH RH	2.0	247.96	20	396.74
14	RR BOOTLID LOCK TOP	1.0	152.80	20	122.24
15	RR BOOTLID LOCK BOTTOM	1.0	75.20	20	60.16
16	RR BOOTLID HINGE LH RH	2.0	88.20	20	141.12
17	RR BOOTLID INNER RUBBER	1.0	275.10	20	220.08
List Price - Parts Sub Total					3,502.41
18	RR BUMPER REVERSE SENSOR	1.0	300.00	0	300.00
Special Nett Price - Parts Sub Total					300.00
Parts Total					3,802.41
19	RR SPARE TYRE PANEL REPAIR	1.0			
20	RR FENDER LH RH REPAIR	1.0			
21	LABOUR TO REMOVE AND REFIT NECESSARY PARTS	1.0	1,200.00	0	1,200.00
22	SPRAY PAINT ON THE AFFECTED AREAS	1.0	1,000.00	0	1,000.00
23	WIRING	1.0	80.00	0	80.00
24	LABOUR TO TRANSFER INNER COMPONENTS FROM OLD BOOTLID TO NEW BOOTLID	1.0	150.00	0	150.00
25	ANTI RUST COATING	1.0	120.00	0	120.00
26	LABOUR TO INSTALL REVERSE SENSOR	1.0	150.00	0	150.00
Labour 1 Sub Total					2,700.00

E. & O. E.

CUSTOMER SIGNATURE

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Page 1 of 2

HOCK WAH MOTOR WORKSHOP PTE LTD

AUTHORISED SIGNATURE

* N = Item not subjected to GST

Issued by : Dehan

HOCK WAH MOTOR WORKSHOP PTE LTD

BLK 9006 TAMPINES ST 93 #01-204
SINGAPORE 528840
TEL :67853933 FAX:67883933
R.O.C No. 200104141D GST Reg No. 20-0104141-D

TO : S8729740C
JORDANN SANTANNA APPADURAI
BLK 253 TAMPINES ST 21
06-40
SINGAPORE 521253
TEL : FAX :
PH : 98758549
ATTN :

ESTIMATE BILL

Number : EBK0000284
Date : 17/09/2019
Case No : ADK0000358
Vehicle No : SJH2120M
Chassis: MR035HY9305074031
Year of Mfr 2008
Policy No
Model : TOYOTA VIOS

Term:

Sn	DESCRIPTION	QTY	U_PRICE	DISC	AMOUNT
SINGAPORE DOLLARS : SIX THOUSAND NINE HUNDRED FIFTY-SEVEN AND CENTS FIFTY-EIGHT ONLY			Less Excess		0.00
			SUBTOTAL		6,502.41
			GST 7.00%		455.17
			TOTAL		6,957.58

Date of accident : 17/09/2019 05:50 AM. Place : T-JUNCTION AT TAMPINES AVE 9 AND AVE 7

E. & O. E.

HOCK WAH MOTOR WORKSHOP PTE LTD

CUSTOMER SIGNATURE

AUTHORISED SIGNATURE