

ASS. REC. BY:

REF: 08/EGT1906396/R15 d3

Special Instruction:

Supervisor: Rasu

ASSIGNMENT (Office)

From (Person): Mimin Pauline Soh

of

EGIDate/Time: 17/9/19 @ 11:10am

Estimated Cost:

Bill to:

OD TP WS/TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLE S163L

Insured:

YL 65769

at Workshop m/s

Trans Eurocars

Tel:

6331 0683

of

27A Tanjung Perjuna

Policy No:

Claim No:

CDMCG19001695

Sum Insured:

Excess:

Make of Veh:

D.O.A.

12/09/2019

(Client's Record)

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time: 11:37am @ 17/9/19

Person Contacted:

Eva

Vehicle IN/OUT

Date/Time

Action/Instruction

Johnny ✓

SLE S163L - XYL 65769 - ECT/A1912011953 / m lupldua: 17/6/201220/9/19@ 17:33 pm revised PA to Ego via mimin

Rame

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SLE 5163Lat Workshop m/s TRANSEUROKARSof 27A, TANGKOR PARKWAYInsured: EGI

Policy No. _____


Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SLE 5163L Yr Regn: 2016 / JulyType: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: MAZDA 5 2-0L C.C. 1998Colour: Brown A/C: Insured / Std / NI / NASp. Reading: 51440 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: JM6CW107160124062Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim orTyre Size: F: 205/55R16

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 6 mm R/Bal. 6 mmL/Bal. 6 mm L/Bal. 6 mmD.O.A. 12/02/19 D.O.I. 19/02/19Survey held at TRANSEUROKARS


Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear n/s

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
21/10/19	Confirmed P/P \$ 8,860.82 @ 6 days with Rasul (\$ 4,913.61 Red - 36%)

RECEIVED 21 OCT 2019


 21/10/2019

Date/Time, File Pass to?

21/10/19

1) Type: _____

Date/Time, File Return to?

2) _____

Report Format:

Lump Sum: 8,860.82Days Of Repair: 6Resurvey No. of Trip: 1Add Fee: ☐ Site Insp (\$)☐ Interview (\$)☐ Tech. Insp (\$)☐ Wash end (\$)

Survey Fee:

Transportation

S + RS \$

Fines

Others

TOTAL

350

11

361

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: ERGO Insurance Pte. Ltd.
5 Temasek Boulevard
#04-01 Suntec Tower Five
Singapore 038985

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn:

Date: 20 Sep 2019

Preliminary Advice

Insured Vehicle No	: YL6576G	Accident Date	: 12/09/2019
TP Vehicle No	: SLE5163L	Assignment Date	: 17/09/2019
Make	: MAZDA 5	Est. Duration of Repair	: 6 days
Date of Inspection	: 19/09/2019		
Inspection At	: Trans Eurokars Pte Ltd - Tanjong Penjuru (HQ) 27A Tanjong Penjuru Singapore 609025		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages rear n/s portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	13,774.43
Revised Amount	:S\$	8,860.82
Check Items (Estimated)	:S\$	1,163.61
Total	:S\$	10,024.43

Lump Sum Repair :S\$

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

- () The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : TP : WP

Nivitha (LKK Auto)

From: ERGO Insurance Pte. Ltd. (Claims Department) <claims@ergo.com.sg>
Sent: Tuesday, 17 September 2019 11:10 AM
To: eva.kok@eurokars.com.sg; Ivy Yong; Phoebe Xie; Admin-D (LKKAuto (admin-d@lkkauto.com); Admin A (admin-a@lkkauto.com); Mei Kwan (LKKAuto (Meikwan@lkkauto.com)
Subject: RE: Claims ref no. (P) CDMCG19001695 TP CLAIMS- SLE5163L & YL6576G DOA 12/9/2019

Hi LKK,

Please conduct this survey request.
(Note: Survey vehicle only)

Kindly contact us if you are not able to make it.

***** NOTE:** Please assist to quote our claims ref no. as the subject matter, when forwarding the Preliminary Reports / Survey Reports.

Thank you.

Date Classification : Confidential, C3

Warmest Regards,
Pauline Soh
ERGO Insurance Pte. Ltd.

5 Temasek Boulevard, #04-05 Suntec Tower Five
Singapore 038985
DID: +65 6829 9194
pauline.soh@ergo.com.sg

ERGO

www.ergo.com.sg

ERGO is one of the major insurance groups in Germany and Europe. Worldwide, ERGO is represented in more than 30 countries and concentrates on Europe and Asia. ERGO is part of Munich Re (Group), one of the world's leading risk carriers.



Disclaimer: This message and its attachments are confidential, intended only for the named addressee, and may be privileged. If you are not the intended recipient, you should not disclose, distribute, copy or use this communication. If you are not the intended recipient, please notify the sender by return email and delete this message. By opening any attachment to this message, you agree to accept the risk that it may contain a virus or damaging code, and you agree that ERGO Insurance Pte Ltd. will not be liable for any loss or damage thereby caused.

From: eva.kok@eurokars.com.sg [mailto:eva.kok@eurokars.com.sg]
Sent: Tuesday, September 17, 2019 10:35 AM
To: ERGO Insurance Pte. Ltd. (Claims Department); Ivy Yong; Phoebe Xie; Pauline Soh
Subject: RE: TP CLAIMS- SLE5163L & YL6576G DOA 12/9/2019

Hi Pauline,

Please assign LKK.

Thank you

Regards,



Eva Kok

Insurance Claims Officer

27A Tanjong Penjuru

Singapore 609042

T: (65) 6331 0680 D: (65) 6331 0683 F: (65) 6331 0690

E: eva.kok@eurokars.com.sg W: www.eurokarsgroup.com

From: ERGO Insurance Pte. Ltd. (Claims Department) <claims@ergo.com.sg>

Sent: 17 September 2019 10:28 AM

To: Eva Kok <eva.kok@eurokars.com.sg>; Ivy Yong <ivy.yong@ergo.com.sg>; Phoebe Xie <phoebe.xie@ergo.com.sg>; Pauline Soh <pauline.soh@ergo.com.sg>

Subject: FW: TP CLAIMS- SLE5163L & YL6576G DOA 12/9/2019

Dear Eva,

Please refer to our list of surveyors

1	AIS	Automobile Inspection Services Pte Ltd
2	FTA	FormTeam Consultancy Pte Ltd
3	IAS	Infiniti Appraisal Service
4	JPk	JP Knights Pte Ltd
5	LBS	L.B.S Auto Consultants Pte Ltd
6	LKK	LKK Auto Consultants Pte Ltd
7	PS	Priority Services
8	VAC	Vicom Ltd
9	AJAX	AJAX Inspection Services Pte Ltd
10	QRM	Quantum Risk Management (S) Pte Ltd
11	AA	Appraisal Associate

Date Classification : Confidential, C3

Warmest Regards,
Pauline Soh
ERGO Insurance Pte. Ltd.

5 Temasek Boulevard, #04-05 Suntec Tower Five
Singapore 038985
DID : +65 6829 9194
pauline.soh@ergo.com.sg

ERGO is one of the major insurance groups in Germany and Europe. Worldwide, ERGO is represented in more than 30 countries and concentrates on Europe and Asia. ERGO is part of Munich Re (Group), one of the world's leading risk carriers.



Disclaimer: This message and its attachments are confidential, intended only for the named addressee, and may be privileged. If you are not the intended recipient, you should not disclose, distribute, copy or use this communication. If you are not the intended recipient, please notify the sender by return email and delete this message. By opening any attachment to this message, you agree to accept the risk that it may contain a virus or damaging code, and you agree that ERGO Insurance Pte Ltd. will not be liable for any loss or damage thereby caused.

From: eva.kok@eurokars.com.sg [mailto:eva.kok@eurokars.com.sg]
Sent: Monday, September 16, 2019 11:56 AM
To: ERGO Insurance Pte. Ltd. (Claims Department)
Cc: samuel.ng@eurokars.com.sg; jobithomas@eurokars.com.sg; jess.francis@eurokars.com.sg; catherinechua@eurokars.com.sg
Subject: TP CLAIMS- SLE5163L & YL6576G DOA 12/9/2019

YOUR REF: YL6576G / OUR REF: SLE5163L THIRD PARTY CLAIM

Dear Sir/Mdm,

Kindly arrange the survey of our client's vehicle,

Attached is the ESTIMATE & ACCIDENT REPORT for your perusal.

We would appreciate it if you can kindly let us know the liability/status of this case.

Regards,



Eva Kok
Insurance Claims Officer
27A Tanjong Penjuru
Singapore 609042
T: (65) 6331 0680 D: (65) 6331 0683 F: (65) 6331 0690
E: eva.kok@eurokars.com.sg W: www.eurokarsgroup.com

Shirley Hiew (LKK Auto)

From: Rasul (LKKAuto)
Sent: Friday, 18 October 2019 6:10 pm
To: catherinechua@eurokars.com.sg
Cc: eva.kok@eurokars.com.sg; Shirley Hiew (LKK Auto)
Subject: RE: SLE5163L - FINALIZATION OF COR

Hi Catherine,

Finalised amount confirmed


Best Regards,

Rasul | Assessor

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Rasul@lkkauto.com | fax: 6841-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



Auto
Consultants
Pte Ltd

Save the Earth. Print only when necessary.

From: catherinechua@eurokars.com.sg [mailto:catherinechua@eurokars.com.sg]
Sent: Friday, 18 October, 2019 3:18 PM
To: Rasul (LKKAuto)
Cc: eva.kok@eurokars.com.sg; CS A Team; Admin A
Subject: SLE5163L - FINALIZATION OF COR

Dear Rasul

Our COR computation with B4 paint photos is attached for your agreement.

COR: \$8860.82 before GST

6 repair days (not including preparation of estimate, wait for survey/authorization/spare parts, Sat/Sun/PH)

Kindly confirm the above as soon as possible

Thanks n Regards



Driving luxury experiences since 1985

Catherine Chua

Insurance Claims Executive

23 Leng Kee Road Singapore 159095

T: (65) 6603 6128 D: (65) 6603 6121 F: (65) 6476 7417

E: catherinechua@mazda.com.sg

This email, including any attachment, is intended for the sole use of the recipient(s) named above and may contain information that is confidential and/or proprietary to the Eurokars Group. If you have received it in error, please notify us immediately by reply email and then delete this message from your system. Please do not copy it or use it for any purpose, or disclose its contents or any attachment to any other person. Thank you.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	12/09/2019 17:27
Date Of Accident	12/09/2019 13:50
Exact Location Of Accident	CLEMENTI AVE 6 TO AYE TOWARDS CHANGI
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLE5163L
Insured/Policyholder	
Name Of Registered Owner	TAY CHIA MENG, BENJAMIN
Work Permit No	S7724707F
Email Address	TAYCHIAMENG@YAHOO.COM.SG
Mobile Phone No	(LOCAL) +65-96502704
Alternative Phone No	OFFICE-NOPHONE

Vehicle Particulars

Manufacturer	MAZDA
Model	MAZDA 5
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	LIBERTY INSURANCE PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	
Cover Note Number	

Driver

Name of Driver	TAY CHIA MENG, BENJAMIN
Work Permit No	S7724707F
Date Of Birth	04/09/1977
Occupation	INDOOR
Date Of Driving Pass	11/10/2000
Driving Experience	18 YEARS AND 11 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-96502704
Fax Number	
Contact Number	OFFICE-NOPHONE
EEmail Address	TAYCHIAMENG@YAHOO.COM.SG

Address BLK 987C JURONG WEST STREET 93 #03-575 SINGAPORE 643987

Postcode

Was driver an employee of the Insured's Company NO

If No, Relationship of the Driver with the Insured OWNER

Vehicle Registration Number of Driver's Own Vehicle -

Insurance Company of Driver's Own Vehicle -

General Information of the Accident

Type Of Accident COLLISION - HEAD TO REAR

Weather Conditions CLEAR

Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO

Number of vehicles (including own vehicle) involved in the accident 2

Was any body injured in the Accident? NO

Was any injured conveyed to hospital by ambulance? NO

Was any other material or property damaged? YES

I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO

Number of Passengers (Including Driver) 2

Passenger 1 NAME: : ONG KYE ZHENG
GENDER: : FEMALE

Details of Police Action

Was the accident reported to the police? NO

If Yes, Please state which Police Station

Was notice of intended Prosecution given? NO

If Yes, against whom?

Circumstances of Accident

REFER TO SKETCH PLAN

Attachment(s)

Are accident photos available for attachment? YES

Was there any video captured by Car Camera? NO

Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number YL6576G

Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category COMMERCIAL VEHICLE

Name of Driver TANG KAI MAN

NRIC/Passport Number S1367030G

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)


SKETCH PLAN


IMPORTANT NOTICE


1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver**.
3. Information provided must be as **truthful and accurate as possible**. Any wilful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability**.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:


- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "**Personal Information**") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "**Insurers**"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "**Purposes**")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.


Policyholder's Signature
Date & Time:


Driver's Signature
(If driver is not the policyholder)
Date & Time:


Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

LICENSE PLATE NO: SLE 5163L

ACCIDENT DATE: 12/09/19

CONTACT NUMBER: 9650-2704

ACCIDENT TIME: 1.52pm

EMAIL: taychiameng@yahoo.com.sg

LOCATION:

I was driving along Clementi Avenue 6 Slip road to AYE (dir of Changi Airport). I stopped at the filter lane for a bus to pass and was hit from behind by a truck (license plate no. YL 6576G).

NOTE: PLEASE NOTE THAT YOUR INSURER MAY HAVE 14 DAYS TIME FRAME FOR YOU TO SUBMIT AN OWN DAMAGE CLAIMS UNDER YOUR OWN POLICY.

PLEASE CHECK YOUR POLICY FOR MORE INFORMATION

PLEASE STATE: ☒ CLAIM OWN POLICY ☐ CLAIM THIRD PARTY ☐ REPORTING ONLY

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Motor Vehicles (Third-Party Risks And Compensation) Act (Chapter 189); Motor Vehicles (Third-Party Risks And Compensation) Rules, 1960; Road Transport Act, 1987 (Malaysia); Motor Vehicles (Third-Party Risks) Rules, 1959 (Malaysia)

Name of Policyholder: TAY CHIA MENG BENJAMIN		Certificate No.: SI19V08122/ VPE / R01
Date of Issue: 28 Jun 2019	Effective Date of Commencement: 25 Jul 2019 00:00	Date of Expiry: 24 Jul 2020 23:59
Registration No.: SLE5163L	Chassis No.: JM6CW1071G0124062	Type of Certificate: MX1

Persons or Classes of Persons entitled to drive*:

- A) The Policyholder.
B) Any other person who is driving on the Policyholder's order or with his permission.

Provided that the person driving is permitted in accordance with the licensing or other laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle.

And provided further that the Motor Vehicle is registered under the Road Traffic Act and its registration under the Road Traffic Act has not been cancelled at the time of the accident loss or damage.

Limitations as to use:

Use only for social, domestic and pleasure purposes and for the Policyholder's business.

The Policy does not cover:

- A) Use for hire or reward.
B) Use for racing, pace-making, reliability trials or speed-testing.
C) Use for the carriage of goods (other than samples) in connection with any trade or business.
D) Use for any purpose in connection with the Motor Trade.

*Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third Party Risks and Compensation) Act (Chapter 189) and Section 95 of the Road Transport Act, 1987 (Malaysia) are not to be included under these headings.

I/We hereby certify that the Policy to which this Certificate relates is issued in accordance with the provisions of the Motor Vehicles (Third Party Risks and Compensation) Act (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia).



For and on behalf of
LIBERTY INSURANCE PTE LTD
Approved Insurers

For Information Only:

Coverage(s):	Comprehensive, Unlimited Windscreen
Sum Insured:	MARKET VALUE AT THE TIME OF LOSS
Excess:	Section I - Named Drivers S\$700, Section I - Unnamed Drivers S\$1200, Additional Excess for Young, Elderly & Inexperienced Drivers S\$3000, Windscreen Excess S\$100
Name of Finance Company:	
Name of Producer:	MDIVINE INSURANCE AGENCY (A1391-2)



TRANS EUROKARS PTE LTD



ESTIMATE COST OF REPAIRS

Ergo Insurance Pte. Ltd. 5 Temasek Blvd, Singapore 038985		NAME : Mr Tay Chia Meng, Benjamin		WIP : 51226	
ATTN : MOTOR CLAIMS		ADDRESS : Apt Blk 987c Jurong West Street 93 #03-575 Singapore 643987		EXCESS :	
FAX :		TEL : 96502704		DATE: 16-Sep-19	
VEH NO :	SLE5163L	DATE IN :		CONTACT PERSON :	Eva 63310683
CHASSIS NO :	JM6CW1071G0124062	MILEAGE :		TYPE OF CLAIM :	TP CLAIMS
MODEL :	MAZDA5	DATE REG.:	25-Jul-16	POLICY NO. :	
NATURE OF WORKS					
Parts Description					
NO	QTY			REVISED	PRICES
1	REAR BUMPER <i>Re</i>	1	MC513-50-221EBB		\$ 961.20
2	REAR REINFORCEMENT <i>? X Svc</i>	1	MC235-56-B9XC		\$ 155.40
3	FASTENER, REAR BUMPER <i>Re</i>	2	MGD7A-50-EA1		\$ 6.40
4	GROMMET, REAR BUMPER <i>Re</i>	2	M9991-00-501		\$ 6.00
5	GROMMET, REAR BUMPER <i>Re</i>	4	MBHN1-50-0Z1A		\$ 10.80
6	GROMMET, REAR BUMPER <i>Re</i>	2	MC235-50-ES1		\$ 9.40
7	RIVET, REAR BUMPER <i>Re</i>	4	MBN8F-50-355		\$ 22.80
8	TAILGATE <i>bt</i>	1	MCGY3-62-02XF		\$ 1,637.00
9	WEATHERSTRIP, TAILGATE <i>Re</i>	1	MC513-62-761C		\$ 177.50
10	VALVE, ONEWAY <i>Re</i>	2	MGHP9-58-867		\$ 24.00
11	TRIM LOWER, TAILGATE <i>? X Svc</i>	1	MC513-68-960B		\$ 432.00
12	FASTENER, TRIM <i>Re</i>	5	MGJ21-68-885B02		\$ 15.00
13	ORNAMENT, MAZDA <i>Re</i>	1	MCGY0-51-711		\$ 45.30
14	ORNAMENT, 5 <i>Re</i>	1	MCGY0-51-721		\$ 36.30
15	MASCOT, REAR <i>Re</i>	1	MTD11-51-731		\$ 44.10
16	ORNAMENT, SKYACTIVE <i>Re</i>	1	MC597-51-771		\$ 80.00
17	FINISHER, TAILGATE <i>CR</i>	1	MC513-50-810F53		\$ 447.90
18	CLIP, FINISHER <i>Re</i>	3	MEG21-51-SJ3		\$ 17.10
19	LAMP LHS, TAILGATE <i>? X Svc</i>	1	MC513-51-3G0G		\$ 388.50
20	GASKET LHS, TAILGATE <i>Re</i>	1	MC513-51-3J8		\$ 95.40
21	GASKET RHS, TAILGATE <i>Re</i>	1	MC513-51-3H8		\$ 95.40
22	REAR MOTOR WIPER <i>? X Svc</i>	1	MC513-67-450		\$ 317.00
23	REAR WINDSCREEN MOULDING <i>Re</i>	1	MC513-50-611		\$ 60.50
24	FASTENER, REAR WINDSCREEN <i>Re</i>	6	MD204-50-896A		\$ 16.80
25	FASTENER, REAR WINDSCREEN <i>Re</i>	2	MC273-50-896		\$ 16.40
26	SPACER, REAR WINDSCREEN <i>Re</i>	4	MGJ6A-50-897		\$ 51.20
27	PIN STUD, REAR WINDSCREEN <i>Re</i>	1	MG21E-63-938B		\$ 11.10
28	DAM, REAR WINDOW <i>Re</i>	1	MDJ01-50-897		\$ 7.20
29	PROTECTOR, SPOILER <i>Re</i>	2	MC514-51-979B		\$ 11.00
30	PROTECTOR, SPOILER <i>Re</i>	2	MC514-51-982B		\$ 24.00

31	PROTECTOR, SPOILER	Ne /	2	MC514-51-972B		\$ 28.20
32	CLIP, SPOILER	Ne /	3	MC514-51-958A		\$ 23.10
33	CLIP, SPOILER	Ne /	1	MC525-51-958A		\$ 8.70
Exhaust tip not consistent						
TOTAL PARTS						\$ 5,282.70
LESS 10%						\$ 528.27
TOTAL PARTS COST						\$ 4,754.43

Labour Description

1	MZ-BR-REAR04	TO REPLACE REAR BUMPER, REAR REINFORCEMENT AND TAILGATE. TO REPAIR REAR END PANEL AND ALL AREAS AFFECTED BY THE ACCIDENT.	1320	\$ 2,640.00
2	MZ-SP-SREAR6	TO RESPRAY REAR BUMPER, REAR REINFORCEMENT, REAR END PANEL AND TAILGATE.	1260	\$ 2,520.00
3	MZ-BR-GLASS1	TO REMOVE & REFIT THE WINDSCREEN GLASS AND CONDUCT WATER LEAK TEST.	NETT	\$ 560.00
4	MZ-BR-GLASS2	TO SUPPLY SEALER ON THE WINDSCREEN GLASS.	NETT	\$ 120.00
5		TO REMOVE AND INSTALL SPOILER TAILGATE.	NETT	\$ 180.00
6	MZ-BR-TAILME	TO TRANSFER TAILGATE MECHANISM.		\$ 330.00
7	MZ-BR-REVSEN	TO TRANSFER REVERSE SENSORS. (WITH REVERSE SENSOR)	330 ^{NETT}	\$ 660.00
8	MZ-BR-CAMERA	TO TRANSFER REVERSE CAMERA.	NETT	\$ 330.00
9	MZ-BR-PLATE1	TO SUPPLY NUMBER PLATE. X 11	NETT	\$ 70.00
10	MZ-BR-TRIMS2	TO REMOVE & REFIT CARPET & TRIMS ON THE REAR SECTION TO GIVE WAY TO THE REPAIR ON THE REAR SECTION.	330	\$ 660.00
11	MZ-BR-CAVITY	TO CARRY-OUT BODY CAVITY PRESERVATION.	150	\$ 250.00
12	MZ-BR-ELECTR	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING.	150	\$ 250.00
13	MZ-BR-REPROG	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS.	180	\$ 350.00
14	MZ-BR-TOW-IN	TO SUPPLY BODY COATING. LPS X 11	NETT	TBA
15	MZ-BR-SUNDRI	SUNDRIES.	NETT	30 ^{100.00}

TOTAL LABOUR	\$ -	\$ 9,020.00
TOTAL PARTS	\$ -	\$ 4,754.43
TOTAL	\$ -	\$ 13,774.43
LESS EXCESS	\$ -	\$ -

TOTAL AFTER EXCESS	\$	-	
GST 7%	\$	-	\$ -
GRAND TOTAL	\$	-	\$ -

TRANS EUROKARS PTE LTD

REMARKS:

THIS IS ONLY AN ESTIMATE FROM VISUAL INSPECTION AND SHOULD THERE BE MORE DAMAGES FOUND DURING THE PROCESS OF REPAIRING, YOU WILL BE INFORMED BEFORE THE REPAIRS ARE BEING CARRIED OUT. TAKE NOTE THAT SHOULD YOU DECIDE NOT TO PROCEED WITH THE REPAIRS, A **QUOTATION FEE OF \$400** WILL BE APPLIED ACCORDINGLY FOR MAN-HOURS INVOLVED IN SOURCING FOR PARTS PRICE AS WELL AS LABOUR CHARGES.

Authorised Signature

[Handwritten Signature]
29/9/19
Case

Hp 90010068

6 days

19/09/19 @ 1400

Resury before paint

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



TRANS EUROKARS PTE LTD



FINALISED COST OF REPAIRS

Ergo Insurance Pte. Ltd. 5 Temasek Blvd, Singapore 038985		NAME : Mr Tay Chia Meng, Benjamin ADDRESS : Apt Blk 987c Jurong West Street 93 #03-575 Singapore 643987 TEL : 96502704		WIP : 51226 EXCESS : DATE : 16-Sep-19	
ATTN. : MOTOR CLAIMS FAX :		DATE IN :		CONTACT PERSON : Eva 63310683	
VEH NO :	SLE5163L	MILEAGE :		TYPE OF CLAIM : TP CLAIMS	
CHASSIS NO :	JM6CW1071G0124062	DATE REG.:	25-Jul-16	POLICY NO. :	
MODEL :	MAZDA5				
NATURE OF WORKS					
Parts Description					
NO	QTY		REVISED	PRICES	
1	1	MC513-50-221EBB	\$ 961.20	\$ 961.20	
2	1	MC235-56-B9XC		\$ 155.40	
3	2	MGD7A-50-EA1	\$ 6.40	\$ 6.40	
4	2	M9991-00-501	\$ 6.00	\$ 6.00	
5	4	MBHN1-50-021A	\$ 10.80	\$ 10.80	
6	2	MC235-50-E51	\$ 9.40	\$ 9.40	
7	4	MBN8F-50-355	\$ 22.80	\$ 22.80	
8	1	MCGY3-62-02XF	\$ 1,637.00	\$ 1,637.00	
9	1	MC513-62-761C	\$ 177.50	\$ 177.50	
10	2	MGHP9-58-867	\$ 24.00	\$ 24.00	
11	1	MC513-68-960B		\$ 432.00	
12	5	MGJ21-68-885B02	\$ 15.00	\$ 15.00	
13	1	MCGY0-51-711	\$ 45.30	\$ 45.30	
14	1	MCGY0-51-721	\$ 36.30	\$ 36.30	
15	1	MTD11-51-731	\$ 44.10	\$ 44.10	
16	1	MC597-51-771	\$ 80.00	\$ 80.00	
17	1	MC513-50-810F53	\$ 447.90	\$ 447.90	
18	3	MEG21-51-SJ3	\$ 17.10	\$ 17.10	
19	1	MC513-51-3G0G		\$ 388.50	
20	1	MC513-51-3J8	\$ 95.40	\$ 95.40	
21	1	MC513-51-3H8	\$ 95.40	\$ 95.40	
22	1	MC513-67-450		\$ 317.00	
23	1	MC513-50-611	\$ 60.50	\$ 60.50	
24	6	MD204-50-896A	\$ 16.80	\$ 16.80	
25	2	MC273-50-896	\$ 16.40	\$ 16.40	
26	4	MGJ6A-50-897	\$ 51.20	\$ 51.20	
27	1	MG21E-63-938B	\$ 11.10	\$ 11.10	
28	1	MDJ01-50-897	\$ 7.20	\$ 7.20	
29	2	MC514-51-979B	\$ 11.00	\$ 11.00	
30	2	MC514-51-982B	\$ 24.00	\$ 24.00	
31	2	MC514-51-972B	\$ 28.20	\$ 28.20	

--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--

REMARKS:

6 REPAIR DAYS (exclude preparation of estimate, wait for survey/authorizat

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/EGI19016396/R1SD3N2

Date: 05/11/2019

REFERENCE

Handling Insurer: ERGO Insurance Pte. Ltd. Policy No:
 Claimant Vehicle No : SLE5163L Insured Vehicle No : YL6576G
 Date of Loss: 12/09/2019 Nature of Claim: TP Claim No: CDMCG19001695

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SLE5163L Engine No: PE10355965
 Make & Model: MAZDA 5, 2.0 5 DR WAGON (A) Chassis No: JM6CW1071G0124062
 Reg. Date: 25/07/2016 (Man. Year: 2016) Odometer: 51440 km
 Colour: Brown
 Engine Capacity: 1998 cc
 Market Value/New Car Price: N/A
 Price:
 Sum Insured (\$\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/55R16 Rear Tyre Size: 205/55R16
 Front Left Side: Yokohama 6 mm Rear Left Side: Yokohama 6 mm
 Front Right Side: Yokohama 6 mm Rear Right Side: Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,924.43	3,620.82	1,303.61	26.47
Miscellaneous Items	0.00	0.00	0.00	
Labour	8,850.00	5,240.00	3,610.00	40.79
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (\$\$)	13,774.43	8,860.82	4,913.61	35.67
+ GST 7.00/7.00% (\$\$)	964.21	620.26	343.95	35.67
Nett Amount (\$\$)	14,738.64	9,481.08	5,257.56	35.67

INSPECTION

Date of Assignment: 17/09/2019

Date Inspected: 19/09/2019 Inspected At:

Trans Eurokars Pte Ltd - Tanjong
 Penjuru (HQ)
 27A Tanjong Penjuru
 Singapore 609025

Estimated Period of Repair: 6.0 days

Adjuster: MOHD RASUL

Manager: Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	(Last Synchronised: 05 Nov 2019)	
Parts:	N/A	MAZDA 5 2.0 5 DR WAGON (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLE5163L)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	961.20 FL	*961.20 FL
2	1		*REAR REINFORCEMENT	Serviceable	155.40 FL	*- FL
3	2		*FASTENER,REAR BUMPER	Necessary	6.40 FL	*6.40 FL
4	2		*GROMMET,REAR BUMPER	Necessary	6.00 FL	*6.00 FL
5	4		*GROMMET,REAR BUMPER	Necessary	10.80 FL	*10.80 FL
6	2		*GROMMET,REAR BUMPER	Necessary	9.40 FL	*9.40 FL
7	4		*RIVET,REAR BUMPER	Necessary	22.80 FL	*22.80 FL
8	1		*TAILGATE	Bent	1,637.00 FL	*1,637.00 FL
9	1		*WEATHERSTRIP,TAILGATE	Necessary	177.50 FL	*177.50 FL
10	2		*VALVE,ONEWAY	Necessary	24.00 FL	*24.00 FL
11	1		*TRIM LOWER,TAILGATE	Serviceable	432.00 FL	*- FL
12	5		*FASTENER,TRIM	Necessary	15.00 FL	*15.00 FL
13	1		*ORNAMENT,5	Necessary	36.30 FL	*36.30 FL
14	1		*MASCOT,REAR	Necessary	44.10 FL	*44.10 FL
15	1		*ORNAMENT,SKYACTIVE	Necessary	80.00 FL	*80.00 FL
16	1		*FINISHER,TAILGATE	Cracked	447.90 FL	*447.90 FL
17	3		*CLIP,FINISHER	Necessary	17.10 FL	*17.10 FL
18	1		*LAMP LHS,TAILGATE	Serviceable	388.50 FL	*- FL
19	1		*GASKET LHS,TAILGATE	Necessary	95.40 FL	*95.40 FL
20	1		*GASKET RHS,TAILGATE	Necessary	95.40 FL	*95.40 FL
21	1		*REAR MOTOR WIPER	Serviceable	317.00 FL	*- FL
22	1		*REAR WINDSCREEN MOULDING	Necessary	60.50 FL	*60.50 FL
23	6		*FASTENER,REAR WINDSCREEN	Necessary	16.80 FL	*16.80 FL
24	2		*FASTENER,REAR WINDSCREEN	Necessary	16.40 FL	*16.40 FL
25	4		*SPACER,REAR WINDSCREEN	Necessary	51.20 FL	*51.20 FL
26	1		*PIN STUD,REAR WINDSCREEN	Necessary	11.10 FL	*11.10 FL
27	1		*DAM,REAR WINDOW	Necessary	7.20 FL	*7.20 FL
28	2		*PROTECTOR,SPOILER	Necessary	11.00 FL	*11.00 FL
29	2		*PROTECTOR,SPOILER	Necessary	24.00 FL	*24.00 FL
30	2		*PROTECTOR,SPOILER	Necessary	28.20 FL	*28.20 FL
31	3		*CLIP,SPOILER	Necessary	23.10 FL	*23.10 FL
32	1		*CLIP,SPOILER	Necessary	8.70 FL	*8.70 FL
33	1		*ORNAMENT,MAZDA	Necessary	45.30 FL	*45.30 FL
34	1		*SUNDRIES	Necessary	100.00 FS	*30.00 FS
35	1		*NUMBER PLATE	Not Necessary	70.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	5,452.70	4,019.80
- List Item Discount on L Items 10.00/10.00% (\$\$)	528.27	398.98
Total Parts (\$\$)	4,924.43	3,620.82

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REPLACE REAR BUMPER,REAR REINFORCEMENT AND TAILGATE.TO REPAIR REAR END PANEL AND ALL AREAS AFFECTED BY THE ACCIDENT	New	2,640.00	1,320.00
2	TO RESPRAY REAR BUMPER,REAR REINFORCEMENT,REAR END PANEL AND TAILGATE	New	2,520.00	1,260.00
3	TO REMOVE & REFIT THE WINDSCREEN GLASS AND CONDUCT WATER LEAK TEST	New	560.00	560.00
4	TO SUPPLY SEALER ON THE WINDSCREEN GLASS	New	120.00	120.00
5	TO REMOVE AND INSTALL SPOILER TAILGATE	New	180.00	180.00
6	TO TRANSFER TAILGATE MECHANISM	New	330.00	330.00
7	TO TRANSFER REVERSE SENSORS.(WITH REVERSE SENSOR)	New	660.00	330.00
8	TO TRANSFER REVERSE CAMERA	New	330.00	330.00
9	TO REMOVE & REFIT CARPET & TRIMS ON THE REAR SECTION TO GIVE WAY TO THE REPAIR ON THE REAR SECTION	New	660.00	330.00
10	TO CARRY-OUT BODY CAVITY PRESERVATION	New	250.00	150.00
11	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING	New	250.00	150.00
12	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS	New	350.00	180.00
13	TO SUPPLY BODY COATING (NPA)	New	0.00	0.00
Gross Labour Cost (S\$)			8,850.00	5,240.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >