

ASS. REC. BY:

REF: CS/MSG 19016401 / U4f3

Special Instruction:

Surveyor: marcus

ASSIGNMENT (Office)

From (Person): Irene Tan Get Ing of MSG Date/Time: 17.9.19 15.0 p.m

Estimated Cost: _____ Bill to: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SGK 4931X Insured: FZ 4442Zat Workshop m/s Soc Leon Tel: 6747 7858of 1 KATI Bukit Ave 6 1A01-91Policy No: MSD/VMT/19-402652-C A Claim No: MS C/V/ 19-001066

Sum Insured: _____ Excess: _____

Make of Veh: _____ D.O.A. 27.8.19

(Client's Record)

CA / REV / REP. / REV 24 HRS

Date/Time: 17.9.19 3.18 p.m Person Contacted: Irene H.O.D. Endorsement: _____Vehicle IN/OUT

Date/Time	Action/Instruction (✓) Estimate
	SGK 4931X - X
	FZ 4442Z - CS/MSG 19003501 / 812602 DOA - 17/09/2019

(08/11/13) wef

ASS. REC. BY: MARCUS

REF:

MSIA

ASSIGNMENT

From:

Date:

Estimated Cost:

OD TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

SGK 4931 X

at Workshop m/s

Soclean

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GLA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days Res.: Yes or No

Lum Sum:

% 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

SGK 4931 X

Yr Regn:

6, 19Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

CA

Make:

Toyota C-HR Hybrid 1797

Colour

maroon

A/C: Insured / Std / NI / NA

Sp. Reading

6304

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

24X10 2035255Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

225/50 R18

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

7

Rear

7

R/Bal.

mm

R/Bal.

mm

L/Bal.

mm

L/Bal.

mm

D.O.A.

27/8/19

D.O.I.

17/9/19

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

18/9/19 contact LYA 58366 4/5 1530 with insur. (led. 1542.62; 497-)

John
18/9/2019

Date/Time, File Pass to?

1) 18/9 Typist

Date/Time, File Return to?

2)

☐ : Preli. Report☒ : Final ReportDays Of Repair: 3

Resurvey No. of Trip:

Survey Fee:

Transportation:

Add Fee:

☐ : Site Insp (\$

) S + RS \$

☐ : Interview (\$

) Photos

☐ : Tech. Invs (\$

) Others

☐ : Weekend (\$

)

Report Format:

TPLump Sum / I.B.I: (\$ 1550)

TOTAL

150
11
161

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	31 Aug 2019		17 Sep 2019 15:01 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	----------

CLAIM SUBFOLDER DETAILS

Insured:	MUHAMMAD ZULFIKAR BIN ABDUL SHARIFF, ID: S9445154Z			[Created by insurer]
Main Claimant:	CHOW MUN WAH, ID: S7117854D			
Vehicle Reg. No.:	SGK4931X	Date of Loss:	27/08/2019 00:00 - :59 [7 Months and 26 Days From LTA Reg Date (Man Yr)]	
Claim Type:	TP / MSC/V/19-001066	Policy/Cover Note No.:	MSD/VMT/19-402652-CA (Third Party Only)	
Vehicle Reg. No. (Insured):	FZ4442Z	Policy No. (Claimant):	Coverage: 21/08/2019 - 20/08/2020	
Repairer:	Soc Leon Motor Works (Kaki Bukit) 1 Kaki Bukit Ave 6, #01-91, AutoBay@Kaki Bukit, 417883 Kaki Bukit - Tel: 6747 7858			Excess:
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Irene Tan Gek Ing - 6594 2541]			
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 18/09/2019]			
Adj Asg. Remarks:	on WP. (Manual Assign to LKK Consultants Pte Ltd - Marcus Chua). Liab: unclear. (Change of workshop)			

ASSOCIATED MAIL RECEIVED

There are no mail for this case.

[View All](#)[Compose Case Mail](#)

ALL ASSOCIATED TASKS

Due Date	Priority	Type	Task Group	Subject	Handler	View All	Search Tasks	Create New Task	Complete
No results.						Assigned By	Completed On	Created On	Done?

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle****Vehicle Owner Particulars**

Owner ID Type:	Singapore NRIC
Owner ID:	854D

Vehicle Details

Vehicle No.:	SGK4931X
Vehicle to be Exported:	No
Intended Deregistration Date:	17 Sep 2019
Vehicle Make:	TOYOTA
Vehicle Model:	C-HR HYBRID 1.8G CVT
Primary Colour:	Red
Manufacturing Year:	2017
Engine No.:	2ZR8096061
Chassis No.:	ZYX102035755
Maximum Power Output:	90.0 kW (120 bhp)
Open Market Value:	\$31,480.00
Original Registration Date:	25 Jun 2019
First Registration Date:	25 Jun 2019
Transfer Count:	0
Actual ARF Paid:	\$26,072.00

Intended PARF Rebate Details

PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	24 Jun 2029
PARF Rebate Amount:	\$19,554.00

Intended COE Rebate Details

COE Expiry Date:	24 Jun 2029
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$39,728.00
COE Rebate Amount:	\$38,812.00
Total Rebate Amount:	\$58,366.00

The information contained herein is correct as at 17 Sep 2019

OK

REPAIRING OF
MOTOR VEHICLES,
PANEL BEATING,
WELDING, SPRAYING,
INSURANCE AGENT,
CLAIMS
DEALING IN 2ND
HAND VEHICLE.

速良摩哆 SOC LEON MOTOR WORKS

AUTOBAY @ KAKI BUKIT
1 Kaki Bukit Ave 6, Blk D, #01-91, Singapore 417883
Tel: 6747 7858, 6747 2343 Fax: 6742 0012
E-mail: slmoi@singnet.com.sg
Reg No. 206639/00K

修理汽車貨車兼
打嗎甲燒奸噴漆
代理保險：車禍
賠償及買賣汽車

MR CHOW MUN WAH

DATE: 13/09/2019

DOA: 27/08/2019

ESTIMATE REPAIR FOR VEHICLE NO. SGK 4931 X (TOYOTA C-HR)

	Description	List Price
1 pc	Rear bumper	\$ ne 581.10
1 pc	Rear bumper reinforcement	\$ del 456.00
10 pcs	Rear bumper clips @S\$8.00	\$ rec 80.00
1 pc	Rear bumper lower garnish	\$ 17.5 513.00
1 pc	Rear bumper centre cover (tow hook cover)	\$ 215 88.40
2 pcs	Rear bumper sensor (centre) @S\$502.50	\$ 111 1,005.00
		\$ 2,723.50
	Less : 25%	\$ (680.88)
		\$ 2,042.62
	<u>Special Nett Items</u>	
	Labour charges for knocking & replacing parts.	\$ 450.00
	Spraypainting	\$ 600.00
	TOTAL :	\$ 3,092.62

NOT Acknowled
17/9/19
3 day.

LKK Auto Consultants hence notify the Reparer of the following:

- * Repairs to be done after spray painting
- * "Without Prejudice" (part(s) during recovery
- * All prices are subject to confirmation
- * Repairs to be done on a "Without Prejudice" basis
- * Repairs to be done on a "Without Prejudice" basis
- * Repairs to be done on a "Without Prejudice" basis

Acknowledged by Reparer
Signature
Date

1/5 \$1550

7-1535-70
252
1151.77
1951.77
1561

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG19016401/UTF3N2

Date: 19/09/2019

REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	MSD/VMT/19-402652-CA
Claimant Vehicle No :	SGK4931X	Insured Vehicle No :	FZ4442Z
Date of Loss:	27/08/2019	Nature of Claim:	TP
		Claim No:	MSC/V/19-001066

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SGK4931X	Engine No:	2ZR8096061
Make & Model:	TOYOTA C-HR, 1.8 (A)	Chassis No:	ZYX102035755
Reg. Date:	25/06/2019 (Man. Year: 2017)	Odometer:	6304 km
Colour:	Maroon		
Engine Capacity:	1797 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/50R16	Rear Tyre Size:	225/50R16
Front Left Side:	Michelin 7 mm	Rear Left Side:	Michelin 7 mm
Front Right Side:	Michelin 7 mm	Rear Right Side:	Michelin 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	2,042.62	1,151.77	890.85	43.61
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,050.00	800.00	250.00	23.81
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	3,092.62	1,951.77	1,140.85	36.89
Approved Total (Overridden) (S\$)		1,550.00		
Nett Amount (S\$)	3,092.62	1,550.00	1,542.62	49.88

INSPECTION

Date of Assignment:	17/09/2019	
Date Inspected:	17/09/2019	Inspected At:
		Soc Leon Motor Works (Kaki Bukit)
		1 Kaki Bukit Ave 6, #01-91,
		AutoBay@Kaki Bukit
		Singapore 417883

Estimated Period of Repair: 3.0 days

Adjuster: MARCUS CHUA

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 19 Sep 2019)
 Parts: M1-SUV TOYOTA C-HR 1.8 (A) (Catalogue:Merimen Singapore 1.0)
 Labour: Repairer's (Price-denominated Standard List)
 Print Code: (Unsubmitted, no print-code for SGK4931X)
 Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
 Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Dented/Deformed	581.10 FL	*581.10 FL
2	1		*REAR BUMPER REINFORCEMENT	Bent	456.00 FL	*456.00 FL
3	10		*REAR BUMPER CLIPS	Necessary	80.00 FL	*50.00 FL
4	1		*REAR BUMPER LOWER GARNISH	Distorted	513.00 FL	*360.20 FL
5	1		*REAR BUMPER CENTRE COVER (TOW HOOK COVER)	Distorted	88.40 FL	*88.40 FL
6	2		*REAR BUMPER SENSOR (CENTRE)	Not Necessary	1,005.00 FL	*- FL
					Sub Total (S\$)	2,723.50 1,535.70
					- List Item Discount on L Items 25.00/25.00% (S\$)	680.88 383.93
					Total Parts (S\$)	2,042.62 1,151.77

F=Franchise part. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	LABOUR CHARGES FOR KNOCKING & REPLACING PARTS	New	450.00	300.00
2	SPRAYPAINTING	New	600.00	500.00
Gross Labour Cost (\$\$)			1,050.00	800.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >