

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: FWD Singapore Pte. Ltd.  
6 Temasek Boulevard  
#18-01 Suntec Tower 4  
Singapore 038986

From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: Lionel Tan

Date: 17 Oct 2019

## **Preliminary Advice**

Insured Vehicle No : SLZ6906T

TP Vehicle No : SLJ3955E

Make : HONDA VEZEL

Date of Inspection : 16/09/2019

Inspection At : LCRF PTE LTD

Accident Date : 12/09/2019

Assignment Date : 17/09/2019

Est. Duration of Repair : 4/Days

### **Point of Impact / General Description of Damages**

The vehicle sustained impact / damages ....Rear... portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	9,100.48
Revised Amount	:S\$	6,604.48
Check Items (Estimated)	:S\$	0.00
Total	:S\$	6,604.48

Lump Sum Repair :S\$

### **Total Loss Consideration**

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

### **Remarks**

- ( ) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- ( ) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- ( X ) Other comments :We have not authorized repairs.