

PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02
SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511
CO. REG:200707743D GST REG:200707743D

16-Sep-19

ESTIMATE REPAIR BILL FOR KIA OPTIMA REGN NO: SHC 6474 R

1 pc	Front o/s head lamp	cut	\$	1,028.00
1 pc	Front bumper	Reh	\$	696.00
1 pc	Front bumper emblem	X an	\$	44.00
1 pc	Front bumper o/s side retainer	X su	\$	16.00
1 pc	Front bumper o/s protector	X su	\$	51.00
1 pc	Front bumper o/s fog lamp cover	X su	\$	66.00
1 pc	Front o/s fender	Reh	\$	384.00
1 pc	Front o/s fender inner shield	X su	\$	120.00
1 pc	Front o/s wheel cover	X su	\$	116.00
				\$ 2,521.00
Less 10%				\$ 252.10
				\$ 2,268.90

S/NETT

1 pc	Front bumper clips	Re	\$	48.00
1 pc	Front o/s fender sticker	X an	\$	30.00
1 set	Front o/s fender inner shield clips	X an	\$	28.00
1 pc	Front o/s tyre (Tyre Brand: Achilies)	X su	\$	200.00

Sundry

To check front o/s wheel alignment

To labour charge for dismantle and renew the accident damaged parts. Including knock-out, straighten, repair, reshape and adjust of the same

To putty and spray painting on front bumper, front o/s fender

To apply rustproofing on the repaired and replaced panels.

\$	50.00	20
\$	80.00	X 1
\$	300	
\$	650.00	
\$	360	
\$	400.00	
\$	120.00	50
\$	3,874.90	

(ALL THE REPAIR COSTS ARE SUBJECTED TO GST)

THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE ANY UNFORESEEN DAMAGES.

Kalir 11/11/19
16/9/19 17:00h
3 hrs.
L/s
After Repair photo