



SINGAPORE CIVIL DEFENCE FORCE

FIRE REPORT

1. GENERAL INFORMATION			
INCIDENT NO. : /20190912/0862	LOCATION OF FIRE:		
FIRE REPORTED ON : 12 September 2019	Along Jurong East Flyover		
TIME OF CALL : 20:19:46 hrs	towards Jurong East Central / Bukit Batok Avenue 1		
STATION COVERAGE : Bukit Batok Fire Station	Singapore		
2. INCIDENT INFORMATION			
FIRE INVOLVED: A Nissan bus (PA 2621A) at the above said location.			
METHOD OF EXTINGUISHMENT: By SCDF crew using four dry powder fire extinguishers, compressed air foam backpack and two 38mm hose line jets from fire appliances.			
PROBABLE CAUSE OF FIRE: Accidental (Overheating at the engine compartment)			
DAMAGE SUSTAINED: As a result of the fire, the bus was damaged. The nearby road concrete barrier and railings sustained varying degrees of heat and smoke damage.			
3. FATALITY/INJURY INFORMATION			
NAME	PIN/FIN	ADDRESS	DEAD/INJURIES SUSTAINED
NIL	NIL	NIL	NIL
REPORT CERTIFIED TRUE AND CORRECT BY:			
EE YONG EN JOEL for COMMISSIONER SINGAPORE CIVIL DEFENCE FORCE			

This is a computer generated Fire Report. No signature is required.