



CHEW MOTOR PTE. LTD.

1 Kaki Bukit Avenue 6, Blk A #01-11 Autobay@Kaki Bukit Singapore 417883

Tel: 6509 5545

Fax: 6509 5567

Website: www.chewmotor.com

Registration No.: 201718369R

GST Reg No.: 201718369R

CYCLE AIRE(S) PTE LTD

17/09/2019

Blk 1 Kaki Bukit Ave 6

01-43

Singapore 417883

TP ALG

Tia Le

Accident date: 17/09/2019

Estimated repair cost for vehicle no: GBJ6728T TOYOTA DYNA 150 M 3.0 '19

CHASSIS: JTFAT35Y40K213606

S/n	Qty	Items	U/price	Amount	
1	1	Front Bumper Bent		\$820.25	✓
2	1	Front L/H Head Lamp ut		\$1,217.45	1158
3	1	Front L/H Head Lamp Panel ALM		\$374.25	+
4	1	Front L/H Head Lamp Lower Rubber ALM		\$121.45	+
5	4	Front L/H Head Lamp Lower Rubber Clip not ALM	\$3.50	\$14.00	+
6	1	Front L/H Corner Panel Dented		\$287.75	✓
7	1	Front L/H Door Dented		\$1,712.45	✓
8	2	Front L/H Door Hinge ALM	\$122.25	\$244.50	+
9	1	Front L/H Door Pillar Repair		\$631.35	+
10	1	Front L/H Door Company Sticker (Special Nett) ALM		\$50.00	30/SN)
11	1	Front L/H Door Inner Lock ALM		\$581.90	+
12	1	Front L/H Door Inner Rubber		\$374.45	+
13	1	Front L/H Door Inner Lower Rubber		\$182.10	+
14	1	Front L/H Door Inner Trim Board		\$781.45	+
15	1	Front L/H Door Gear Motor Assy		\$581.10	+
16	1	Front L/H Step Panel ut		\$274.10	✓
17	1	Front L/H Arch Panel Repair		\$281.90	+
18	1	Front L/H Arch Panel Garnish ALM		\$274.25	+

Subtotal :- **\$8,804.70**

4252.55 S.N. 30

3189.41

Labour charges

To remove & refit front L/H door, gear motor, glass, lock, rubber & trim board

~~\$180.00~~ 80

To check wiring

~~\$100.00~~ 30

Tuff kote

1310 ~~\$150.00~~ 1

Panel beating

~~\$1,400.00~~ 600

Spray painting

~~\$1,400.00~~ 600.

Subtotal :- \$3,230.00

Total:- \$12,034.70

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed **and** is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

total : 4329.41 (P/P)

04 days

4329.41