

GARAGE 833 LLP

Block 25 Kaki Bukit Road 4 #06-51 Synergy@KB Singapore 417800
HP: 92712214

KHOR TECK TUAN
25 KAKI BUKIT ROAD4
06-51 SYNERGY @KB
Singapore 417800

TP EQ
Xiao Tony

12nd SEP 2019

Accident date: 09th SEPTEMBER 2019
Estimated repair cost for vehicle no. : SDW75R BMW 640i ' 2013

S/n	Qty	Items	U/price	Amount
1	1	Rear R/H door <i>Distorted.</i>		\$1,482.00 ✓
2	2	Rear R/H door hinges <i>Best</i>	\$185.30	\$370.60 ✓
3	1	rear door top moulding <i>new</i>		\$221.20 x
4	1	Rear R/H door inner lock <i>Damaged.</i>		\$570.00 ✓
5	1	Rear R/H door inner trim board <i>new</i>		\$1,358.00 x
6	1	Rear R/H door glass gear <i>Damaged</i>		\$385.20 ✓
7	1	Rear R/H door gear motor <i>new</i>		\$485.00 x
8	1	Rear R/H lower skirt <i>Defound</i>		\$420.00 ✓
9	15	Rear R/H lower skirt clips <i>new</i>	\$3.50	\$52.50 30
10	1	Rear R/H fender <i>new</i>		\$1,490.00 x
11	1	Rear sport rim-RH <i>at</i>		\$600.00 ✓
12	1	Front door-RH <i>Distorted.</i>		\$1,520.40 ✓
13	1	Front door top hinge <i>new</i>		\$185.10 x
14	1	Front door lower hinge		\$185.30 x
15	1	Front door inner gear <i>Damaged</i>		\$388.20 ✓
16	1	Front door inner motor <i>new</i>		\$495.00 x
17	1	Front door inner lock <i>Damaged</i>		\$561.80 ✓
18	1	Front door side mirror-RH <i>new</i>		\$981.40 x
19	1	Front door top moulding		\$221.20 x
20	1	Front door inner trim board <i>new</i>		\$1,450.10 x
21	1	Front door inner rubber <i>new</i>		\$182.25 ✓
22	1	Front door inner sponge <i>new</i>		\$0.00 x
23	1	Front door pillar <i>new</i>		\$852.60 x
24	1	Front door handle -RH <i>new</i>		\$188.20 x

Subtotal :- \$14,646.05

Labour charges

To remove & re-fix cushion

\$120.00 ✓

Tuff kote

~~\$120.00~~ 50

To Check Wiring System

~~\$60.00~~ 30

Ceramic Coating RH front & rear door

~~\$1,000.00~~ 600

To panel beating

~~\$800.00~~ 600

Spray painting

~~\$800.00~~ 750

Subtotal :- \$2,900.00

Total :- \$17,546.05

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

total: 800940
c/s: 64K.
06 Days.

Enquire PARF/COE Rebate for Registered Vehicle

754F

Yes

09 Oct 2019

B.M.W.

640I GRAN COUPE 4DR SR LED DSC NAV HUD

Black

2013

08248456N55B30A

WBA6A02050DZ11564

235.0 kW (315 bhp)

\$81,156.00

30 Aug 2013

30 Aug 2013

2

\$118,081.00

Yes

29 Aug 2023

\$76,752.00

29 Aug 2023

E - Open Category

10

\$83,001.00

\$31,777.00

\$108,529.00

OK

https://vrl.lta.gov.sg/lta/vrl/action/enquireRebateByPublicBeforeDeregInput?FUNCTION_ID=F030... 9/10/2019