



ZOOM AUTOWERKS PTE LTD

130 Bedok Reservoir Road
#08-1339 Singapore 470130
Tel: 9450 7920
* zoomautowerks@gmail.com

LPC
Khaachna

18 September 2019

REG NO.: GBH 1185 C
MAKE/MODEL: TOYOTA DYNA

not Affected
1/5 \$8000 /
17/9/19
The photo Affected

ESTIMATED REPAIR COST FOR THE VEHICLE MENTIONED ABOVE

QTY	DESCRIPTION	AMT(\$)
	<u>LIST ITEMS</u>	
1	Rear tailgate	\$ 20/20 1,265.60
1	Rear tailgate lower panel	\$ 30 878.50
2	Rear tailgate lower stopper rubbers	\$ 11 145.20
2	Rear tailgate lower stopper brackets	\$ 11 213.00
1	Rear tailgate "TOYOTA" sticker	\$ 100 180.95
2	Rear taillamps	\$ 0/5 CME 659.30
2	Rear taillamp panels	\$ 11 399.00
1	Rear number plate panel	\$ 11 98.50
1	Rear exhaust pipe	\$ 30 752.60
1	Rear exhaust mounting	\$ 11 48.90
1	Front wiper panel	\$ 11 262.50
2	Front headlamps	\$ CME 2,161.00
1	Front panel	\$ 10/10 1,066.50
1	Front panel "DYNA" sticker	\$ 11 58.50
1	Front grille	\$ CME 648.69
1	Front grille clip set	\$ 11 68.50
1	Front grille logo	\$ CME 75.00
1	Front bumper	\$ 11 682.80
2	Front bumper brackets	\$ 30 316.00
1	Front chassis crossmember	\$ 11 698.55
		\$ 10,679.59
	Less 25%	\$ 2,669.90
		\$ 8,009.69

6093.74
252
6070.30

LKK Auto Consultants hence notify the Repairer of the following:

- Survey before/after spray painting
- To only damaged part(s) during resurvey
- Particulars are subject to confirmation
- The survey is on a "Without Prejudice" basis
- Any modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:

SPECIAL NETT ITEMS

1	Rear tailgate inner aluminium board	\$ <i>berl</i>	1,250.00	<i>600</i>
1	Rear tailgate "13 PAX" sticker	\$ <i>MR</i>	25.00	<i>10</i>
1	Rear tailgate "70KM/H" sticker	\$ <i>MR</i>	25.00	<i>10</i>
1	Rear step bar	\$ <i>berl</i>	300.00	<i>200</i>
1	Rear number plate	\$ <i>berl</i>	50.00	<i>14</i>
1	Rear reverse sensor (1 set)	\$ <i>Shub</i>	350.00	<i>200</i>
1	Front number plate	\$ <i>berl</i>	50.00	<i>15</i>
		\$	2,050.00	

S/NLABOUR CHARGES

1	To check wiring and reset headlamps focusing.	\$	80.00	<i>30</i>
2	To remove, replaced damaged lamps and check up rear wiring.	\$	80.00	
3	To remove and refit rear reverse sensor.	\$	150.00	<i>50</i>
4	To remove, replace air-con condenser and conduct leakage test.	\$	180.00	<i>100</i>
5	To remove, refit and replace exhaust silencer and mountings.	\$	150.00	<i>60</i>
6	To apply undercoating.	\$	200.00	<i>80</i>
7	Panel beating.	\$	2,000.00	<i>1400</i>
8	To re-spray painting on the affected areas.	\$	1,800.00	<i>1200</i>
		\$	4,640.00	

GRAND TOTAL :

\$	14,699.69
----	-----------

1- 6070.30
S.N- 1049.00
L - 2920.00

10039.30
282

8031