



陳林摩哆私人有限公司
TAN LIM MOTOR PTE LTD

1 Defu Lane 6 Singapore 539365
Tel : 68585151 (24 Hours) Fax : 68580877
GST Regn. No. : M2-8922054-2

Lonpac Insured's Veh No : SBN6881L
Date of Accident : 12 September 2019

Miss Lim Lucy

Date : 17 September 2019

Estimate To Repair SKL63A - Maserati Grancabrio
Chassis No : ZAMKM45C000053232

26/09/19 @ 1530h
26/09/19 @ 1530h

S/No	Quantity	Description	Amount
		<u>LIST ITEMS</u>	
01	1 pc	front bumper repair	\$ 5,450.00
02	1 pc	front bumper side retainer left X	\$ 150.00
03	1 pc	front bumper side lower grille left X	\$ 520.00
			\$ 6,120.00
		Less 10 %	\$ 612.00
			\$ 5,508.00
		<u>LABOUR & MISC. CHARGES</u>	
01		To check electrical lighting concerned.	\$ 60 100.00
02		Panel beating, knocking and straighten the necessary portion, remove and renewal of parts, adjust and realign the same.	\$ 800 1,000.00
03		Putty and spray painting of the affected portion.	\$ 800 1,200.00
			\$ 2,300.00
		Total	\$ 7,808.00

?
request
from
Tan
Lim

Rasul
Hp 90010068

4 days

26/09/19 @ 1530

3 p/p

Resurvey after repair

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: