

# TTS EUROCARS PTE LTD

383 Sin Ming drive Singapore 575717

Date : 16.09.2019

## RE: VEHICLE REPAIR QUOTATION

Insurance Company	:	
Vehicle Reg No	:	SKV5400A
Name of Insured	:	Chen Xueni
Policy Number	:	P1023861R00
Date of Accident	:	13.09.2019
Tyre of Claim	:	Third Party Claim
Model	:	Mini Cooper
Chassis No	:	WMWSU32020TY90153

We are please to submit our estimate of repairs to the above mention vehicle.

		Parts	Labour
1	FRONT RH FENDER PROTECTOR <i>scd</i>	\$ 130.00	
3	FRONT BONNET <i>X</i>	\$ 1,000.00	
4	FRONT RH DOOR <i>repair</i>	\$ 1,050.00	
5	FRONT RH SIDE MIRROR ASSY <i>repair</i>	\$ 223.00	
6	FRONT RH SIDE SKIRT <i>X</i>	\$ 73.00	
7	FRONT RH RIM <i>scd</i>	\$ 655.00	
8	FRONT RH WHEEL BEARING <i>?</i>	\$ 185.00	
9	FRONT RH WHEEL HUB <i>?</i>	\$ 385.00	
10	FRONT RH SHOCK ABSORBER <i>X</i>	\$ 390.00	
11	FRONT RH LOWER ARM <i>X</i>	\$ 265.00	
12	FRONT RH UPPER ARM <i>X</i>	\$ 280.00	
13	BALL JOINT <i>X</i>	\$ 105.00	
14	FRONT RH TPMS <i>?</i>	\$ 154.00	

Sub Total Parts \$ 4,895.00

Less 10% \$ 489.50

Total Parts \$ 4,405.50

1	Sundries	\$ 30	<del>80.00</del>
2	Wiring connection and check.	\$	150.00 <i>X</i>
3	Tuff kote and spray anti rust proofing	\$	<del>120.00</del> 20
4	Labour charges to dismantle & refix RHF fender, bonnet, front bumper, front headlamp and side mirror To repair and adjust affected portion to specific dimension.	\$	1,500.00 <del>2</del> 300
5	To spray paint front bonnet, front bumper, front RH fender, RH side mirror, RHF door and all other accident affected portion	\$	1,500.00 <del>400</del>
6	To remove and refix rh door panel, trim board to replace rh side mirror	\$	<del>250.00</del> <i>X</i>
7	To conduct and adjust headlamp focus and angle, calibration and coding for steering	\$	150.00 <i>X</i>

	radius		
8	To conduct 4 wheel alignment	\$	<del>150.00</del> 60
9	To replace front RH rim, conduct wheel balancing	\$	<del>60.00</del> 40
10	To replace front RH under carriage	\$	<del>550.00</del> 100
11	Remove and replace front bumper sensor	\$	150.00 X
15	Sealant for body panel, front bonnet and front rh fender	\$	150.00 X
16	To conduct ECU programming, check and clear fault codes, restore programme modules	\$	<del>550.00</del> X

Total (Labour)		\$	<u>5,360.00</u>
Sub Total :	\$4,405.50 + \$5,360.00	\$	9,765.50
GST 7%		\$	683.59
<b>Grand Total :</b>		<b>\$</b>	<b><u>10,449.09</u></b>

The above estimates are base on visual inspection and it is possible that further materials and labour may be required upon dismantling. Should this occur, we will submit supplementary quotation for further approval.

*Issue*  
*Hp 90000068*  
*4 days*  
*P/P*  
*18/09/19 @ 1110*  
*Revy after repair*