

TTS EUROCARS PTE LTD

383 Sin Ming drive Singapore 575717

Date : 16.09.2019

RE: VEHICLE REPAIR QUOTATION

Insurance Company	:	
Vehicle Reg No	:	SKV5400A
Name of Insured	:	Chen Xueni
Policy Number	:	P1023861R00
Date of Accident	:	13.09.2019
Tyre of Claim	:	Third Party Claim
Model	:	Mini Cooper
Chassis No	:	WMWSU32020TY90153

We are please to submit our estimate of repairs to the above mention vehicle.

		Parts	Labour
1	FRONT RH FENDER PROTECTOR <i>scd</i>	\$ 130.00	✓
3	FRONT BONNET <i>X scd</i>	\$ 1,000.00	
4	FRONT RH DOOR <i>repair</i>	\$ 1,050.00	
5	FRONT RH SIDE MIRROR ASSY <i>repair</i>	\$ 223.00	
6	FRONT RH SIDE SKIRT <i>X scd</i>	\$ 73.00	
7	FRONT RH RIM <i>scd</i>	\$ 655.00	✓
8	FRONT RH WHEEL BEARING <i>? x scd</i>	\$ 185.00	
9	FRONT RH WHEEL HUB <i>? x scd</i>	\$ 385.00	
10	FRONT RH SHOCK ABSORBER <i>X scd</i>	\$ 390.00	
11	FRONT RH LOWER ARM <i>X scd</i>	\$ 265.00	
12	FRONT RH UPPER ARM <i>X scd</i>	\$ 280.00	
13	BALL JOINT <i>X scd</i>	\$ 105.00	
14	FRONT RH TPMS <i>? x scd</i>	\$ 154.00	

Sub Total Parts \$ 4,895.00

Less 10% \$ 489.50

Total Parts \$ 4,405.50

1	Sundries	\$ 80.00 30
2	Wiring connection and check.	\$ 150.00 <i>X 11</i>
3	Tuff kote and spray anti rust proofing	\$ 120.00 20
4	Labour charges to dismantle & refix RHF fender, bonnet, front bumper, front headlamp and side mirror To repair and adjust affected portion to specific dimension.	\$ 1,500.00 300
5	To spray paint front bonnet, front bumper, front RH fender, RH side mirror, RHF door and all other accident affected portion	\$ 1,500.00 400
6	To remove and refix rh door panel, trim board to replace rh side mirror	\$ 250.00 11
7	To conduct and adjust headlamp focus and angle, calibration and coding for steering	\$ 150.00 <i>X 11</i>

radius			
8	To conduct 4 wheel alignment	\$	150.00 60 ✓
9	To replace front RH rim, conduct wheel balancing	\$	60.00 40 ✓
10	To replace front RH under carriage	\$	550.00 100 XAN
11	Remove and replace front bumper sensor	\$	150.00 XAN
15	Sealant for body panel, front bonnet and front rh fender	\$	150.00 XAN
16	To conduct ECU programming, check and clear fault codes, restore programme modules	\$	550.00 XAN
Total (Labour)		\$	<u>5,360.00</u>
Sub Total :		\$	9,765.50
GST 7%		\$	683.59
Grand Total :		\$	<u>10,449.09</u>

The above estimates are base on visual inspection and it is possible that further materials and labour may be required upon dismantling. Should this occur, we will submit supplementary quotation for further approval.

Issue
 Hp 90000068
 4 days
 P/P
 18/09/19 @ 1110
 Rem after repair

PRE INVOICE

INDIA INTERNATIONAL INSURANCE
64 CECIL STREET
#04-05 IOB BUILDING
SINGAPORE 049711

DOCUMENT NO : IN19-000040
DATE : 05/10/2019

Vehicle No: SKV5400A
MINI COOPER
Mileage: 0000

Staff ID : KAVIDHA
Account No : INDIA INSU
JOB NO : TN19-000040

No	Description	quantity U	Cost Price	Disc %	Amount
1	Frt RH fender potector	1	\$ 130.00		\$ 130.00 ✓
2	Frt RH rim	1	\$ 655.00		\$ 655.00 ✓

Total Parts \$ 785.00
less 10% \$ 78.50
Total \$ 706.50

Labour

1	Sundries	1		\$ 30.00 ✓
2	Tuff kote and spray anti rust	1		\$ 20.00 ✓
3	Labour charge todismantle side mirror,repair adjust affected portion	1		\$ 300.00 ✓
4	Spray paint frt RH fender RH side mirror, RHF door and all other affected accident portion	1		\$ 400.00 ✓
4	Conduct wheel alignment	1		\$ 60.00 ✓
5	replace frt RH rim conduct wheel balancing	1		\$ 40.00 ✓

Total labour \$ 850.00

Subtotal **\$1,556.50**
Add 7% GST \$108.96
Total **\$1,665.46**

* Acknowledgement by Customer *

I confirm that the goods stated in this invoice have been received by me in good working order and condition.

I further confirm that all services and /or repair jobs

Stated in this invoice are completed and done to my Satisfaction.

TTS EUROCARS PTE LTD

Name/Signature/NRIC No/Co Stamp (where applicable)

Authorised Signature



TTS EUROCARS pte ltd

Company Reg. No: 200413930H

393O-H

383 Sin Ming Drive, TTS Centre, Singapore 575717 Sales: +65 6842 2222 Admin: +65 6757 0122 Aftersales: +65 6757 2622 Fax: +65 6741 1626
Branch : No.15, Commonwealth Lane, Lot A1, Commonwealth Car Mall, Singapore 149554 Tel : +65 6462 1111 Fax : +65 6252 4834
For corporate, fleet & leasing enquiries, please contact +65 6462 1111 24-Hour Emergency Assistance: +65 6475 2722

Website: www.lts.com.sg