

Case Details

Case Reference Number : TAX/09/19/2045
Type of Repair : Accident Repair
Vehicle Registration Number : SHD6350J

Company Type : SMRT Taxis Pte Ltd
Estimation ID : EST-8500-ID
Assigned By : Taxi Claims Manager Team

Insurance Company Name : AIG Asia Pacific Insurance Pte Ltd
Accident Date and Time : 13/09/2019 05:10 AM
Vehicle Age(In Months) : 46

Documents / Photographs

[View Documents / Photographs](#)

Total Documents: 1

Estimation Details

Spare Part's Cost Detail

SMRT Recommendation										Surveyor Approval				
BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks
One Time Key In	Main			SUPPORT SUB-ASSY	1	1,460.40	1,460.40	25.00	1,095.30	Replace	0	0	Not Give	X SVC
One Time Key In	Main			BUMPER FRT	1	482.00	482.00	25.00	361.50	Replace	1	361.50	Replace	/ DD
One Time Key In	Main			BUMPER CLIPS	10	1.61	16.10	25.00	12.08	Replace	10	12.08	Replace	/ Nec
One Time Key In	Main			BUMPER SUPPORT F/RH	1	76.40	76.40	25.00	57.30	Replace	1	57.30	Replace	/ Nec
One Time Key In	Main			BUMPER SUPPORT F/LH	1	76.40	76.40	25.00	57.30	Replace	0	0	Not Give	X SVC
One Time Key In	Main			BUMPER ENERGY ABSORBER FRT	1	78.80	78.80	25.00	59.10	Replace	0	0	Not Give	X SVC
One Time Key In	Main			BUMPER REINFORCEMENT FRT	1	498.40	498.40	25.00	373.80	Replace	0	0	Check	X NN
One Time Key In	Main			ARM SUB-ASSY,FR BUMPER LH	1	250.40	250.40	25.00	187.80	Replace	0	0	Not Give	X SVC
One Time Key In	Main			ARM SUB-ASSY,FR BUMPER RH	1	250.40	250.40	25.00	187.80	Replace	1	187.80	Replace	/ Nec
One Time Key In	Main			COVER, FR BUMPER HOLE RH	1	18.50	18.50	25.00	13.88	Replace	1	13.88	Replace	/ SCH

Total Spare Part Cost	5,326.09	Surveyor Total	2,177.19
Lump Sum Discount (%)	20.00	Lump Sum Dis (%)	20
Final Spare Part Cost	4,260.87	Final Sur Total	1,741.75

BOM Type	Costing Type	Portion	Material Number	SMRT Recommendation						Surveyor Approval				
				Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks
One Time Key In	Main			BUMPER GRILLE SUB-ASSY,LOWER	1	311.10	311.10	25.00	233.33	Replace	1	233.33	Replace ▾	✓ SCH
One Time Key In	Main			FOG LAMP RH	1	295.20	295.20	10.00	265.68	Replace	0	0	Not Give ▾	X SVC
One Time Key In	Main			LENS & BODY,FR TURN RH	1	511.80	511.80	10.00	460.62	Replace	1	460.62	Replace ▾	✓ SCH
One Time Key In	Main			BUMPER FRT ABSORBER LOWER	1	127.70	127.70	25.00	95.78	Replace	0	0	Check ▾	X NN
One Time Key In	Main			HEAD LAMP RH	1	945.20	945.20	10.00	850.68	Replace	1	850.68	Replace ▾	✓ SCH
One Time Key In	Main			FENDER FRT/RH	1	723.40	723.40	25.00	542.55	Replace	0	0	Not Give ▾	X NN SVC
One Time Key In	Main			NAME PLATE (HYBRID)	1	51.90	51.90	25.00	38.92	Replace	0	0	Not Give ▾	X NN SVC
One Time Key In	Main			FENDER LINER FRT/RH	1	171.70	171.70	25.00	128.77	Replace	0	0	Not Give ▾	X SVC
One Time Key In	Main			GRILLE, RADIATOR	1	310.60	310.60	25.00	232.95	Replace	0	0	Check ▾	X NN
One Time Key In	Main			GRILLE, RADIATOR LOWER NO.2	1	94.60	94.60	25.00	70.95	Replace	0	0	Check ▾	X NN
Total Spare Part Cost									5,326.09	Surveyor Total		2,177.19		
Lump Sum Discount (%)									20.00	Lump Sum Dis (%)		20		
Final Spare Part Cost									4,260.87	Final Sur Total		1,741.75		

Labour's Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO REPAIR FRONT PORTION	507.00	250	
Total:			507.00	250.00	

Spray Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO REPSRAY FRONT BUMPER	378.00	200	
Total:			936.00	300.00	

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
2	Main	TO RESPRAY FRONT FENDER RH	378.00	0	
3	Main	TO RESPRAY FRONT BUMPER LOWER GRILLE	180.00	100	
Total:			936.00	300.00	

Other Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO REPLACE SUNDRY PARTS	100.00	20	✓ NEC
2	Main	TO CHECK WIRING AND SYSTEM FUNCTION	80.00	20	✓ NEC
3	Main	TO WASH AND VACUUM	60.00	0	
4	Main	TO APPLY RUST-PROOFING ON AFFECTED AREA	100.00	20	✓ NEC.
5	Main	TOWING CHARGE	84.00	0	
Total:			424.00	60.00	

Summary

	Estimator Assesment(\$)	Surveyor Assesment(\$)
Total Spare Part Detail	4,260.87	1,741.75
Total Labour Cost	507.00	250.00
Total Spray Painting	936.00	300.00
Other	424.00	60.00
Overall Total	6,127.87	2,787.19
Lump Sum Repair Option		✓
Lump Sum Total	6,150.00	2,800.00
Surveyor Approved Amount		2,800.00
No of Repair Days*	5	3
Remarks	-	Lumsum repair, Take after spray
Surveyor Name		STEVE CHEN

Estimator Assesment(\$)

Surveyor Assesment(\$)

Signature



Save

Clear

Survey Date

16/09/2019

**LKK Auto Consultants hence notify
the Repairer of the following:**

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: