



Section A - Accident Details

Registration Number	SHD6350J
Case Reference Number	TAX/09/19/2045
Registration Date	20/11/2015
Company Type	SMRT Taxis Pte Ltd
Make	TOYOTA
Model	PRIUS
Name of Driver	CHUA CHEE KHIAN
Type of Accident	Side Swipe
Accident Date and Time	13/9/2019 1:10 PM
Accident Reported Date and Time	14/9/2019 10:02 AM
Is Surveyor Required?	Yes
Survey by	
Vehicle is Towed Back?	Yes
Towed Back Date and Time	13/9/2019 1:36 PM
Replacement Vehicle issued?	No
Job Card Number	24103351
Special Instruction to ARC, if any	TOWED \$60 / BP
Prepared Date and Time	14/9/2019 12:14 PM
Chassis Number	
Mileage	
Work Shop	
Repair Completion Date and Time	



ib/here/ib

Section B - Summary of Repair Estimates

Summary of Repair Estimates		
	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$507.00	\$250.00
Total Spray Cost	\$936.00	\$300.00
Total Spare Part Cost	\$4,260.87	\$1,741.75
Total Other Cost	\$424.00	\$120.00
TOTAL COST	\$8,127.87	\$2,411.75
Lump Sum Total	\$6,150.00	\$2,400.00 (L/S)
Number of Repair Days	5.0	3.0
Prepared / Adjusted By	Ang Bang Kien	STEVE CHEN (LKK) / AIG
ARC / Surveyor Sign Off Date	16/09/2019 5:52 PM	16/09/2019 3:50 PM
Signature		
Remarks		Lumpsum repair, Take after spray

Section C - Quotation and Accident Invoice Details

Quotation Number	QN-1909-0437	Invoice Number	
Quotation Date	25.09.2019	Invoice Date	
Invoice Amount		Prepared Date	

Section D - Details of Repair Estimates

Part 1 - Labour Works

Job Scope	Quotation from AR	Adjusted by Surveyor, if applicable
TO REPAIR FRONT PORTION	\$507.00	\$250.00
Total Labour	\$507.00	\$250.00

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPSRAY FRONT BUMPER	\$378.00	\$200.00
TO RESPRAY FRONT FENDER RH	\$378.00	\$0.00
TO RESPRAY FRONT BUMPER LOWER GRILLE	\$180.00	\$100.00
Total Spray Painting & Panel Beating	\$936.00	\$300.00

Part 3 - Other Costs - Accident and Accident Repair Related Expense

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPLACE SUNDRY PARTS	\$100.00	\$20.00
TO CHECK WIRING AND SYSTEM FUNCTION	\$80.00	\$20.00
TO WASH AND VACUUM	\$60.00	\$0.00
TO APPLY RUST-PROOFING ON AFFECTED AREA	\$100.00	\$20.00
TOWING CHARGE	\$84.00	\$60.00
Total Other Costs	\$424.00	\$120.00

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
		53201-47902	SUPPORT SUB-ASSY	0.00	\$1,460.40	0.00	\$0.00	Replace	Not Given ✓
		52119-47930	BUMPER FRT	1.00	\$482.00	25.00	\$361.50	Replace	Replace ✓
		52161-16010	BUMPER CLIPS	10.00	\$1.61	25.00	\$12.08	Replace	Replace ✓
		52115-47040	BUMPER SUPPORT F/RH	1.00	\$76.40	25.00	\$57.30	Replace	Replace ✓
		52116-47040	BUMPER SUPPORT F/LH	0.00	\$76.40	0.00	\$0.00	Replace	Not Given X
		52611-47080	BUMPER ENERGY ABSORBER FRT	0.00	\$78.80	0.00	\$0.00	Replace	Not Given X
		52021-47023	BUMPER REINFORCEMENT FRT	0.00	\$498.40	0.00	\$0.00	Replace	Check X
		57014-47030	ARM SUB-ASSY.FR BUMPER LH	0.00	\$250.40	0.00	\$0.00	Replace	Not Given X
		57013-47030	ARM SUB-ASSY.FR BUMPER RH	1.00	\$250.40	25.00	\$187.80	Replace	Replace ✓
		52127-47930	COVER, FR BUMPER HOLE RH	1.00	\$18.50	25.00	\$13.88	Replace	Replace ✓
		53102-47020	BUMPER GRILLE SUB-ASSY, LOWER	1.00	\$311.10	25.00	\$233.33	Replace	Replace ✓
		81210-12230	FOG LAMP RH	0.00	\$295.20	0.00	\$0.00	Replace	Not Given X
		81511-47050	LENS & BODY.FR TURN RH	1.00	\$511.80	10.00	\$460.62	Replace	Replace ✓
		52618-47050	BUMPER FRT ABSORBER LOWER	0.00	\$127.70	0.00	\$0.00	Replace	Check X

	81130-47500	HEAD LAMP RH	1.00	\$945.20	10.00	\$850.68	Replace	Replace	✓
	53801-47050	FENDER FRT/RH	0.00	\$723.40	0.00	\$0.00	Replace	Not Given	X
	75374-47051	NAME PLATE (HYBRID)	0.00	\$51.90	0.00	\$0.00	Replace	Not Given	X
	53875-47030	FENDER LINER FRT/RH	0.00	\$171.70	0.00	\$0.00	Replace	Not Given	X
	53111-47040	GRILLE, RADIATOR	0.00	\$310.60	0.00	\$0.00	Replace	Check	X
	53113-47040	GRILLE, RADIATOR LOWER NO.2	0.00	\$94.60	0.00	\$0.00	Replace	Check	X
Total				\$6,736.51		\$2,177.19			

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
Total									

2177.19

- 208

1741.75

+ 250.00

+ 420.00

2411.75

4/5 \$2400/-

Estimator Assessment(\$)

Surveyor Assessment(\$)

Signature



Save Clear

Survey Date

16/09/2019

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed ~~and~~
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



Case Details

Case Reference Number : TAX/09/19/2045
 Type of Repair : Accident Repair
 Vehicle Registration Number : SHD6350J

Company Type : SMRT Taxis Pte Ltd
 Estimation ID : EST-8500-ID
 Assigned By : Taxi Claims Manager Team

Insurance Company Name : AIG Asia Pacific Insurance Pte Ltd
 Accident Date and Time : 13/09/2019 05:10 AM
 Vehicle Age(In Months) : 46

Documents / Photographs

View Documents / Photographs Total Documents : 1

Estimation Details

Spare Part's Cost Detail

SMRT Recommendation											Surveyor Approval			
BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks
One Time Key In	Main			SUPPORT SUB-ASSY	1	1,460.40	1,460.40	25.00	1,095.30	Replace	0	0	Not Give	* X SVC
One Time Key In	Main			BUMPER FRT	1	482.00	482.00	25.00	361.50	Replace	1	361.50	Replace	* / DD
One Time Key In	Main			BUMPER CLIPS	10	1.61	16.10	25.00	12.08	Replace	10	12.08	Replace	* / Nec
One Time Key In	Main			BUMPER SUPPORT F/RH	1	76.40	76.40	25.00	57.30	Replace	1	57.30	Replace	* / Nec
One Time Key In	Main			BUMPER SUPPORT F/LH	1	76.40	76.40	25.00	57.30	Replace	0	0	Not Give	* X SVC
One Time Key In	Main			BUMPER ENERGY ABSORBER FRT	1	78.80	78.80	25.00	59.10	Replace	0	0	Not Give	* X SVC
One Time Key In	Main			BUMPER REINFORCEMENT FRT	1	498.40	498.40	25.00	373.80	Replace	0	0	Check	* X NN
One Time Key In	Main			ARM SUB-ASSY,FR BUMPER LH	1	250.40	250.40	25.00	187.80	Replace	0	0	Not Give	* X SVC
One Time Key In	Main			ARM SUB-ASSY,FR BUMPER RH	1	250.40	250.40	25.00	187.80	Replace	1	187.80	Replace	* / Nec
One Time Key In	Main			COVER, FR BUMPER HOLE RH	1	18.50	18.50	25.00	13.88	Replace	1	13.88	Replace	* / SCH
Total Spare Part Cost									5,326.09	Surveyor Total		2,177.19		
Lump Sum Discount (%)									20.00	Lump Sum Dis (%)		20		
Final Spare Part Cost									4,260.87	Final Sur Total		1,741.75		

BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	SMRT Recommendation					Surveyor Approval			
						List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks
One Time Key In	Main			BUMPER GRILLE SUB-ASSY.LOWER	1	311.10	311.10	25.00	233.33	Replace	1	233.33	Replace	* / SCH
One Time Key In	Main			FOG LAMP RH	1	295.20	295.20	10.00	265.68	Replace	0	0	Not Give	* X SVC
One Time Key In	Main			LENS & BODY.FR TURN RH	1	511.80	511.80	10.00	460.62	Replace	1	460.62	Replace	* / SCH
One Time Key In	Main			BUMPER FRT ABSORBER LOWER	1	127.70	127.70	25.00	95.78	Replace	0	0	Check	* X NN
One Time Key In	Main			HEAD LAMP RH	1	945.20	945.20	10.00	850.68	Replace	1	850.68	Replace	* / SCH
One Time Key In	Main			FENDER FRT/RH	1	723.40	723.40	25.00	542.55	Replace	0	0	Not Give	* X NN SVC
One Time Key In	Main			NAME PLATE (HYBRID)	1	51.90	51.90	25.00	38.92	Replace	0	0	Not Give	* X NN SVC
One Time Key In	Main			FENDER LINER FRT/RH	1	171.70	171.70	25.00	128.77	Replace	0	0	Not Give	* X SVC
One Time Key In	Main			GRILLE, RADIATOR	1	310.60	310.60	25.00	232.95	Replace	0	0	Check	* X NN
One Time Key In	Main			GRILLE, RADIATOR LOWER NO.2	1	94.60	94.60	25.00	70.95	Replace	0	0	Check	* X NN

Total Spare Part Cost	5,326.09	Surveyor Total	2,177.19
Lump Sum Discount (%)	20.00	Lump Sum Dis (%)	20
Final Spare Part Cost	4,260.87	Final Sur Total	1,741.75

Labour's Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO REPAIR FRONT PORTION	507.00	250	
Total:			507.00	250.00	

Spray Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO REPSRAY FRONT BUMPER	378.00	200	
Total:			936.00	300.00	

S.No.	Coating Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
2	Main	TO RESPRAY FRONT FENDER RH	378.00	0	
3	Main	TO RESPRAY FRONT BUMPER LOWER GRILLE	180.00	100	
Total:			936.00	300.00	

Other Cost Detail

S.No.	Coating Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO REPLACE SUNDRY PARTS	100.00	20	✓ NPC
2	Main	TO CHECK WIRING AND SYSTEM FUNCTION	80.00	20	✓ NPC
3	Main	TO WASH AND VACUUM	60.00	0	
4	Main	TO APPLY RUST-PROOFING ON AFFECTED AREA	100.00	20	✓ NPC
5	Main	TOWING CHARGE	84.00	60	✓
Total:			424.00	120	

Summary

	Estimator Assessment(\$)	Surveyor Assessment(\$)
Total Spare Part Detail	4,260.87	1,741.75
Total Labour Cost	507.00	250.00
Total Spray Painting	936.00	300.00
Other	424.00	60.00
Overall Total	6,127.87	2,787.19
Lump Sum Repair Option		✓
Lump Sum Total	6,150.00	2,800.00
Surveyor Approved Amount		2,800.00
No. of Repair Days*	5	3
Remarks		Lumpsum repair, Take after spray
Surveyor Name		STEVE CHEN