

ASS. REC. BY:

REF: CS/CTI/7016442/US f3

Special Instruction:

SURVIVOR

Marcus

ASSIGNMENT (Office)

From (Person): Chong Euan Sen

of CTI

Date/Time: 17.9.19 11-03p.m

Estimated Cost:

Bill to:

OD (TP) / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: GZ 6975C

Insured: SLD 3458E

at Workshop m/s Automobile Hub

Tel: 97864483

of 1 Koki Bukit Ave 5, 12-11

Policy No: DMPCSN 30184119011

Claim No: SNM19D204356C02

Sum Insured:

Excess:

Make of Veh:

D.O.A. 14.9.19

(Client's Record)

CA / REV / REP. / REV 24 HRS

map'

H.O.D. Enforcement:

Date/Time: 17.9.19 4.22p.m

Person Contacted: Ah Song

Vehicle IN (OUT)

Date/Time	Action/Instruction (✓) Estimate
	GZ 6975C - VAL EG 15012624/d2
	SLD 3458E - X

D.O.A. - 24/09/2019

REF: C71

ASS. REC. BY:

ASSIGNMENT

From: _____ Date: 12.9.2019

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: G2 6975C

at Workshop m/s Automobile Hub

of 1 Kaki Bukit Ave 5, #2-11

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: 10.00 a.m. Over waiting

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: 13800

IDAC Accident Report: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repair: 4 days Res.: Yes or No

Lum Sum: 20 % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Date / Time Action / Instruction

Call 31-7-2021 1yrs. 10mths.
next 2000

Veh No: G26975C Yr Regn: 8, 06

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Toyota Dyna C.C. 2986

Colour: Silver A/C: Insured / Std / NI / NA

Sp. Reading: 404258 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: JTFUF347/X030/2017

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 185-214 MIC

R: 155-212

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO YOKO or

Front

R/Bal. 6 mm

L/Bal. 6 mm

D.O.A. 14/9/19

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

RECEIVED 27 SEP 2019

Date/Time, File Pass to?

27/09/19

1) Type

Date/Time, File Return to?

2)

Report Format:

Long Short/Text

☐ : Prel. Report☒ : Final Report

Days Of Repair: 4

Resurvey No. of Trip: 2

Add Fee:

☐ : Site Insp (\$)☐ : Interview (\$)☐ : Tech. Invs (\$)☐ : Wheel and (\$)

Survey Fee:

Transportation:

S + RS \$

Photos

Notes

TOTAL

220

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	17 Sep 2019		17 Sep 2019 16:08 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	----------

CLAIM SUBFOLDER DETAILS

Insured:	TAN HUEY SENG, ID: S78239541		[Created by Insurer]
Main Claimant:	AH HONG AIRCOOL, Co. Reg. No.: 53085008K		
Vehicle Reg. No.:	GZ6975C	Date of Loss:	14/09/2019 08:00 - :59 [157 Months and 10 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / SNM19D204356C02	Policy/Cover Note No.:	DMPCSN30184119011
Vehicle Reg. No. (Insured):	SLD3458E	Policy No. (Claimant):	D19MTPCVE002454
		Excess:	S\$0.00
Repairer:	Automobile Hub Enterprise () 1 KAKI BUKIT AVENUE 5, #2-11 AUTOBAY @ KAKI BUKIT, 417883 Kaki Bukit - Tel:		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Chong Boon Sen]		
Claimant's Insurer:	Sompo Insurance Singapore Pte. Ltd. (HQ) - Tel: 6461 6555		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 26/09/2019]		
Driver/Custodian (Insured):	TAN HUEY SENG (41 / Male), NRIC: S78239541 Email:		
Adj Asg. Remarks:	to assign Mr Marcus Chua for SJE, thank you.		

ASSOCIATED MAIL RECEIVED

There are no mail for this case.

[View All](#) [Compose Case Mail](#)

ALL ASSOCIATED TASKS

Due Date	Priority	Type	Task Group	Subject	Handler	View All	Search Tasks	Create New Task	Complete
No results.						Assigned By	Completed On	Created On	Done?

New Cars

Used Cars

Sell My Car

Directory

Products

Insurance

Articles

F



Dunlop
Tire
Tread



Quality
Exterior
Upgrades
Services



Importing
Bringing
From Overseas



dyna

Price Range

Depreciation

> 10 year(s)

Vehicle Type



Home » Used Cars » SB Motoring Pte Ltd » Toyota Dyna 150 3.0M (COE till 12/2021)

Toyota Dyna 150 3.0M (COE till 12/2021)

Overview

Financial

Accessories

Similar

Research

Photos

Map

Price \$16,900 **Lifespan** 02-Jan-2027

Depreciation ⓘ \$7,400 /yr **Reg Date** 03-Jan-2007
(2yrs 3mths 12days COE left)

Mileage N.A. **Manufactured** ⓘ 2006

Road Tax ⓘ N.A. **Transmission** Manual

Dereg Value ⓘ \$11,081 as of today (change) **OMV** ⓘ \$24,285

COE ⓘ \$24,249 **No. of Owners** ⓘ 5

Engine Cap 2,982 cc

Curb Weight ⓘ 1,780 kg

Type of Vehicle Truck

Features

View specs of the Toyota Dyna 150 (2014)

Category

COE Car

Status

Available

Resources



Car Valuation - Free

Find out the market value of your existing car for free. Get started



Vehicle Evaluation

Afraid of lemons? Request to have this car evaluated professionally. Find out more



Shortlist

Com

Report Error

M

Seller Information

Company

SB I

» de

» 9

Address

3 An

Seav

Location

Link

Office No

674:

Contact Person(s)

And

Marj

Marj

Marj

Posted on: 08-Sep-2019 | Last Updated on: 08-Sep-2019

Up Compare

[> Back to OneMotoring](#)

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type:	Business
Owner ID:	008K

Vehicle Details

Vehicle No.:	GZ6975C
Vehicle to be Exported:	No
Intended Deregistration Date:	19 Sep 2019
Vehicle Make:	TOYOTA
Vehicle Model:	DYNA 150 D
Primary Colour:	Silver
Manufacturing Year:	2006
Engine No.:	5L5655796
Chassis No.:	JTFUF34YX03012017
Maximum Power Output:	-
Open Market Value:	\$23,681.00
Original Registration Date:	04 Aug 2006
First Registration Date:	04 Aug 2006
Transfer Count:	1
Actual ARF Paid:	\$1,185.00

Intended PARF Rebate Details

PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00

Intended COE Rebate Details

COE Expiry Date:	31 Jul 2021
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	5
PQP Paid:	\$22,247.00
COE Rebate Amount:	\$8,300.00
Total Rebate Amount:	\$8,300.00

Message

Please note that all future COE renewals for this vehicle can only be for a 5-year period, subject to the statutory lifespan (if applicable) of the vehicle.

The information contained herein is correct as at 19 Sep 2019

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	16/09/2019 11:45
Date Of Accident	14/09/2019 08:50
Exact Location Of Accident	YIO CHU KANG RD TWDS BOUNDARY RD
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	GZ6975C
Insured/Policyholder	
Name Of Registered Owner	AH HONG AIRCOOL
Co Reg No	53085008K
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	Office-90291655

Vehicle Particulars

Manufacturer	TOYOTA
Model	DYNA 150-3.0 D (M)
Exact Purpose for which vehicle was being used at time of accident	COMMERCIAL USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	COMMERCIAL VEHICLE

Insurance Company

Name of Insurance Company	SOMPO INSURANCE SINGAPORE PTE. LTD.
Type Of Coverage	THIRD PARTY
Fleet Policy	NO
Policy Number	D19MTPCVE002454
Cover Note Number	04/08/2019 - 03/08/2020

Driver

Name of Driver	YAP SENG HONG
NRIC No	S1326415E
Date Of Birth	16/01/1958
Occupation	INDOOR
Date Of Driving Pass	15/03/1976
Driving Experience	43 YEARS AND 5 MONTHS

Gender	MALE
Mobile Number	(LOCAL) +65-90291655
Fax Number	
Contact Number	
Email Address	NOEMAIL
Address	BLK 965 HOUGANG AVE 9 #04-652
Postcode	530965
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	HOUGANG NEIGHBOURHOOD POLICE CENTRE
Police Station Address	ROAD: 60 HOUGANG AVE 9 , POSTCODE: 538775 , COUNTRY: SINGAPORE
Police Station Contact	TEL NO: 1800-4890999 - FAX NO: 63128989
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO POLICE REPORT NO: T/20190914/2076.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SLD3458E
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR

Name of Driver	JASON TAN
NRIC/Passport Number	
Contact Number	81833911
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

DETAILS OF INJURED PERSON 1

Name	YAP SENG HONG
Approximate Age	61
Injuries Sustain	PAIN AT NECK AREA
Injured person in which vehicle?	GZ6975C
Were seat belts worn?	
Was this injured conveyed to hospital by ambulance?	NO
Address	BLK 965 HOUGANG AVE 9 #04-652
Postcode	530965

Sketch Plan

SKETCH PLAN

VEHICLE NO.: 526975C
INSURER: JOMIO
DATE & TIME: 16/09/19 @ 0850

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorized Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to regulate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature
Date & Time:

Driver's Signature
(if driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name: DUDYIN (ANNE)
NRIC/FIN No.: 16/09/19

Boundary rd.

←

1/10 Chu Kong rd

A: 526975C
(010012)

B: 5103458E

Vehicle No: 6Z6975C (Sompot)
Date & Time: 14/09/19 @ 08:50 (Cranbury)
Refer to police report no: 7/20190914/2076

Note: Please note that your insurer may have 14 days Time Frame for you to submit an Own Damage Claim under your own comprehensive policy. Please check with your policy for more information.

I/We declare the foregoing particulars are true in every respect

16/9/89

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time

Reporting Centre Personnel's Signature
Name: AMK
NRIC/FIN No.:

GARMC: SafetyPlanForm_V2 () Claim Own Policy () Claim Third Party () Reporting Only
() Claim Other at other workshop (No Wan Hung)



**SINGAPORE
POLICE FORCE**



T/20190914/2076

Police Station Of Origin:
Hougang N.P.C
60 Hougang Avenue 9 SINGAPORE 538775
Tel No: 1800-4890999

1 of 3

Report No: T/20190914/2076

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 14/09/2019 13:28		Vide Report No.:	Station Diary No.: 58
Informant's Particulars			
Name of Informant: YAP SENG HONG		Address: APT BLK 965 HOUGANG AVENUE 9 #04-652 SINGAPORE 530965	
ID Type / ID No.: NRIC NO / S1326415E		Contact No.: Home/Office: Mobile: 90291655	
Nationality: SINGAPORE CITIZEN		Email:	
Sex: Male	Age: 61	Date of Birth: 16/01/1958	Type of Informant: Driver
Race: Chinese		Language: English	Institution / School Name:
Occupation: AIR CON SERVICE		Driving Licence Information: Class: 3,4 Date of Expiry:	

General Information of the Accident

Type of Accident:	Injury Others	Drink Drive: No	Date/Time of Accident: 14/09/2019 08:50	Type of Location:
Location: Along Road 1 YIO CHU KANG ROAD BOUNDARY ROAD yio chu road towards boundary road				
Weather: Clear		Road Surface: Dry	Road Speed Limit:	
Traffic Flow:		Traffic Control:	Traffic Volume: Heavy	
Type of Collision: Between Moving Vehicles - Head To Rear			Anyone conveyed by ambulance: No	

Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
GZ6975C	Lorry	TOYOTA			Slightly Damaged	0
SLD3458E	Car	TOYOTA			Seriously Damaged	0

Details of Person Involved

Any Pedestrian Involved: No	
No. of Pedestrians Injured: NIL	Use of Pedestrian Crossing: NA



**SINGAPORE
POLICE FORCE**



T/20190914/2076

Police Station Of Origin:
Hougang N.P.C
60 Hougang Avenue 9 SINGAPORE 538775
Tel No: 1800-4890999

2 of 3

Report No. T/20190914/2076

CONTINUATION OF REPORT

Driver				
Name	YAP SENG HONG		ID No.	S1326415E
Related Vehicle	GZ6975C (Lorry)		Contact No.	90291655
Hospital/Clinic	TEIN CLINIC&SURGERY		Class of Driving Licence & Expiry Date	Class: 3,4 Date of Expiry: NIL
Date Treatment	14/09/2019		Date Discharge	14/09/2019
No. of Days granted Medical Leave	03		Degree of Injury	NIL

Brief Details.

On 14/9/2019 at about 0850hrs, I was driving my lorry bearing GZ6975C along Yio Chu kang Road. While I was at the filter lane to make a left turn onto boundary road, I made a check and as there was on going traffic, I stop my lorry. Suddenly I felt an huge impact on the rear of my vehicle. I quickly alighted to make a check and saw this car bearing SLD3458E collided on the rear of my lorry. Due to the collision, the rear of my lorry was dented in. No one was injured at the point of time. No ambulance or police attended. I did not took down his NRIC but I have his contact details : Jason Tan Hp:81833911.

I do not have a rear CCTV installed.

After the accident, I felt pain at my neck area as such I went to Tein Clinic & surgery and was issued a 3 days MC from 14/9/2019 to 16/9/2019, mc number: 52312.

I am lodging this report for insurance claims.



**SINGAPORE
POLICE FORCE**



T/20190914/2076

Police Station Of Origin:
Hougang N.P.C
60 Hougang Avenue 9 SINGAPORE 538775
Tel No: 1800-4890999

3 of 3

Report No: T/20190914/2076

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report:

F /

Sgt 2 LEE JIA YI

Signature Of Informant:

Signature Of Interpreter:

Not applicable

Date/Time:

14/09/2019 13:28

Officer In Charge Of Case:

TP / AEIT /

SI MOHAMAD ZULFAZDLI BIN ABDULLAH

Contact No.: 65476204

Classification Of Case:

Authentication Stamp

NP168

Repair Estimate

Automobile Hub Enterprise

1 Kaki Bukit Avenue 6 #02-11 Autobay @ Kaki Bukit Singapore 417883
Tel: (65) 9786 4483 Fax: (65) 6509 6584 Email: autohub325@gmail.com

Make/Model: TOYOTA DYNA
Engine/Chassis No.: JTFUF34YX03012017
Date of accident:
Damaged area: Rear

Date: 16/09/2019
Claim Type: TP
VRN: GZ6975C



List Items				
S/N	Parts description	QTY	UNIT PRICE	AMOUNT
1	Tail gate <i>20/set</i>	1	\$ 1,997.00	\$ 1,997.00
2	Tail gate upper hinge <i>11</i>	3	\$ 68.00	\$ 204.00
3	Tail gate outer lock <i>11</i>	1	\$ 363.00	\$ 363.00
4	Tail gate outer handle <i>11</i>	1	\$ 93.00	\$ 93.00
5	Tail gate inner panel <i>11</i>	1	\$ 958.00	\$ 958.00
6	Tail lamp panel bracket <i>0.5 set</i>	2	\$ 383.00	\$ 766.00
7	Tail lamp <i>0.5 set</i>	2	\$ 573.00	\$ 1,146.00
8	Rear licence plate lamp <i>11</i>	1	\$ 77.00	\$ 77.00
9	Rear aluminium outer frame <i>NS</i>	1	\$ 2,175.00	\$ 2,175.00
10	Rear aluminium outer frame stopper <i>NS</i>	4	\$ 28.00	\$ 112.00
11	Rear spare tyre carrier <i>set/bm</i>	1	\$ 486.00	\$ 486.00
12	Tail gate upper hinge pin <i>11</i>	3	\$ 134.00	\$ 402.00
13	Tail gate lock striker <i>11</i>	1	\$ 176.00	\$ 176.00
14	Tail gate lower member <i>set</i>	1	\$ 1,714.00	\$ 1,714.00
15	Tail gate lower member hook <i>hook 11</i>	4	\$ 158.00	\$ 632.00
16	Exhaust silencer <i>545-10 set</i>	1	\$ 982.00	\$ 982.00
17	Exhaust hanger <i>11</i>	1	\$ 66.00	\$ 66.00
18	Rear licence plate base panel <i>19910 set</i>	1	\$ 270.00	\$ 270.00
Subtotal				\$ 12,619.00
List discount				25.00%
Total				\$ 9,464.25

Special nett items				
No.	Parts description	QTY	UNIT PRICE	AMOUNT
1	Rear number plate <i>set</i>	1	\$ 55.00	\$ 55.00
2	Rear tailgate "SG 50" sticker <i>NA</i>	1	\$ 10.00	\$ 10.00

Mr. Adnan Han
18/9/19
1/5 #4300
4th
Wahye. Attharipir

1200 S.N
X
X
X
X
IPC 115 S.N
IPC 150 S.N
X
X
280 S.N
X
X
500 S.N
X
X
14 S.N
X

Repair Estimate

3	Rear tailgate "70km/h" sticker	all	1	\$ 15.00	\$ 15.00
4	Tailgate advertisement sticker	all	1	\$ 450.00	\$ 450.00
5	Spare tyre	11	2	\$ 380.00	\$ 760.00
6	Rear floor panel inner top aluminium board	all	1	\$ 1,900.00	\$ 1,900.00
7	Rear floor panel inner top aluminium board rivet- set	11	1	\$ 150.00	\$ 150.00
8	Rear brake lamp bulb	11	2	\$ 10.00	\$ 20.00
9	Rear signal bulb	11	2	\$ 10.00	\$ 20.00
10	Sundries	11	1	\$ 50.00	\$ 50.00
				Total	\$ 3,430.00

10
✓
X
800
X
X
X

Labour				
No.	Description	Work unit	Amount	
1	To dismantle / renew accident damaged portion. To panel beat, reshape, straighten, orientate and align repair / replacement parts.	6	\$	1,200.00
2	To disconnect rear wire harness of electrical components to facilitate repairs, reconnect and check functions including tailamp lightings.	0.25	\$	50.00
3	To remove and replace, straighten and readjust exhaust pipe.	0.5	\$	100.00
4	To align rear cargo frame and to conduct chassis alignment on Car-O-Liner.	1	\$	200.00
5	Supply spray paint material and necessary items to respray affected area / panel.	5	\$	1,000.00
6	To rust proof all affected portions after repair.	0.5	\$	100.00
Total labour			\$	2,650.00

850
30
60
u1 X
380
X

Estimate Grand Total	\$ 15,544.25
-----------------------------	---------------------

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Part prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No change/modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

P- 74420
257
P- 558.15
S.V- 3519.00
L- 1320.00
5397.15
202
4317

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CT19016442/USF3N2

Date: 01/10/2019

REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMPCSN30184119011	
Claimant Vehicle No :	GZ6975C	Insured Vehicle No :	SLD3458E	
Date of Loss:	14/09/2019	Nature of Claim:	TP	Claim No: SNM19D204356C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	GZ6975C	Engine No:	5L5655796
Make & Model:	TOYOTA DYNA 150, 3.0 D (M)	Chassis No:	JTFUF34YX03012017
Reg. Date:	04/08/2006 (Man. Year: 2006)	Odometer:	404258 km
Colour:	Silver		
Engine Capacity:	2986 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	185 R14	Rear Tyre Size:	155 R12(D)
Front Left Side:	Michelin 6 mm	Rear Left Side:	Yokohama 6/6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Yokohama 6/6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	12,894.25	4,077.15	8,817.10	68.38
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,650.00	1,320.00	1,330.00	50.19
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	15,544.25	5,397.15	10,147.10	65.28
Approved Total (Overridden) (\$\$)		4,300.00		
Nett Amount (\$\$)	15,544.25	4,300.00	11,244.25	72.34

INSPECTION

Date of Assignment:	17/09/2019	
Date Inspected:	18/09/2019	Inspected At: Automobile Hub Enterprise 1 KAKI BUKIT AVENUE 5, #2 -11 AUTOBAY @ KAKI BUKIT Singapore 417883

Estimated Period of Repair: 4.0 days

Adjuster: MARCUS CHUA

Manager: Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	(Last Synchronised: 01 Oct 2019)	
Parts:	N/A	TOYOTA DYNA 150 3.0 D (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GZ6975C)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	3		*TAIL GATE UPPER HINGE	Not Necessary	204.00 FL	*- FL
2	1		*TAIL GATE OUTER LOCK	Not Necessary	363.00 FL	*- FL
3	1		*TAIL GATE OUTER HANDLE	Not Necessary	93.00 FL	*- FL
4	1		*TAIL GATE INNER PANEL	Not Necessary	958.00 FL	*- FL
5	1		*REAR LICENCE PLATE LAMP	Not Necessary	77.00 FL	*- FL
6	1		*REAR ALUMINIUM OUTER FRAME	No such part	2,175.00 FL	*- FL
7	4		*REAR ALUMINIUM OUTER FRAME STOPPER	No such part	112.00 FL	*- FL
8	3		*TAIL GATE UPPER HINGE PIN	Not Necessary	402.00 FL	*- FL
9	1		*TAIL GATE LOCK STRIKER	Not Necessary	176.00 FL	*- FL
10	4		*TAIL GATE LOWER MEMBER HOOK	Not Necessary	632.00 FL	*- FL
11	1		*EXHAUST SILENCER	Bent	982.00 FL	*545.10 FL
12	1		*EXHAUST HANGER	Not Necessary	66.00 FL	*- FL
13	1		*REAR LICENCE PLATE BASE PANEL	Bent	270.00 FL	*199.10 FL
14	1		*TAIL GATE	Dented/Bent	1,497.75 FS	*1,200.00 FS
15	1		*TAIL LAMP BRACKET	O/s Bent	574.50 FS	*115.00 FS
16	1		*TAIL LAMPS	O/s Cracked	859.50 FS	*150.00 FS
17	1		*REAR SPARE TYRE CARRIER	Bent/Jammed	364.50 FS	*280.00 FS
18	1		*TAIL GATE LOWER MEMBER	Bent	1,285.50 FS	*500.00 FS
19	1		*REAR NUMBER PLATE	Bent	55.00 FS	*14.00 FS
20	1		*REAR TAILGATE SG50 STICKER	Not Necessary	10.00 FS	*- FS
21	1		*REAR TAILGATE 70KM/H STICKER	Necessary	15.00 FS	*10.00 FS
22	1		*TAILGATE ADVERTISEMENT STICKER	Necessary	450.00 FS	*450.00 FS
23	2		*SPARE TYRE	Not Necessary	760.00 FS	*- FS
24	1		*REAR FLOOR PANEL INNER TOP ALUMINIUM BOARD OUTER	Bent	1,900.00 FS	*800.00 FS
25	1		*SET REAR FLOOR PANEL INNER TOP ALUMINIUM BOARD RIVET	Not Necessary	150.00 FS	*- FS
26	2		*REAR BRAKE LAMP BULB	Not Necessary	20.00 FS	*- FS
27	2		*REAR SIGNAL BULB	Not Necessary	20.00 FS	*- FS
28	1		*SUNDRIES	Not Necessary	50.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
				Sub Total (S\$)	14,521.75	4,263.20
				- List Item Discount on L Items 25.00/25.00% (S\$)	1,627.50	186.05
				Total Parts (S\$)	12,894.25	4,077.15

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO DISMANTLE/RENEW ACCIDENT DAMAGED PORTION TO PANEL BEAT, RESHAPE, STRAIGHTEN, ORIENTATE AND ALIGN REPAIR/REPLACEMENT PARTS	New	1,200.00	850.00
2	TO DISCONNECT REAR WIRE HARNESS OF ELECTRICAL COMPONENTS TO FACILITATE REPAIRS, RECONNECT AND CHECK FUNCTIONS INCLUDING TAILLAMP LIGHTINGS	New	50.00	30.00
3	TO REMOVE AND REPLACE, STRAIGHTEN AND READJUST EXHAUST PIPE	New	100.00	60.00
4	TO ALIGN REAR CARGO FRAME AND TO CONDUCT CHASSIS ALIGNMENT ON CAR-O-LINER	New	200.00	0.00
5	SUPPLY SPRAY PAINT MATERIAL AND NECESSARY ITEMS TO RESPRAY AFFECTED AREA/PANEL	New	1,000.00	380.00
6	TO RUST PROOF ALL AFFECTED PORTIONS AFTER REPAIR	New	100.00	0.00
Gross Labour Cost (\$\$)			2,650.00	1,320.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >