

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Muhd Ashik B Madi

Date: 25 Sep 2019

Preliminary Advice

Insured Vehicle No : SKJ9409M

TP Vehicle No : SHA7705D

Make : TOYOTA PRIUS

Date of Inspection : 18/09/2019

Inspection At : Chunni Motor Work Pte Ltd - Amk (HQ)
Blk 10 #01-05/06, AMK Autopoint
Singapore 568047

Accident Date : 14/09/2019

Assignment Date : 17/09/2019

Est. Duration of Repair : 7 days

Point of Impact / General Description of Damages

The vehicle sustained impact / damages o/s rear portion & o/s body and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	14,185.24
Revised Amount	:S\$	10,742.40
Check Items (Estimated)	:S\$	0.00
Total	:S\$	10,742.40

Lump Sum Repair	:S\$
-----------------	------

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

() The vehicle is economical/not economical for repair.

(X) The above survey was conducted on a 'without prejudice' basis.