

ASS. REC. BY Steve

REF:

NTUC NS/INC PD/6455/Ext302

## ASSIGNMENT

From

Date:

17/9/19

Estimated Cost:

OD (TP) WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

SHB 5919L

at Workshop m/s

SMRT

of

woodlands Depot

Insured: SME 3636R

Policy No. 5104122826 (28/09/2018 - 27/12/2019)

Claims No.

MT 1062454-002

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S
	XX

Bal. or Market Value:

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: days Res.: Yes or No

Lump Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS (up)

Vehicle: IN / OUT

Date: Person Contacted:

Veh No:

SHB 5919L

Yr Regn: 12/Dec/2017.

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Toyota Prius 4.

C.C. 1798

Colour

Maroon.

A/C: Insured / Std / NI / NA

Sp. Reading

149733

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

JTDKB3FU103576046.

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F: 195/65 R15

R: 195/65 R15

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Falken.

Front

Rear

R/Bal. 5 mm

R/Bal. 5 mm

L/Bal. 5 mm

L/Bal. 5 mm

D.O.A. 15/09/2019

D.O.I. 17/9/2019

Survey held at

SMRT

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear OK

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

SHB 2919 L - CC31A/G 180171181 R/h/2 20A-17/09/2018 TP

SME 3636R - X

SME 3636R

2/19/19 Finalize (note \$1712.09 (P/P), 3 days (Poh Suan)

09/19/2049

(Red 4957.11, 7410)

RECEIVED 03 OCT 2019

Date/Time, File Path to?

☐

Preli. Report

1)

☐

Final Report

Date/Time, File Return to?

2) 3/10-typist

Days Of Repair: 3

Resurvey No. of Trip: 1

Survey Fee:

Transportation:

\$ + RS. \$1

Photos

Other:

TOTAL

Report Format:

TP

Lump Sum / E.R.T.C

1712.09

Add Fee: ☐ Site Insp (\$)☐ Interview (\$)☐ Tech. Insp (\$)☐ Weekend (\$)

160

160

TP Claims against NTUC Income: Follow-Through Survey

S/NO	Income Reference	Claimant (Owner / Taxi Company)	Claimant Vehicle No	Income Vehicle No.	D.O.A	Time of Accident	Estimate	Tentative repair cost
1	NOT OI	SMRT TAXIS PTE LTD	SHC 4198B	SJT 7918H	9/9/2019	20:30	\$8,981.80	\$3,245.89
2	MT/1062454-002	SMRT TAXIS PTE LTD	SHB 5919L	SME 3636R	15/9/2019	15:15	\$6,669.20	\$1,712.09
3	MT/1065177-001	COMFORT TRANSPORTATION P L	SHC 8248P	YP 4792R	27/9/2019	22:10	\$766.00	\$500.00

Claim received from LKK Auto

My Desktop  
Notice of Loss

Policy Query

Policy No.

Date of Accident

15/09/2019 09:32

Vehicle No.(For Motor)

SME3636R

Certificate Number

Search

Select	Policy No.	Certificate Number	Policyholder Name	Policyholder NRIC	Product	Cover Type	Vehicle No.	Insured Object	Commence Date	Expiry Date
	5104122826		SHAWN YEO YING RUI (YANG YINGRUI)	S9245289A	GPC	drive CLASSIC	SME3636R	SME3636R	28/09/2018	27/12/2019

Continue

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle****Vehicle Owner Particulars**

Owner ID Type:	Company
Owner ID:	369K

**Vehicle Details**

Vehicle No.:	SHB5919L
Vehicle to be Exported:	No
Intended Deregistration Date:	17 Sep 2019
Vehicle Make:	TOYOTA
Vehicle Model:	PRIUS HYBRID 1.8 CVT
Primary Colour:	Maroon
Manufacturing Year:	2017
Engine No.:	2ZRS111324
Chassis No.:	JTDKB3FU103576046
Maximum Power Output:	90.0 kW (120 bhp)
Open Market Value:	\$29,007.00
Original Registration Date:	12 Dec 2017 ✓
First Registration Date:	12 Dec 2017
Transfer Count:	0
Actual ARF Paid:	\$5,000.00

**Intended PARF Rebate Details**

PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	11 Dec 2025
PARF Rebate Amount:	\$3,750.00

**Intended COE Rebate Details**

COE Expiry Date:	11 Dec 2025
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	8
PQP Paid:	\$34,159.00
COE Rebate Amount:	\$26,611.00
<b>Total Rebate Amount:</b>	<b>\$30,361.00</b>

**Message**

Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 17 Sep 2019

OK

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	16/09/2019 08:57
Date Of Accident	15/09/2019 15:15
Exact Location Of Accident	TPE TOWARDS PUNGGOL
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SHB5919L
<b>Insured/Policyholder</b>	
Name Of Registered Owner	SMRT TAXIS PTE LTD
Co Reg No	198905369K
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-80000000

### Vehicle Particulars

Manufacturer	TOYOTA
Model	FRIUS TAXI-1.8 (A)
Exact Purpose for which vehicle was being used at time of accident	HIRE AND REWARD
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	TAXI

### Insurance Company

Name of Insurance Company	MS FIRST CAPITAL INSURANCE LTD
Type Of Coverage	THIRD PARTY FIRE AND/OR THEFT
Fleet Policy	YES
Policy Number	D-19093197MFSH
Cover Note Number	

### Driver

Name of Driver	WEE SWEE POH
NRIC No	S0171660C
Date Of Birth	16/05/1951
Occupation	OUTDOOR
Date Of Driving Pass	30/06/1989
Driving Experience	30 YEARS AND 2 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-80000000
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address	11
Postcode	
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - HIRER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

#### General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	YES
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	4
Passenger 1	NAME: : UNKNOWN GENDER: : MALE
Passenger 2	NAME: : UNKNOWN GENDER: : FEMALE
Passenger 3	NAME: : UNKNOWN GENDER: : FEMALE

#### Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

I WAS TRAVELLING ALONG TPE TOWARDS PUNGGOL WITH THREE PASSENGERS (COUPLE/ DAUGHTER CHINESE) ON BOARD. A VEHICLE INFRONT OF MY TAXI SLOWED DOWN AND I FOLLWED SUIT. AFTER WHICH I FELT AN IMPACT AT THE REAR OF MY TAXI. A VEHICLE SME3636R HAD COLLIDED ONTO THE REAR RIGHT PORTION OF MY TAXI.

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	FILE TOO BIG
Was there any audio recorded?	NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SME3636R
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR

Name of Driver

SHAWN YEO YING RUI

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage


No. Of Passenger (Including Driver)

TPE towards Punggol



A - 5HB5919L

B - SME 3636R



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

[illegible]

## DECLARATION

I/We declare <sup>that</sup> the foregoing particulars are true in every respect.

Policyholder's Signature

Date &amp; Time:

Driver's Signature

(If driver is not the policyholder)

Date &amp; Time:

Reporting Centre Personnel's Signature

Name: \_\_\_\_\_

NRIC/FIN No.:



SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature  
Date & Time:

Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:

## Case Details

Case Reference Number :

TAX/09/19/2049

Type of Repair : Accident Repair

Vehicle Registration Number : SHB5919L

Company Type : SMRT Taxis Pte Ltd

Estimation ID : EST-8509-ID

Assigned By : Taxi Claims Manager Team

Insurance Company Name : NTUC Income Insurance Co-operative Ltd

Accident Date and Time : 15/09/2019 07:15 AM

Vehicle Age(In Months) : 21

## Documents / Photographs

[View Documents / Photographs](#)

Total Documents: 1

## Estimation Details

### Spare Part's Cost Detail

SMRT Recommendation										Surveyor Approval				
BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks
One Time Key In	Main			COVER, RR BUMPER ASSY	1	423.90	423.90	25.00	317.92	Replace	1	317.92	Replace	✓ DO
One Time Key In	Main			CLIPS PIECE, FRT & RR BUMPER	10	1.50	15.00	25.00	11.25	Replace	10	11.25	Replace	✓ Nec
One Time Key In	Main			PAD, RR BUMPER, RH & LH , 1	2	3.80	7.60	25.00	5.70	Replace	2	5.70	Replace	✓ Nec
One Time Key In	Main			PAD, RR BUMPER, RH & LH , 2	2	3.80	7.60	25.00	5.70	Replace	2	5.70	Replace	✓ Nec
One Time Key In	Main			PAD, RR BUMPER, RH & LH , 3	2	3.80	7.60	25.00	5.70	Replace	2	5.70	Replace	✓ Nec
One Time Key In	Main			SEAL, RR BUMPER ARM, RH & LH	2	11.00	22.00	25.00	16.50	Replace	2	16.50	Replace	✓ Nec
One Time Key In	Main			FILLER, RR BUMPER , LH	1	119.90	119.90	25.00	89.93	Replace	0	0	Not Give	✓ X SVC
One Time Key In	Main			FILLER, RR BUMPER , RH	1	119.90	119.90	25.00	89.93	Replace	0	0	Not Give	✓ X SVC
One Time Key In	Main			REAR BUMPER REINFORCEMENT	1	318.80	318.80	25.00	239.10	Replace	0	0	Check	✓ X NN
One Time Key In	Main			SENSOR REVERSE	1	180.00	180.00	0.00	180.00	Replace	1	180.00	Replace	✓ short
Total Spare Part Cost									3,349.26	Surveyor Total			1,182.07	
Lump Sum Discount (%)									0.00	Lump Sum Dis (%)			0	
Final Spare Part Cost									3,349.26	Final Sur Total			1,182.07	

BOM Type	Costing Type	Portion	Material Number	SMRT Recommendation							Surveyor Approval			
				Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks
One Time Key In	Main			PIXEL STICKER	2	60.00	120.00	0.00	120.00	Replace	2	120.00	Replace	✓ NEC
One Time Key In	Main			RETAINER, RR BUMPER, LH	1	111.50	111.50	25.00	83.63	Replace	0	0	Not Give	✗ SVC
One Time Key In	Main			RETAINER, RR BUMPER, RH	1	112.70	112.70	25.00	84.53	Replace	1	84.53	Replace	✓ NEC
One Time Key In	Main			SEAL, RR BUMPER, RH	1	85.20	85.20	25.00	63.90	Replace	0	0	Not Give	✗ SVC
One Time Key In	Main			GUARD, RR BUMPER, LOWER	1	558.30	558.30	25.00	418.72	Replace	1	418.72	Replace	✓ DP
One Time Key In	Main			COVER, GUARD RR BUMPER LOWER	1	14.80	14.80	25.00	11.10	Replace	1	11.10	Replace	✓ MIS
One Time Key In	Main			PAD, RR BUMPER, CTR	3	2.20	6.60	25.00	4.95	Replace	3	4.95	Replace	✓ NEC
One Time Key In	Main			LENS & BODY ASSY, RR BUMPER, RH	1	486.80	486.80	10.00	438.12	Replace	0	0	Not Give	✗ SVC
One Time Key In	Main			WIRE, LUGGAGE ROOM	1	143.50	143.50	10.00	129.15	Replace	0	0	Not Give	✗ SVC
One Time Key In	Main			COVER, REAR FLOOR UNDER, LH	1	234.30	234.30	25.00	175.73	Replace	0	0	Not Give	✗ SVC
One Time Key In	Main			COVER, REAR FLOOR UNDER, RH	1	169.50	169.50	25.00	127.13	Replace	0	0	Not Give	✗ SVC
One Time Key In	Main			COVER, REAR FLOOR UNDER CENTER	1	222.60	222.60	25.00	166.95	Replace	0	0	Not Give	✗ SVC
One Time Key In	Main			END PANEL SUBASSY, BODY LOWER BACK	1	629.80	629.80	25.00	472.35	Replace	0	0	Not Give	✗ SVC
One Time Key In	Main			SEALANT SIKAFLEX	1	37.00	37.00	0.00	37.00	Replace	0	0	Not Give	✗ SVC
One Time Key In	Main			ANTENNA, ELECTRICAL KEY	1	60.30	60.30	10.00	54.27	Replace	0	0	Not Give	✗ SVC
Total Spare Part Cost									3,349.26	Surveyor Total		1,182.07		
Lump Sum Discount (%)									0.00	Lump Sum Dis (%)		0		
Final Spare Part Cost									3,349.26	Final Sur Total		1,182.07		

Labour's Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO REPAIR REAR PORTION	676.00	250	
Total:			676.00	250.00	

#### Spray Cost Detail



S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO RESPRAY REAR BUMPER	378.00	200	
2	Main	TO RESPRAY BUMPER BEAM	180.00	0	
3	Main	TO RESPRAY FILLER RR BUMPER LH	180.00	0	
4	Main	TO RESPRAY FILLER RR BUMPER RH	180.00	0	
5	Main	TO RESPRAY REAR PANEL	180.00	0	
Total:			1,098.00	200.00	

#### Other Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO CHECK WIRING AND SYSTEM FUNCTION	80.00	20	✓ NEC
2	Main	TO TEST AND REFIX REVERSE SENSOR SYSTEM	120.00	20	✓ NEC
3	Main	TO REMOVE AND INSTALL LUGGAGE COMPARTMENT TRIM TO FACILITATE REPAIR.	120.00	0	
4	Main	TO REMOVE AND REFIT WIRE HARDESS	200.00	20	✓ NEC
5	Main	TO REPLACE SUNDRY PARTS	100.00	20	✓ NEC
6	Main	TO WASH AND VACUUM	60.00	0	
Total:			680.00	80.00	

## Summary

	Estimator Assesment(\$)	Surveyor Assesment(\$)
Total Spare Part Detail	3,349.26	1,182.07
Total Labour Cost	676.00	250.00
Total Spray Painting	1,098.00	200.00
Other	680.00	80.00
Overall Total	5,803.26	1,712.07

	Estimator Assesment(\$)	Surveyor Assesment(\$)
Lump Sum Repair Option		
*Lump Sum Total	0.00	1,712.07
Surveyor Approved Amount		1,712.07
No of Repair Days*	5	3
Remarks	-	P/P Repatr, Take before spary
Surveyor Name		STEVE CHEN
Signature		 18/9/19
Survey Date	17/09/2019	<input type="button" value="Save"/> <input type="button" value="Clear"/>

17/09/2019  
P/P Repair.  
IP without Prejudice.  
Repair day - 3 days.

LKK Auto Consultants hence notify  
the Repairer of the following:



- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and  
is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date:

## Section A - Accident Details

Registration Number	SHB5919L
Case Reference Number	TAX/09/19/2049
Registration Date	12/12/2017
Company Type	SMRT Taxis Pte Ltd
Make	TOYOTA
Model	PRIUS4
Name of Driver	WEE SWEE POH
Type of Accident	Head to Rear
Accident Date and Time	15/9/2019 3:15 PM
Accident Reported Date and Time	16/9/2019 9:06 AM
Is Surveyor Required?	Yes
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	24103383
Special Instruction to ARC, if any	DROVE IN / TP
Prepared Date and Time	16/9/2019 1:11 PM
Chassis Number	
Mileage	
Work Shop	
Repair Completion Date and Time	

## Section B - Summary of Repair Estimates

Summary of Repair Estimates		
	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$676.00	\$250.00
Total Spray Cost	\$1,098.00	\$200.00
Total Spare Part Cost	\$3,349.26	\$1,182.09
Total Other Cost	\$680.00	\$80.00
TOTAL COST	\$5,803.26	\$1,712.09 (P/P)
Lump Sum Total	\$0.00	\$0.00
Number of Repair Days	5.0	3.0
Prepared / Adjusted By	Tuck Foo Kok	STEVE CHEN (LKK) / NTUC
ARC / Surveyor Sign Off Date	16/09/2019 1:36 PM	17/09/2019 1:44 PM
Signature		
Remarks		P/P Repair, Take before spary



## SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd  
 60 Woodlands Industrial Park E4, Singapore 757605  
 FAX Number: 63655592  
 Estimator Telephone Number: 63652623  
 Accident Reporting Number: 8862472

Date Generated: 02/10/2019

User ID: PehBuan

## Section C - Quotation and Accident Invoice Details

Quotation Number	QN-1909-0480	Invoice Number	
Quotation Date	27.09.2019	Invoice Date	
Invoice Amount		Prepared Date	

## Section D - Details of Repair Estimates

## Part 1 - Labour Works

Job Scope	Quotation from AR	Adjusted by Surveyor, if applicable
TO REPAIR REAR PORTION	\$676.00	\$250.00
Total Labour	\$676.00	\$250.00

## Part 2 - Spray Painting &amp; Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO RESPRAY REAR BUMPER	\$378.00	\$200.00
TO RESPRAY BUMPER BEAM	\$180.00	\$0.00
TO RESPRAY FILLER RR BUMPER LH	\$180.00	\$0.00
TO RESPRAY FILLER RR BUMPER RH	\$180.00	\$0.00
TO RESPRAY REAR PANEL	\$180.00	\$0.00
Total Spray Painting & Panel Beating	\$1,098.00	\$200.00

## Part 3 - Other Costs - Accident and Accident Repair Related Expense

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO CHECK WIRING AND SYSTEM FUNCTION	\$80.00	\$20.00
TO TEST AND REFIX REVERSE SENSOR SYSTEM	\$120.00	\$20.00
TO REMOVE AND INSTALL LUGGAGE COMPARTMENT TRIM TO FACILITATE REPAIR.	\$120.00	\$0.00
TO REMOVE AND REFIT WIRE HARDESS	\$200.00	\$20.00
TO REPLACE SUNDRY PARTS	\$100.00	\$20.00
TO WASH AND VACUUM	\$60.00	\$0.00
Total Other Costs	\$680.00	\$80.00

## Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
		52159479 13	COVER, RR BUMPER ASSY	1.00	\$423.90	25.00	\$317.93	Replace	Replace
		52161160 10	CLIPS PIECE, FRT & RR BUMPER	10.00	\$1.50	25.00	\$11.25	Replace	Replace
		52462470 30	PAD, RR BUMPER, RH & LH, 1	2.00	\$3.80	25.00	\$5.70	Replace	Replace
		52462470 20	PAD, RR BUMPER, RH & LH, 2	2.00	\$3.80	25.00	\$5.70	Replace	Replace
		52462470 10	PAD, RR BUMPER, RH & LH, 3	2.00	\$3.80	25.00	\$5.70	Replace	Replace
		52191470 30	SEAL, RR BUMPER ARM, RH & LH	2.00	\$11.00	25.00	\$16.50	Replace	Replace
		52566479 00	FILLER, RR BUMPER, LH	0.00	\$119.90	0.00	\$0.00	Replace	Not Given
		52565479 00	FILLER, RR BUMPER, RH	0.00	\$119.90	0.00	\$0.00	Replace	Not Given
		52023470 30	REAR BUMPER REINFORCEMENT	0.00	\$318.80	0.00	\$0.00	Replace	Check
			SENSOR REVERSE	1.00	\$180.00	0.00	\$180.00	Replace	Replace
			PIXEL STICKER	2.00	\$60.00	0.00	\$120.00	Replace	Replace

DD  
 nrc  
 nrc  
 nrc  
 nrc  
 nrc  
 nrc  
 SVC  
 SVC  
 nrc  
 short  
 nrc

	52576470 40	RETAINER, RR BUMPER, LH	0.00	\$111.50	0.00	\$0.00	Replace	Not Given	X
	52575470 40	RETAINER, RR BUMPER, RH	1.00	\$112.70	25.00	\$84.53	Replace	Replace	
	52591470 50	SEAL, RR BUMPER, RH	0.00	\$85.20	0.00	\$0.00	Replace	Not Given	X
	52453470 10	GUARD, RR BUMPER, LOWER	1.00	\$558.30	25.00	\$418.73	Replace	Replace	
	52169470 20	COVER, GUARD RR BUMPER LOWER	1.00	\$14.80	25.00	\$11.10	Replace	Replace	
	52461470 10	PAD, RR BUMPER, CTR	3.00	\$2.20 6.60	25.00	\$4.95	Replace	Replace	
	81581470 10	LENS & BODY ASSY, RR BUMPER, RH	0.00	\$486.80	0.00	\$0.00	Replace	Not Given	X
	82183470 20	WIRE, LUGGAGE ROOM	0.00	\$143.50	0.00	\$0.00	Replace	Not Given	X
	58399470 30	COVER, REAR FLOOR UNDER, LH	0.00	\$234.30	0.00	\$0.00	Replace	Not Given	X
	58398470 50	COVER, REAR FLOOR UNDER, RH	0.00	\$169.50	0.00	\$0.00	Replace	Not Given	X
	66259470 10	COVER, REAR FLOOR UNDER CENTER	0.00	\$222.60	0.00	\$0.00	Replace	Not Given	X
	58307470 90	END PANEL SUBASSY, BODY LOWER BACK	0.00	\$629.80	0.00	\$0.00	Replace	Not Given	X
		SEALANT SIKAFLEX	0.00	\$37.00	0.00	\$0.00	Replace	Not Given	X
	89997301 00	ANTENNA, ELECTRICAL KEY	0.00	\$60.30	0.00	\$0.00	Replace	Not Given	X
Total				\$4,114.90		\$1,182.09			

SVC  
nec  
SVC  
DD  
MS  
nec  
SVC

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
Total									

1182.09  
+ 250.00  
+ 280.00  
-----  
1712.09



**Veron Chen (LKKAuto)**

---

**From:** Yeo Poh Suan (Auto Svcs/ARC/ARC/Taxis) <YeoPohsuan@smrt.com.sg>  
**Sent:** Thursday, 3 October 2019 8:21 AM  
**To:** Steve Chen (LKK Auto)  
**Cc:** Veron Chen (LKKAuto)  
**Subject:** RE: SHB5919L

Hi,

Amount confirmed as per your recommendation, thanks.

Regards  
Poh Suan

-----Original Message-----

From: Steve Chen (LKK Auto) [mailto:SteveChen@lkkauto.com]  
Sent: Wednesday, 2 October 2019 7:42 PM  
To: Yeo Poh Suan (Auto Svcs/ARC/ARC/Taxis)  
Cc: Veron Chen (LKKAuto)  
Subject: SHB5919L

Dear Poh Suan,

We confirm the finalize \$1,712.09 (P/P, before GST). 3 repair days.

Thanks

Best Regards,  
Steve Chen | Assistant Automotive Assessor

LKK Auto Consultants

Phone: 6256 3561 | Email: SteveChen@lkkauto.com | fax: 6256-4315 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

-----Original Message-----

From: Yeo Poh Suan (Auto Svcs/ARC/ARC/Taxis) [mailto:YeoPohsuan@smrt.com.sg]  
Sent: Wednesday, October 02, 2019 4:47 PM  
To: Steve Chen (LKK Auto)  
Cc: SUR; CS A Team  
Subject: SHB5919L

Hi Steve,

Attached herewith the repair estimate of SHB 5919L having Case No: TAX/09/19/2049.

There is no change to the approved amount of \$1,712.09 @ 3 working days under part by part repair.

Cost of Repair invoice will be generated as approved.

Please finalize with me within 7 working day, thanks.

Thanks & Regards  
Poh Suan

-----Original Message-----

From: Yeo Poh Suan (Auto Svcs/ARC/ARC/Taxis)

Sent: Wednesday, 2 October 2019 4:48 PM

To: Yeo Poh Suan (Auto Svcs/ARC/ARC/Taxis)

Subject: Scan Data from FX-D421D6

## Veron Chen (LKKAuto)

---

**From:** Steve Chen (LKK Auto)  
**Sent:** Wednesday, 2 October 2019 7:42 PM  
**To:** Yeo Poh Suan (Auto Svcs/ARC/ARC/Taxis)  
**Cc:** Veron Chen (LKKAuto)  
**Subject:** SHB5919L

Dear Poh Suan,

We confirm the finalize \$1,712.09 (P/P, before GST). 3 repair days.

Thanks

Best Regards,  
Steve Chen | Assistant Automotive Assessor

LKK Auto Consultants

Phone: 6256 3561 | Email: [SteveChen@lkkauto.com](mailto:SteveChen@lkkauto.com) | fax: 6256-4315 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

-----Original Message-----

From: Yeo Poh Suan (Auto Svcs/ARC/ARC/Taxis) [<mailto:YeoPohsuan@smrt.com.sg>]  
Sent: Wednesday, October 02, 2019 4:47 PM  
To: Steve Chen (LKK Auto)  
Cc: SUR; CS A Team  
Subject: SHB5919L

Hi Steve,

Attached herewith the repair estimate of SHB 5919L having Case No: TAX/09/19/2049.

There is no change to the approved amount of \$1,712.09 @ 3 working days under part by part repair.

Cost of Repair invoice will be generated as approved.

Please finalize with me within 7 working day, thanks.

Thanks & Regards  
Poh Suan

-----Original Message-----

From: Yeo Poh Suan (Auto Svcs/ARC/ARC/Taxis)  
Sent: Wednesday, 2 October 2019 4:48 PM  
To: Yeo Poh Suan (Auto Svcs/ARC/ARC/Taxis)  
Subject: Scan Data from FX-D421D6


**National Assessment Centre Services**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



NTUC INCOME INSURANCE CO-OPERATIVE LTD Ref: NS/INC19016455/Evf3e2			
73 BRAS BASAH ROAD			
#05-01 NTUC TRADE UNION HOUSESINGAPORE 189556			
		Date: 10-10-2019	
		Code: INC4	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>			
Insured Veh.	SME 3636R	Veh. Inspected	SHB 5919L
Policy No.	5104122826	Coverage (\$)	0.00
Claim No.	MT/1062454-002	Excess (\$)	0.00
Assign From		Assign Date	17/09/2019
<b>2. Vehicle Particulars &amp; Condition</b>			
Make & Model	TOYOTA PRIUS	c.c	1798
Engine No.	HIDDEN	Year of Reg.	2017
Chassis No.	JTDKB3FU103576046	Colour	MAROON
Odometer	149733	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	FAIR		
<b>3. Conditions of Tyres</b>			
	Size	Make	Balance
R/H Front Tyre	195/65 R15	FALKEN	5 mm
L/H Front Tyre	195/65 R15	FALKEN	5 mm
R/H Rear Tyre	195/65 R15	FALKEN	5 mm
L/H Rear Tyre	195/65 R15	FALKEN	5 mm
<b>4. Description of Damages</b>			
THE VEHICLE SUSTAINED DAMAGES AT THE REAR O/S PORTION.			
DAMAGES SEE DETAILS.			
<b>5. General Information</b>			
Accident Date	15/09/2019	Inspection Date	17/09/2019
Survey held at	SMRT AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4 SINGAPORE 757705		
<b>5a. Remarks</b>			
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
<b>5b. Estimate Days of Repair</b>			
ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days	



## National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:1 of 2

### ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHB 5919L

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b><u>REPLACEMENT OF PARTS</u></b>				
1	COVER, RR BUMPER ASSY (DISC 25%)	DENTED	423.90	317.93
10	CLIPS PIECE, FRT & RR BUMPER @\$1.50 (DISC 25%)	NECESSARY	15.00	11.25
2	PAD, RR BUMPER, RH & LH, 1 @\$3.80 (DISC 25%)	NECESSARY	7.60	5.70
2	PAD, RR BUMPER, RH & LH, 2 @\$3.80 (DISC 25%)	NECESSARY	7.60	5.70
2	PAD, RR BUMPER, RH & LH, 3 @\$3.80 (DISC 25%)	NECESSARY	7.60	5.70
2	SEAL, RR BUMPER ARM, RH & LH @\$11.00 (DISC 25%)	NECESSARY	22.00	16.50
1	RETAINER, RR BUMPER, RH (DISC 25%)	NECESSARY	112.70	84.53
1	GUARD, RR BUMPER, LOWER (DISC 25%)	DENTED	558.30	418.73
1	COVER, GUARD RR BUMPER LOWER (DISC 25%)	MISSING	14.80	11.10
3	PAD, RR BUMPER, CTR @\$2.20 (DISC 25%)	NECESSARY	6.60	4.95
1	SENSOR REVERSE (SN)	SHORTED	180.00	180.00
2	PIXEL STICKER @\$60.00 (SN)	NECESSARY	120.00	120.00
1	REAR BUMPER REINFORCEMENT	NOT NECESSARY	318.80	-
1	FILLER, RR BUMPER, LH	SERVICEABLE	119.90	-
1	FILLER, RR BUMPER, RH	SERVICEABLE	119.90	-
1	RETAINER, RR BUMPER, LH	SERVICEABLE	111.50	-
1	SEAL, RR BUMPER, RH	SERVICEABLE	85.20	-
1	LENS & BODY ASSY, RR BUMPER, RH	SERVICEABLE	486.80	-
1	WIRE, LUGGAGE ROOM	SERVICEABLE	143.50	-
1	COVER, REAR FLOOR UNDER, LH	SERVICEABLE	234.30	-
1	COVER, REAR FLOOR UNDER, RH	SERVICEABLE	169.50	-
1	COVER, REAR FLOOR UNDER CENTER	SERVICEABLE	222.60	-
1	END PANEL SUBASSY, BODY LOWER BACK	SERVICEABLE	629.80	-
1	SEALANT SIKAFLEX	SERVICEABLE	37.00	-
1	ANTENNA, ELECTRICAL KEY	SERVICEABLE	60.30	-
			4,215.20	1,182.09
<b><u>LABOUR</u></b>				
	PANEL BEATING & BODY WORK.		676.00	250.00
	SPRAY PAINT.		1,098.00	200.00
	TO CHECK WIRING AND SYSTEM FUNCTION.		80.00	20.00

Report Ref No. NS/INC19016455/Evf3e2



## National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO TEST AND REFIX REVERSE SENSOR SYSTEM.		120.00	20.00
	TO REMOVE AND INSTALL LUGGAGE COMPARTMENT TRIM TO FACILITATE REPAIR.	NOT NECESSARY	120.00	-
	TO REMOVE AND REFIT WIRE HARDESS.		200.00	20.00
	TO REPLACE SUNDRY PARTS.		100.00	20.00
	TO WASH AND VACUUM.	NOT NECESSARY	60.00	-
			2,454.00	530.00
GRAND TOTAL			6,669.20	1,712.09
RECOMMENDED COST OF REPAIRS (CONFIRMED)				1,712.09

Report Ref No. NS/INC19016455/Evf3e2

CHEN TSUE YEE

Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,  
MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.