

ASS. REC. BY:

REF: CS/FCI 19012469/USf3

Special Instruction:

Suivants: Marcus

ASSIGNMENT (Office)

From (Person): Sithara of FCI Date/Time: 18.9.19 11.59A.M

Estimated Cost: Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SGU 2673B Insured: SHC 7472P

at Workshop m/s NPH Auto Tel: 6746 5405 6784 0663

of BIK 9005 Tompinst Street 93 #01-246/254

Policy No: Claim No: 01900595MFSH

Sum Insured: Excess:

Make of Veh: D.O.A. 13.9.2019
(Client's Record)

CA / REV / REP. / REV 24 HRS mp" Loy

Date/Time: 18.9.19 12.00p.m. Person Contacted: Peggy Foo H.O.D. Endorsement:

Vehicle (IN) OUT

Date/Time	Action/Instruction (V) Estimate
	SGU 2673B - NA/IN (18013539/Y) DOA - 12/10/2018
	SHC 7472P - NA/AIG (6014183/r3) DOA - 01/02/2016
19/09/19	@ 16:56 pm must pending clearance from repairer to Sithara via email

(03/11/13) wef
ASS. REC. BY: *MORAN*

REF:

FCI
ASSIGNMENT

From: _____ Date: _____
Estimated Cost: _____
OD *(C)* / WS / TP RES / OD RES / EVA / INV / MV
To Inspect Vehicle No: *SGU 2673B*
at Workshop m/s: *NPH*
of *SHC 7472P*
Insured: _____
Policy No.: _____
Claims No.: _____
Sum Insured: _____ Excess: _____
(Client's Record)
Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: *18500*

IDAC Accident Rpt: _____

Consistent?: Yes or No

(C) / PR Seen: *✓*

Consistent?: Yes or No

Est. Repairs: *6*

days

Res.: Yes or No

Lum Sum: *20*

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____

Person Contacted: _____

404B
Vehicle: IN / OUT

Veh No: *SGU 2673B* Yr Regn: *5 07*
Type: *(C)* / M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
Truck / Trailer or *(M)*
Make: *Toyota Corolla Axio* C.C. *1496*
Colour: *Gold* A/C: Insured / Std / NI / NA
Sp. Reading: *169058* T/Radio: Insured / Std / NI / NA
Eng/No: _____
C/No: *NZE1416019382*
Gen. Cond: *(C)* / Good / Fair / Poor / Burnt
Steering: *(C)* / In order / Jammed / Leaked / Burnt or
Brake: *(C)* / In order / Jammed / Leaked / Burnt or
Modi: Nil / S/Rim / STD A/Rim or
Tyre Size: F: *185/70R14*
R: _____
BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / *(C)* or
Front: _____ Rear: _____
R/Bal. *6* mm R/Bal. *6* mm
L/Bal. *6* mm L/Bal. *6* mm
D.O.A. *13/9/19* D.O.L. *18/9/19*
Survey held at: _____
Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or
Rear
The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

27/9/19 *coe 7-5-2022 2yrs 7mth*

LTA 13338 nett F162

L/S 4700 Confirmed with Roy
(\$ 1,782.90 Red - 28%)

MV - \$ 18,500/-

LTA - \$ 13,338/-

Nett - \$ 5,162.00

RECEIVED 27 SEP 2019

Date/Time, File Pass to?

27/09/19

1)

Date/Time, File Return to?

2)

☐ : Preli. Report
☒ : Final Report

Days Of Repair: *6*

Resurvey No. of Trip: _____

Survey Fee:

Transportation:

Add Fee:

☐ : Site Insp (\$ _____)

☐ : Interview (\$ _____)

☐ : Tech. Invs (\$ _____)

☐ : Weekend (\$ _____)

Photos

Others

TOTAL

Report Format:

Lump Sum / I.B.I. (\$ *4,700/- L/S*)

145
50
<i>✓</i>
104
299

MOTOR SURVEY ASSIGNMENT

Date 16-09-2019 **Our Ref No.** D19005951MFSH

Accident Date 13-09-2019 **Claim Type.** Third Party

Insured Vehicle SHC7472P **Third Party Vehicle.** SGU2673B

Survey Location BLK 9005 TAMPINES STREET 93 #01-246/254

Contact Person. PEGGY FOO

Contact No. 67465405/ 0 **Fax No.** 67458520

Survey Type WITHOUT PREJUDICE: WE ADMIT LIABILITY QUANTUM TO BE AGREED:

Appointed Surveyor LKK AUTO CONSULTANTS PTE LTD

Contact Person NA **Fax No.** 68416315

Contact Number. NA

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop NPH AUTO SERVICE **Attention.** NIL

Cc : TP Solicitor NA **TP Solicitor Fax No.** NA

Officer Incharge SITHARA

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
 This is a computer generated letter, no signature required.

Re: SURVEY ASSESSMENT - D19005951MFSH/1

Shirley Hiew (LKK Auto)

Thu 19/9/2019 4:56 PM

To: 'Sithara' <Sithara@msfirstcapital.com.sg>; 'CWS Motor Claims' <cwsmotorclaims@msfirstcapital.com.sg>

Cc: assignments <assignments@lkkauto.com>; SUR <sur@lkkauto.com>

Dear Sithara,

Please be informed that we have inspected the vehicle SGU 2673B on 16/09/2019.

We are pending estimate from repairer.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte LtdPhone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto) <admin-d@lkkauto.com>**Sent:** Wednesday, 18 September 2019 12:03 PM**To:** 'CWS Motor Claims' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>; SUR <sur@lkkauto.com>**Cc:** 'Sithara' <Sithara@msfirstcapital.com.sg>**Subject:** RE: SURVEY ASSESSMENT - D19005951MFSH/1

Dear Sir/Madam,

Thank you for your assignment.

Best Regards,

Summer Lee | Admin**LKK Auto Consultants Pte Ltd**Phone: 6741-8434 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: CWS Motor Claims <cwsmotorclaims@msfirstcapital.com.sg>**Sent:** Wednesday, 18 September, 2019 11:59 AM**To:** ASSIGNMENTS@LKKAUTO.COM**Cc:** CWS Motor Claims <cwsmotorclaims@msfirstcapital.com.sg>; Sithara <Sithara@msfirstcapital.com.sg>**Subject:** PRI: SURVEY ASSESSMENT - D19005951MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Note: All the accident reports are uploaded into CWS for your perusal.

New Cars

Used Cars

Sell My Car

Directory

Products

Insurance

Articles

F



axio

Price Range

Depreciation

> 10 year(s)

Vehicle Type



Home » Used Cars » Car World Automobile » Toyota Corolla Axio 1.5A X (New 5-yr COE)

Toyota Corolla Axio 1.5A X (New 5-yr COE)

Overview

Financial

Insurance

Accessories

Similar


Research

Photos

Map



CARWORLD AUTOMOBILE



Price \$29,800

Depreciation \$5,950 /yr

Reg Date 14-Sep-2009
(5yrs COE left)

Mileage N.A.

Manufactured 2008

Road Tax \$682 /yr

Transmission Auto

Dereg Value N.A.

OMV \$16,322

COE N.A.

ARF \$16,322

Engine Cap 1,496 cc

Power 81.0 kW (108 bhp)

Curb Weight 1,130 kg

No. of Owners 3

Type of Vehicle Mid-Sized Sedan

Features

View specs of the Toyota Corolla Axio (2007-2012)

Description

L Loan Available At Monthly \$600 Plus) Interest Rate From 3.88%, Showroom Condition Guarantee, Price Include New Paint/New Leather Seats, Rims, Comes With 6 Months Engine And Gearbox Warranty, All Our Quality Pre-owned Car Are Selling At Low Depreciation Price. STA/VICOM/AA Are Welcome, Bank Loan Or In House Financing Available. Viewing Available Anytime By Appointment. Welcome Trade In.

Category

COE Car

Status

Available

Compare



Location Map

Price Chart



Click on the point to view

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle****Vehicle Owner Particulars**

Owner ID Type: Singapore NRIC

Owner ID: 804B

Vehicle Details

Vehicle No.: SGU2673B

Vehicle to be Exported: No

Intended Deregistration Date: 19 Sep 2019

Vehicle Make: TOYOTA

Vehicle Model: COROLLA AXIO 1.5X M

Primary Colour: Beige

Manufacturing Year: 2007

Engine No.: 1NZC450544

Chassis No.: NZE1416019382

Maximum Power Output: 81.0 kW (108 bhp)

Open Market Value: \$10,710.00

Original Registration Date: 08 May 2007

First Registration Date: 08 May 2007

Transfer Count: 0

Actual ARF Paid: \$11,781.00

Intended PARF Rebate Details

PARF Eligibility: Forfeited

PARF Eligibility Expiry Date: -

PARF Rebate Amount: \$0.00

Intended COE Rebate Details

COE Expiry Date: 07 May 2022

COE Category: A - Car (1600cc & below)

COE Period(Years): 5

PQP Paid: \$25,333.00

COE Rebate Amount: \$13,338.00

Total Rebate Amount: \$13,338.00**Message**

Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 19 Sep 2019

OK



NPH AUTO SERVICE

Block 9005 Tampines Street 93 #01-246/254 Singapore 528839 Tel: 67840663 (8 Lines) Fax: 67840692
GST Reg No: MX 0869103 NO Business Reg No: 394773/00D
E-mail: nphauto@pacific.net.sg



Your Ref :

Our Ref : TP0067/09/19

THIRD PARTY CLAIM

M/S : HARJINDER SINGH

APT BLK 160 SIMEI ROAD #11-272
SINGAPORE 520160

Attn :

Dear Sir/Madam

RE: ACCIDENT REPAIR ON : SGU2673B TOYOTA AXIO
INSURED : HAJINDER SINGH
DATE OF ACCIDENT : 13/09/2019
POLICY NO : MP302729

Page : 1/2

Date : 16/09/2019

ENGINE# :
CHASSIS# :

not allowed
Lbr
2/s \$4700
18/9/19
thept. Affair
6dy.

APPENDED BELOW ARE THE ESTIMATED COST OF REPAIR & TO BE REPLACED:

		Qty	U/Cost	U/Price	Total	
			\$	\$	\$	
<u>Replacement of Parts</u>						
1	Rear boot hinge L&R	2	72.00	72.00	144.00	X
2	Rear boot Axio Emblem	1	47.60	47.60	47.60	/
3	X Emblem	1	36.60	36.60	36.60	/
5	Rear boot lock top	1	95.00	95.00	95.00	/
6	Rear boot carpet clips	11	5.00	5.00	55.00	X
7	Rear lamp assembly L&R	2	415.00	415.00	830.00	/
8	Rear lamp panel new NIS	1	135.00	135.00	135.00	/
9	Rear lamp new center panel	1	468.00	468.00	468.00	/
10	Rear bumper	1	655.10	655.10	655.10	/
11	Bumper side retainer L&R	2	96.60	96.60	193.20	1PC
12	Rear lamp retainer L&R	2	98.00	98.00	196.00	1PC
13	Rear bumper bracket L&R	2	55.60	55.60	111.20	1PC
14	Rear fender inner cowling LH	1	62.00	62.00	62.00	/
15	Bumper inner cowling clips LH	3	5.00	5.00	15.00	/
16	Rear lamp center panel inner garnish	1	195.00	195.00	195.00	/
17	Rear boot lock lower catch	1	38.00	38.00	38.00	X
18	Rear lamp inner carpet new Rear fender inner from NIS	1	355.00	355.00	355.00	/
19	Inner carpet clips Rear fender inner from NIS	6	5.00	5.00	30.00	/
20	Rear spare tyre board	1	565.00	565.00	565.00	/
21	Rear boot lid	1	655.50	655.50	655.50	/
22	Spare tyre screw	1	25.00	25.00	25.00	/
					4,917.20	
Total Material						
Special Nett Items						
1	HS Emblem	1	45.00	45.00	45.00	/
2	Rear number plate with casing	1	45.00	45.00	45.00	X

25%

\$3,687.90



NPH AUTO SERVICE

Block 9005 Tampines Street 93 #01-246/254 Singapore 528839 Tel: 67840663 (8 Lines) Fax: 67840692
GST Reg No: MX 0869103-NO Business Reg No: 394773/00D
E-mail: nphauto@pacific.net.sg



Your Ref :

Our Ref : TF0067/09/19

Page

: 2/2

Date

: 16/09/2019

THIRD PARTY CLAIM

APPENDED BELOW ARE THE ESTIMATED COST OF REPAIR & TO BE REPLACED:

	Qty	U/Cost	U/Price	Total
		\$	\$	\$
3 Rear bumper sensor 1 set	10	200.00	200.00	200.00
				290.00

Total S/Nett

Labour & Misc

\$290.00

- 1 Remove and install rear lamp, rear boot, rear bumper, cut out and renew rear lamp panel, rear lamp center panel, knocking rear fender LH, rear spare tyre panel, chassis member and restraighthen body & chassis

1,100.00

- 2 Spray Painting

1,200.00

- 3 Check Wiring System

25.00

- 4 Renew Parking Sensor

100.00

- 5 Remove & Install rear boot carpet

80.00

2,505.00

0.00

Total Labour

\$2,505.00

Nett Total Before Gst

\$6,482.90

Your faithfully

NPH AUTO SERVICE
(Manager)

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

8-4430
257
2-3322.50
S.N-245.00
L-2335.00
5972.50
202



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
MS FIRST CAPITAL INSURANCE LTD		Ref : CS/FCI19016469/Usf3n2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 04-10-2019	
		Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SHC 7472P	Veh. Inspected	SGU 2673B
Policy No.		Coverage (\$)	0.00
Claim No.	D19005951MFSH	Excess (\$)	0.00
Assign From	SITHARA	Assign Date	18/09/2019
2. Vehicle Particulars & Condition			
Make & Model	TOYOTA COROLLA AXIO (M)	c.c	1496
Engine No.	HIDDEN	Year of Reg.	2007
Chassis No.	NZE1416019382	Colour	GOLD
Odometer	169058	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	185/70 R14	YOKOHAMA	6 mm
L/H Front Tyre	185/70 R14	YOKOHAMA	6 mm
R/H Rear Tyre	185/70 R14	YOKOHAMA	6 mm
L/H Rear Tyre	185/70 R14	YOKOHAMA	6 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	13/09/2019	Inspection Date	18/09/2019
Survey held at	NPH AUTO SERVICE BLK 9005 TAMPINES STREET 93 #01-246/254 SINGAPORE 528839		
5a. Remarks			
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		6 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SGU 2673B

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
2	REAR BOOT HINGE L&R @\$72.00	TO REPAIR SEE LABOUR	144.00	-
1	REAR BOOT AXIO EMBLEM	NECESSARY	47.60	47.60
1	X EMBLEM	NECESSARY	36.60	36.60
1	REAR BOOT LOCK TOP	TWISTED	95.00	95.00
11	REAR BOOT CARPET CLIPS @\$5.00	NOT NECESSARY	55.00	-
2	REAR LAMP ASSEMBLY L&R @\$415.00	CRACKED	830.00	830.00
1	REAR LAMP PANEL N/S	BENT	135.00	135.00
1	REAR LAMP CENTER PANEL	BADLY DENTED	468.00	468.00
1	REAR BUMPER	DISTORTED	655.10	655.10
2	BUMPER SIDE RETAINER L&R @\$96.60	N/S BENT	193.20	96.60
2	REAR LAMP RETAINER L&R @\$98.00	N/S CRACKED	196.00	98.00
2	REAR BUMPER BRACKLET L&R @\$55.60	N/S DENTED	111.20	55.60
1	REAR FENDER INNER COWLING LH	TORN	62.00	62.00
3	BUMPER INNER COWLING CLIPS LH @\$5.00	NECESSARY	15.00	15.00
1	REAR LAMP CENTER PANEL INNER GARNISH	TWISTED	195.00	195.00
1	REAR BOOT LOCK LOWER CATCH	NOT NECESSARY	38.00	-
1	REAR FENDER INNER TRIM N/S	TORN	365.00	365.00
6	REAR FENDER INNER TRIM CLIPS N/S @\$5.00	NECESSARY	30.00	30.00
1	REAR SPARE TYRE BOARD	CRACKED	565.00	565.00
1	REAR BOOTLID	BENT / BUCKLED	655.50	655.50
1	REAR SPARE TYRE SCREW	TWISTED	25.00	25.00
	LESS 25% DISCOUNT		-1,229.30	-1,107.50
			3,687.90	3,322.50
SPECIAL NETT ITEMS				
1	HS EMBLEM (SN)	NECESSARY	45.00	45.00
1	REAR NUMBER PLATE WITH CASING (SN)	SERVICEABLE	45.00	-
1	SET REAR BUMPER SENSOR (SN)	SHORTED / TORN	200.00	200.00
			290.00	245.00



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	LABOUR			
	REMOVE AND INSTALL REAR LAMP,REAR BOOT,REAR BUMPER,CUT OUT AND RENEW REAR LAMP PANEL,REAR LAMP CENTER PANEL,KNOCKING REAR FENDER LH,REAR SPARE TYRE PANEL,CHASSIS MEMBER AND RESTRAIGHTEN BODY & CHASSIS.INCLUSIVE OF THE REPAIR OF REAR BOOT HINGE L&R.		1,100.00	1,000.00
	SPRAY PAINTING.		1,200.00	1,180.00
	CHECK WIRING SYSTEM.		25.00	25.00
	RENEW PARKING SENSOR.		100.00	50.00
	REMOVE & INSTALL REAR BOOT CARPET.		80.00	80.00
			2,505.00	2,335.00
	GRAND TOTAL		6,482.90	5,902.50
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			4,700.00

Report Ref No. CS/FCI19016469/Usf3n2

MARKET VALUE: \$18,500.00 (EST)-LTA REIMBURSEMENT VALUE: \$13,338.00=NETT VALUE: \$5,162.00

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.