

ASS. REC. BY:

REF: ES/INC19016480/ETd302

Special Instruction:

Surveyor: Steve

ASSIGNMENT (Office)

From (Person): Annie Koh

of

INC

Date/Time:

9:29am @ 18/9/19

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLD 8401K

Insured:

SJA 5936T

at Workshop m/s

Lion City Rental

Tel:

97422188

of

Go Jelen from Hwa #04-01

Policy No:

Claim No:

MT/1060773-002

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

31/08/2019

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time: 10:02am @ 18/9/19

Person Contacted:

Mr. Sim

Vehicle

IN / OUT

Date/Time	Action/Instruction
	SLD 8401K - X
	SJA 5936T - NA/INC14001593/ d2
	20A: 8/3/2014
	Lump Sum \$6150 - (Red: 7613.48; 53%)
	check with Mr Sim confirm, 8 days.

ASS. REC. BY:

Stew

REP:

INC

ASSIGNMENT

From:

Date: 18/9/19

Estimated Cost:

OT / TP WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SLD 8401K

at Workshop m/s

Lion City Rental

of Go Jalen Lam Hunt #04-01

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

Car In.

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: days Res.: Yes or No

Lum Sum: % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

cup

Vehicle: IN / OUT

Date: Person Contacted:

Veh No:

SLD 8401K

Yr Regn:

29/6/16

Type: ☒ M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Toyota Sienta 1.5X

C.C.

1496

Colour

Black

A/C: Insured / Std / NI / NA

Sp. Reading

227314

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

NSP 1707031840

Gen. Cond: ☒ Good / Fair / Poor / BurntSteering: ☒ In order / Jammed / Leaked / Burnt orBrake: ☒ In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

185/60R15

R:

4

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Fireza

Front

Rear

R/Bal. 5 mm

R/Bal. 5 mm

L/Bal. 5 mm

L/Bal. 5 mm

D.O.A. 31/8/19

D.O.I. 18/9/19 1201PM

Survey held at

Lion City

Des. of Damages ☒ Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

MV-6SK

RECEIVED 16 DEC 2019

Date/Time, File Pass to?



: Preli. Report

1) 16/12 Typist



: Final Report

Date/Time, File Return to?

2)

Days Of Repair: 8

Resurvey No. of Trip: 1

Add Fee:



: Site Insp (\$)



: Interview (\$)



: Tech. Insp (\$)



: Weekend (\$)

Survey Fee:

Transportation:

3 + RS. \$

Photos

Other:

TOTAL

250

250

Report Format:

TP

Lump Sum / L&L: \$

67507

Nivitha (LKK Auto)

From: Annie Koh <annie.koh@income.com.sg>
Sent: Wednesday, 18 September 2019 9:44 AM
To: 'assignments@lkkauto.com'; Admin-D (LKKAuto)
Subject: RE: TP CASES FARMED OUT TO LKK ON 18/09/2019

Re-send

Warmest Regards

Annie Koh
Senior Admin,
Motor Insurance
T +65 64307899
www.income.com.sg



From: Annie Koh
Sent: Wednesday, 18 September 2019 9:29 AM
To: 'assignments@lkkauto.com' <assignments@lkkauto.com>; 'Admin-D (LKKAuto)' <admin-d@lkkauto.com>
Cc: Thio Tse Kiat <tsekiat.thio@income.com.sg>; Teng Ken Leong <kenleong.teng@income.com.sg>
Subject: RE: TP CASES FARMED OUT TO LKK ON 18/09/2019

Dear LKK,

Please assist to survey the following vehicles as per Mr Teng's instruction :-

SN	OIC	Claim No.	Vehicle	WorkShop Name	WorkShop Address	WorkShop Contact	OI VEH	DOA	Additional Remarks
----	-----	-----------	---------	---------------	------------------	------------------	--------	-----	--------------------

1	Eng Huey Huey	MT/1060773-002	SLD8401K	LION CITY RENTALS PTE LTD	60 JALAN LAM HUAT #04-01 CARROS CENTRE SINGAPORE 737869	S.T.Sim / 97422188	SJA5936T	31/8/19	
2	Azhari	MT/1062866-001	SKX9109E	MASSIVE TRADING & AUTO	BLK 5038 #01-405 ANG MO KIO INDUSTRIAL PARK 2 SINGAPORE 569541	Anthony Cheong / 91082728	SLB5957D	16/9/19	
3		PENDING ADVISE	YN6081G	SMRT AUTOMOTIVE SERVICES PTE LTD	60 WOODLANDS INDUSTRIAL PARK E4 SINGAPORE 757705	Mr. Tan YuWei / 98506093			
4	Wo Jessie	MT/1062709-002	SHC2038T	SOON HOCK MOTOR PTE LTD	10 ANG MO KIO IND PK 2-A #01-05/06 AMK AUTOPOINT SINGAPORE 568047	Ms Lynn / 65425119	SGB5888D	15/9/19	Ms Irene at 6542 7162

Please contact workshops.

Please revert to officer-in-charge after survey.

Thank you.

Annie Koh
Senior Admin Assistant, Motor Insurance
T +65 6430 7899
www.income.com.sg





Disclaimer

This e-mail contains privileged or confidential information which is intended only for the use of the recipient(s) named above. If you have received this message in error, please notify the sender immediately and delete all copies of it. Thank you.

Shiau Chan (LKKAuto)

From: Admin-D (LKKAuto)
Sent: Friday, 13 December 2019 11:14 AM
To: 'Eng Huey Huey'; assignments
Cc: SUR
Subject: RE: TP CASES FARMED OUT TO LKK ON 18/09/2019 [MT/1060773-002]

Dear Sir/Mdm,

Thank you for the email.

Dear Denise,

Kindly assist

FYNA Our Ref : CS/INC19016480/Etd3



Wishes you a Merry Christmas & Happy New Year 2020

Best Regards

G.NIVITHA

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Eng Huey Huey [mailto:hueyhuey.eng@income.com.sg]
Sent: Wednesday, 11 December 2019 5:00 PM
To: 'assignments@lkkauto.com' <assignments@lkkauto.com>; 'Admin-D (LKKAuto)' <admin-d@lkkauto.com>
Subject: FW: TP CASES FARMED OUT TO LKK ON 18/09/2019 [MT/1060773-002]

Hi,

Please submit report, thank you.

1	Eng Huey Huey	MT/1060773-002	SLD8401K	LION CITY RENTALS PTE LTD	60 JALAN LAM HUAT #04-01 CARROS CENTRE SINGAPORE 737869	S.T.Sim / 97422188	SJA5936T	31/8/19
---	---------------	----------------	----------	---------------------------	---	--------------------	----------	---------

Regards,
Eng Huey Huey
Senior Claims Executive
Operations, Motor and Personal Lines (PL)
T +65 6430 7921
www.income.com.sg

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type:	Company
Owner ID:	621K

Vehicle Details

Vehicle No.:	SLD8401K
Vehicle to be Exported:	No
Intended Deregistration Date:	18 Sep 2019
Vehicle Make:	TOYOTA
Vehicle Model:	SIENTA 1.5X A
Primary Colour:	Black
Manufacturing Year:	2016
Engine No.:	2NR8614460
Chassis No.:	NSP1707031840
Maximum Power Output:	80.0 kW (107 bhp)
Open Market Value:	\$17,927.00
Original Registration Date:	29 Jun 2016
First Registration Date:	29 Jun 2016
Transfer Count:	2
Actual ARF Paid:	\$7,927.00

Intended PARF Rebate Details

PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	28 Jun 2026
PARF Rebate Amount:	\$5,945.00

Intended COE Rebate Details

COE Expiry Date:	28 Jun 2026
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$47,020.00
COE Rebate Amount:	\$31,869.00
Total Rebate Amount:	\$37,814.00

The information contained herein is correct as at 18 Sep 2019

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	02/09/2019 16:37
Date Of Accident	31/08/2019 11:10
Exact Location Of Accident	ALONG PAN ISLAND EXPRESS WAY
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLD8401K
Insured/Policyholder	
Name Of Registered Owner	LION CITY RENTALS PTE LTD
Co Reg No	201504621K
Email Address	RENTALS@LIONCITYRENTALS.COM.SG
Mobile Phone No	
Alternative Phone No	OFFICE-31381884

Vehicle Particulars

Manufacturer	TOYOTA
Model	SIENTA-1.5 (A)
Exact Purpose for which vehicle was being used at time of accident	PRIVATE HIRE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	TOKIO MARINE INSURANCE SINGAPORE LTD
Type Of Coverage	THIRD PARTY
Fleet Policy	YES
Policy Number	19-MK000206-R00
Cover Note Number	

Driver

Name of Driver	CHOU KOK POH
NRIC No	S1466502A
Date Of Birth	31/08/1961
Occupation	OUTDOOR
Date Of Driving Pass	20/02/1993
Driving Experience	26 YEARS AND 6 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-87570420
Fax Number	
Contact Number	
EMail Address	NOEMAIL

Address 137 MARSILING ROAD
#04-2002

Postcode 730137

Was driver an employee of the Insured's Company NO

If No, Relationship of the Driver with the Insured OTHER - HIRER

Vehicle Registration Number of Driver's Own Vehicle -
-
-

Insurance Company of Driver's Own Vehicle -
-
-

General Information of the Accident

Type Of Accident CHAIN COLLISION

Weather Conditions CLEAR

Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO

Number of vehicles (including own vehicle) involved in the accident 3

Was any body injured in the Accident? NO

Was any injured conveyed to hospital by ambulance? NO

Was any other material or property damaged? NO

I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO

Number of Passengers (Including Driver) 3

Passenger 1
NAME: : NA
GENDER: : FEMALE

Passenger 2
NAME: : NA
GENDER: : FEMALE

Details of Police Action

Was the accident reported to the police? YES

If Yes, Please state which Police Station

Police Station Name TRAFFIC POLICE DIVISION HQ

Police Station Address ROAD: 10 UBI AVENUE 3 , POSTCODE: 408865 , COUNTRY: SINGAPORE

Police Station Contact TEL NO: 65470000 - FAX NO:

Was notice of intended Prosecution given? NO

If Yes, against whom?

Circumstances of Accident

REFER TO SKETCH PLAN

Attachment(s)

Are accident photos available for attachment? NOT AVAILABLE DUE TO CIRCUMSTANCES OF ACCIDENT

Was there any video captured by Car Camera? NO

Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SJA5936T

Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category PRIVATE CAR

Name of Driver

NRIC/Passport Number
Contact Number
Address
Postcode
Insurance Company Name
Nature Of Damage
No. Of Passenger (Including Driver)

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number SLX5049J
Vehicle Make/Model/Colour
Details Of Properties
Vehicle Category PRIVATE CAR
Name of Driver
NRIC/Passport Number
Contact Number
Address
Postcode
Insurance Company Name
Nature Of Damage
No. Of Passenger (Including Driver)

Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

Please report correctly the details of the accident to speed up the claims process.

This Form must be completed by the Policyholder and/or the Authorised Driver.

Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to rescind policy liability.

The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.

Any false reporting may be referred to the Police for investigation.

The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for preserving and that copies of this report will for a fee be made available upon application by interested parties.

By the lodgment of this report to the insurers, you hereby consent to its archiving of this report at the Centre and to copies of the report being made available afterwards.

Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this (form) and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in the accident (to be marked with their names and vehicle(s) involved in this accident) to be collectively referred to as the "Insurers", the Insurers' lawyer/law firm, the Ministry/Authority of Singapore and any relevant government agency/authority (such as the Police, for the past month of:
 - processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - investigating the accident and/or my claims;
 - carrying out and/or dealing with my instructions or responding to my enquiries by me;
 - administering my claims (including the mailing of correspondence, statements, notices, reports or notices to me, which could involve disclosure of certain personal data about me to being about delivery of the notice as well as in the external cover of your vehicle and packages); and/or
 - complying with applicable law in administering, processing, handling and/or dealing with my Personal Information ("Purposes").
- all insurer(s) who have insured vehicle(s) involved in the accident and the Insurers' lawyer/law firm, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be used outside of Singapore, for one or more of the above Purposes;
- my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims;
- the information so collected under (d) above may be shared / disclosed:
 - to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing their regulators, law enforcement and government agencies as reasonably required for the purposes stated; or
 - for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
(Date & Time)




Driver's Signature
(If driver is not the policyholder)
(Date & Time)

Reporting Centre Personnel's Signature
Name:
NRIC/ID No.

Sketch Plan #2

TCH PLAN

C = SLX5049J
B = SLD8401K
A = SJA5936T



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

PLEASE REFER TO POLICE REPORT, T.O.

DECLARATION

I/We declare the foregoing information are true in every respect.


Policyholder's Signature




Driver's Signature

02/09/17
11:30am


Reporting Centre Personnel's Signature

LCRF PTE LTD
CARROS CENTER
60 JALAN LAM HUAT #04-01 S(737869)
Main +65 62524991

Ms NTUC Income Insurance Co-operative Ltd

Date: 17/09/2019

Attn : MOTOR CLAIMS DEPT

ESTIMATE

VEHICLE NO.SLD8401K

CHASSIS NO : NSP1707031840

MAKE / MODEL : Toyota Sienta 1.5X Auto

DATE OF ACCIDENT : 31/08/2019

YOUR INSURED VEHICLE NUMBER : SJB2255P

MILEAGE : 227314 km

	<u>PARTS DESCRIPTION</u>	<u>QTY</u>	<u>UNIT PRICE</u>	<u>LIST PRICE</u>	
1	Front bumper / DO ? X NN	1PC	\$1,257.83	\$1,257.83	679 ✓
2	Front bumper reinforcement ? X NN	1PC	\$285.00	\$285.00	X
3	Front bumper energy absorber ? X NN	1PC	\$120.00	\$120.00	X
4	Front grille / BR	1PC	\$596.25	\$596.25	✓
5	Rear tailgate / DO	1PC	\$1,879.00	\$1,879.00	1086 ✓
6	Rear tailgate weatherstrip ✓ TN	1PC	\$432.00	\$432.00	329 ✓
7	Rear tailgate lock / BT	1PC	\$504.00	\$504.00	420 ✓
8	Rear tailgate lock catch X NN	1PC	\$64.80	\$64.80	X
9	Rear tailgate center garnish ? X NN	1PC	\$342.00	\$342.00	X no photo
10	Rear tailgate Toyota logo / NIC	1PC	\$60.00	\$60.00	✓
11	Rear end panel / DO	1PC	\$828.00	\$828.00	609.70 ✓
12	Rear end panel lower / DO	1PC	\$633.60	\$633.60	410.50 ✓
13	Rear end panel top garnish / CRV	1PC	\$250.00	\$250.00	142.10 ✓
14	Rear bumper reinforcement X CRV	1PC	\$338.10	\$338.10	X no such part
15	Rear bumper sponge / BR	1PC	\$157.50	\$157.50	98 ✓
16	Rear bumper / DO	1PC	\$1,257.83	\$1,257.83	645 ✓
17	Rear bumper RH retainer / BR	1PC	\$67.05	\$67.05	✓
18	Rear bumper LH retainer / BR	1PC	\$67.05	\$67.05	✓
19	Rear bumper LH seal X NN	1PC	\$104.40	\$104.40	X
20	Rear bumper RH seal X NN	1PC	\$104.40	\$104.40	X
21	Rear bumper RH support X NN	1PC	\$88.05	\$88.05	X
22	Rear bumper LH support X NN	1PC	\$88.05	\$88.05	X
23	Rear bumper LH extension / CNT	1PC	\$216.00	\$216.00	✓
24	Rear bumper RH extension X NN	1PC	\$216.00	\$216.00	X
25	Rear bumper center extension X NN	1PC	\$288.00	\$288.00	X
26	Rear bumper pad / CRV	1PC	\$64.80	\$64.80	✓
27	Rear bumper RH reflector X NN	1PC	\$93.60	\$93.60	X
28	R/R taillamp X NN	1PC	\$550.00	\$550.00	X
29	R/L taillamp / CNT	1PC	\$550.00	\$550.00	450 ✓
30	R/R taillamp reflector X NN	1PC	\$380.00	\$380.00	X
31	R/L taillamp reflector / CNT	1PC	\$380.00	\$380.00	✓
32	Bonnet / DO \$1288	656			7395.45
33	Spare tool kit box \$480	419			-25% 5546.58
LIST TOTAL S\$:				\$12,263.31	

25.00% DISCOUNT S\$: \$3,065.83
\$9,197.48

SPECIAL NETT

1	Bumper clips / <i>AK</i>	1 SET	\$80.00	<i>60</i>
2	Reverse sensor / <i>SAM</i>	1 SET	\$260.00	<i>200</i>
3	Windscreen sealant / <i>AK</i>	1PC	\$100.00	<i>40</i>
4	Body sealant / <i>AK</i>	1PC	\$300.00	<i>50</i>
5	Front & rear number plates / <i>CU7</i>	1 PC	\$100.00	<i>70</i>
Special Nett Total S\$:			<u>\$840.00</u>	

420

LABOUR CHARGES

- | | | |
|---|--|--------------------------|
| 1 | To labour charge for removing front bumper out to facilitate replacement of parts | \$30.00 250 / |
| 2 | To respray front bumper | \$400.00 200 |
| 3 | To remove and install rear tailgate glass | \$120.00 / |
| 4 | Transfer tailgate mechanism | \$100.00 50 |
| 5 | To labour charge for removing rear tailgate, rear bumper, end panel and spare tyre panel out to facilitate repairs and replacemnt of damaged parts | \$1,000.00 800 |
| 6 | To respray rear tailgate, rear end panel, spare tyre panel and rear bumper | \$1,000.00 800 |
| 7 | Towing fee | \$50.00 / |
| 8 | To conduct a standard of opearting procedures post repairs diagnostic scan test as a requirements for hybrid cars upon | \$300.00 200 |

LABOUR TOTAL S\$:	\$3,000.00
TOTAL S\$:	\$13,037.48
7% GST	\$912.62
GRAND TOTAL S\$:	<u>\$13,950.11</u>

2470

14363 48

[Signature]
20/9/19
Steve (LKK) WML

18/9/19, 12.30pm

8 days

LIS

Ry AL SH

P-5546-58

NI- 429

L- 2470

8436-58

L/S- 6749.26

= 6750

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

14363 48

LCRF PTE LTD
CARROS CENTER
60 JALAN LAM HUAT #04-01 S(737869)
Main +65 62524991

Ms NTUC Income Insurance Co-operative Ltd

Date: 17/09/2019

Attn : MOTOR CLAIMS DEPT

ESTIMATE

VEHICLE NO.SLD8401K

CHASSIS NO : NSP1707031840

MAKE / MODEL : Toyota Sienta 1.5X Auto

DATE OF ACCIDENT : 31/08/2019

YOUR INSURED VEHICLE NUMBER : SJB2255P

MILEAGE : 227314 km

	PARTS DESCRIPTION	QTY	UNIT PRICE	LIST PRICE
1	Front bumper / <i>DD</i>	1PC	\$1,257.83	\$1,257.83
2	Front bumper reinforcement <i>?</i>	1PC	\$285.00	\$285.00
3	Front bumper energy absorber <i>?</i>	1PC	\$120.00	\$120.00
4	Front grille / <i>BR</i>	1PC	\$596.25	\$596.25
5	Rear tailgate / <i>DD</i>	1PC	\$1,879.00	\$1,879.00
6	Rear tailgate weatherstrip / <i>TN</i>	1PC	\$432.00	\$432.00
7	Rear tailgate lock / <i>BT</i>	1PC	\$504.00 <i>4W</i>	\$504.00 <i>4W</i>
8	Rear tailgate lock catch <i>X</i>	1PC	\$64.80	\$64.80
9	Rear tailgate center garnish <i>?</i>	1PC	\$342.00	\$342.00
10	Rear tailgate Toyota logo / <i>AK</i>	1PC	\$60.00	\$60.00
11	Rear end panel / <i>DD</i>	1PC	\$828.00	\$828.00
12	Rear end panel lower / <i>DD</i>	1PC	\$633.60	\$633.60
13	Rear end panel top garnish / <i>CRV</i>	1PC	\$250.00	\$250.00
14	Rear bumper reinforcement / <i>CRV</i>	1PC	\$338.10	\$338.10
15	Rear bumper sponge / <i>BR</i>	1PC	\$157.50	\$157.50
16	Rear bumper / <i>DD</i>	1PC	\$1,257.83	\$1,257.83
17	Rear bumper RH retainer / <i>BR</i>	1PC	\$67.05	\$67.05
18	Rear bumper LH retainer / <i>BR</i>	1PC	\$67.05	\$67.05
19	Rear bumper LH seal <i>X</i>	1PC	\$104.40	\$104.40
20	Rear bumper RH seal <i>X</i>	1PC	\$104.40	\$104.40
21	Rear bumper RH support <i>X</i>	1PC	\$88.05	\$88.05
22	Rear bumper LH support <i>X</i>	1PC	\$88.05	\$88.05
23	Rear bumper LH extension / <i>CNT</i>	1PC	\$216.00	\$216.00
24	Rear bumper RH extension <i>X</i>	1PC	\$216.00	\$216.00
25	Rear bumper center extension <i>X</i>	1PC	\$288.00	\$288.00
26	Rear bumper pad / <i>CRV</i>	1PC	\$64.80	\$64.80
27	Rear bumper RH reflector <i>X</i>	1PC	\$93.60	\$93.60
28	R/R taillamp <i>X</i>	1PC	\$550.00	\$550.00
29	R/L taillamp / <i>CNT</i>	1PC	\$550.00	\$550.00
30	R/R taillamp reflector <i>X</i>	1PC	\$380.00	\$380.00
31	R/L taillamp reflector / <i>CNT</i>	1PC	\$380.00	\$380.00

LIST TOTAL S\$: \$12,263.31

9,797.01

Supply for bumper
Toolkit box *Supplementary* *PTO*

25.00% DISCOUNT S\$: $\frac{\$3,065.83}{\$9,197.48}$

SPECIAL NETT

1	Bumper clips / AK	1 SET	\$80.00	60
2	Reverse sensor / SHH	1 SET	\$260.00	200
3	Windscreen sealant / AK	1PC	\$100.00	40
4	Body sealant / AK	1PC	\$300.00	50
5	Front & rear number plates / CH	1PC	\$100.00	70
Special Nett Total S\$: $\frac{\$840.00}{\$420.00}$				

420.00

Supplementary

- 1) front bonnet $\$1,288.00$
- 2) Spare tool kit box 480.00

Parts $11,565.01$
 Len 25% $2,891.25$
 $\frac{8,673.75}{SN \quad 420.00}$
 Labor $2,420.00$
 $\frac{11,513.75}{}$

Imp on $\$9,200.00$

8 days

LABOUR CHARGES

- | | | |
|---|--|--|
| 1 | To labour charge for removing front bumper out to facilitate replacement of parts | \$30 ⁰ .00 250 / |
| 2 | To respray front bumper | \$400.00 200 |
| 3 | To remove and install rear tailgate glass | \$120.00 / |
| 4 | Transfer tailgate mechanism | \$100.00 50 |
| 5 | To labour charge for removing rear tailgate, rear bumper, end panel and spare tyre panel out to facilitate repairs and replacemnt of damaged parts | \$1,000.00 800 |
| 6 | To respray rear tailgate, rear end panel, spare tyre panel and rear bumper | \$1,000.00 800 |
| 7 | Towing fee | \$50.00 / |
| 8 | To conduct a standard of opearting procedures post repairs diagnostic scan test as a requirements for hybrid cars upon | \$300.00 200 |

LABOUR TOTAL S\$:	\$3,000.00
TOTAL S\$:	\$13,037.48
7% GST	\$912.62
GRAND TOTAL S\$:	\$13,950.11

2420.00

Store (LKK) with M/L 18/9/19, 12.30pm
8 days
L/S
Ry AL sky

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

DAMAGE ASSESSMENT REPORT

NTUC INCOME INSURANCE CO-OPERATIVE LTD Ref: CS/INC19016480/Etd3e2

73 BRAS BASAH ROAD

Date: 17-12-2019

#05-01 NTUC TRADE UNION HOUSESINGAPORE

189556



ATTN : ENG HUEY HUEY

Code: INC

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SJA 5936T	Veh. Inspected	SLD 8401K
Policy No.		Coverage (\$)	0.00
Claim No.	MT/1060773-002	Excess (\$)	0.00
Assign From	ANNIE KOH	Assign Date	18/09/2019

2. Vehicle Particulars & Condition

Make & Model	TOYOTA SIENTA 1.5X	c.c	1496
Engine No.	HIDDEN	Year of Reg.	2016
Chassis No.	NSP1707031840	Colour	BLACK
Odometer	227314 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	185/60 R15	FIRENZA	5 mm
L/H Front Tyre	185/60 R15	FIRENZA	5 mm
R/H Rear Tyre	185/60 R15	FIRENZA	5 mm
L/H Rear Tyre	185/60 R15	FIRENZA	5 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT AND REAR PORTION. DAMAGES SEE DETAILS.
--

5. General Information

Accident Date	31/08/2019	Inspect Date / Time	18/09/2019 (12:01 PM)
Survey held at	LION CITY RENTALS PTE LTD 60 JALAN LAM HUAT# 04-01 CARROS CENTRE, 728862 SINGAPORE.		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	8 Working Days
-------------------------------------	----------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLD 8401K

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	FRONT BUMPER	DENTED	1,257.83	679.00
1	FRONT BUMPER REINFORCEMENT	NOT NECESSARY	285.00	-
1	FRONT BUMPER ENERGY ABSORBER	NOT NECESSARY	120.00	-
1	FRONT GRILLE	BROKEN	596.25	596.25
1	REAR TAILGATE	DENTED	1,879.00	1,086.00
1	REAR TAILGATE WEATHERSTRIP	TORN	432.00	329.00
1	REAR TAILGATE LOCK	BENT	504.00	420.00
1	REAR TAILGATE LOCK CATCH	NOT NECESSARY	64.80	-
1	REAR TAILGATE CENTER GARNISH	NOT NECESSARY	342.00	-
1	REAR TAILGATE TOYOTA LOGO	NECESSARY	60.00	60.00
1	REAR END PANEL	DENTED	828.00	609.70
1	REAR END PANEL LOWER	DENTED	633.60	410.50
1	REAR END PANEL TOP GARNISH	CRUSHED	250.00	142.10
1	REAR BUMPER REINFORCEMENT	NO SUCH PARTS	338.10	-
1	REAR BUMPER SPONGE	BROKEN	157.50	98.00
1	REAR BUMPER	DENTED	1,257.83	645.00
1	REAR BUMPER RH RETAINER	BROKEN	67.05	67.05
1	REAR BUMPER LH RETAINER	BROKEN	67.05	67.05
1	REAR BUMPER LH SEAL	NOT NECESSARY	104.40	-
1	REAR BUMPER RH SEAL	NOT NECESSARY	104.40	-
1	REAR BUMPER RH SUPPORT	NOT NECESSARY	88.05	-
1	REAR BUMPER LH SUPPORT	NOT NECESSARY	88.05	-
1	REAR BUMPER LH EXTENSION	CUT	216.00	216.00
1	REAR BUMPER RH EXTENSION	NOT NECESSARY	216.00	-
1	REAR BUMPER CENTER EXTENSION	NOT NECESSARY	288.00	-
1	REAR BUMPER PAD	CRUSHED	64.80	64.80
1	REAR BUMPER RH REFLECTOR	NOT NECESSARY	93.60	-
1	R/R TAILLAMP	NOT NECESSARY	550.00	-
1	R/L TAILLAMP	CUT	550.00	450.00
1	R/R TAILLAMP REFLECTOR	NOT NECESSARY	380.00	-
1	R/L TAILLAMP REFLECTOR	CUT	380.00	380.00

Report Ref No. CS/INC19016480/Etd3e2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	BONNET	DENTED	1,288.00	656.00
1	SPARE TOOL KIT BOX	BROKEN	480.00	419.00
	LESS 25% DISCOUNT		-3,507.83	-1,848.86
			10,523.48	5,546.59
	<u>SPECIAL NETT ITEMS</u>			
1	SET BUMPER CLIPS (SN)	NECESSARY	80.00	60.00
1	SET REVERSE SENSOR (SN)	SHORTED	260.00	200.00
1	WINDSCREEN SEALANT (SN)	NECESSARY	100.00	40.00
1	BODY SEALANT (SN)	NECESSARY	300.00	50.00
2	FRONT & REAR NUMBER PLATES (SN)	CUT	100.00	70.00
			840.00	420.00
	<u>LABOUR</u>			
	TO LABOUR CHARGE FOR REMOVING FRONT BUMPER OUT TO FACILITATE REPLACEMENT OF PARTS.		300.00	250.00
	TO RESPRAY FRONT BUMPER.		400.00	200.00
	TO REMOVE AND INSTALL REAR TAILGATE GLASS.		120.00	120.00
	TRANSFER TAILGATE MECHANISM.		100.00	50.00
	TO LABOUR CHARGE FOR REMOVING REAR TAILGATE, REAR BUMPER, END PANEL AND SPARE TYRE PANEL OUT TO FACILITATE REPAIRS AND REPLACEMENT OF DAMAGED PARTS.		1,000.00	800.00
	TO RESPRAY REAR TAILGATE, REAR END PANEL, SPARE TYRE PANEL AND REAR BUMPER.		1,000.00	800.00
	TOWING FEE.		50.00	50.00
	TO CONDUCT A STANDARD OF OPEARTING PROCEDURES POST REPAIRS DIAGNOSTIC SCAN TEST AS A REQUIREMENTS FOR HYBRID CARS UPON.		300.00	200.00
			-	-
			-	-
			-	-
			-	-
			-	-
			3,270.00	2,470.00
	GRAND TOTAL		14,633.48	8,436.59

Report Ref No. CS/INC19016480/Etd3e2



RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED)			6,750.00
---	--	--	----------

Report Ref No. CS/INC19016480/Etd3e2

CHEN TSUE YEE

Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,
MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.