

ASS. REC. BY:

REF: CS/CT1 19016482/UT f3

Special Instruction:

Surveyor: Marcus

ASSIGNMENT (Office)

From (Person): Ong chin kiat of CT1 Date/Time: 18.9.19 14.08 p.m.

Estimated Cost: Bill to:

OD TP RES / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: FBM 8431U Insured: SFH 5Z

at Workshop m/s AS Phooch Tel: 65150770

of BIK 36 Toh Guan Road East Enterprise Hub #01-35

Policy No: DMP/CSN3091219033 Claim No: SNM 19D204192102

Sum Insured: Excess:

Make of Veh: D.O.A. 4.9.2019
(Client's Record)

CA / REV / REP. / REV 24 HRS

Date/Time: 18.9.19 2.17 p.m. Person Contacted: MR Kee Vehicle: IN/OUT

Date/Time	Action/Instruction (✓) Estimate
	Inspection: BIK 3007 ubi road 1 #01-432
	FBM 8431U - X
	SFH 5Z -

(08/11/13) wef

ASS. REC. BY: Marcus

REF:

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

GIA / PR Seen:

Est. Repairs:

Lum Sum:

Consistent? : Yes or No

Consistent? : Yes or No

Res.: Yes or No

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Date / Time

Action / Instruction

Vehicle: IN / OUT

Veh No:

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Colour

Sp. Reading

Eng/No:

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / SRim / STD A/Rim or

Tyre Size:

F:

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal.

L/Bal.

D.O.A.

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Yr Regn:

C.C

A/C: Insured / Std / NI / NA

T/Radio: Insured / Std / NI / NA

N/S	O/S

Front	6	mm	Rear	6	mm
R/Bal.			R/Bal.		mm
L/Bal.		mm	L/Bal.		mm
D.O.A.	4/9/19		D.O.I.	18/9/19	

RECEIVED 15 OCT 2019

Date/Time, File Pass to?

☐

Preli. Report

1) 15/10 Typst

☒

Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech. Invs (\$

☐

Weekend (\$

) S + RS, SI

) Photos

) Others

TOTAL

Report Format:

Lump Sum / I.B.I. (\$ 2900/-)

220

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	10 Sep 2019		18 Sep 2019 14:08 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	HO SIOW POH, ID: S2597704A								
Main Claimant:	MUHAMMAD RAFI BIN ABU BAKAR, ID: S9807420A								
Vehicle Reg. No.:	FBM8431U	Date of Loss:	04/09/2019 21:00 - :59						
Claim Type:	TP / SNM19D204192C02	Policy/Cover Note No.:	DMPCSN30919219033						
Vehicle Reg. No. (Insured):	SFH5Z	Policy No. (Claimant):	AN3175691						
		Excess:	S\$0.00						
Repairer:	A S Phoon Pte Ltd (toh Guan) (HQ) BLK 36 TOH GUAN ROAD EAST ENTERPRISE HUB #01-35, 408701 Jurong Island - Tel:								
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Ong Chin Kiat]								
Claimant's Insurer:	AXA Insurance Pte Ltd (HQ) - Tel: 6338 7288								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 27/09/2019]								
Adj Asg. Remarks:	to assign Mr Marcus Chua for SJE, thank you.								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Singapore NRIC
Owner ID: 420A

Vehicle Details

Vehicle No.: FBM8431U
Vehicle to be Exported: No
Intended Deregistration Date: 19 Sep 2019
Vehicle Make: YAMAHA
Vehicle Model: RXZ
Primary Colour: Silver
Manufacturing Year: 1987
Engine No.: 2UX000365
Chassis No.: 2UX000365
Maximum Power Output: -
Open Market Value: \$0.00
Original Registration Date: 29 Jul 1987
First Registration Date: 29 Jul 1987
Transfer Count: 18
Actual ARF Paid: \$0.00

Intended PARF Rebate Details

PARF Eligibility: No
PARF Eligibility Expiry Date: -
PARF Rebate Amount: \$0.00

Intended COE Rebate Details

COE Expiry Date: 31 Mar 2024
COE Category: D - Motorcycle
COE Period(Years): 10
PQP Paid: \$2,474.00
COE Rebate Amount: \$1,136.00
Total Rebate Amount: \$1,136.00

Message

Please note that the National Environment Agency (NEA) is offering an incentive for the owner of this motorcycle to deregister the motorcycle on or before 5 April 2023.

This motorcycle is currently eligible for an incentive of \$3,500 from NEA. If the COE is renewed from now till its deregistration on or before 5 April 2023, the incentive will be reduced to \$2,000. The last registered owner of this motorcycle will receive the incentive from NEA.

This motorcycle will no longer be allowed for use on Singapore's roads after 30 June 2028.

For more information, please visit <http://www.nea.gov.sg/mtcincentive> or contact NEA at 1800-2255-632.

The information contained herein is correct as at 19 Sep 2019

Listing Type	Paid Ad
Brand	Yamaha (/listing/usedbike/brand/yamaha/)
Model	Yamaha RXZ (/listing/usedbike/model/yamaha-rxz/)
Engine Capacity	133cc
Classification	Class 2B (/listing/usedbike/model/motorcycle-for-sale/class/class-2b/)
Registration Date	08/06/1998
COE Expiry Date	30/04/2023 (3 years 7 months left)
Mileage	55088km
No. of owners	3
Type of Vehicle	Street Bikes (/listing/usedbike/model/motorcycle-for-sale/street-bikes/)

Price: SGD\$7000

DETAILS

Very well maintained. Welcome trade in. Loan available. Ambra Enterprises is located at Block 5034 Ang Mo Kio Industrial Park 2 #01-327.

Accessories

New tyre set.

SIMILAR BIKES

[VIEW ALL \(/LISTING/USEDBIKES/LISTING/\)](/LISTING/USEDBIKES/LISTING/)



Yamaha RXZ



Yamaha RXZ

FBM 8431 M STATE / 07 A. S. PHOON PTE LTD

- REPUBLIC OF SINGAPORE
IDENTITY CARD NO S9807420A



MUHAMMAD RAFI BIN ABU
BAKAR

Male
MARRY
Date of Birth 03-03-1968 M
Country of Birth SINGAPORE



SALES CONTRACT



Vehicle No: S9807420A



Date of Issue 25-04-2013

APT 11K 31 CHAI CHEE AVENUE
F08-172
SINGAPORE 461031

VEHICLE NO: S9807420A COE UNDER: ASP / OWNER SALES PERSON: Xiny

Make/Model/Colour: Yamaha RYZ Engine No: 0314760315 Classic No: 0314760315 Inspection Y/N: Yes

BUYER: MUHAMMAD RAFI BIN ABU BAKAR

Company Name/Office Address: Foodpanda

Telephone: 90622935 H/Phone: 90622935 Marital Status: (S) M

Occupation: Dispatch Rider (Motor)

Remarks: COE 08-2013/2014

PRICE	\$ 7000 + 504 = 7504	
D/PAYMENT	\$ 800	PAID AMOUNT / RECEIPT / DATE
LOAN	\$ 6704	DEPOSIT \$ 200 - 18/6/13
INTEREST	\$ 211	PAYMENT \$ 1906 - 528
BALANCE	\$ 8111.85	PAYMENT \$ 600 - 22/6/13
		PAYMENT \$ 1906 - 601
		BALANCE \$

Total 36 months of instalment. Monthly \$ 226, Final \$ 201.85. Sign → X

Large interest will be charged after 14 days of the due date.

NAMED RIDER NAME: (ACT AS GUARANTOR) HAMIDAH BINTI MAHMOOD Date of Birth: 11/02/1968 Occupation: Dishwasher

NRIC: S6802220C Relationship: Mother

Company Name/Office Address: ABR (Svensen's Nex Mall)

INSURANCE 504 Type N/F/S ()
☐ MITSUI ☐ Comprehensive
☐ NTUC ☐ TPL Fire/Theft
☒ AXA/AIG ☒ Third Party
 Any accident in past three years?
☐ YES ☒ NO AMT: 1.2

I also g. of FBP 66264
I will have a valid SINGPASS on delivery date



潘發展私人有限公司

A. S. PHOON PTE LTD

'cos no one else

Head Off : 399, Changi Road S'pore 419846. Tel: (65) 6747 0770 Fax: (65) 6841 1263
 Ubi : Blk 3007 #01-432/436 Ubi Road 1, S'pore 408701. Tel: (65) 6744 0770 Fax: (65) 6742 0250
 Toh Guan : Blk 36 Toh Guan Road East #01-35 S'pore 608580 Tel: (65) 6515 0770 Fax: (65) 6515 0779
 Website : www.asphoon.com Email: Enquiry@asphoon.com Co Reg No: 197701213H

Not Added
 2/5 2800/
 18/9/19
 5 days
 to highlight
 rep.

FBM8431U YAMAHA RXZ 135 REPAIR ESTIMATE (17/09/2019)

ITEM	DESCRIPTION	AMOUNT (SGD)
1	FRONT WHEEL ASSY	one \$280.00
2	FRONT WHEEL AXLE	set \$18.00
3	FRONT WHEEL BEARING X2	set \$40.00
4	DUST COVER X2	11 \$16.00
5	FRONT BRAKE DISC	set \$125.00
6	FRONT BRAKE CALIPER	2pc \$210.00
7	FRONT FORK ASSY R/H & L/H @\$320	set \$640.00
8	STEM STEERING	set \$165.00
9	CONE BEARING SET	set \$65.00
10	FRONT FORK CROWN	set \$85.00
11	FRONT FENDER	set \$68.00
12	FRONT COWLING	one \$110.00
13	WINDSHIELD	set \$28.00
14	COWLING STAY @ \$15	set \$30.00
15	HEADLAMP	one \$120.00
16	HEADLAMP BRACKET	set \$80.00
17	FRONT SIGNAL LH & RH	2pc \$96.00
18	HANDLEBAR RH	set \$68.00
19	BRAKE LEVER	set \$18.00
20	BRAKE SWITCH	one \$18.00
21	BALANCER	set \$30.00
22	METER ASSY	one \$390.00
23	STAY METER	set \$25.00
24	CLUTCH LEVER	set \$18.00
25	HANDLEBAR LH	set \$68.00
26	SIDE MIRROR	set \$50.00
27	SIDE FAIRING LH	set \$65.00
28	SIDE STAND COMPLETE	set \$60.00
29	GEAR PEDAL	set \$55.00
30	FRONT FOOTREST LH	set \$48.00
31	FRONT FOOTREST BRACKET LH	set \$75.00



潘發展私人有限公司

A. S. PHOON PTE LTD

'cos no one else

Head Off : 399, Changi Road S'pore 419846. Tel: (65) 6747 0770 Fax: (65) 6841 1263
Ubi : Blk 3007 #01-432/436 Ubi Road 1, S'pore 408701. Tel: (65) 6744 0770 Fax: (65) 6742 0250
Toh Guan : Blk 36 Toh Guan Road East #01-35 S'pore 608580 Tel: (65) 6515 0770 Fax: (65) 6515 0779
Website : www.asphoon.com Email: Enquiry@asphoon.com Co Reg No: 197701213H

FBM8431U YAMAHA RXZ 135 REPAIR ESTIMATE (17/09/2019)

ITEM	DESCRIPTION	AMOUNT (SGD)
32	MAINSTAND	1 \$80.00
33	EXHAUST COMP	2 \$390.00
34	GASKET EXHAUST X1	11 \$8.00
35	HEAT PROTECTION	511 \$20.00
36	SIDE FAIRING RH	511 \$65.00
37	FRONT FOOTREST RH	111 \$48.00
38	FRONT FOOTREST BRACKET RH	511 \$75.00
39	BRAKE PEDAL	111 \$68.00
40	KICK STARTER	111 \$85.00
41	FUEL TANK	111 \$390.00
42	2T PUMP COVER	111 \$60.00
43	HORN	511 \$30.00
44	WORKMANSHIP	\$600.00
45	TRANSPORTATION TP-IDAC-BIKESHOP	\$100.00
46	BODY CHASSIS REPAIR	\$450.00
47	TRANSPORTATION X2 @ \$50	Repairs \$100.00
TOTAL		\$5,733.00

LINK Auto Consultants hence notify the Insurer of the following:

- To be done immediately after spray painting
- To be done immediately after part(s) during assembly
- Repairs are subject to confirmation
- This estimate is on a "Without Prejudice" basis
- Any modification(s) is allowed
- Supplementary item(s) must be removed and is subject to final approval from Insurance Company

Acknowledged by Repairer:

Signature:

Date:

3771
102
3393.90
40589

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CT119016482/UTF3N2

Date: 16/10/2019

REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMPCSN30919219033	
Claimant Vehicle No :	FBM8431U	Insured Vehicle No :	SFH5Z	
Date of Loss:	04/09/2019	Nature of Claim:	TP	Claim No: SNM19D204192C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	FBM8431U	Engine No:	2UX000365
Make & Model:	YAMAHA RXZ, 133cc (M)	Chassis No:	2UX000365
Reg. Date:	29/07/1987 (Man. Year: 1987)	Odometer:	90496 km
Colour:	White/Blue		
Engine Capacity:	133 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	80-90-18	Rear Tyre Size:	3.00-18
Front Left Side:	Pirelli 6 mm	Rear Left Side:	Pirelli 6 mm
Front Right Side:	0 mm	Rear Right Side:	0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	4,483.00	3,393.90	1,089.10	24.29
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,250.00	665.00	585.00	46.80
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	5,733.00	4,058.90	1,674.10	29.20
Approved Total (Overridden) (\$\$)		2,800.00		
(\$\$)	5,733.00	2,800.00	2,933.00	51.16
+ GST 7.00/7.00% (\$\$)	401.31	196.00	205.31	51.16
Nett Amount (\$\$)	6,134.31	2,996.00	3,138.31	51.16

INSPECTION

Date of Assignment:	18/09/2019
Date Inspected:	18/09/2019 Inspected At:

Blk 3007 Ubi Road 1 #01-432
 Repairer: A S Phoon Pte Ltd (toh Guan)
 BLK 36 TOH GUAN ROAD EAST
 ENTERPRISE HUB #01-35
 Singapore 408701

Estimated Period of Repair:	5.0 days
------------------------------------	----------

Adjuster: MARCUS CHUA

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	(Last Synchronised: 16 Oct 2019)	
Parts:	N/A	YAMAHA RXZ 133cc (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for FBM8431U)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT WHEEL ASSY	Cracked	280.00 F	*280.00 FL
2	1		*FRONT WHEEL AXLE	Bent	18.00 F	*18.00 FL
3	2		*FRONT WHEEL BEARING	Necessary	40.00 F	*40.00 FL
4	2		*DUST COVER	Not Necessary	16.00 F	*- FL
5	1		*FRONT BRAKE DISC	Bent	125.00 F	*125.00 FL
6	1		*FRONT BRAKE CALIPER	Damaged	210.00 F	*210.00 FL
7	2		*FRONT FORK ASSY R/H & L/H	Bent/Twisted	640.00 F	*640.00 FL
8	1		*STEM STEERING	Bent	165.00 F	*165.00 FL
9	1		*SET CONE BEARING	Necessary	65.00 F	*65.00 FL
10	1		*FRONT FORK CROWN	Bent	85.00 F	*85.00 FL
11	1		*FRONT FENDER	Broken	68.00 F	*68.00 FL
12	1		*FRONT COWLING	Cracked	110.00 F	*110.00 FL
13	1		*WINDSHIELD	Scratched	28.00 F	*28.00 FL
14	2		*COWLING STAY	Bent	30.00 F	*30.00 FL
15	1		*HEADLAMP	Cracked	120.00 F	*120.00 FL
16	1		*HEADLAMP BRACKET	Repair	80.00 F	*- FL
17	1		*FRONT SIGNAL LH & RH	O/s Cut	96.00 F	*48.00 FL
18	1		*HANDLE BAR RH	Bent	68.00 F	*68.00 FL
19	1		*BRAKE LEVER	Scratched	18.00 F	*18.00 FL
20	1		*BRAKE SWITCH	Cut	18.00 F	*18.00 FL
21	1		*BALANCER	Scratched	30.00 F	*30.00 FL
22	1		*METER ASSY	Cracked	390.00 F	*390.00 FL
23	1		*STAY METER	Bent	25.00 F	*25.00 FL
24	1		*CLUTCH LEVER	Twisted	18.00 F	*18.00 FL
25	1		*HANDLE BAR LH	Bent	68.00 F	*68.00 FL
26	1		*SIDE MIRROR	Broken	50.00 F	*50.00 FL
27	1		*SIDE FAIRING LH	Broken	65.00 F	*65.00 FL
28	1		*SIDE STAND COMPLETE	Broken/Missing	60.00 F	*60.00 FL
29	1		*GEAR PEDAL	Twisted	55.00 F	*55.00 FL
30	1		*FRONT FOOTREST LH	Twisted	48.00 F	*48.00 FL
31	1		*FRONT FOOTREST BRACKET LH	Bent	75.00 F	*75.00 FL
32	1		*MAINSTAND	Repair	80.00 F	*- FL
33	1		*EXHAUST COMP	Repair	390.00 F	*- FL
34	1		*GASKET EXHAUST	Not Necessary	8.00 F	*- FL
35	1		*HEAT PROTECTION	Scratched	20.00 F	*20.00 FL
36	1		*SIDE FAIRING RH	Broken	65.00 F	*65.00 FL
37	1		*FRONT FOOTREST RH	Twisted	48.00 F	*48.00 FL
38	1		*FRONT FOOTREST BRACKET RH	Bent	75.00 F	*75.00 FL
39	1		*BRAKE PEDAL	Bent	68.00 F	*68.00 FL
40	1		*KICK STARTER	Cut	85.00 F	*85.00 FL
41	1		*FUEL TANK	Dented	390.00 F	*390.00 FL
42	1		*2T PUMP COVER	Not Necessary	60.00 F	*- FL
43	1		*HORN	Serviceable	30.00 F	*- FL

F=Franchise part. L=ListItemDisc.

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
Sub Total (S\$)					4,483.00	3,771.00
- List Item Discount on L Items 0.00/10.00% (S\$)					0.00	377.10
Total Parts (S\$)					4,483.00	3,393.90

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	WORKMANSHIP	New	600.00	380.00
2	TRANSPORTATION TP-IDAC-BIKESHOP	New	100.00	35.00
3	BODY CHASSIS REPAIR	New	450.00	250.00
4	TRANSPORTATION X2	New	100.00	0.00
Gross Labour Cost (S\$)			1,250.00	665.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >